



Surveyor *Patric*

REF:

8477 / 163 / 3-550

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: **SKN 70014**  
at Workshop m/s: **PERFORMANCE**  
of \_\_\_\_\_  
Insured: **AK/np**  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: **5** days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SKN 70014** Yr Regn: **2013 / 3UN**  
Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: **B.M.W 535I AT.** C.C. **2979**  
Colour: **Grey** A/C Insured / Std / NI / NA  
Sp. Reading: **100923** T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: **WBAFR72070C958800**  
Gen. Cond: Good / **Fair** / Poor / Burnt  
Steering: **Order** / Jammed / Leaked / Burnt or  
Brake: **Order** / Jammed / Leaked / Burnt or  
Modl: **Nil** / **SRim** / STD A/Rim or  
Tyre Size: F: **215/35R19**  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / **PIR** / SUMI /  
TOYO / YOKO or

Front		Rear
R/Bal. <b>6</b> mm		R/Bal. <b>6</b> mm
L/Bal. <b>6</b> mm		L/Bal. <b>6</b> mm
D.O.A. <b>04/05/18</b>		D.O.I. <b>16/05/18</b>
Survey held at: <b>PERFORMANCE</b>		

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

**op FR**  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

**\$ 9,015.95**

**R (\$ 2,741.25/237.)**

Date/Time: File Pass to?

☐ : Prel. Report  
☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) B x RS. SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ )

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18008477/ub3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 09-05-2018



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 8775E	Veh. Inspected	SKN 7001Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	04/05/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64767770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796401 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

08 MAY 2018

Estimate No. : b1 46861  
Date Estimated : 08/05/2018  
Prepared By : Merina Chia San San

Page No. : 1 of 2

### - ESTIMATE REPAIR FOR -

Himanshu S/O R L Bakhda  
299 Bedok South Ave 3  
#01-16 Bedok Court

Singapore 469298

- ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN7001Y	C958800	21/06/2013	535iA	0

### DESCRIPTION

To replace front bumper, front right fender including attachments etc and to knock out dented area caused by accident

1700 ~~2,550.00~~

To paint front bumper and front right fender

1730 ~~1,923.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~177.00~~

To carry out body cavity preservation.  
(Per panel).

100 ~~118.00~~

Sundries.

80 ~~150.00~~

Total Labour 1: 4,918.00

### DESCRIPTION

FRT RH 2 SIDE PANEL BRACKET  
FRT RH 3 SIDE PANEL BRACKET  
FRT RH 4 SIDE PANEL BRACKET  
FRT RH 1 SIDE PANEL BRACKET  
FRT RH FENDER  
FRT RH BOTTOM DEFORMATION ELEMENT  
FRT BUMPER RH CONNECTOR  
FRT BUMPER CARRIER  
FRT BUMPER TOP IMPACT ABSORBER  
FRT BUMPER BOTTOM MOUNT  
FRT BUMPER RH SPACER  
COVERING PRIMEND LH  
FRT BUMPER TRIM PRIMED (PDC)  
EMBLEM GROMMET  
BMW EMBLEM  
RH BI-XENON HEADLIGHT  
RH FOG LIGHT  
DECOUPLING RING PDC TORQUE CONVERTE

QTY PRIC

1 32.15  
1 32.15  
1 32.15  
1 32.15  
1 863.35  
1 101.70  
1 54.75  
1 684.75  
1 48.00  
1 157.50  
1 9.45  
1 46.45  
1 1,277.55  
2 0.80  
1 69.50  
1 2,631.15  
1 260.75  
4 5.05

VALUE

32.15  
32.15  
32.15  
32.15  
863.35  
101.70  
54.75  
684.75  
48.00  
157.50  
9.45  
46.45  
1,277.55  
1.60  
69.50  
2,631.15  
260.75  
20.20



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438186  
Tel. 63180886 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/E30 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 46861  
Date Estimated : 08/05/2018  
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN7001Y	C958800	21/06/2013	535iA	0

Total Parts : 6,355.30

**LKK Auto Consultancy** hereby notify  
the Repairer of the following:

- To resurvey before or spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Client ID (or Policy No.) 16/05/18 @ 1700  
 Reg No. 90010068  
 Date 16/05/18  
 Signature Rashid  
 Approved 5 days

Labour 1	:	4,918.00
Parts	:	6,355.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	789.13
<b>Grand Total</b>	:	<b>12,062.43</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401509M; GST Reg. No. M2-0020091-X



## FINAL REPORT

Estimate No. : b1 46861  
Date Estimated : 08/05/2018  
Prepared By : Merina Chia San San

Page No. :

**REPAIR FOR -**  
Himanshu S/O R L Bakhda  
299 Bedok South Ave 3  
#01-16 Bedok Court

**- ACCOUNT - 121**  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 469298

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SKN7001Y	C958800	21/06/2013	535iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, front RH fender include knocking out dented areas caused by the accident	1700.00		1,700.00	
To spray paint front bumper and front RH fender	1730.00		1,730.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
* To replace RH bi xenon headlight include programming and conducting checks for proper function	451.00		451.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH FENDER	863.35	1.00		863.35
FRT BUMPER TRIM PRIMED (PDC)	1,277.55	1.00		1,277.55
# RIVET *	0.45	3.00		1.35
# HEADLIGHT GASKET SET *	31.55	1.00		31.55
RH BI-XENON HEADLIGHT	2,631.15	1.00		2,631.15

### # SUPPLEMENTARY ITEMS

Total Labour :	4,211.00
Total Parts :	4,804.95
Total Labour & Parts :	9,015.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,015.95
GST @7%:	631.12
<b>Grand Total :</b>	<b>9,647.07</b>

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197601559W, GST Reg. No. M3-0000091-X



## SUPPLEMENTARY

Estimate No. : b1 46861  
Date Estimated : 08/05/2018  
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -  
Himanshu S/O R L Bakhda  
299 Bedok South Ave 3  
#01-16 Bedok Court

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 469298

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKN7001Y	C958800	21/06/2013	535iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RIVET *	0.45	3.00		1.35
# HEADLIGHT GASKET SET *	31.55	1.00		31.55

Total Labour :	
Total Parts :	32.90
Total Labour & Parts :	32.90

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SKN7001Y	Model:	
Date of Accident:	4.5.2018		

Global Sum Settlement	: [ ] Yes [ ] No	
Repair Estimate	: \$	12062.43
Final Repair Cost	: \$	9647.07
Loss of Use	: \$	days at \$ per day
Rental (if any)	: \$	— days
LTA / GIA Search Fee	: \$	2.00
Others:	: \$	
	: \$	
Final Settlement Sum	: \$	9649.07

Is Third Party Workshop GIA Registered? [ ] YES [ ] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	: \$ 9647.07
2)	Performance Motors Ltd	: \$ 2.00
3)		: \$

Signed by appointed surveyor \_\_\_\_\_

Date \_\_\_\_\_

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
Survey Report; Medical Report/ Bill (if any))



## Print Received Message

This mail is associated with :

**\*SKN7001Y (2549104502SG)  
[GBC8775E]**

TP

HIMANSHU R L BAKDHA

May 4 2018 1:00PM

[SUNBEAM AQUARIUM PTE LTD]

Performance Motors Limited

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 14/12/2018 15:31 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10419.47) - SKN7001Y - Claim Handler: Syed-Yusoff, Saliha

Approved:10419.47:approval for settlement is subject to final repair bill & ATA

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Wednesday, 6 June 2018 4:37 PM  
**To:** 'enquiry@sunbeamaquarium.com'  
**Subject:** RE: ACCIDENT INVOLVING GBC 8775E & SKN 7001Y ON 04/05/2018



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18008477/ub3

06 JUNE 2018

**SUNBEAM AQUARIUM PTE LTD**

Dear Sir/Madam,

**ACCIDENT INVOLVING GBC 8775E & SKN 7001Y ON 04/05/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)


**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**


I, HIMANSHU S/O R L BAKHDA (the third party claimant) of 299 Bedok South Ave 3 # 01-16 Bedok Court (419298) (address), owner of SKN7001Y (vehicle no.) hereby authorize Performance Motors Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SKN7001Y that was damaged pursuant to the accident which occurred on 4.5.2018 (date) along THOMSON ROAD (location) involving vehicle no/s 6BC877SE ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 16 (day) of 05 (month) 20 18 (year)

  
Signed by "the third party claimant"  
(with chop if applicable)

  
Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Express Third Party Claim)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$9647.07 (Repair Cost), S\$770.40 (Loss of rental/use), S\$ 2 (Disbursement), for vehicle no. SKN7001Y that was damaged pursuant to the accident which occurred on 4.5.18 (date) along THOMSON ROAD (location) involving vehicle no/s 686872SE. This is pursuant to the inspection conducted on 16.5.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Himanshu S/o R L Rakhda ("the third party claimant") of vehicle no. SKN7001Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKN7001Y (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17 (day) of DEC (month) 2018 (year)

  
meB

Signed by appointed surveyor

  
☆

Signed by "the workshop" (with chop)

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159943  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747772

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190886 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/538 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : B1 1268001

Date IN : 17/05/2018

Cust. Svc. Advisor: Merina Chia San San

Page No. : 1 of 2

Invoice Number : 2004817 / WSB

Invoice Date : 05/09/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

**- CUSTOMER INFORMATION -**

Mr Himanshu S/O R L Bakhda  
299 Bedok South Ave 3  
#01-16 Bedok Court

Singapore 469298

**- INVOICE TO - 121**

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO. /  
SKN7001Y

CHASSIS NO.  
C958800

REGN. DATE  
21/06/2013

MODEL  
535IA

MILEAGE  
100923

**- - - - LABOUR 1 - - - -**

To replace front bumper and front right fender including  
to remove and install body parts in order to carry out  
painting job.

To respray front bumper and front right fender.

To check electrical wiring systems at the front section  
for proper function including adjustments of headlights.

To carry out body cavity preservation.

To replace right Bi-Xenon headlight and check for proper  
function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 4.5.2018. 3RD PARTY CAR : GBC8775E.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO ON  
16.5.2018 AT 5.00 PM. AUTHORISED REPAIR BY MS THIN THIN  
HLAING FROM LKK ON 15.5.2018 VIA E-MAIL.

CAR RENTAL PROVIDED BY AIG.

GIA SEARCH FEE = \$2.00.

NETT

1,700.00

1,730.00

150.00

100.00

451.00

80.00

0.00

0.00

0.00

Total Labour 1: **4,211.00****- - - - PARTS - - - -**

FRT RH FENDER

FRT BUMPER TRIM PRIMED (PDC)

RH BI-XENON HEADLIGHT

HEADLIGHT GASKET SET

RIVET

Qty Retail  
Price

1 863.35

1 1,277.55

1 2,631.15

1 31.55

3 0.45

NETT

863.35

1,277.55

2,631.15

31.55

1.35

Total Parts : **4,804.95**



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampung Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

111, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1268001</b>	Page No. : <b>2 of 2</b>
Date IN : <b>17/05/2018</b>	Invoice Number : <b>2004817 / WSB</b>
Cust. Svc. Advisor: <b>Merina Chia San San</b>	Invoice Date : <b>05/09/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

Labour Charges : <b>4,131.00</b>	Total Labour & Parts Charges : <b>S\$ 9,015.95</b>
Parts Charges : <b>4,804.95</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>80.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 9,015.95</b>
	GST @ 7% : <b>S\$ 631.12</b>
	Invoice Total Amount Include GST : <b>S\$ 9,647.07</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 9,647.07**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





## TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
AIG ASIA PACIFIC INSURANCE PTE. LTD. 78 SHENTON WAY #07-16 SINGAPORE 079120 ATTN: CLAIMS DEPARTMENT C/O LKK AUTO CONSULTANT PTE LTD

DATE	INVOICE NO.
24-May-2018	P 1187

DESCRIPTION	VHA NO.	DUE DATE	VEH. NO.
	P 1187	24-May-2018	SKL 5444 B
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 16 MAY 2018 TO 22 MAY 2018 (INCLUDED ONE SATURDAY AND ONE SUNDAY) YOUR REF: SKN7001Y & GBC8775E (PERFORMANCE)	6	120.00	720.00
GST @ 7%			\$50.40
TOTAL			\$770.40

All cheques must be made payable to BKW Rent A Car Pte Ltd.  
Please write the vehicle and invoice number on the reserve.

### BKW Rent-A-Car Pte Ltd

120 Lower Delta Road #02-15 Cendex Centre (S) 169208 Tel: 6738 7777 Fax: 6738 6666

ACRA No: 200106276D GST Reg. No: 20-0106276-D Website: www.bkw.sg

A subsidiary of BKW Automobile Pte Ltd



**bizSAFE**

**HIRER'S PARTICULARS**

Name (as in IC): **HIMANSHU S/O R L BAKHDA**  
 NRIC/Passport No: **S7443055D** Date of Birth: **03.12.1974**  
 Address: **5 MAYFIELD AVENUE** Age: **43**  
 S( **438019** )  
 Name & Address of Employer: **-**  
 Occupation: **-** Driving Exp: **13**  
 Driving Licence No: **S7443055D** Passed Date: **07.12.2004**  
 D/L Type: Local/Int'l/Other: **-**  
 Tel(O) **-** (R) **-** HP **9321 9321**

**DRIVER'S PARTICULARS**

Name (as in IC): **POOJA**  
 NRIC/Passport No: **S7782376Z** Date of Birth: **25.06.1977**  
 Address: **5 MAYFIELD AVENUE** Age: **40**  
 S( **438019** )  
 Occupation: **-** Driving Exp: **21** Yrs  
 Driving Licence No: **S7782376Z** Passed / Expiry Date: **26.07.1996**  
 D/L Type: Local/Int'l/Other: **-** Contact No: **-**

Hirer's Own Vehicle No: **SKN7001Y** Replace Veh No: **-**  
 Loan Vehicle No: **SKL5444B** VR No: **-**  
 Make & Model: **TOYOTA CAMRY** Auto/Manual Group: **-**

CHARGES		\$	cts
Daily	<b>06</b> day @ \$ <b>120</b>	Per day	<b>720 00</b>
Weekly/Monthly	week @ \$	Per week/Monthly	
Others			
CDW/PAI	@ \$	Per day/Monthly	
Delivery/Collection Svc			
GST			
OR No: (A) SUB-TOTAL			
Petrol Level & Surcharge	OUT IN	E 1/4 1/2 3/4 F	
First	km FREE per day	GST	<b>7%</b> <b>50 40</b>
Excess mileage is chargeable at		TOTAL CHARGES	<b>770 40</b>

Security Deposit : \$ **-** Bank: **Citi**  
 CASH/NETS/VISA/MC/AMEX/CHQ No: **4147-4630-0292-4664**

Expiry Date: **06/18** Card ID No: **5232**  
 Name as in Card: **Himanshu Bakhda**


NON WAIVER EXCESS (Subject to GST): \$ **3,000/-**

**ACCESSORIES CHECK**

☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge  
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature : **[Signature]** Additional Driver's Signature : **[Signature]**

**SINGAPORE Use Only**



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given BKW Rent A Car Pte Ltd in connection with this agreement is true.

**IMPORTANT**

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be Borne by the Hirer/the Authorised Driver.
- All vehicles are supplied with petrol and should returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace a replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other marketing matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
16.05.18	1700	73686	EMWIN	

Return Of Vehicle: The Hirer Driver is Required To Sign In The Column 'Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)'

Date In	Time In	Mileage	Check By	Remarks
22.05.18	1400	74366	EMW	

Hirer's/Driver Signature

Hirer's/Driver Signature



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-069303  
Date of Request: 08/05/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 08/05/2018  
Enquiry By Vivi  
TP Vehicle No. GBC8775E  
Accident Date 04/05/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBC8775E	AIG Asia Pacific Insurance Pte. Ltd.	07/02/2018-06/02/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-069303  
Date of Request: 08/05/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 08/05/2018  
Enquiry By Vivi  
TP Vehicle No. GBC8775E  
Accident Date 04/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:  
Date:  
☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2018 <a href="#">Edit Reg</a>		16 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$9,015.95</b> <a href="#">Edit Estimates</a>	<b>S\$9,015.95</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SUNBEAM AQUARIUM PTE LTD. Co. Reg. No.: 198105215Z		
Main Claimant:	HIMANSHU R L BAKDHA. ID: S7443055D		
Vehicle Reg. No.:	SKN7001Y	Date of Loss:	04/05/2018 13:00 - :59 [58 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2549104502SG	Policy/Cover Note No.:	2100363714 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC8775E	Policy No. (Claimant):	2100489764
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/05/2018]		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG\_EXPRESS (14/12/2018): Alert - Adj Mandate Approved (S\$10419.47) - SKN7001Y - Claim Handler: Syed-Yusof...

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKN7001Y (2549104502SG)  
[GBC8775E]  
TP  
HIMANSHU R L BAKDHA  
May 4 2018 1:00PM  
[SUNBEAM AQUARIUM PTE LTD]  
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser</span>	
<b>Letters/Correspondences</b>										1 per page <span style="float: right;">1</span>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown						1		Edit	
<b>Photos/Images</b>										3 per page <span style="float: right;">3</span>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	05/12/18 16:46	General View						1		Load JPG	
2	05/12/18 16:46	General View						1		Load JPG	
3	05/12/18 16:46	General View						1		Load JPG	
4	05/12/18 16:46	General View						1		Load JPG	
5	05/12/18 16:46	General View						1		Load JPG	
6	05/12/18 16:46	General View						1		Load JPG	
7	05/12/18 16:46	General View						1		Load JPG	
8	05/12/18 16:46	General View						1		Load JPG	
9	05/12/18 16:46	General View						1		Load JPG	
10	05/12/18 16:46	General View						1		Load JPG	
11	05/12/18 16:46	General View						1		Load JPG	
12	05/12/18 16:46	General View						1		Load JPG	
13	05/12/18 16:46	General View						1		Load JPG	
14	05/12/18 16:46	General View						1		Load JPG	
15	05/12/18 16:46	General View						1		Load JPG	
16	05/12/18 16:46	General View						1		Load JPG	
17	05/12/18 16:46	General View						1		Load JPG	
18	05/12/18 16:46	General View						1		Load JPG	
19	05/12/18 16:46	General View						1		Load JPG	
20	05/12/18 16:46	General View						1		Load JPG	
21	05/12/18 16:46	General View						1		Load JPG	
22	05/12/18 16:46	Reinspection Photo						1		Load JPG	
23	05/12/18 16:46	Reinspection Photo						1		Load JPG	
24	05/12/18 16:46	Reinspection Photo						1		Load JPG	
25	05/12/18 16:46	Reinspection Photo						1		Load JPG	
26	05/12/18 16:46	Reinspection Photo						1		Load JPG	
27	05/12/18 16:46	Reinspection Photo						1		Load JPG	
28	05/12/18 16:46	Reinspection Photo						1		Load JPG	
29	05/12/18 16:46	Reinspection Photo						1		Load JPG	
30	05/12/18 16:46	Reinspection Photo						1		Load JPG	
31	05/12/18 16:46	Reinspection Photo						1		Load JPG	
32	05/12/18 16:46	Reinspection Photo						1		Load JPG	
33	05/12/18 16:46	Reinspection Photo						1		Load JPG	
34	05/12/18 16:46	Reinspection Photo						1		Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/18 12:53	TP EST & GIA REPORT	 Load TIF	
2	22/05/18 08:33	TP ESTIMATE- MARKED	 Load PDF	
3	28/05/18 19:10	RENTAL RECEIPT	 Load PDF	
4	03/12/18 09:46	GIA SEARCH	 Load PDF	
5	19/12/18 09:44	WORKSHOP INVOICE	 Load PDF	
6	19/12/18 09:44	AUTHORISATION TO ACT FORM	 Load PDF	
7	19/12/18 09:44	Release Voucher	 Load PDF	
8	19/12/18 09:44	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/05/18 12:36	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBC8775E (Insd veh)	Model:	BMW 535i 3.0 (A)
	SKN7001Y (TP veh)		
Date of Accident:	04/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	12,580.20
Final Repair Cost	:	\$	9,647.07
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	770.40 6 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,419.47
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____(%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: <del>Yes</del> / No BOLA Scenario No: _____			
BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 9,649.07
2)	BKW Rent-A-Car Pte Ltd	:	\$ 770.40
3)		:	\$

JOANNE LEE KHANG MIN

19 Dec  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18008477/R1JB3Q2

Date: 19/12/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100363714
<b>Claimant Vehicle No :</b> SKN7001Y	<b>Insured Vehicle No :</b> GBC8775E
Date of Loss: 04/05/2018	Nature of Claim: TP Claim No: 2549104502SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN7001Y	Engine No:	05988290N55B30A
Make & Model:	BMW 535i, 3.0 (A)	Chassis No:	WBAFR72070C958800
Reg. Date:	21/06/2013 (Man. Year: 2012)	Odometer:	100923 km
Colour:	Grey		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/35 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,538.20	4,884.95	1,653.25	25.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,219.00	4,131.00	1,088.00	20.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,757.20</b>	<b>9,015.95</b>	<b>2,741.25</b>	<b>23.32</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>823.00</b>	<b>631.12</b>	<b>191.88</b>	<b>23.31</b>
<b>Nett Amount (S\$)</b>	<b>12,580.20</b>	<b>9,647.07</b>	<b>2,933.13</b>	<b>23.32</b>
<b>+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		<b>770.40</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>10,419.47</b>		

### INSPECTION

Date of Assignment:	16/05/2018	
Date Inspected:	16/05/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

---

**Adjuster:** MOHD RASUL**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRT RH 2 SIDE PANEL BRACKET	Serviceable	32.15 FS	*- FS
3	1		*FRT RH 3 SIDE PANEL BRACKET	Serviceable	32.15 FS	*- FS
4	1		*FRT RH 4 SIDE PANEL BRACKET	Serviceable	32.15 FS	*- FS
5	1		*FRT RH 1 SIDE PANEL BRACKET	Serviceable	32.15 FS	*- FS
6	1		*FRT RH FENDER	Bent	863.35 FS	*863.35 FS
7	1		*FRT RH BOTTOM DEFORMATION ELEMENT	Serviceable	101.70 FS	*- FS
8	1		*FRT BUMPER RH CONNECTOR	Serviceable	54.75 FS	*- FS
9	1		*FRT BUMPER CARRIER	Serviceable	684.75 FS	*- FS
10	1		*FRT BUMPER TOP IMPACT ABSORBER	Serviceable	48.00 FS	*- FS
11	1		*FRT BUMPER BOTTOM MOUNT	Serviceable	157.50 FS	*- FS
12	1		*FRT BUMPER RH SPACER	Serviceable	9.45 FS	*- FS
13	1		*COVERING PRIMEND LH	Serviceable	46.45 FS	*- FS
14	1		*FRT BUMPER TRIM PRIMED (PDC)	Deformed	1,277.55 FS	*1,277.55 FS
15	2		*EMBLEM GROMMET	Not Necessary	1.60 FS	*- FS
16	1		*BMW EMBLEM	Not Necessary	69.50 FS	*- FS
17	1		*RH BI-XENON HEADLIGHT	Cracked	2,631.15 FS	*2,631.15 FS
18	1		*RH FOG LIGHT	Not Necessary	260.75 FS	*- FS
19	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
20	3		*RIVET	Necessary	1.35 F	*1.35 F
21	1		*SET HEADLIGHT GASKET	Necessary	31.55 F	*31.55 F
Total Parts (\$\$)					6,538.20	4,884.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER ,FRONT RIGHT FENDER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	2,550.00	1,700.00
2	TO PAINT FRONT BUMPER AND FRONT RIGHT FENDER	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
5	TO REPLACE RH BI XENON HEADLIGHT INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	451.00	451.00
Gross Labour Cost (S\$)			5,219.00	4,131.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >