

9R (LOR-BKW)

1715 10.00

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 MAY 2018

Estimate No.	: b1 46861	Page No. :	1 of 2
Date Estimated	: 08/05/2018		
Prepared By	: Merina Chia San San		

- ESTIMATE REPAIR FOR - Himanshu S/O R L Bakhda 299 Bedok South Ave 3 #01-16 Bedok Court Singapore 469298	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN7001Y	C958800	21/06/2013	535iA	0

DESCRIPTION	VALUE
To replace front bumper, front right fender including attachments etc and to knock out dented area caused by accident	1700 2,550.00
To paint front bumper and front right fender	1730 1,923.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	? 150.00
Total Labour 1:	4,918.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH 2 SIDE PANEL BRACKET	1	32.15	? 32.15
FRT RH 3 SIDE PANEL BRACKET	1	32.15	? 32.15
FRT RH 4 SIDE PANEL BRACKET	1	32.15	? 32.15
FRT RH 1 SIDE PANEL BRACKET	1	32.15	? 32.15
FRT RH FENDER	1	863.35	863.35
FRT RH BOTTOM DEFORMATION ELEMENT	1	101.70	? 101.70
FRT BUMPER RH CONNECTOR	1	54.75	? 54.75
FRT BUMPER CARRIER	1	684.75	? 684.75
FRT BUMPER TOP IMPACT ABSORBER	1	48.00	? 48.00
FRT BUMPER BOTTOM MOUNT	1	157.50	? 157.50
FRT BUMPER RH SPACER	1	9.45	? 9.45
COVERING PRIMEND LH	1	46.45	? 46.45
FRT BUMPER TRIM PRIMED (PDC)	1	1,277.55	Repair 1,277.55
EMBLEM GROMMET	2	0.80	x 1.60
BMW EMBLEM	1	69.50	x 69.50
RH BI-XENON HEADLIGHT	1	2,631.15	CR 2,631.15
RH FOG LIGHT	1	260.75	? 260.75
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	? 20.20

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No.	: b1 46861	Page No. : 2 of 2
Date Estimated	: 08/05/2018	
Prepared By	: Merina Chia San San	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN7001Y	C958800	21/06/2013	535iA	0

Total Parts : **6,355.30**

LKK Auto Consultant hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>16/05/18 @ 1700</u>	Excess S\$ _____
Surveyor's Name <u>Rafael</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Arrival of Date _____	Time _____
REPAIR TO BE DONE BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>5 days</u>	

Labour 1	:	4,918.00
Parts	:	6,355.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	789.13
Grand Total	:	12,062.43

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **