

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 09/05/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : BEENA RAI
: AXA INSURANCE PTE LTD
Certificate No : GA115767/1
Vehicle No : SJV-6309-L
Accident Date : 27/04/2018
Make & Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG 19

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT BUMPER	195.00	de
2	FRONT BUMPER RETAINER	100.00	ner
2	FRONT BUMPER BRACKET	140.00	ner
1	FRONT BUMPER LOWER GRILLE	45.00	de
1	FRONT BUMPER SPONGE	42.00	?
1	FRONT BUMPER REINFORCEMENT	135.00	?
10	FRONT BUMPER CLIPS	20.00	de
1	FRONT NUMBER PLATE BASE HOLDER	55.00	de
1	FRONT GRILLE	170.00	ner

Date : 09/05/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : BEENA RAI
: AXA INSURANCE PTE LTD

Certificate No : GA115767/1

Accident Date : 27/04/2018

Vehicle No : SJV-6309-L

Make & Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG 19

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE LOGO	25.00	✓
2	FRONT GRILLE SIDE CLIPS	16.00	✓
1	BONNET	380.00	✓
10	BONNET INSULATOR CLIPS	15.00	✓
1	BONNET LOCK	55.00	?
2	HEADLAMP RH/LH	620.00	LH-?, RH-00 ✓
2	FRONT AIRGUIDE RH/LH	90.00	LH-P, RH-de ✓
1	SUPPORT PANEL ASSY	350.00	RY
1	BRACE PANEL	38.00	✓
1	AIRCON CONDENSER	180.00	?

Date : 09/05/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : BEENA RAI
: AXA INSURANCE PTE LTD

Certificate No : GA115767/1

Accident Date : 27/04/2018

Vehicle No : SJV-6309-L

Make & Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG 19

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	FRONT FENDER RH/LH	RESTORE	
	Sub Total	2671.00	
	Add 0% On Parts	0.00	
	Special Nett Item		
1	FRONT NUMBER PLATE	35.00	67
1	COOLANT	30.00	?
	Sub Total	65.00	
	Labour & Misc		700
	LABOUR TO FACILITATE REPAIR	900.00	
	TO RESPRAY AFFECTED AREAS	900.00	700

Date : 09/05/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : BEENA RAI
: AXA INSURANCE PTE LTD

Certificate No : GA115767/1

Accident Date : 27/04/2018

Vehicle No : SJV-6309-L

Make & Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG 19

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	✓
	TO TOP UP AIRCON GAS	100.00	?
	Sub Total	1930.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: **SUB TOTAL** 4,666.00
Date:

GST 7.0 % 326.62

TOTAL 4,992.62

Remarks:

Surveyor's name:

Tan Jia 97495745

Principal's name: BEENA RAI

Survey Date & Time: 10/5/18 @ 1115

Resurvey before paint 5 days
Repair, Not Adjust
Ex: to be advise.

PAGE: 4