



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

1 2009 TOYOTA CAMRY 2.0 (SVJ6309L)

Date of Loss

April 27, 2018

Time of Loss

15.15

Loss Description

SVJ6309L (INSD) HIT IN REAR OF SHC5053D

Comment

### Workshop Details

Total Rebate Amount

18772

Nett Loss Amount

\$14,228.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion \*

08/09/2018



Days of work completion \*

84



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

SJV6309L

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date \*

02/02/2010



Mileage

193112

Age of Vehicle

8

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

### Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... CAMRY 2.0

ASSESSMENT INFO... CAMRY 2.0 AUTO ABS AIRBAG

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MR053BK4107054143

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driver License #

ASSESSMENT INFO... MR053BK4107054143

CATEGORY Engine No

POLICY INFORMAT... 1AZE160125

ASSESSMENT INFO... 1AZE160125

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1998

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 33000

FNOL INFORMATI...  
POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy

CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

## Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

## Detailed Assessment

Inspection Date \*

05/10/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/50R17

## Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



## Tyre Condition

Spare wheel

Rear Tyre Size

225/50R17

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm





SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

### Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

## Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary   **Parts**

Add

Approve

Deny

Submit All

|                          | EDIT | SR NO | QUANTITY | MATERIAL | SIDE | PART NAME                      | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR./ BTTR% | DISCOUNT% | SALVAGE% | PART PRICE(NET) | ACTION (PARTS) |
|--------------------------|------|-------|----------|----------|------|--------------------------------|-------------|------------------------|-----------|------------|--------------|-----------|----------|-----------------|----------------|
| <input type="checkbox"/> |      | 1     | 1        |          |      | FRONT BUMPER                   |             |                        | Deformed  | 195        |              |           |          | 195             | Review         |
| <input type="checkbox"/> |      | 2     | 2        |          |      | FRONT BUMPER RETAINER          |             |                        | Necessary | 50         |              |           |          | 100             | Review         |
| <input type="checkbox"/> |      | 3     | 2        |          |      | FRONT BUMPER BRACKET           |             |                        | Necessary | 70         |              |           |          | 140             | Review         |
| <input type="checkbox"/> |      | 4     | 1        |          |      | FRONT BUMPER LOWER GRILLE      |             |                        | Deformed  | 45         |              |           |          | 45              | Review         |
| <input type="checkbox"/> |      | 5     | 1        |          |      | FRONT BUMPER SPONGE            |             |                        | Deformed  | 42         |              |           |          | 42              | Review         |
| <input type="checkbox"/> |      | 6     | 1        |          |      | FRONT BUMPER REINFORCEMENT     |             |                        | Bent      | 135        |              |           |          | 135             | Review         |
| <input type="checkbox"/> |      | 7     | 10       |          |      | FRONT BUMPER CLIPS             |             |                        | Necessary | 2          |              |           |          | 20              | Review         |
| <input type="checkbox"/> |      | 8     | 1        |          |      | FRONT NUMBER PLATE BASE HOLDER |             |                        | Deformed  | 55         |              |           |          | 55              | Review         |
| <input type="checkbox"/> |      | 9     | 1        |          |      | FRONT GRILLE                   |             |                        | Cracked   | 170        |              |           |          | 170             | Review         |
| <input type="checkbox"/> |      | 10    | 1        |          |      | FRONT GRILLE LOGO              |             |                        | Necessary | 25         |              |           |          | 25              | Review         |
| <input type="checkbox"/> |      | 11    | 2        |          |      | FRONT GRILLE SIDE CLIPS        |             |                        | Necessary | 8          |              |           |          | 16              | Review         |
| <input type="checkbox"/> |      | 12    | 1        |          |      | BONNET                         |             |                        | Bent      | 180        |              |           |          | 180             | Review         |

|                          | EDIT | SR NO | QUANTITY | MATERIAL | SIDE | PART NAME              | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPR/ BTTR% | DISCOUNT% | SALVAGE% | PART PRICE(NET) | ACTION (PARTS) |
|--------------------------|------|-------|----------|----------|------|------------------------|-------------|------------------------|-------------|------------|-------------|-----------|----------|-----------------|----------------|
| <input type="checkbox"/> |      | 13    | 10       |          |      | BONNET INSULATOR CLIPS |             |                        | Necessary   | 1.5        |             |           |          | 15              | Review         |
| <input type="checkbox"/> |      | 14    | 1        |          |      | BONNET LOCK            |             |                        | Bent        | 55         |             |           |          | 55              | Review         |
| <input type="checkbox"/> |      | 15    | 2        |          |      | HEADLAMP RH / LH       |             |                        | Cracked     | 310        |             |           |          | 620             | Review         |
| <input type="checkbox"/> |      | 16    | 1        |          |      | HEADLAMP LH            |             |                        | Serviceable | 0          | 0           | 0         | 0        | 0               | Deny           |
| <input type="checkbox"/> |      | 17    | 1        |          |      | FRONT AIRGUIDE RH      |             |                        | Deformed    | 45         |             |           |          | 45              | Review         |
| <input type="checkbox"/> |      | 18    | 1        |          |      | FRONT AIRGUIDE LH      |             |                        | Serviceable | 0          | 0           | 0         | 0        | 0               | Deny           |
| <input type="checkbox"/> |      | 19    | 1        |          |      | SUPPORT PANEL ASSY     |             |                        | Repair      | 0          | 0           | 0         | 0        | 0               | Deny           |
| <input type="checkbox"/> |      | 20    | 1        |          |      | BRACE PANEL            |             |                        | Bent        | 38         |             |           |          | 38              | Review         |
| <input type="checkbox"/> |      | 21    | 1        |          |      | AIRCON CONDENSER       |             |                        | Serviceable | 0          | 0           | 0         | 0        | 0               | Deny           |
| <input type="checkbox"/> |      | 22    | 2        |          |      | FRONT FENDER RH / LH   |             |                        | Repair      | 0          | 0           | 0         | 0        | 0               | Deny           |

#### Labour

|                          | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                    | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | RI |
|--------------------------|------|-------|-------------------------|----------------------------------------------|------------|---------------|-------|-----------------|---------|----|
| <input type="checkbox"/> |      | 1     |                         | LABOUR TO FACILITATE REPAIR                  | 700        | 0             | 0     | Reviewing       |         | 1  |
| <input type="checkbox"/> |      | 2     |                         | TO RESPRAY AFFECTED AREAS                    | 700        | 0             | 0     | Reviewing       |         | 1  |
| <input type="checkbox"/> |      | 3     |                         | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS | 30         | 0             | 0     | Reviewing       |         | 1  |

|  | EDIT                                                                              | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME            | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | RI |
|--|-----------------------------------------------------------------------------------|-------|-------------------------|----------------------|------------|---------------|-------|-----------------|---------|----|
|  |  | 4     |                         | TO TOP UP AIRCON GAS | 0          | 0             | 0     | Deny            |         | 1  |

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

|                          | EDIT                                                                                | SR NO | NAME                      | ACTION    | AMOUNT | COMMENT                   | REMOVE                                                                                |
|--------------------------|-------------------------------------------------------------------------------------|-------|---------------------------|-----------|--------|---------------------------|---------------------------------------------------------------------------------------|
| <input type="checkbox"/> |    | 1     | DAYS OF REPAIR : 5 DAYS   | Reviewing |        |                           |    |
| <input type="checkbox"/> |    | 2     | FRONT NUMBER PLATE        | Reviewing | 35     | BENT                      |    |
| <input type="checkbox"/> |    | 3     | COOLANT                   | Deny      | 0      | NOT NECESSARY             |    |
| <input type="checkbox"/> |    | 4     | FRONT GRILLE CLIPS (5PCS) | Reviewing | 7.5    | NECESSARY (SUPPLEMENTARY) |    |
| <input type="checkbox"/> |  | 5     | FRONT BUMPER TOW COVER    | Reviewing | 8      | CUT (SUPPLEMENTARY)       |  |
| <input type="checkbox"/> |  | 6     | BONNET HINGE (2PCS)       | Reviewing | 48     | BENT (SUPPLEMENTARY)      |  |

# Assessment Details

|                            |  |                          |  |                   |  |               |  |                |  |               |  |         |  |
|----------------------------|--|--------------------------|--|-------------------|--|---------------|--|----------------|--|---------------|--|---------|--|
| General & Workshop Details |  | Vehicle & Driver Details |  | Vehicle Condition |  | Taxes & Ratio |  | Parts & Labour |  | Miscellaneous |  | Summary |  |
| Claim Amount               |  | \$3,424.50               |  | Claim Amount      |  | \$3,424.50    |  |                |  |               |  |         |  |

| CATEGORY      | ESTIMATE   | REVISED AMOUNT |
|---------------|------------|----------------|
| Labour        | \$1,430.00 | \$1,430.00     |
| Miscellaneous | \$98.50    | \$98.50        |
| Spare Parts   | \$1,896.00 | \$1,896.00     |

Submit for Review