

INS. CASE OWNER:

CC 4/LPC1800 8481 Nj63n2

LKK:
IDAC:

Surveyor:

mnrihs

DOI:

ASSIGNMENT

21/5/18

Date / Time:

9/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJW 8806A

Name of Insured:

TED WEI ZIN ARON JAMES

Insured Tel No.:

HP:

82376347

Excess Sec II :\$S

D.O.A.:

8/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

12/18/18/VP051020591

Policy No.:

12/VP0516554

Make / Model:

K14

Place of Accident:

TANAH MERIAN COAST RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJE 3904C



INSRS:

WSP:

Tel:

Liability:

RMKS:

specialists



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

10/6/18

904

15-5-18

SJE 3904C - 4 SJW 8806A - 4

3 VC, OI 3RD & LAST - j

LIABILITY CLEAR SENT.

4-7.18

FOR MANDATE

RECEIVED 04 JUL 2018

STAGE	DATE / PIC	
Non-Reporting ltr (1st):	NA	
Non-Reporting ltr (2nd):		
Non-Reporting ltr (Final):		
Notification ltr (if non-pickup):		
Call OI:		
After call ltr to OI:		
Documentation Check List:		
Notification ltr (if non-pickup)	☒	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice:	☐	☐
LTA / GIA:	☒	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☒	☐
Others:	☐	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	43	SS 5,100	(8 days) Reduction: 55 %
FINAL SETTLEMENT		Date/Time: 12.07.19	Confirm with: RENE
Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.: 28
Repair Cost:	GST	SS 6,099.44	
Loss of Rental (LOR):	SS	1,000	(10 days) X 100
Loss of Use (LOU):	SS	-	(S x days)
Loss of Income (LOI):	SS	-	(S x days)
LOR only ☐ LOU only ☐		LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	SS	2.10	
Medical:	SS	-	
Disbursement:	SS	-	(e.g. Tow/ Independent)
Legal Cost	SS	-	
Total:	SS	7,101	Global Sum SS: 7,100
FINAL PAYMENT		Date/Time: 12.7.19	Confirm with: RENE
Payee 1:	SS 7,100	Name 1:	SPECIALISTS MOTOR PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: 450

(06/11/13) waf

REF:

ASS. REC. BY: *Morley*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *STE3904C*at Workshop n/s *Specialist*

of _____

Insured: *SYW 8806A*

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *30k.*

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *8* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *STE3904C*Yr Regn: *4 of*Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or *GA /*Make: *Honda Jazz*C.C. *1339*Colour: *Blue*A/C: ☐

Insured / Std / NI / NA

Sp. Reading: *15-7402*T/Radio: ☐

Insured / Std / NI / NA

Eng/No: _____

C/No: *JHM4D1850852/0801*Gen. Cond: *8* / Fair / Poor / BurntSteering: *8* / In order / Jammed / Leaked / Burnt orBrake: *8* / In order / Jammed / Leaked / Burnt orModi: *8* / Nil / S/Brim / STD A/Rim orTyre Size: F: *195/50 R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *FRANK*

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *8/5/18*D.O.I. *21/5/18*

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*47A 19016 we until 22-4-2023 net 10984**L/S \$5,700**CRED: 6,948.12 55%*

Data/Time, File Pass to?



: Prel. Report

1)



: Final Report

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ > RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18008481/jb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 09-05-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 8806A	Veh. Inspected	SJE 3904C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/05/2018	Inspection Date		
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18008481/Ujb3

Date: 23.05.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJE3904C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.05.2018 at the premises of M/s Specialists Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	12,648.12
Revised Estimate Amount	: S\$	6,813.84
"Check" Items Amount	: S\$	123.84
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 8 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Honda Jazz

Price Range

Depreciation

2008

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Direct Owners » Honda Jazz 1.3A L (New 5-yr COE)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS & UNIQUE Vehicle No.
Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale!
Click here to see all Auspicious Number!

SUREWIN INSTANT LUCKY SPIN
Just 3 simple steps: Scan, Register & WIN!

Honda Jazz 1.3A L (New 5-yr COE)

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$35,000**Depreciation** \$7,000 /yr**Reg Date** 11-Dec-2008
(5yrs COE left)**Manufactured** 2008**Mileage** 48,000 km (5.1k /yr)**Transmission** Auto**Engine Cap** 1,339 cc**Road Tax** \$590 /yr**Power** 73.0 kW (97 bhp)
View specs of the [Honda Jazz \(2008-2014\)](#)**Curb Weight** 1,060 kg**Features** Alpine Radio. Paddle Shift. New Floor Mat. No Repairs Needed.**Accessories** All Wear And Tear Replaced With Honda Original Parts. Item Replaced, Brake Pads, Gearbox Oil, Engine Oil, Coolant, Aircan Compressor.**Description** Almost New Honda Jazz 1.3L. 100% Accident Free! New Road Tax! Full Agent Serviced Record. Ideal For Renewal Of COE. Genuine Mileage Of 48000Km. No More Loan. Instant Transfer. Immediate.**COE** -**OMV** \$19,038**ARF** \$19,038**No. of Owners** 2**Type of Veh** Hatchback**Category** COE Car, Direct Owner Sale, Low Mileage Car**Availability** Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 19-May-2018 | Last Updated on: 21-May-2018

Tags: Honda Jazz, 2008 Honda Jazz, Honda, Jazz, Used Honda



Preferred Viewing Area

Seller Information

Contact Person(s) Sheng Long**Contact No.** 81284900

USEFUL FORMS

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



VEHICLE INSPECTION

Make sure of this car condition with STA Evaluation.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

cee CONSUMER
ELECTRONICS
EXHIBITION
24-27 MAY
LEVEL 3, 11AM-9PM
LEVEL 4, 12AM-9PM
Compare

Upfront Payment

» more Financial info

Transfer Fee \$25**Down Payment** \$10,500 (change)

Maximum 70% Loan

1st Instalment \$485

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	9166F

Vehicle Details

Vehicle No.:	SJE3904C
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	L13A55000469
Chassis No.:	JHMGD18508S210801
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$14,772.00
Original Registration Date:	23 Apr 2008
First Registration Date:	23 Apr 2008
Transfer Count:	2
Actual ARF Paid:	\$16,250.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	22 Apr 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,328.00
COE Rebate Amount:	\$19,016.00
Total Rebate Amount:	\$19,016.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 May 2018

OK

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJE3904C		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	JAZZ 1.4A		
Chassis No. :	JHMGD18508S210801		
Propellant :	Petrol		
Engine No. :	L13A55000469		
Engine Capacity :	1339 cc		
Maximum Power Output :	60.0 kW (80 bhp)		
Maximum Laden Weight :	1490 kg		
Unladen Weight :	1040 kg		
Year Of Manufacture :	2008		
Original Registration Date :	23 Apr 2008		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
PQP Paid :	\$19,328.00		
COE Expiry Date :	22 Apr 2023		
Road Tax Expiry Date :	22 Oct 2018		
Inspection Due Date :	22 Apr 2019		
Intended Transfer Date :	08 May 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJE3904C/1805083

8th May 2018

The Manager
Motor Claim Dept.
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

*Not Attached
21/5/18
a/s
The ph. Attached
Sdy.*

Date of Accident : 8th May 2018
Location : Tanah Merah Coast Road
Third Party Claim Vehicle No : SJW8806A
Repair Cost For Vehicle No : SJE 3904 C Honda Jazz

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia	1	523.50	\$ 523.50 ✓
2	Front bumper beam	1	154.80	\$ 154.80 ✓
3	Front bumper grille	1	121.60	\$ 121.60 ✓
4	Front bumper lower grille	1	121.60	\$ 121.60 ✓
5	Front bumper lower side grille	1	26.00	\$ 26.00 ✓
6	Front bumper side bracket L & R	2	11.40	\$ 22.80 ✓
7	Front bumper tow cover	1	14.10	\$ 14.10 ✓
8	Headlamp assy L & R	2	486.20	\$ 972.40 ✓
9	Trunk lid	1	849.90	\$ 849.90 ✓
10	Trunk lid weather strip	1	97.20	\$ 97.20 ✓
11	Trunk lid emblem "JAZZ"	1	31.60	\$ 31.60 ✓
12	Rear windscreen glass	1	617.70	\$ 617.70 ✓
13	Rear windscreen rubber	1	36.50	\$ 36.50 ✓
14	Rear trunk lid lock assy	1	109.40	\$ 109.40 ✓
15	Rear lamp assy L & R	2	243.10	\$ 486.20 ✓
16	Rear end panel	1	296.60	\$ 296.60 ✓
17	Rear end panel inner garnish	1	63.20	\$ 63.20 ✓
18	Rear bumper fascia	1	490.80	\$ 490.80 ✓
19	Rear bumper side bracket	1	13.70	\$ 13.70 ✓
20	Rear fender inner garnish	1	94.80	\$ 94.80 ✓
21	Rear boot floor panel	1	737.00	\$ 737.00 ✓
				\$ 5,881.40
Less			20%	\$ 1,176.28
				\$ 4,705.12

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJE3904C/1805083

8th May 2018

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 4,705.12
22	Front no. plate with holder (s/nett)	1	50.00	\$ 50.00 40
23	Rear windscreen sealant (s/nett)	1	60.00	\$ 60.00 40
24	Rear bumper reverse sensor (s/nett)	1	380.00	\$ 380.00 200
25	Radiator coolant (s/nett)	1	28.00	\$ 28.00 X
				\$ 5,223.12

Labour Charges :-

	Amounts
Remove & refix front engine cooling system, radiator assy, engine cooling fan & motor assy, radiator tank, inlet tube, all affected parts & etc	\$ 180.00 X
Remove & install air con system, vacuum & top up air con gas	\$ 120.00 X
Cut out, renew, knocking & welding front reinforcement beam, front bulkhead support panel, remove & install all damage parts, straighten & re-align body.	\$ 1,200.00 400
Spray painting on front damage parts	\$ 1,300.00 400
Remove & refix rear windscreen glass	\$ 120.00 ✓
Remove & refix rear boot lock assy, rear garnish, trimming, furnisher, rear seats, all affected parts & etc	\$ 160.00 60
Cut out, renew, knocking & welding rear boot floor panel, rear end panel, rear lamp panel, remove & install all damage parts, straighten & re-align body.	\$ 2,200.00 1200
Spray painting on damage parts	\$ 1,800.00 1100
Tuff-kote on damage parts	\$ 200.00 80
Check all lighting & focus headlamp after repairs	\$ 65.00 30
Remove & install rear bumper sensor	\$ 80.00 50

Labour Charge

Total Amount

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

\$ 7,425.00

\$12,648.12

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJE3904C/1805083

8th May 2018

The Manager
Motor Claim Dept.
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

not Attached
after
21/5/18
a/s 257001 contd.
take photo. Attached
Sdy.

Date of Accident : 8th May 2018
Location : Tanah Merah Coast Road
Third Party Claim Vehicle No : SJW8806A
Repair Cost For Vehicle No : SJE 3904 C Honda Jazz

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia	2/10e 1	523.50	\$ 523.50 ✓
2	Front bumper beam	10 1	154.80	\$ 154.80 ✓
3	Front bumper grille	17 1	121.60	\$ 121.60 X
4	Front bumper lower grille	17 1	121.60	\$ 121.60 X
5	Front bumper lower side grille	17 1	26.00	\$ 26.00 X
6	Front bumper side bracket L & R	2 2	11.40	\$ 22.80 ✓
7	Front bumper tow cover	10.11 1	14.10	\$ 14.10 ✓
8	Headlamp assy L & R	n/s holder 2	486.20	\$ 972.40 ✓
9	Trunk lid	body 1	849.90	\$ 849.90 ✓
10	Trunk lid weather strip	10 1	97.20	\$ 97.20 ✓
11	Trunk lid emblem "JAZZ"	10 1	31.60	\$ 31.60 ✓
12	Rear windscreen glass	17 1	617.70	\$ 617.70 X
13	Rear windscreen rubber	10 1	36.50	\$ 36.50 ✓
14	Rear trunk lid lock assy	10 1	109.40	\$ 109.40 ✓
15	Rear lamp assy L & R	n/s 2	243.10	\$ 486.20 ✓
16	Rear end panel	body 1	296.60	\$ 296.60 ✓
17	Rear end panel inner garnish	10 1	63.20	\$ 63.20 ✓
18	Rear bumper fascia	10 1	490.80	\$ 490.80 ✓
19	Rear bumper side bracket	10 1	13.70	\$ 13.70 ✓
20	Rear fender inner garnish 2/5	2e/c 1	94.80	\$ 94.80 ✓
21	Rear boot floor panel	crushed/que 1	737.00	\$ 737.00 ✓
				\$ 5,881.40
Less				20%
				\$ 1,176.28
				\$ 4,705.12

4265.2
3412.16

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJE3904C/1805083

8th May 2018

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 4,705.12
22	Front no. plate with holder (s/nett)	1	50.00	\$ 50.00
23	Rear windscreen sealant (s/nett)	1	60.00	\$ 60.00
24	Rear bumper reverse sensor (s/nett)	1	380.00	\$ 380.00
25	Radiator coolant (s/nett)	1	28.00	\$ 28.00
				<u>\$ 5,223.12</u>

Labour Charges :-

	Amounts
Remove & refix front engine cooling system, radiator assy, engine cooling fan & motor assy, radiator tank, inlet tube, all affected parts & etc	\$ 180.00
Remove & install air con system, vacuum & top up air con gas	\$ 120.00
Cut out, renew, knocking & welding front reinforcement beam, front bulkhead support panel, remove & install all damage parts, straighten & re-align body.	\$ 1,200.00
Spray painting on front damage parts	\$ 1,300.00
Remove & refix rear windscreen glass	\$ 120.00
Remove & refix rear boot lock assy, rear garnish, trimming, furnisher, rear seats, all affected parts & etc	\$ 160.00
Cut out, renew, knocking & welding rear boot floor panel, rear end panel, rear lamp panel, remove & install all damage parts, straighten & re-align body.	\$ 2,200.00
Spray painting on damage parts	\$ 1,800.00
Tuff-kote on damage parts	\$ 200.00
Check all lighting & focus headlamp after repairs	\$ 65.00
Remove & install rear bumper sensor	\$ 80.00

Labour Charge

Total Amount

GST will be reflected in the final bills.

Notes :- Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental claim(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

\$ 7,425.00

\$12,648.12

7132.16.

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 9 May, 2018 11:43 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: ACCIDENT INVOLVING SJE3904C AND SJW8806A ON 08/05/2018 AT TANAH MERAH COAST ROAD
Attachments: 3451_001.pdf

Dear Catherine,

Kindly proceed to conduct the survey accordingly and revert on liability.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Specialists Motor Pte Ltd [mailto:cardoc@singnet.com.sg]
Sent: Wednesday, 9 May, 2018 11:48 AM
To: GERALD POH WEE BIN
Subject: ACCIDENT INVOLVING SJE3904C AND SJW8806A ON 08/05/2018 AT TANAH MERAH COAST ROAD

WITHOUT PREJUDICE

Dear Sir

Please refer to the above matter.

Our client (SJE3904C) is claiming against your insured (SJW8806A)

Kindly arrange the surveyor to survey the vehicle SJE3904C and also check for us the above claim liability and OIC as soon as possible.

Thanks & Regards
Irene Ting
6747 2112

From: cardoc@singnet.com.sg [mailto:cardoc@singnet.com.sg]
Sent: Wednesday, 9 May, 2018 10:31 AM
To: CARDOC
Subject: Attached Image

*Veh Out
Check liability first*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 3904C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER FASCIA	DENTED / DEFORMED	523.50	523.50
1	FRONT BUMPER BEAM	DENTED	154.80	154.80
1	FRONT BUMPER GRILLE	NOT NECESSARY	121.60	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	121.60	-
1	FRONT BUMPER LOWER SIDE GRILLE	NOT NECESSARY	26.00	-
2	FRONT BUMPER SIDE BRACKET L & R @\$11.40	BENT	22.80	22.80
1	FRONT BUMPER TOW COVER	TORN	14.10	14.10
2	HEADLAMP ASSY L & R @\$486.20	N/S HOLDER CRACKED	972.40	486.20
1	TRUNK LID	BADLY DENTED	849.90	849.90
1	TRUNK LID WEATHER STRIP	TWISTED	97.20	97.20
1	TRUNK LID EMBLEM "JAZZ"	NECESSARY	31.60	31.60
1	REAR WINDSCREEN GLASS	NOT NECESSARY	617.70	-
1	REAR WINDSCREEN RUBBER	NECESSARY	36.50	36.50
1	REAR TRUNK LID LOCK ASSY	DENTED	109.40	109.40
2	REAR LAMP ASSY L & R @\$243.10	N/S CRACKED	486.20	243.10
1	REAR END PANEL	BADLY DENTED	296.60	296.60
1	REAR END PANEL INNER GARNISH	TWISTED	63.20	63.20
1	REAR BUMPER FASCIA	DISTORTED	490.80	490.80
1	REAR BUMPER SIDE BRACKET	BENT	13.70	13.70
1	REAR FENDER INNER GARNISH O/S	DEFORMED / CRACKED	94.80	94.80
1	REAR BOOT FLOOR PANEL	CRUMPLED / BUCKLED	737.00	737.00
	LESS 20% DISCOUNT		-1,176.28	-853.04
			4,705.12	3,412.16
SPECIAL NETT ITEMS				
1	FRONT NO PLATE WITH HOLDER (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	380.00	200.00

Report Ref No. CC4/LPC18008481/Ueb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR COOLANT (SN)	NOT NECESSARY	28.00	-
			518.00	280.00
	LABOUR			
	REMOVE & REFIX FRONT ENGINE COOLING SYSTEM,RADIATOR ASSY,ENGINE COOLING FAN & MOTOR ASSY,RADIATOR TANK,INLET TUBE,ALL AFFECTED PARTS & ETC.	NOT NECESSARY	180.00	-
	REMOVE & INSTALL AIR CON SYSTEM,VACUUM & TOP UP AIR CON GAS.	NOT NECESSARY	120.00	-
	CUT OUT,RENEW,KNOCKING & WELDING FRONT REINFORCEMENT BEAM,FRONT BULKHEAD SUPPORT PANEL,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY.		1,200.00	400.00
	SPRAY PAINTING ON FRONT DAMAGE PARTS.		1,300.00	400.00
	REMOVE & REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	REMOVE & REFIX REAR BOOT LOCK ASSY,REAR GARNISH,TRIMMING,FURNISHER,REAR SEATS,ALL AFFECTED PARTS & ETC.		160.00	60.00
	CUT OUT,RENEW,KNOCKING & WELDING REAR BOOT FLOOR PANEL,REAR END PANEL,REAR LAMP PANEL,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY.		2,200.00	1,200.00
	SPRAY PAINTING ON DAMAGE PARTS.		1,800.00	1,100.00
	TUFF-KOTE ON DAMAGE PARTS.		200.00	80.00
	CHECK ALL LIGHTING & FOCUS HEADLAMP AFTER REPAIRS.		65.00	30.00
	REMOVE & INSTALL REAR BUMPER SENSOR.		80.00	50.00
			7,425.00	3,440.00
GRAND TOTAL			12,648.12	7,132.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CC4/LPC18008481/Ueb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.