

INS. CASE OWNER

CC 4/QBE1800 8483, R 163/18

LKK:

IDAC

Surveyor:

Faisal  
Faudhah

DOI:

ASSIGNMENT

09/05/18

Date / Time:

9/5/18

Registered in Meritum:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XD 9515M

Claim No.:

VCO11456

Name of Insured:

FOH KOCK LEONG ENTERPRISE PTE

Policy No.:

8-V015944-H44

Insured Tel No.:

HP:

Make / Model:

VOLVO

Excess Ser II :\$

D.O.A.:

6/9/18

Place of Accident:

MARINA EAST BR RD

Is driver the owner?

(YES/NO)

Nature of Accident:

If NO, Driver Name / Age:

SHIBAN MUNI PRM KANAK R.

OI GIA REPORT: YES/NO

TP GIA REPORT: YES/NO

Driver Tel No.:

(V/L: YES/NO)

Insured Liability:

Final? Yes/No

5675644P



INSRS:

WSP:

Tel:

Liability:

RMKS:

connect3



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE		Date/Time: 10/05/18	Sent By: b3
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	P/P	\$5,784.01 / 12 days	Reduction: 15 %
FINAL SETTLEMENT		Date/Time: 14/09/18	Confirm with: WINNING
Final Liability:	\$ 100	(Agreed / Assessed)	BOLA S/N No.: 71
Repair Cost:	\$5,784.01		
Loss of Rental (LOR):	\$5	( ) days	
Loss of Use (LOU):	\$5	720.00 x 60 x 12 days	
Loss of Income (LOI):	\$5	(5 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search:	\$5		
Medical:	\$5		
Disbursement:	\$5	(e.g. Tow/Independent)	
Legal Cost:	\$5		
Total:	\$5,784.01	Global Sum \$5:	—
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$5,784.01	Name 1:	CONNOR 3
Payee 2: (Strike if N.A.)	\$5	Name 2:	—
Payee 3: (Strike if N.A.)	\$5	Name 3:	—

RECEIVED 17 SEP 2018

REF:

6300K

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No \_\_\_\_\_

Claims No \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 90K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: — % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLJ 5644P Yr Regn: 2016 / DEC

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN QASHQAI 1.2 C.C. 1197

Colour: GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 12490 W/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: SJNF6AJ11U1775638

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Good / Jammed / Leaked / Burnt orBrake: ☒ Good / Jammed / Leaked / Burnt or

Modi: Nil / B/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: 215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 06/05/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Plp @ 13,784.01  
(2016: @ 2,411.84 / 15%.)

MV: @ 90,000 (cont)  
LCA: @ 51,587 (cont)  
Nett: @ 38,413 (cont)

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RES. \$

) Photo

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18008483/T1hb3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 09-05-2018		
		Code : QBE		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 9525M	Veh. Inspected	SLJ 5644P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	06/05/2018	Inspection Date		
Survey held at	CONNECT3 7 OLD TOH TUCK ROAD SINGAPORE 597648			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/QBE18008483/R1hb3

Date: 10.05.2018

The Motor Claims Department  
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLJ5644P**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.05.2018 at the premises of M/s Connect3 and have the following to report:-

Workshop Estimate Amount	: S\$	42,300.00
Revised Estimate Amount	: S\$	21,782.30
"Check" Items Amount	: S\$	7,148.10
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 12 days

Yours faithfully,

MOHD. RASUL  
Licensed Appraiser

**CONNECT 3**

566 Woodlands Road ( Mandai Estate ) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT18/SLJ5644P/TPC-217

QBE Insurance (Singapore) Pte Ltd

1 Raffles Quay

#29-10 South Tower

Singapore 048583

Dear Sir,

Cost of Repair to Vehicle SLJ5644P

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear windscreen	1	1,116.00	Bro / 1,116.00
2.	Tailgate	1	2,936.80	M / 2,936.80
3.	Tailgate inner lock	1	116.70	Sam / 116.70
4.	Tailgate reflector RH & LH	2	225.90	CR / 451.80
5.	Tailgate trimboard (32)	1	316.50	CR / 316.50
6.	Tailgate rubber	1	158.70	me / 158.70
7.	Tailgate emblem ( Qashqai )	1	87.00	me / 87.00
8.	Tailgate logo center	1	59.70	me / 59.70
9.	Tailgate handle (33,34)	1	28.10	cut / 28.10
10.	Tailgate number plate garnish (35)	1	336.00	scd / 336.00
11.	Tailgate wiper arm	1	63.80	scd / 63.80
12.	Tailgate wiper blade	1	19.60	cut / 19.60
13.	Tailgate wiper motor	1	411.70	CR / 411.70
14.	Tailgate wiper arm cover	1	14.25	cut / 14.25
15.	Rear fender inner garnish RH	1	231.70	DE / 231.70
16.	Rear fender extension RH	1	323.40	DE / 323.40
17.	Rear fender inner duct	1	75.30	DE / 75.30
18.	Rear end panel	1	482.60	PA / 482.60
19.	Rear end panel top inner garnish	1	65.30	DE / 65.30

# CONNECT 3

566 Woodlands Road ( Mandai Estate ) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

20.	Rear bumper	1	717.00	DE / 717.00
21.	Rear bumper reinforcement	1	619.20	HA / 619.20
22.	Rear bumper inner sponge	1	146.20	TORE / 146.20
23.	Rear bumper side retainer	1	71.80	NA / 71.80
24.	Rear bumper bracket	1	252.00	HA / 252.00
25.	Rear bumper clip	1	25.00	NA / 25.00
26.	Rear bumper tow hook cover	1	26.80	MS / 26.80
27.	Taillamp LH & RH	2	323.70	PRO / 647.40
28.	Taillamp clips	1	50.00	NA / 50.00
29.	Door back	1	170.00	CR / 170.00
30.	RH boot lamp	1	320.00	PRO / 320.00
31.	Over fender RR RH	1	483 560.00	DE / 560.00
32.	Back door lower - photo shows tailgate trim handle	1	X 580.00	580.00
33.	Back door } tailgate handle	1	X 350.00	350.00
34.	Back door	1	X 170.00	170.00
35.	Back door handle - tailgate number plate garnish	1	X 50.00	50.00
36.	Side finisher upper RH	1	230.00	DE / 230.00
37.	Boot lamp LH	1	390.00	CR / 390.00
38.	Rear number plate SN	1	35.00	HA / 35.00
39.	Reverse sensors SN	1	330.00	NA / 330.00
40.	Check wiring	1	30.00	30.00
41.	Transfer tailgate fittings	1	60.00	60.00
42.	Replace bumper etc labour charges	1	1,500.00	1,500.00
43.	Remove & refit rear inner trims	1	100.00	100.00 60
44.	Remove & refit rear windscreen	1	120.00	120.00
45.	Apply sealant	1	40.00	40.00

### CONNECT 3

566 Woodlands Road ( Mandai Estate ) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

46.	Replace reverse sensor	1	60.00	60.00 ✓
47.	Spray painting	1	1,200.00	1,200.00 ✓
SUB-TOTAL				SS16,145.35

Thank you.  
Yours faithfully,



Winnie Chai  
HP: 9850-9666



LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Vic (LKKAuto)

---

**From:** Winnie Chai <connect3winnie@gmail.com>  
**Sent:** Wednesday, 8 August, 2018 11:05 AM  
**To:** Vic (LKKAuto)  
**Cc:** Rasul (LKKAuto); Admin A; Olivia Lau (LKKAuto)  
**Subject:** Re: Your Ref: SLJ 5644P\_ACCIDENT INVOLVING VEHICLES XD 9525M AND SLJ 5644P ON 06/05/2018  
**Attachments:** img001.jpg; img002.jpg; img003.jpg

Hi Vic,

Attached is the amended estimate for Rasul ref.

Pls kindly revert on the finalization by today 6pm.

Thanks

On Mon, Aug 6, 2018 at 9:35 AM, Winnie Chai <connect3winnie@gmail.com> wrote:  
Hi Vic,

As spoken to you earlier, we are advised from you that yr surveyor Rasul was on urgent leave last week and hence unable to revert on the finalization and you will try to revert on the finalization by today.

Pls kindly expedite for this case as it has been dragging for very long.

Thanks

On Tue, Jul 31, 2018 at 9:53 AM, Winnie Chai <connect3winnie@gmail.com> wrote:  
Hi Rasul

Pls ref to attached photos again for the damaged items.

I have listed one by one for u just in case u are not sure which items belongs to which one for easy ref.

- 1) door back - \$170.00
- 2) RH boot lamp - \$320.00
- 3) Over Fender RR RH - \$560.00
- 4) Back door lower - \$580.00
- 5) Back door - \$350.00
- 6) Back door - \$170.00
- 7) Back door handle - \$50.00
- 8) Side finisher Upper RH - \$ 230.00
- 9) Boot Lamp LH - 390.00

Pls recalculate the finalization and revert back asap.

Thanks

On Mon, Jul 30, 2018 at 4:14 PM, Vic (LKKAuto) <vicalpeh@lkkauto.com> wrote:

Without Prejudice

QT18/SLJ5644P/TPC-217

QBE Insurance (Singapore) Pte Ltd  
 1 Raffles Quay  
 #29-10 South Tower  
 Singapore 048583

Dear Sir,

Cost of Repair to Vehicle SLJ5644P

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	Rear bumper 717.00	1	2,111.00	DE / 2,111.00	✓
2.	Rear bumper sponge torn 126.80	1	163.80	8. 163.80	✓
3.	Rear bumper tow cover 18.80	1	65.00	MUS / 65.00	✓
4.	Rear bumper center cover	1	170.00	DE / 170.00	✓
* 5.	Rear absorber (photo) HN	1	280.00	7. 280.00	X
6.	Rear bumper reinforcement 41 419.00	1	1,400.00	2. 1,400.00	✓
7.	Rear Stay LH 126.00	1	280.00	7. 280.00	✓
8.	Rear Stay RH 126.00	1	280.00	7. 280.00	✓
9.	Rear bumper retainer RH 135.00	1	135.00	135.00	✓
10.	Rear bumper retainer LH 135.00	1	135.00	135.00	✓
11.	Rear number plate S/N	1	40.00	DE / 40.00	35 s/a
12.	Rear tonneau cover	1	521.00	X 521.00	
13.	Tailgate panel 2656.90	1	4,500.00	PA / 4,500.00	
14.	Tailgate moulding	1	850.00	X 850.00	
15.	Rear windscreen with moulding 1954.00	1	1,954.00	Pro / 1,954.00	
16.	Tailgate lock sensor X 153.00	1	153.00	153.00	X
17.	Tailgate inner lock 185.80	1	185.80	185.80	
X 18.	Tailgate absorber LH X	1	350.00	X 350.00	
X 19.	Tailgate absorber RH X	1	350.00	X 350.00	

5687.40

# CONNECT 3

7 Old Toh Tuck Road Singapore 597648  
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

X

245.60

Crack 491-20,

20.	Tailgate reflector	2	<del>RH 316.80</del>	LH <del>3.633.00</del>	✓
21.	Tailgate lock outer (photo)	1	423.00	X 423.00	
22.	Tailgate panel trim deformed	1	<del>331.10 550.00</del>	<del>2. 550.00</del>	✓
23.	Weatherstripe for tailgate 185.90	1	350.00	me / 350.00	✓
24.	Rear emblem 87.00	1	160.00	me / 160.00	✓
25.	Rear RH taillamp	1	<del>465.60 970.00</del>	<del>BR 970.00</del>	✓
26.	Rear LH taillamp	1	<del>465.60 970.00</del>	<del>CRA 970.00</del>	✓
27.	Rear lamp inner X (photo)	1	550.00	X 550.00	
28.	Rear lamp outer X (photo)	1	550.00	X 550.00	
29.	Rear number plate lamp LH & RH X	2	280.00	<del>CRA 560.00</del>	
30.	End panel 482.00	1	1,900.00	PA 1,900.00	
31.	End panel top garnish deformed	1	<del>165 565.00</del>	<del>2. 565.00</del>	✓
32.	Spare tyre panel (repair buck)	1	3,700.00	R 3,700.00	
33.	Spare tyre board SVL	1	850.00	<del>2. 850.00</del>	X
34.	Spare tyre top garnish SVL	1	856.00	<del>2. 856.00</del>	X
35.	Spare Tyre Box L HH	1	480.00	<del>2. 480.00</del>	X
36.	Reverse sensors SW 110.00	<del>13 pcs</del>	150.00	<del>me / 600.00</del>	330,
37.	Spare tyre lock screw X	1	45.00	X 45.00	
38.	Spare tyre tool compartment sponge SVL	1	304.00	<del>2. 304.00</del>	X
39.	Rear fender RH & LH X reg ~	2	<del>BH 2,152.00</del>	<del>LH 4,304.00</del>	X
40.	Rear wheel arch moulding RH	1	<del>L10.50 860.00</del>	<del>DE 860.00</del>	
41.	Rear wheel arch moulding LH deformed	1	<del>210.50 860.00</del>	<del>2. 860.00</del>	✓
42.	Exhaust pipe X	1	1,200.00	X 1,200.00	
43.	Rear bumper reflector RH HH	1	186.00	<del>2. 186.00</del>	X
44.	Rear bumper reflector LH X	1	186.00	X 186.00	
45.	Tailgate wiper motor	1	483.50	<del>R 483.50</del>	

3578.50

photo

5011.00  
 365.00 X  
 3070.00  
 10,252.02  
 12 days - P/P

46.	Tailgate wiper arm	1	105.50	see / 105.50
47.	Tailgate number plate garnish	1	253.00	see / 253.00
48.	Spare tyre panel acoustic insulator X	1	472.70 180.00	X 180.00
49.	Clips 5687.40	40	5.00	<del>200.00</del> 301-
50.	XTRONIC CVT emblem X 3578.50	1	93.00	X 93.00
51.	Nissan Logo 472.30	1	39.00	see / 39.00
52.	Qashqai Emblem 9138.60 30%	1	45.20	see / 45.20
53.	Rear number plate holder 6817.02	1	35.00	X 35.00
54.	Check wiring	1	80.00	30 80.00
55.	To replace rear bumper, tailgate, M-panel, side member LH & RH both side fenders mouldings etc	1	1,800.00	1500 1,800.00
56.	Transfer tailgate fittings	1	120.00	60 120.00
57.	To replace exhaust system	1 labor	120.00	X 120.00
58.	To remove & refit rear inner trims to assist repair	1	180.00	60 180.00
59.	To remove & refit rear windscreen	1	150.00	120 150.00
60.	To apply sealant to rear windscreen	1	60.00	40 60.00
61.	To replace reverse sensors	1	120.00	60 120.00
62.	To replace rear camera	1 150	300.00	<del>180.00</del> 300.00 X
63.	Spray painting	1	1,400.00	1200 1,400.00
S/N - 365			<b>SUB-TOTAL</b>	<b>SS42,300.00</b>

Thank you.  
 Yours faithfully,

Winnie Chai  
 HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
 Hp 90010068  
 12 days  
 P/P  
 09/05/18 @ 1730  
 Resurvey by paint

**CONNECT3**

7 Old Toh Tuck Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT18/SLJ5644P/TPC-217

QBE Insurance (Singapore) Pte Ltd  
1 Raffles Quay  
#29-10 South Tower  
Singapore 048583

Dear Sir,

Cost of Repair to Vehicle SLJ5644P

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$S)	AMOUNT (\$S)	
1.	rear windscreen	1	\$1,116.00	\$1,116.00	Photo ✓
2.	tail-gate	1	\$2,936.80	\$2,936.80	PA ✓
3.	tail-gate inner lock	1	\$116.70	\$116.70	2 Am ✓
4.	tailgate reflector (rh)	1	\$225.90	\$225.90	Photo ✓
5.	tailgate reflector (lh)	1	\$225.90	\$225.90	CRA ✓
6.	tail-gate trim board	1	\$316.50	\$316.50	DE ✓
7.	tail-gate trim board lower	1	\$97.90	\$97.90	X
8.	tail-gate rubber	1	\$158.70	\$158.70	see ✓
9.	tail-gate emblem (qashqai)	1	\$87.00	\$87.00	na ✓
10.	tail-gate logo centre	1	\$59.70	\$59.70	na ✓
11.	tail-gate handle ✓	1	\$28.10	\$28.10	X
12.	tail-gate no plate garnish	1	\$336.00	\$336.00	DE ✓
13.	tail-gate wiper arm	1	\$63.80	\$63.80	see ✓
14.	tail-gate wiper blade	1	\$19.60	\$19.60	cut ✓
15.	tail-gate wiper motor	1	\$411.70	\$411.70	CRA ✓
16.	tail-gate wiper arm cover	1	\$14.25	\$14.25	cut ✓
17.	rear fender (rh) repair photo shows	1	\$1,169.40	\$1,169.40	repair ✓
18.	rear fender inner garnish (rh)	1	\$231.70	\$231.70	DE ✓
19.	rear fender extension (rh)	1	\$323.40	\$323.40	DE ✓

66 43 65

# CONNECT 3

7 Old Toh Tuck Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

X

20.	rear fender wheel arch garnish @ \$15.00	6	\$15.00	\$90.00	DE ✓
21.	rear fender under colwing clip @ \$12.00	20	\$12.00	\$240.00	X ?
22.	rear fender inner duct	1	\$75.30	\$75.30	DE ✓
23.	rear end panel	1	\$482.60	\$482.60	Bt ✓
24.	rear end panel top inner garnish	1	\$65.30	\$65.30	DE ✓
25.	rear bumper	1	\$717.00	\$717.00	DE ✓
26.	rear bumper reinforcement	1	\$619.20	\$619.20	Bt ✓
27.	rear bumper inner sponge	1	\$146.20	\$146.20	form ✓
28.	rear bumper side retainer @ \$35.90	2	\$35.90	\$71.80	new ✓
29.	rear bumper bracket @ \$126.00	1	\$252.00	\$252.00	Bt ✓
30.	rear bumper clip (white) @ \$22.50	1	\$225.00	X \$225.00	X
31.	rear bumper clip @ \$10.00 2.50	20/10	\$10.00	25 \$200.00	X
32.	rear bumper tow hook cover	1	\$26.80	\$26.80	new ✓
33.	rear bumper bracket cover	1	\$21.00	\$21.00	X
34.	tail-lamp (rh)	1	\$323.70	\$323.70	Bao ✓
35.	tail-lamp (lh)	1	\$323.70	\$323.70	car ✓
36.	tail-lamp clip @ \$18.80 50	8	\$18.80	\$150.40	X
SUB-TOTAL				SS11,969.05	3103.61

report  
2nd  
not necessary  
to replace

photo?

Thank you.  
Yours faithfully,

Winnie Chai  
HP: 9850-9666



9747.25  
30%  
6823.07

6823.07  
365.00  
3070.00  
10,258.07

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6300K
Vehicle Details	
Vehicle No.:	SLJ5644P
Vehicle to be Exported:	No
Intended De-registration Date:	10 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	HRA2306532A
Chassis No.:	SJNFEAJ11U1775638
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,725.00
Original Registration Date:	16 Dec 2016
First Registration Date:	16 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$13,725.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2026
PARF Rebate Amount:	\$10,293.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$41,264.00
<b>Total Rebate Amount:</b>	<b>\$51,557.00</b>

The information contained herein is correct as at 10 May 2018

OK

90,000  
51,557  
38,443

## Vic (LKKAUTO)

---

**From:** Winnie Chai <connect3winnie@gmail.com>  
**Sent:** Friday, 14 September, 2018 2:23 PM  
**To:** Vic (LKKAUTO)  
**Cc:** Admin A; Olivia Lau (LKKAUTO); Rasul (LKKAUTO)  
**Subject:** Re: Your Ref: SLJ 5644P\_ACCIDENT INVOLVING VEHICLES XD 9525M AND SLJ 5644P ON 06/05/2018 LKK REF CC4/QBE18008483/R1hb3q2  
**Attachments:** DV.jpg

Hi

Attached is the duly chopped & signed Dv for yr ref.

The original DV will be posted to yr office tdy via mail.

Thanks

On Fri, Sep 14, 2018 at 10:48 AM, Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)> wrote:

Without Prejudice

Dear Winnie,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we offer settlement as below:

Cost of Repair	\$ 13,724.01
Loss of Use (\$60 x 12 days)	\$ 720.00
<b>TOTAL</b>	<b>\$ 14,454.01</b>

If agreeable, kindly let the owner sign the attached DV then forward back to us a copy for payment processing.

The above amount is to be made payable to CONNECT3.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.*

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK** Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAuto)

**Sent:** Friday, 14 September, 2018 9:36 AM

**To:** Winnie Chai

**Cc:** Admin A; Olivia Lau (LKKAuto); Rasul (LKKAuto); Vic (LKKAuto)


**Subject:** RE: Your Ref: SLJ 5644P\_ACCIDENT INVOLVING VEHICLES XD 9525M AND SLJ 5644P ON 06/05/2018 LKK REF CC4/QBE18008483/R1hb3q2

Without Prejudice

Dear Winnie,

We refer to the below email.

Please be informed that we are pending for mandate approval from our principal.



566 Woodlands Rd ( Mandai Estate ) Singapore 728697  
UEN no: 53360061L  
HP: (+65) 9850-9666 Email: Connect3winnie@gmail.com

Your Ref : Pls advise

14 August 2018

QBE Insurance (Singapore) Pte Ltd  
1 Raffles Quay  
#29-10 South Tower  
Singapore 048583

Dear Sir,

**TO PROPOSE A CLAIM OF AN ACCIDENT INVOLVING SLJ5644P & XD9525M  
ON 06/05/2018.**

We refer to the above, we are authorized by owner San's Tours & Car Rentals of vehicle no SLJ5644P to negotiate and settle the claim on his behalf.

We hereby quantify our claim as follows:-

- |                                 |     |           |
|---------------------------------|-----|-----------|
| 1) Repair Cost                  | S\$ | 13,734.01 |
| 2) Loss of Use @ \$100 X 12 day | S\$ | 1,200.00  |

<b>Total</b>	<b>S\$</b>	<b>14,934.01</b>
--------------	------------	------------------


We enclosed a copy of each of the following for your consideration:


- 1) Repair Bill inv: 376
- 2) Motor Accident report of vehicle no.SLJ5644P
- 3) Letter Authorization (original available upon request)
- 4) Insurance Certificate
- 5) Vehicle registration card
- 6) Pre repair inspection (done by Rasul LKK on 09/05/18)

Kindly acknowledge receipt of the above said documents and hope to receive your favourable reply ASAP.

Thank you.

Yours sincerely

  
Winnie Chai  
HP: 9850-9666





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/QBE18008483/R1hb3**

16<sup>th</sup> May 2018

**KOH HOCK LEONG ENTERPIRSE PTE LTD**

24 Tuas Avenue 2,  
Singapore 639455.

Attn: Mr Jeff

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING XD 9525M AND SLJ 5644P ALONG  
MARINA EAST DRIVE ROAD ON 06.05.2018**

We refer to the above accident where we are acting for QBE Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

  
Poh Kin, Chong  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)

c.c. *QBE Insurance (Singapore)Pte Ltd  
(Motor Claims Dept)*

**LETTER OF AUTHORITY & INDEMNITY**

To Connect3

566 Woodlands Road ( Mandai Estate ) S 728697)

ACCIDENT INVOLVING VEHICLE NO. SLJ5644P AND X09525M  
 AT Mandai Road Dr. Traffic Light Rd ON 06/05/2018

1. I/ We, the owner of vehicle no. SLJ5644P hereby instruct and authorize you to commence repairs to the said vehicle and to make 3<sup>rd</sup> party claim on my behalf for my loss and damage.
2. You are further authorized to appoint solicitors on my/ our behalf and give the solicitors full instructions as if the appointment is made and instructions are given by me/ us with respect to the conduct of my/ our claim against the third party driver and or his insurers including if necessary, to commence legal proceedings in Court in my/ our name against the 3<sup>rd</sup> party.
3. You have my/ our full authority to instruct my/ our solicitor to negotiate a settlement with the third party and/ or his insurers on such terms as you deem fit.
4. Upon resolving my/ our claim, you are authorized to agree with my/ our solicitors on the amount of their professional costs and disbursements for acting for me/ us and to receive payment of the balance of the settlement sum on my/ our behalf directly into your account.
5. In the event that I/ we am/ are required to attend at my/ our solicitors' office or to attend Court connection with my/ our claim, I/ we shall render full co-operation.
6. In the event that my/ our claim against the 3<sup>rd</sup> party and/ or his insurers is not successful or cannot be proceeded with, I/ we authorize you to make a claim against my/ our own insurers for the cost of repairs and any losses recoverable under my/ our policy of insurance. In this respect, I/ we understand and accept that personally liable to bear all Legal Costs incurred by you in claiming back for the repair costs by your solicitors.
7. I/ We hereby irrevocably direct all insurer to make all settlement sums payable to "Connect3" or my/ our solicitors, and not to me. Such payment shall be full and valid discharge by me/ us.
8. If the settlement sum is paid to me/ us directly by cheque from the insurer in their disobedience and/ or negligence of my above direction, I/ We shall forthwith exchange with you or pay you for the said cheque by my/ our cheque/ cash of the same amount or return you any payment in any manner as directed by you.
9. If for whatever reason, my/ our insurers reject my/our claim for indemnity for the cost of repairs and/ or any other losses recoverable under the policy of insurance or make an offer to pay less than the amount claimed by you or my insurance policy does not cover such claim, I/ we agree and undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonable incurred on my/ our behalf or to pay you the difference in amount, as the case may be.


X

Date this 08 of 05 2018Signature: [Signature]Name: Michael MyNRIC No.: E160173201

(Company stamp, if applicable)

Name of Witness: \_\_\_\_\_

NRIC No.: \_\_\_\_\_



# DISCHARGE VOUCHER

Without Prejudice  
Save As to Costs

Your Reference : SLJ 5644P  
Our Reference : VC011456

I/We, SAN'S TOURS & CAR RENTALS do hereby acknowledge the sum of Singapore Dollars: Fourteen Thousand Four Hundred Fifty Four and Cents One Only (\$\$14,454.01) being full discharge and satisfaction of all claims against QBE Insurance (Singapore) Pte Ltd and their Insured, 'KOH KOCK LEONG ENTERPRISE PTE LTD', over damage to my/our vehicle SLJ 5644P from an accident involving XD 9525M and SLJ 5644P at/along MARINA EAST DRIVE TOWARDS FORT ROAD, which occurred on 06 MAY 2018 at about 1055hours.

Further, I/we hereby acknowledge and accept that the above said sum paid to me is 'strictly on a without admission of liability basis' and I/we hereby discharge and release the said QBE Insurance (Singapore) Pte Ltd and their Insured 'KOH KOCK LEONG ENTERPRISES PTE LTD', from all claims, demands or action of damages as a result of the said accident.

Also, I/we hereby agree to indemnify and keep indemnified the said QBE Insurance (Singapore) Pte Ltd against all and any claims whatsoever made or to be made by any person or persons on my/our behalf in respect of the said accident.

Dated this (day) 14 of (month) Sept (year) 2018

Signature

Claimant's Name

FIN/NRIC No.

Address

Witness's Signature

Witness's Name

FIN/NRIC No.


Address

Please return to:  
General Claims Department

60 Anson Road  
#11-01 Mapletree Anson  
Singapore 079914  
Fax: 6534 5356

Company stamp if applicable





Authorised Signature

## Vic (LKKAUTO)

**From:** Joyce Foo <joyce.foo@qbe.com>  
**Sent:** Friday, 14 September, 2018 10:20 AM  
**To:** Vic (LKKAUTO)  
**Cc:** Admin A  
**Subject:** RE: <SEEK MANDATE> VC011456 RE: Request for pre repair inspection for accident involving SLJ5644P & XD9525M ( yr insured ) on 06/05/18 LKK REF CC4/QBE18008483/R1hb3 - VC011456

Hi Vic

Please proceed to settle as advised urgently as TP is chasing.

Thank You & Best Regards

---

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: joyce.foo@qbe.com  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



---

**From:** Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]  
**Sent:** Friday, 14 September, 2018 9:36 AM  
**To:** Joyce Foo <joyce.foo@qbe.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Jenny Toh <jenny.toh@qbe.com>  
**Subject:** <SEEK MANDATE> VC011456 RE: Request for pre repair inspection for accident involving SLJ5644P & XD9525M ( yr insured ) on 06/05/18 LKK REF CC4/QBE18008483/R1hb3

**YOUR REF – VC011456**  
**LKK REF – CC3/QBE18008483/R1hb3**  
=====

Dear Joyce,

**ACCIDENT INVOL VING VEHICLES XD 9525M (OI) AND SLJ 5644P (TP) ON 06/05/2018**

We refer to the above matter.

This is a clear cut case where Insured Driver had rear-ended to the TP vehicle.

We had spoken to the Insured PIC Mr Jeff where he confirmed accident details and was informed of TP claim, liability and NCD issues. A letter was sent out to Insured to informed of the TP claim and NCD issues. No feedback from Insured till date.

In view of the above, we are of the view that liability is not to our Insured's favour.

Summary to offer to repairer **CONNECT3** is as follows:

TP CLAIMED		REVISED - TO OFFER
Cost of Repair	\$ 16,145.35	\$ 13,734.01
Loss of Use (\$100 x 12 days)	\$ 1,200.00	\$ 720.00 (\$60 x 12 days)
<b>TOTAL</b>	<b>\$ 17,345.35</b>	<b>\$ 14,454.01</b>

Breakdown of days is as follows:

Our surveyor's recommended days to repair	12 days
<b>TOTAL</b>	<b>12 days</b>

Relevant supporting claim documents are attached herewith for your perusal and reference.

For your approval and/or further instructions please.

Thank you.


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**From:** Vic (LKKAuto)

**Sent:** Friday, 10 August, 2018 9:26 AM

**To:** 'Joyce Foo'

**Cc:** Admin A; Vic (LKKAuto)

**Subject:** RE: Request for pre repair inspection for accident involving SLJ5644P & XD9525M ( yr insured ) on 06/05/18  
LKK REF CC4/QBE18008483/R1hb3

Dear Joyce,

We refer to your below email.

Please be informed that we are currently finalizing the COR with repairer.

We will expedite and will forward our report the as soon as possible.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Joyce Foo [<mailto:joyce.foo@qbe.com>]

**Sent:** Wednesday, 8 August, 2018 8:16 AM

**To:** Admin A; Vic (LKKAuto)

**Subject:** RE: Request for pre repair inspection for accident involving SLJ5644P & XD9525M ( yr insured ) on 06/05/18

Our Ref. VC011456

Hi Vic

Please update and expedite your report soon.

Thank You & Best Regards

---

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: [joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



---

**From:** Joyce Foo

**Sent:** Monday, 16 July, 2018 10:39 AM

**To:** 'Admin A' <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

**Subject:** RE: Request for pre repair inspection for accident involving SLJ5644P & XD9525M ( yr insured ) on 06/05/18

Our Ref. VC011456

Hi Vic

We refer to the above.

As spoken, please finalise the above and let us have your report asap.

Thank You & Best Regards

---

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: [joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



**From:** Joyce Foo

**Sent:** Wednesday, 9 May, 2018 10:15 AM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** FW: Request for pre repair inspection for accident involving SLJ5644P & XD9525M ( yr insured ) on 06/05/18

Our Ref. VC011456

Hi

Please assist to arrange for WP survey – Direct settlement.

Thank You & Best Regards

---

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: [joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



**From:** Winnie Chai [<mailto:connect3winnie@gmail.com>]

**Sent:** Tuesday, 8 May, 2018 3:20 PM

**To:** Joyce Foo <[joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)>

**Subject:** Request for pre repair inspection for accident involving SLJ5644P & XD9525M ( yr insured ) on 06/05/18

Afternoon Joyce,

I have attached the GIA & estimate for my client SLJ5644P for yr ref.

Pls kindly assign yr surveyor down for the survey.

Survey location : 566 Woodlands Rd ( Mandai Estate ) S728697

Thanks

--

Winnie Chai  
Connect3  
HP:9850-9666

-----  
**IMPORTANT NOTICE :** The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

-----  
**IMPORTANT NOTICE :** The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18008483/R1hb3q2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 26-09-2018		
		Code : QBE		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 9525M	Veh. Inspected	SLJ 5644P	
Policy No.	8-V0015974-MVA	Coverage (\$)	0.00	
Claim No.	VC011456	Excess (\$)	0.00	
Assign From	JOYCE	Assign Date	09/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN QASHQAI 1.2	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SJNFEAJ11U1775638	Colour	GREY	
Odometer	12490	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	GOODYEAR	6 mm	
L/H Front Tyre	215/60 R17	GOODYEAR	6 mm	
R/H Rear Tyre	215/60 R17	GOODYEAR	6 mm	
L/H Rear Tyre	215/60 R17	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/05/2018	Inspection Date	09/05/2018	
Survey held at	CONNECT3 566 WOODLANDS ROAD (MANDAI ESTATE) SINGAPORE 728697			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 5644P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR WINDSCREEN	BROKEN	1,116.00	1,116.00
1	TAILGATE	BENT	2,936.80	2,936.80
1	TAILGATE INNER LOCK	JAMMED	116.70	116.70
2	TAILGATE REFLECTOR RH & LH @\$225.90	CRACKED	451.80	451.80
1	TAILGATE TRIMBOARD )	CRACKED	316.50	316.50
1	BACK DOOR LOWER )		580.00	-
1	TAILGATE RUBBER	NECESSARY	158.70	158.70
1	TAILGATE EMBLEM (QASHQAI)	NECESSARY	87.00	87.00
1	TAILGATE LOGO CENTER	NECESSARY	59.70	59.70
1	TAILGATE HANDLE )	CUT	28.10	28.10
1	BACK DOOR )		350.00	-
1	BACK DOOR )		170.00	-
1	TAILGATE NUMBER PLATE GARNISH )	SCRATCHED	336.00	336.00
1	BACK DOOR HANDLE )		50.00	-
1	TAILGATE WIPER ARM	SCRATCHED	63.80	63.80
1	TAILGATE WIPER BLADE	CUT	19.60	19.60
1	TAILGATE WIPER MOTOR	CRACKED	411.70	411.70
1	TAILGATE WIPER ARM COVER	CUT	14.25	14.25
1	REAR FENDER INNER GARNISH RH	DEFORMED	231.70	231.70
1	REAR FENDER EXTENSION RH	DEFORMED	323.40	323.40
1	REAR FENDER INNER DUCT	DEFORMED	75.30	75.30
1	REAR END PANEL	BENT	482.60	482.60
1	REAR END PANEL TOP INNER GARNISH	DEFORMED	65.30	65.30
1	REAR BUMPER	DEFORMED	717.00	717.00
1	REAR BUMPER REINFORCEMENT	BENT	619.20	619.20
1	REAR BUMPER INNER SPONGE	TORN	146.20	146.20
1	REAR BUMPER SIDE RETAINER	NECESSARY	71.80	71.80
1	REAR BUMPER BRACKET	BENT	252.00	252.00
1	REAR BUMPER CLIP	NECESSARY	25.00	25.00
1	REAR BUMPER TOW HOOK COVER	MISSING	26.80	26.80
2	TAILLAMP LH & RH @\$323.70	BROKEN	647.40	647.40

Report Ref No. CC4/QBE18008483/R1hb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP CLIPS	NECESSARY	50.00	50.00
1	DOOR BACK	CRACKED	170.00	170.00
1	RH BOOT LAMP	BROKEN	320.00	320.00
1	OVER FENDER RR RH	DEFORMED	560.00	483.00
1	SIDE FINISHER UPPER RH	DEFORMED	230.00	230.00
1	BOOT LAMP LH	CRACKED	390.00	390.00
	LESS 10% DISCOUNT		-	-1,144.34
			12,670.35	10,299.01
	<b>SPECIAL NETT ITEMS</b>			
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
1	REVERSE SENSOR (SN)	NOT WORKING	330.00	330.00
			365.00	365.00
	<b>LABOUR</b>			
	CHECK WIRING.		30.00	30.00
	TRANSFER TAILGATE FITTINGS .		60.00	60.00
	REPLACE BUMPER ETC LABOUR CHARGES.		1,500.00	1,500.00
	REMOVE & REFIT REAR INNER TRIMS.		100.00	60.00
	REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	APPLY SEALANT .		40.00	40.00
	REPLACE REVERSE SENSOR .		60.00	60.00
	SPRAY PAINTING.		1,200.00	1,200.00
			3,110.00	3,070.00
	<b>GRAND TOTAL</b>		<b>16,145.35</b>	<b>13,734.01</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>13,734.01</b>

Report Ref No. CC4/QBE18008483/R1hb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.