

CONNECT 3

7 Old Toh Tuck Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT18/SLJ5644P/TPC-217

QBE Insurance (Singapore) Pte Ltd

1 Raffles Quay

#29-10 South Tower

Singapore 048583

Dear Sir,

Cost of Repair to Vehicle SLJ5644P

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Rear bumper	1	2,111.00	DE / 2,111.00
2.	Rear bumper sponge	1	163.80	? 163.80
3.	Rear bumper tow cover	1	65.00	MIS / 65.00
4.	Rear bumper center cover	1	170.00	DE / 170.00
5.	Rear absorber	1	280.00	? 280.00
6.	Rear bumper reinforcement	1	1,400.00	? 1,400.00
7.	Rear Stay LH	1	280.00	? 280.00
8.	Rear Stay RH	1	280.00	? 280.00
9.	Rear bumper retainer RH	1	135.00	RE / 135.00
10.	Rear bumper retainer LH	1	135.00	RE / 135.00
11.	Rear number plate	1	40.00	DE / 40.00 35 \$/h
12.	Rear tonneau cover	1	521.00	X 521.00
13.	Tailgate panel	1	4,500.00	BA / 4,500.00
14.	Tailgate moulding	1	850.00	RE / 850.00
15.	Rear windscreen with moulding	1	1,954.00	PRO / 1,954.00
16.	Tailgate lock sensor	1	153.00	? 153.00
17.	Tailgate inner lock	1	185.80	JAM / 185.80
18.	Tailgate absorber LH	1	350.00	X 350.00
19.	Tailgate absorber RH	1	350.00	X 350.00

CONNECT 3

7 Old Toh Tuck Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

20.	Tailgate reflector	2	RH-BL 316.80	LH-? 633.60
21.	Tailgate lock outer	1	423.00	X 423.00
22.	Tailgate panel trim	1	550.00	? 550.00
23.	Weatherstripe for tailgate	1	350.00	nu / 350.00
24.	Rear emblem	1	160.00	nu / 160.00
25.	Rear RH taillamp	1	970.00	BL / 970.00
26.	Rear LH taillamp	1	970.00	CRA / 970.00
27.	Rear lamp inner	1	550.00	X 550.00
28.	Rear lamp outer	1	550.00	X 550.00
29.	Rear number plate lamp LH & RH	2	280.00	X 560.00
30.	End panel	1	1,900.00	PA / 1,900.00
31.	End panel top garnish	1	565.00	? 565.00
32.	Spare tyre panel	1	3,700.00	R 3,700.00
33.	Spare tyre board	1	850.00	? 850.00
34.	Spare tyre top garnish	1	856.00	? 856.00
35.	Spare Tyre Box L	1	480.00	? 480.00
36.	Reverse sensors	1 3 pcs	150.00	nu / 600.00
37.	Spare tyre lock screw	1	45.00	X 45.00
38.	Spare tyre tool compartment sponge	1	304.00	? 304.00
39.	Rear fender RH & LH	2	RH-BL 2,152.00	LH-R 4,304.00
40.	Rear wheel arch moulding RH	1	860.00	DE / 860.00
41.	Rear wheel arch moulding LH	1	860.00	X 860.00
42.	Exhaust pipe	1	1,200.00	X 1,200.00
43.	Rear bumper reflector RH	1	186.00	? 186.00
44.	Rear bumper reflector LH	1	186.00	X 186.00
45.	Tailgate wiper motor	1	483.50	? 483.50

CONNECT 3

7 Old Toh Tuck Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

46.	Tailgate wiper arm	1	105.50	scr / 105.50
47.	Tailgate number plate garnish	1	253.00	scr / 253.00
48.	Spare tyre panel acoustic insulator	1	180.00	X 180.00
49.	Clips	40	5.00	200.00
50.	XTRONIC CVT emblem	1	93.00	X 93.00
51.	Nissan Logo	1	39.00	scr / 39.00
52.	Qashqai Emblem	1	45.20	scr / 45.20
53.	Rear number plate holder	1	35.00	X 35.00
54.	Check wiring	1	80.00	30 80.00
55.	To replace rear bumper, tailgate, M-panel, side member LH & RH both side fenders mouldings etc	1	1,800.00	1500 1,800.00
56.	Transfer tailgate fittings	1	120.00	60 120.00
57.	To replace exhaust system	1	120.00	X 120.00
58.	To remove & refit rear inner trims to assist repair	1	180.00	60 180.00
59.	To remove & refit rear windscreen	1	150.00	120 150.00
60.	To apply sealant to rear windscreen	1	60.00	40 60.00
61.	To replace reverse sensors	1	120.00	60 120.00
62.	To replace rear camera	1	300.00	300.00 X
63.	Spray painting	1	1,400.00	1200 1,400.00
			SUB-TOTAL	SS42,300.00

Thank you.
Yours faithfully,

Winnie Chai

Winnie Chai
HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
HP 90010068

12 days

P/P

09/05/18 @ 1730

Resurvey by paint