55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0528/2018/GW

Date : 5-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm. Tan Lay Geok
Address : 7 Lenter Street

Singapore 786753

 Telephone
 : HP +65 91899940

 Type of Claim
 : Own Damage Claim

 Policy No.
 : 2100420155-02

 Vehicle No
 : SKS 6878 P

Model Code : Audi A6 1.8 TFSI Ultra

Model / Year : Apr-15
Engine No : CYG 003599

Chassis No : WAUZZZ4G0FN065593

Mileage : Date In : Liability : Excess Cost :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 2-May-18

Place of Accident : De La Salle Street

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 6878 P.

S/N	Nature of Jobs		Estimated Charges		
1	To remove and transfer lhs rear door's multi-lock system and power window devices.	S/N	\$	360.00	
2	To remove and transfer rear parking aid. Check function.	S/N	\$	280.00 🗡	
3	To dismantle lhs rear door, lhs side member trim and rear bumper. Repair lhs front door and lhs rear fender. Renew all damaged trims. Reinstall all parts removed.		\$	3,150.00	
4	To respray lhs front and rear doors, door handle, lhs side member trim, lhs rear fender and rear bumper.		\$	4,300.00 2750	
5	To renew lhs rear rim and carry out wheel alignment.	S/N	\$	280.00	
6	To carry out diagnostic check.	S/N	\$	192.00	
	TOTAL LABOUR CHARGES	:	\$	8,562.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 6878 P.

1 REAR DOOR-LH TREATCO 2 DOOR ATTACHMENT PARTS ? \$ 72.00 ? 3 REAR OUTER DOOR SEAL-LH AM \$ 202.00 . 4 BONDING AGENT \$ 43.00 ? 5 CLEANING SOLUTION ? \$ 64.00 ? 6 REAR DOOR CATCH-LH AM \$ 105.00 & 7 REAR DOOR WHEAHER LOWER STRIP-LH ? \$ 162.00 ? 8 REAR EXTERIOR DOOR HANDLE-LH AM \$ 5752.00 & 10 ATTACHMENT PARTS CLIP -LH \$ 77.00 & 11 ATTACHMENT PARTS ADHESIVE TAPE-LH \$ 14.00 & 12 REAR STONE GUARD FILM-LH AM \$ 102.00 & 13 REAR BUMPER FIXING PAR \$ 2,300.00 & 14 REAR BUMPER FIXING PAR \$ 234.00 & 15 REAR BUMPER GUIDE SECTION-LH \$ 824.00 & 16 REAR ALUMINIUM -LH AM \$ 824.00 & 17 SUNDRIES \$ 200.00 & TOTAL SPARE PARTS \$ \$ 8,924.00 & TOTAL LABOUR CHARGES \$ \$ 8,562.00 & GRAND TOTAL	S/N	Parts Description	<u>Damage Pa</u> S/NETT	arts & Prices REMARKS
2 DOOR ATTACHMENT PARTS ? 3 REAR OUTER DOOR SEAL-LH			 	•
3 REAR OUTER DOOR SEAL-LH	1		\$ 3,211.00	
4 BONDING AGENT 5 CLEANING SOLUTION 7 REAR DOOR CATCH-LH 7 REAR DOOR WHEAHER LOWER STRIP-LH 7 REAR DOOR WHEAHER LOWER STRIP-LH 8 REAR EXTERIOR DOOR HANDLE-LH 9 SIDE MEMBER TRIM-LH 9 SIDE MEMBER TRIM-LH 10 ATTACHMENT PARTS CLIP - LH 11 ATTACHMENT PARTS ADHESIVE TAPE-LH 12 REAR STONE GUARD FILM-LH 13 REAR BUMPER 14 REAR BUMPER FIXING PAR 15 REAR BUMPER GUIDE SECTION-LH 16 REAR ALUMINIUM - LH 17 SUNDRIES 18 SP24.00 18 TOTAL SPARE PARTS 18 SP34.00 19 TOTAL LABOUR CHARGES 19 S 8,562.00	2	DOOR ATTACHMENT PARTS	\$ 72.00	7.
5 CLEANING SOLUTION ? \$ 64.00 ? 6 REAR DOOR CATCH-LH	3	REAR OUTER DOOR SEAL-LH	\$ 202.00	/ `
6 REAR DOOR CATCH-LH	4	BONDING AGENT	\$ 43.00	?
7 REAR DOOR WHEAHER LOWER STRIP-LH ? \$ 162.00 ? 8 REAR EXTERIOR DOOR HANDLE-LH AGAIN \$ 516.00 \$ 9 SIDE MEMBER TRIM-LH PARTS CLIP - LH \$ 775.00 \$ 10 ATTACHMENT PARTS ADHESIVE TAPE-LH \$ 14.00 \$ 11 ATTACHMENT PARTS ADHESIVE TAPE-LH \$ 102.00 \$ 12 REAR STONE GUARD FILM-LH \$ \$ 2,300.00 \$ 14 REAR BUMPER PARTS \$ 234.00 \$ 15 REAR BUMPER GUIDE SECTION-LH \$ \$ 46.00 \$ 16 REAR ALUMINIUM - LH \$ \$ 824.00 \$ 17 SUNDRIES \$ 200.00 \$ 18 TOTAL SPARE PARTS \$ 8,924.00 \$ 19 TOTAL LABOUR CHARGES \$ 8,562.00	5	CLEANING SOLUTION ?	\$ 64.00	?
8 REAR EXTERIOR DOOR HANDLE-LH AGAN 9 SIDE MEMBER TRIM-LH PARTS CLIP - LH 10 ATTACHMENT PARTS CLIP - LH 2 REAR STONE GUARD FILM-LH SUM 11 REAR BUMPER PARTS 102.00 13 REAR BUMPER FIXING PAR 14 REAR BUMPER FIXING PAR 15 REAR BUMPER GUIDE SECTION-LH 16 REAR ALUMINIUM - LH GAN 17 SUNDRIES 102.00 18 S24.00 19 S16.00 10 TOTAL SPARE PARTS 102.00 10 S16.00 11 SUNDRIES 102.00 11 SUNDRIES 102.00 12 SUNDRIES 13 S24.00 15 SUNDRIES 15 S8,924.00 16 S8,562.00	6	REAR DOOR CATCH-LH	\$ 105.00	K
9 SIDE MEMBER TRIM-LH	7	REAR DOOR WHEAHER LOWER STRIP-LH ?	\$ 162.00	j
10 ATTACHMENT PARTS CLIP - LH	8	REAR EXTERIOR DOOR HANDLE-LH	\$ 516.00	*
11 ATTACHMENT PARTS ADHESIVE TAPE-LH 12 REAR STONE GUARD FILM-LH 13 REAR BUMPER REAL 14 REAR BUMPER FIXING PAR 15 REAR BUMPER GUIDE SECTION-LH 16 REAR ALUMINIUM -LH 17 SUNDRIES 18 102.00 \$ 2,300.00 \$ 46.00 \$ 46.00 \$ 824.00 TOTAL SPARE PARTS 18 8,924.00 \$ 8,562.00	9	SIDE MEMBER TRIM-LH	\$ 752.00	*
12 REAR STONE GUARD FILM-LH	10	ATTACHMENT PARTS CLIP - LH 2 New	\$ 77.00	
\$ 2,300.00 \(\). 14 REAR BUMPER FIXING PAR \$ 234.00 \(\) 15 REAR BUMPER GUIDE SECTION-LH \$ 46.00 \(\) 16 REAR ALUMINIUM -LH \(\) 17 SUNDRIES \$ 200.00 \(\) TOTAL SPARE PARTS \$ 8,924.00 \(\) TOTAL LABOUR CHARGES \$ 8,562.00	11	ATTACHMENT PARTS ADHESIVE TAPE-LH	\$ 14.00	K.
14 REAR BUMPER FIXING PAR \$ 234.00 * 15 REAR BUMPER GUIDE SECTION-LH \$ 46.00 * 16 REAR ALUMINIUM -LH & \$ 824.00 * 17 SUNDRIES \$ 200.00 * TOTAL SPARE PARTS \$ 8,924.00 TOTAL LABOUR CHARGES \$ 8,562.00	12	REAR STONE GUARD FILM-LH	\$ 102.00	
15 REAR BUMPER GUIDE SECTION-LH \$ 46.00 \(\) 16 REAR ALUMINIUM -LH \(\) 17 SUNDRIES \$ 200.00 \(\) TOTAL SPARE PARTS : \$ 8,924.00 TOTAL LABOUR CHARGES : \$ 8,562.00	13	REAR BUMPER REAL	\$ 2,300.00	K .
16 REAR ALUMINIUM - LH	14	REAR BUMPER FIXING PAR	\$ 234.00	۲
17 SUNDRIES \$ 200.00 TOTAL SPARE PARTS : \$ 8,924.00 TOTAL LABOUR CHARGES : \$ 8,562.00	15	REAR BUMPER GUIDE SECTION-LH	\$ 46.00 °	۲.
TOTAL SPARE PARTS : \$ 8,924.00 TOTAL LABOUR CHARGES : \$ 8,562.00	16	REAR ALUMINIUM -LH &	\$ 824.00 1	
TOTAL LABOUR CHARGES : \$ 8,562.00	17	SUNDRIES	\$ 200.00	?
		TOTAL SPARE PARTS :	\$ 8,924.00	•
GRAND TOTAL : \$ 17.486.00		TOTAL LABOUR CHARGES :	\$ 8,562.00	
. 7 27,3000		GRAND TOTAL :	\$ 17,486.00	

All charges are not inclusive of GST.

Leaend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name

Surveyed Date

Authorised Date

Excess Cost

Liability Remarks

: Not Anthorsed, 06 Drys

Tel:6768 9828 for appointment.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo **Body Repair Manager** Allan Wu Claims Consultant