# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #07-16

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Date: 09 May 2018 Attn: Lee, Ming-Yao

## **Preliminary Advice**

Vehicle No : SKS6878P Accident Date : 02/05/2018 Make : AUDI A6 Policy No. : 2100420155-02

: 09/05/2018 Assignment Date **Excess** : S\$0.00 Date of Inspection : 08/05/2018 Est. Duration of Repair : 6.00

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,486.00
Revised Amount	:S\$	9,012.00
Check Items (Estimated)	:S\$	541.00
Total	:S\$	9,553.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 138,000.00 COE / PARF Rebate :S\$ 82,934.00

Salvage Value :S\$

Margin for Repair :S\$ 55,066.00

### Remarks

( /	<b>`</b> )	let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(	)	Other comments :