

INS 2010

INS. CASE OWNER:

WATER LOU
KIAN CHUAN

CC 4 KSM / AXA1800

8493, J6352

LKK:

IDAC:

Surveyor:

U/S

DOI:

ASSIGNMENT

10/5/18

Date / Time:

9/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJH 9594H

Name of Insured:

MO WING

Insured Tel No.:

HP:

98767080

Excess Sec II :SS

D.O.A:

5/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

88M006BX / 46227

Policy No.:

GAMP38571

Make / Model:

SHIBARU

Place of Accident:

PIE TWO3 LAMM1

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SEP 9164L



INSRS:

WSP:

Tel:

Liability:

RMKS:

WEEK
MAN.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/5/18
704

SEP 9164L - X
SJH 9594H - X
PIE TWO3 LAMM1

GTX 36730 - PIR AGAINST

OI HIT TP FROM ALAN
2 HIT TP HIT TAXI, TAXI HIT
LORRY.

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
Documentation Check List: Handler Typist	
Notification ltr (if non-pickup)	☐
After call ltr to OI:	☐
Authorisation To Act:	☐
Release Voucher:	☐
Final Repair Bill:	☐
Car Rental Invoice:	☐
Towing Invoice:	☐
LTA / GIA:	☐
Medical Bill:	☐
PIR:	☐
Mandate/Reject Instruction:	☐
LOD:	☐
Payment Breakdown Form:	☐
Post-Repair Photos:	☐
Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No.:
Repair Cost:	SS		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS	(\$ x days)	
Loss of Income (LOI):	SS	(\$ x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search:	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost:	SS		
Total:	SS	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT

WP - INSTRUCTION
FROM A.P.A.
TP PASSED TO LAWYER
TO WP.

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee: \$250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008493/jb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 09-05-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 9594H	Veh. Inspected	SKP 9164L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/05/2018	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 3655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

Term:

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	957.40	20	765.92
2	BOOTLID HINGE LH	1.0	145.40	20	116.32
3	BOOTLID HINGE RH	1.0	145.40	20	116.32
4	BOOTLID LOCK	1.0	177.30	20	141.84
5	BOOTLID CABLE	1.0	55.10	20	44.08
6	BOOTLID RUBBER	1.0	129.30	20	103.44
7	BOOTLID EMBLEM	1.0	74.40	20	59.52
8	BOOTLID LOGO - MAZDA 3	1.0	53.40	20	42.72
9	BOOTLID - SKYACTIV	1.0	63.60	20	50.88
10	BOOTLID LAMP RH	1.0	265.00	20	212.00
11	BOOTLID LAMP LH	1.0	265.00	20	212.00
12	BOOTLID SWITCH	1.0	164.00	20	131.20
13	TAIL LAMP RH	1.0	509.40	20	407.52
14	TAIL LAMP LH	1.0	509.40	20	407.52
15	TAIL LAMP PANEL RH	1.0	377.80	20	302.24
16	TAIL LAMP PANEL LH	1.0	377.80	20	302.24
17	TAIL LAMP CLIP	8.0	5.00	20	32.00
18	REAR FENDER RH	1.0	1,175.30	20	940.24
19	REAR FENDER LH	1.0	1,175.30	20	940.24
20	REAR FENDER INNER PANEL GARNISH RH	1.0	235.60	20	188.48
21	REAR FENDER INNER PANEL GARNISH LH	1.0	235.60	20	188.48
22	REAR WINDSCREEN MOULDING	1.0	73.30	20	58.64
23	END PANEL	1.0	505.10	20	404.08
24	END PANEL TOP GARNISH	1.0	85.10	20	68.08
25	SPARE TYRE PANEL	1.0	524.70	20	419.76
26	SPARE TYRE PANEL TRIMBOARD	1.0	350.10	20	280.08
27	SPARE TYRE PANEL BRACKET	1.0	70.40	20	56.32
28	SPARE TYRE PANEL SCREW	1.0	138.00	20	110.40
29	REAR BUMPER	1.0	925.10	20	740.08
30	REAR BUMPER REFLECTOR RH	1.0	50.40	20	40.32
31	REAR BUMPER REFLECTOR LH	1.0	50.40	20	40.32
32	REAR BUMPER RETAINER RH	1.0	36.10	20	28.88
33	REAR BUMPER RETAINER LH	1.0	36.10	20	28.88
34	REAR BUMPER BRACKET RH	1.0	72.20	20	57.76

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	REAR BUMPER BRACKET LH <i>NS</i>	1.0	72.20	20	57.76
36	REAR BUMPER TOWING COVER LH <i>To.1</i>	1.0	16.20	20	12.96
37	REAR BUMPER TOWING COVER RH <i>To.1</i>	1.0	16.20	20	12.96
38	SPARE TYRE LOWER BRACKET PANEL CENTER <i>NS</i>	1.0		20	
39	EXHAUST BOX <i>bed / fuel</i>	1.0	1,075.80	20	860.64
40	EXHAUST CENTER PIPE <i>bed / fuel</i>	1.0	1,433.40	20	1,146.72
41	EXHAUST MOUNTING <i>To.1</i>	4.0	33.30	20	106.56
42	EXHAUST SHIELD <i>bed</i>	1.0	270.40	20	216.32
43	SPARE TYRE SPONGE LH <i>NS</i>	1.0		20	
44	SPARE TYRE SPONGE RH <i>NS</i>	1.0		20	
45	REAR AXLE <i>11</i>	1.0	828.20	20	662.56
46	REAR LOWER ARM LH <i>NS</i>	1.0	250.20	20	200.16
47	REAR LOWER ARM RH <i>NS</i>	1.0	250.20	20	200.16
48	REAR SHOCK ABSORBER RH <i>11</i>	1.0	344.70	20	275.76
49	REAR SHOCK ABSORBER LH <i>11</i>	1.0	344.70	20	275.76
50	REAR WHEEL BEARING LH <i>11</i>	1.0	414.40	20	331.52
51	REAR WHEEL BEARING RH <i>11</i>	1.0	414.40	20	331.52
52	BONNET <i>suc</i>	1.0	1,067.30	20	853.84
53	BONNET HINGE RH <i>bed</i>	1.0	41.10	20	32.88
54	BONNET HINGE LH <i>bed</i>	1.0	41.10	20	32.88
55	BONNET GRILLE <i>one</i>	1.0	335.00	20	268.00
56	BONNET RUBBER <i>bed</i>	2.0	63.60	20	101.76
57	BONNET LOCK <i>fuel</i>	1.0	197.10	20	157.68
58	SUPPORT PANEL <i>one</i>	1.0	469.70	20	375.76
59	SUPPORT PANEL AIR DUCT LH <i>fuel</i>	1.0	35.60	20	28.48
60	SUPPORT PANEL TOP GARNISH <i>one</i>	1.0	33.40	20	26.72
61	SUPPORT PANEL TOP PANEL <i>NS</i>	1.0	140.00	20	112.00
62	SUPPORT PANEL CENTER GARNISH <i>dis</i>	1.0	469.70	20	375.76
63	SUPPORT PANEL AIR DUCT RH <i>NS</i>	1.0	35.60	20	28.48
64	SUPPORT GRILLE LOWER INNER GARNISH <i>dis</i>	1.0	92.70	20	74.16
65	BRACE PANEL <i>~</i>	1.0	38.80	20	31.04
66	AIR CON CONDENSER <i>bed / fuel</i>	1.0	1,063.00	20	850.40
67	RADIATOR <i>one</i>	1.0	1,064.90	20	851.92
68	RADIATOR COWLING, FAN & MOTOR <i>11</i>	1.0	1,356.80	20	1,085.44

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
69	RADIATOR BOTTOM HOSE 1A	1.0	65.60	20	52.48
70	RADIATOR TOP HOSE 1A	1.0	65.60	20	52.48
71	RADIATOR SPARE TANK 1A	1.0	65.80	20	52.64
72	HEADLAMP ASSEMBLY LH Cae	1.0	773.30	20	618.64
73	HEADLAMP ASSEMBLY RH 220	1.0	773.30	20	618.64
74	HEADLAMP BRACKET RH 1A	1.0	15.10	20	12.08
75	HEADLAMP BRACKET LH 1A	1.0	15.10	20	12.08
76	HEADLAMP CLIP 1A	4.0	8.00	20	25.60
77	FRONT GRILLE INNER GARNISH OM	1.0	119.60	20	95.68
78	FRONT GRILLE CHROME RH Cae	1.0	176.70	20	141.36
79	FRONT GRILLE CHROME LH OM	1.0	176.70	20	141.36
80	FRONT GRILLE EMBLEM SCN	1.0	44.20	20	35.36
81	FRONT BUMPER CENTER BRACKET 32	2.0	15.10	20	24.16
82	FRONT BUMPER NUMBER GARNISH 2.5	1.0	51.70	20	41.36
83	FRONT BUMPER CENTER GARNISH 2.5	1.0	335.80	20	268.64
84	FRONT BUMPER LOWER INNER GARNISH 1A	1.0	102.40	20	81.92
85	FRONT BUMPER RETAINER RH 32	1.0	18.70	20	14.96
86	FRONT BUMPER RETAINER LH 32	1.0	18.70	20	14.96
87	FRONT BUMPER REINFORCEMENT 32	1.0	565.10	20	452.08
88	FRONT BUMPER INNER CENTER BRACKET RH 1A	1.0	35.60	20	28.48
89	FRONT BUMPER INNER CENTER BRACKET LH 1A	1.0	35.60	20	28.48
90	FRONT GRILLE INNER BRACKET LH 1A	1.0	15.10	20	12.08
91	FRONT BUMPER INNER BRACKET RH 1A	1.0	15.10	20	12.08
92	FRONT BUMPER 2.5	1.0	925.10	20	740.08
93	FRONT BUMPER LOWER GRILLE 1A	1.0		20	
94	FRONT BUMPER LOWER GARNISH 1A	1.0	83.70	20	66.96
95	FRONT BUMPER FOG LAMP LH 1A	1.0	50.40	20	40.32
96	FRONT BUMPER FOG LAMP RH 1A	1.0	50.40	20	40.32
97	FRONT BUMPER FOG LAMP COVER LH 1A	1.0	42.50	20	34.00
98	FRONT BUMPER FOG LAMP COVER RH 1A	1.0	42.50	20	34.00
99	FRONT BUMPER TRIANGLE COVER LH 1A	1.0	28.00	20	22.40
100	FRONT BUMPER TRIANGLE COVER RH 1A	1.0	28.00	20	22.40
101	ENGINE LOWER DUST COVER 1A	1.0	95.70	20	76.56
102	FRONT FENDER RH 32	1.0	333.90	20	267.12

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
103	FRONT FENDER LH <i>Bul/Buc</i>	1.0	333.90	20	267.12
104	FRONT FENDER INNER SHIELD LH <i>11</i>	1.0	129.30	20	103.44
105	FRONT FENDER INNER SHIELD RH <i>11</i>	1.0	129.30	20	103.44
106	FRONT BUMPER TOWING COVER <i>For 11</i>	1.0	28.60	20	22.88
107	FRONT BUMPER INNER CENTER BRACKET LH <i>NS</i>	1.0	15.10	20	12.08
108	FRONT BUMPER INNER CENTER BRACKET RH <i>NS</i>	1.0	15.10	20	12.08
109	STEERING AIR BAG <i>Subst</i>	1.0	1,082.50	20	866.00
110	STEERING CLOCK SENSOR <i>Subst</i>	1.0	192.90	20	154.32
111	DASHBOARD AIRBAG <i>Subst</i>	1.0	1,169.60	20	935.68
112	DASHBOARD <i>Subst</i>	1.0	1,429.10	20	1,143.28
113	FRONT SEAT BELT RH <i>Subst</i>	1.0	1,022.10	20	817.68
114	FRONT SEAT BELT LH <i>Subst</i>	1.0	1,022.10	20	817.68
115	FRONT SEAT BELT BUCKLE RH <i>11</i>	1.0	94.80	20	75.84
116	FRONT SEAT BELT BUCKLE LH <i>11</i>	1.0	94.80	20	75.84
117	FRONT SEAT BELT INNER GARNISH RH <i>11</i>	1.0		20	
118	FRONT SEAT BELT INNER GARNISH LH <i>11</i>	1.0		20	
119	AIR BAG ECU <i>Subst</i>	1.0	1,444.40	20	1,155.52
120	AIR BAG IMPACT SENSOR <i>Subst</i>	1.0	145.90	20	116.72
121	CONTROL ECU (BELOW HEADLAMP LH) <i>11</i>	1.0	2,867.10	20	2,293.68
List Price - Parts Sub Total					31,172.40
122	CERAMIC COATING <i>11</i>	1.0	700.00	0	700.00
123	WINDSCREEN SEALANT <i>11</i>	2.0	24.00	0	48.00
124	SPARE TYRE SEAL <i>11</i>	1.0	80.00	0	80.00
125	REVERSE SENSOR <i>Subst</i>	1.0	280.00	0	280.00
126	REAR NUMBER PLATE <i>Subst</i>	1.0	30.00	0	30.00
127	REAR NUMBER PLATE HOLDER <i>Subst</i>	1.0	30.00	0	30.00
128	FRONT NUMBER PLATE <i>Subst</i>	1.0	30.00	0	30.00
129	REAR CHASSIS LH - REPAIR <i>11</i>	1.0			
130	REAR CHASSIS RH - REPAIR <i>11</i>	1.0			
131	FRONT DOOR LH - REPAIR <i>11</i>	1.0			
132	FRONT DOOR RH - REPAIR <i>11</i>	1.0			
133	REAR DOOR RH - REPAIR <i>11</i>	1.0			
134	REAR DOOR LH - REPAIR <i>11</i>	1.0			

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
Special Nett Price - Parts Sub Total					1,198.00
Parts Total					32,370.40
135	LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR)	1.0	2,500.00	0	2,500.00
136	SPRAY PAINT ON THE AFFECTED AREAS (REAR)	1.0	1,800.00	0	1,800.00
137	ANTI-RUST COATING (REAR)	1.0	300.00	0	300.00
138	WIRING (REAR)	1.0	80.00	0	80.00
139	TO REMOVE & REFIT WINDSCREEN (REAR)	1.0	180.00	0	180.00
140	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	350.00	0	350.00
141	TO REMOVE & REFIT FUEL TANK	1.0	350.00	0	350.00
142	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
143	TO REMOVE & REFIT UNDERCARRIAGE (REAR)	1.0	500.00	0	500.00
144	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
Labour 1 Sub Total					6,390.00
145	LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT)	1.0	1,200.00	0	1,200.00
146	SPRAY PAINT ON THE AFFECTED AREAS (FRONT)	1.0	1,200.00	0	1,200.00
147	ANTI-RUST COATING (FRONT)	1.0	250.00	0	250.00
148	WIRING (FRONT)	1.0	80.00	0	80.00
149	TO SERVICE & TOP-UP AIR-CON GAS	1.0	180.00	0	180.00
150	TO REMOVE & REFIT DASHBOARD	1.0	450.00	0	450.00
Labour 2 Sub Total					3,360.00
SINGAPORE DOLLARS : FORTY-FIVE THOUSAND SIXTY-EIGHT AND CENTS EIGHTY-THREE ONLY					
Less Excess					0.00
SUBTOTAL					42,120.40
GST 7.00%					2,948.43
TOTAL					45,068.83

Date of accident : 05/05/2018 10:45 PM; Place : PIE AFTER LORNE ROAD > CHANGI

E. & O. E.

LKK Auto Consultants hence notify the Insurer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The resurvey is on a "Without Prejudice" basis
- No repair/modification is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CUSTOMER SIGNATURE

Signature:

Date:

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL: FAX:
PH: 96528596
ATTN:

ESTIMATE BILL

Number: EB00004820
Date: 08/05/2018
Case No: AD00009719
Vehicle No: SKP9164L
Chassis: JM6BM42A8F0150535
Year of Mfr: 2014
Policy No: 5074725906-02
Model: MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	957.40	20	765.92
2	BOOTLID HINGE LH	1.0	145.40	20	116.32
3	BOOTLID HINGE RH	1.0	145.40	20	116.32
4	BOOTLID LOCK	1.0	177.30	20	141.84
5	BOOTLID CABLE	1.0	55.10	20	44.08
6	BOOTLID RUBBER	1.0	129.30	20	103.44
7	BOOTLID EMBLEM	1.0	74.40	20	59.52
8	BOOTLID LOGO - MAZDA 3	1.0	53.40	20	42.72
9	BOOTLID - SKYACTIV	1.0	63.60	20	50.88
10	BOOTLID LAMP RH	1.0	265.00	20	212.00
11	BOOTLID LAMP LH	1.0	265.00	20	212.00
12	BOOTLID SWITCH	1.0	164.00	20	131.20
13	TAIL LAMP RH	1.0	509.40	20	407.52
14	TAIL LAMP LH	1.0	509.40	20	407.52
15	TAIL LAMP PANEL RH	1.0	377.80	20	302.24
16	TAIL LAMP PANEL LH	1.0	377.80	20	302.24
17	TAIL LAMP CLIP	8.0	5.00	20	32.00
18	REAR FENDER RH	1.0	1,175.30	20	940.24
19	REAR FENDER LH	1.0	1,175.30	20	940.24
20	REAR FENDER INNER PANEL GARNISH RH	1.0	235.60	20	188.48
21	REAR FENDER INNER PANEL GARNISH LH	1.0	235.60	20	188.48
22	REAR WINDSCREEN MOULDING	1.0	73.30	20	58.64
23	END PANEL	1.0	505.10	20	404.08
24	END PANEL TOP GARNISH	1.0	85.10	20	68.08
25	SPARE TYRE PANEL	1.0	524.70	20	419.76
26	SPARE TYRE PANEL TRIMBOARD	1.0	350.10	20	280.08
27	SPARE TYRE PANEL BRACKET	1.0	70.40	20	56.32
28	SPARE TYRE PANEL SCREW	1.0	138.00	20	110.40
29	REAR BUMPER	1.0	925.10	20	740.08
30	REAR BUMPER REFLECTOR RH	1.0	50.40	20	40.32
31	REAR BUMPER REFLECTOR LH	1.0	50.40	20	40.32
32	REAR BUMPER RETAINER RH	1.0	36.10	20	28.88
33	REAR BUMPER RETAINER LH	1.0	36.10	20	28.88
34	REAR BUMPER BRACKET RH	1.0	72.20	20	57.76

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	REAR BUMPER BRACKET LH <i>NS</i>	1.0	72.20	20	57.76
36	REAR BUMPER TOWING COVER LH <i>To 1</i>	1.0	16.20	20	12.96
37	REAR BUMPER TOWING COVER RH <i>To 1</i>	1.0	16.20	20	12.96
38	SPARE TYRE LOWER BRACKET PANEL CENTER <i>NS</i>	1.0		20	
39	EXHAUST BOX <i>Set/Pair</i>	1.0	1,075.80	20	860.64
40	EXHAUST CENTER PIPE <i>Set/Pair</i>	1.0	1,433.40	20	1,146.72
41	EXHAUST MOUNTING <i>To 1</i>	4.0	33.30	20	106.56
42	EXHAUST SHIELD <i>Set</i>	1.0	270.40	20	216.32
43	SPARE TYRE SPONGE LH	1.0		20	
44	SPARE TYRE SPONGE RH	1.0		20	
45	REAR AXLE	1.0	828.20	20	662.56
46	REAR LOWER ARM LH <i>NS</i>	1.0	250.20	20	200.16
47	REAR LOWER ARM RH <i>NS</i>	1.0	250.20	20	200.16
48	REAR SHOCK ABSORBER RH	1.0	344.70	20	275.76
49	REAR SHOCK ABSORBER LH	1.0	344.70	20	275.76
50	REAR WHEEL BEARING LH	1.0	414.40	20	331.52
51	REAR WHEEL BEARING RH	1.0	414.40	20	331.52
52	BONNET <i>Set</i>	1.0	1,067.30	20	853.84
53	BONNET HINGE RH <i>Set</i>	1.0	41.10	20	32.88
54	BONNET HINGE LH <i>Set</i>	1.0	41.10	20	32.88
55	BONNET GRILLE <i>one</i>	1.0	335.00	20	268.00
56	BONNET RUBBER <i>one</i>	2.0	63.60	20	101.76
57	BONNET LOCK <i>one</i>	1.0	197.10	20	157.68
58	SUPPORT PANEL <i>one</i>	1.0	469.70	20	375.76
59	SUPPORT PANEL AIR DUCT LH <i>one</i>	1.0	35.60	20	28.48
60	SUPPORT PANEL TOP GARNISH <i>one</i>	1.0	33.40	20	26.72
61	SUPPORT PANEL TOP PANEL <i>NS</i>	1.0	140.00	20	112.00
62	SUPPORT PANEL CENTER GARNISH <i>Dis</i>	1.0	469.70	20	375.76
63	SUPPORT PANEL AIR DUCT RH	1.0	35.60	20	28.48
64	SUPPORT GRILLE LOWER INNER GARNISH <i>Dis</i>	1.0	92.70	20	74.16
65	BRACE PANEL <i>one</i>	1.0	38.80	20	31.04
66	AIR CON CONDENSER <i>Set/Pair</i>	1.0	1,063.00	20	850.40
67	RADIATOR	1.0	1,064.90	20	851.92
68	RADIATOR COWLING, FAN & MOTOR	1.0	1,356.80	20	1,085.44

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392

TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
69	RADIATOR BOTTOM HOSE	1.0	65.60	20	52.48
70	RADIATOR TOP HOSE	1.0	65.60	20	52.48
71	RADIATOR SPARE TANK	1.0	65.80	20	52.64
72	HEADLAMP ASSEMBLY LH <i>cne</i>	1.0	773.30	20	618.64
73	HEADLAMP ASSEMBLY RH <i>B20</i>	1.0	773.30	20	618.64
74	HEADLAMP BRACKET RH	1.0	15.10	20	12.08
75	HEADLAMP BRACKET LH	1.0	15.10	20	12.08
76	HEADLAMP CLIP <i>17</i>	4.0	8.00	20	25.60
77	FRONT GRILLE INNER GARNISH <i>on</i>	1.0	119.60	20	95.68
78	FRONT GRILLE CHROME RH <i>cne</i>	1.0	176.70	20	141.36
79	FRONT GRILLE CHROME LH <i>on</i>	1.0	176.70	20	141.36
80	FRONT GRILLE EMBLEM <i>scr</i>	1.0	44.20	20	35.36
81	FRONT BUMPER CENTER BRACKET	2.0	15.10	20	24.16
82	FRONT BUMPER NUMBER GARNISH <i>2.5</i>	1.0	51.70	20	41.36
83	FRONT BUMPER CENTER GARNISH	1.0	335.80	20	268.64
84	FRONT BUMPER LOWER INNER GARNISH	1.0	102.40	20	81.92
85	FRONT BUMPER RETAINER RH <i>3.5</i>	1.0	18.70	20	14.96
86	FRONT BUMPER RETAINER LH <i>3.5</i>	1.0	18.70	20	14.96
87	FRONT BUMPER REINFORCEMENT <i>3.5</i>	1.0	565.10	20	452.08
88	FRONT BUMPER INNER CENTER BRACKET RH	1.0	35.60	20	28.48
89	FRONT BUMPER INNER CENTER BRACKET LH	1.0	35.60	20	28.48
90	FRONT GRILLE INNER BRACKET LH	1.0	15.10	20	12.08
91	FRONT BUMPER INNER BRACKET RH	1.0	15.10	20	12.08
92	FRONT BUMPER <i>2.5</i>	1.0	925.10	20	740.08
93	FRONT BUMPER LOWER GRILLE	1.0		20	
94	FRONT BUMPER LOWER GARNISH	1.0	83.70	20	66.96
95	FRONT BUMPER FOG LAMP LH	1.0	50.40	20	40.32
96	FRONT BUMPER FOG LAMP RH	1.0	50.40	20	40.32
97	FRONT BUMPER FOG LAMP COVER LH	1.0	42.50	20	34.00
98	FRONT BUMPER FOG LAMP COVER RH	1.0	42.50	20	34.00
99	FRONT BUMPER TRIANGLE COVER LH	1.0	28.00	20	22.40
100	FRONT BUMPER TRIANGLE COVER RH	1.0	28.00	20	22.40
101	ENGINE LOWER DUST COVER	1.0	95.70	20	76.56
102	FRONT FENDER RH <i>3.5</i>	1.0	333.90	20	267.12

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
103	FRONT FENDER LH <i>Sub/Buc</i>	1.0	333.90	20	267.12
104	FRONT FENDER INNER SHIELD LH <i>11</i>	1.0	129.30	20	103.44
105	FRONT FENDER INNER SHIELD RH <i>For</i>	1.0	129.30	20	103.44
106	FRONT BUMPER TOWING COVER <i>For</i>	1.0	28.60	20	22.88
107	FRONT BUMPER INNER CENTER BRACKET LH	1.0	15.10	20	12.08
108	FRONT BUMPER INNER CENTER BRACKET RH	1.0	15.10	20	12.08
109	STEERING AIR BAG <i>Sub</i>	1.0	1,082.50	20	866.00
110	STEERING CLOCK SENSOR <i>Sub</i>	1.0	192.90	20	154.32
111	DASHBOARD AIRBAG <i>Sub</i>	1.0	1,169.60	20	935.68
112	DASHBOARD <i>To 11</i>	1.0	1,429.10	20	1,143.28
113	FRONT SEAT BELT RH <i>Sub</i>	1.0	1,022.10	20	817.68
114	FRONT SEAT BELT LH <i>Sub</i>	1.0	1,022.10	20	817.68
115	FRONT SEAT BELT BUCKLE RH <i>11</i>	1.0	94.80	20	75.84
116	FRONT SEAT BELT BUCKLE LH <i>11</i>	1.0	94.80	20	75.84
117	FRONT SEAT BELT INNER GARNISH RH <i>11</i>	1.0		20	
118	FRONT SEAT BELT INNER GARNISH LH <i>11</i>	1.0		20	
119	AIR BAG ECU <i>Sub</i>	1.0	1,444.40	20	1,155.52
120	AIR BAG IMPACT SENSOR <i>Sub</i>	1.0	145.90	20	116.72
121	CONTROL ECU (BELOW HEADLAMP LH) <i>11</i>	1.0	2,867.10	20	2,293.68
List Price - Parts Sub Total					31,172.40
122	CERAMIC COATING	1.0	700.00	0	700.00
123	WINDSCREEN SEALANT <i>rec</i>	2.0	24.00	0	48.00
124	SPARE TYRE SEAL <i>11</i>	1.0	80.00	0	80.00
125	REVERSE SENSOR <i>Sub</i>	1.0	280.00	0	280.00
126	REAR NUMBER PLATE <i>Sub</i>	1.0	30.00	0	30.00
127	REAR NUMBER PLATE HOLDER <i>Sub</i>	1.0	30.00	0	30.00
128	FRONT NUMBER PLATE <i>1320</i>	1.0	30.00	0	30.00
129	REAR CHASSIS LH - REPAIR <i>2x</i>	1.0			
130	REAR CHASSIS RH - REPAIR <i>2x</i>	1.0			
131	FRONT DOOR LH - REPAIR <i>2x</i>	1.0			
132	FRONT DOOR RH - REPAIR <i>2x</i>	1.0			
133	REAR DOOR RH - REPAIR <i>2x</i>	1.0			
134	REAR DOOR LH - REPAIR <i>2x</i>	1.0			

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
Special Nett Price - Parts Sub Total					1,198.00
Parts Total					32,370.40
135	LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR)	1.0	2,500.00	0	2,500.00
136	SPRAY PAINT ON THE AFFECTED AREAS (REAR)	1.0	1,800.00	0	1,800.00
137	ANTI-RUST COATING (REAR)	1.0	300.00	0	300.00
138	WIRING (REAR)	1.0	80.00	0	80.00
139	TO REMOVE & REFIT WINDSCREEN (REAR)	1.0	180.00	0	180.00
140	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	350.00	0	350.00
141	TO REMOVE & REFIT FUEL TANK	1.0	350.00	0	350.00
142	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
143	TO REMOVE & REFIT UNDERCARRIAGE (REAR)	1.0	500.00	0	500.00
144	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
Labour 1 Sub Total					6,390.00
145	LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT)	1.0	1,200.00	0	1,200.00
146	SPRAY PAINT ON THE AFFECTED AREAS (FRONT)	1.0	1,200.00	0	1,200.00
147	ANTI-RUST COATING (FRONT)	1.0	250.00	0	250.00
148	WIRING (FRONT)	1.0	80.00	0	80.00
149	TO SERVICE & TOP-UP AIR-CON GAS	1.0	180.00	0	180.00
150	TO REMOVE & REFIT DASHBOARD	1.0	450.00	0	450.00
Labour 2 Sub Total					3,360.00
SINGAPORE DOLLARS : FORTY-FIVE THOUSAND SIXTY-EIGHT AND CENTS EIGHTY-THREE ONLY			Less Excess		0.00
			SUBTOTAL		42,120.40
			GST 7.00%		2,948.43
			TOTAL		45,068.83

Date of accident : 05/05/2018 10:45 PM. Place : PIE AFTER LORNIE ROAD > CHANGI

E. & O. E.

PKK Auto Consultants hence notify the Insurer of the following:

- To supply damaged parts during resurvey
- Prices are subject to confirmation
- The survey is on an "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CUSTOMER SIGNATURE

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

Service Request Details

Claim:

S8M00GBX

Reference

None 

Loss Date

May 5, 2018

Request Date

May 9, 2018

Due Date

May 16, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SKP9164L

Make

TPVD MAZDA

Hoofe wah.
May. @ 2.35pm Veh In.

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Service Address

Primary Contact/Insured

HO WILLY

BLK 520C TAMPINES CENTRAL 8, #14-61, 523520, Singapore

98762080

EVO2080@GMAIL.COM

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

5/9/18 9:51 AM

FROM

CHAN Kian Chuan

SUBJECT

REQ DOC

BODY

REQ FOR TO REPAIR ESTI, TP VIDEO FOOTAGE IF ANY, L...





TP has passed the case to lawyer. Please let us have your WP report

Type

🔗 Question

Message

TP has passed the case to lawyer. Please let us have your WP report

Reply

Catherine Chong (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Friday, 7 December, 2018 4:13 PM
To: 'Catherine Chong (LKK Auto)'
Cc: 'Chee Kiong'; samson@seahong.com.sg; amanda@seahong.com.sg; sharon@seahong.com.sg
Subject: RI ON 12.12.18 AT 11AM / SKP 9164L [Our file ref: 18.24576 PD-O]
Importance: High

Dear Catherine,

CLAIMANT : LEE ENG HUAT
VEHICLE NUMBER : SKP 9164L
ALLEGED ACCIDENT DATE : 05 MAY 2018
AXA VEHICLE NUMBER : SJH 9594H

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. Copies of the relevant documents can be downloaded via <https://1drv.ms/b/s!AtyQ5g-oo66hiZo8xtaRIkaycDImwQ>.

As spoken between our goodselves this afternoon, we confirm your surveyor will attend the RI as follows:-

Date/Time : Wednesday, 12.12.18, 11.00am
Place : 4 Sea Breeze Walk Singapore 487392
Attention : Mr Lee
Contact No. : 9652 8596 (call upon arrival)

Kindly let us have your survey report and invoice, for our further action. Thanks!

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)
Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Tel: 6536 5369
Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message,

please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

LAWRENCE LEE & CO

Advocates & Solicitors

李伟平律师楼

UEN: 53159236K

133 New Bridge Road #13-05
Chinatown Point Singapore 059413
tel: 6533 3680 fax: 6533 3689
email: info@lawrencelee.com.sg

3 0 1 9 4 3 1 0 4 6 - - -

Your ref: (please advise)
Our ref: LWP/LEH/3997A/18/sm(ec)

This is a letter of claim issued pursuant to
the Non-Injury Motor Accident Practice
Direction of the State Courts

6 JUL 2018

Mr Ho Willy
520C Tampines Central 8
#14-61
Singapore 523520

CERTIFICATE OF POSTING

61160866

Dear Sir

**ACCIDENT ALONG PIE TWDS CHANGI ON 05.05.18
INVOLVING GX3673D, SHC7618L, SKP9164L & SJH9594H**



We act for Mr Lee Eng Huat, owner of the above vehicle SKP9164L.

We are instructed to claim against you in connection with the above accident involving our client's vehicle and vehicle SJH9594H owned by you and driven by your servant/agent one Soh Sze Ron at the material time.

We are instructed that the accident was caused by your servant/agent's negligent driving, management and/or control of your vehicle; for whose actions you are vicariously liable.

As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

Particulars

- | | | | |
|----|---|--------------|------------------------|
| 1. | Cost of repairs | \$ 45,068.83 | (\$42,120.40 plus GST) |
| 2. | Rental of alternative vehicle | \$ 1,900.00 | |
| | (19 days x \$100pd from 19.05.18 to 06.06.18) | | |

Disbursements

- | | | |
|----|---------------|-----------|
| 3. | LTA fee | \$ 14.98 |
| 4. | GIA fees | \$ 57.00 |
| 5. | TP fee | \$ 15.00 |
| 6. | Legal costs | \$ 900.00 |
| 7. | Miscellaneous | \$ 50.00 |



A copy of each of the following documents is enclosed with the copy of this letter to your insurer:

1. LTA search with receipt;
2. Our client's LTA online enquiry;
3. Our client's GIA report with receipts;
4. Our client's TP report with receipt;
5. TP letter dated 21.05.18;
6. Copy of Estimate Bill. EB00004820 from Hock Wah Motor Workshop Pte Ltd; and
7. Copy of Rental Agreement and Invoice CINV - 200033 from H W Car Rental.

Please note that:

- a. If you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer.
- b. You or your insurer should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.
- c. If you have any witnesses or photographs of the accident scene, please send to us the witnesses' names/addresses/contact nos. or the photographs within 14 days of your receipt of this letter.
- d. If you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

In the event that your vehicle had been driven by someone not in the capacity as your servant/agent, please inform us in writing within 14 days otherwise we will name you as a defendant in the Writ that may be issued and you may be liable for legal costs.

Yours faithfully



LEE WEE PENG LAWRENCE
Secretary: Ms Lim Suk Mei
Email: sukmei@lawrencelee.com.sg



Cc AXA Insurance Pte Ltd
(Insurer of SJH9594H)

BY PDX WITH ENCS

Cc Clients

^ **Enquire Vehicle & Owner Information (Vehicle No. SJH9594H As At 05 May 2018 / 22:45:00)**

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LWP/LEH/3997A/18/SM

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7939377J

Owner Name: HO WILLY

Registered Address Type: HDB / HUDC

Registered Block/House No.: 520C

Registered Street Name: TAMPINES CENTRAL 8

Registered Unit No.: # 14 - 61

Registered Building Name: -

Registered Postal Code: 523520

Current Vehicle Details

Vehicle No.: SJH9594H

Make Description/Model: SUBARU / IMPREZA 5D 2.0 R-S AWD AT ABS

Insurance Company Name: AXA INSURANCE PTE LTD



Thank you

Lee Wee Peng Lawrence has successfully logged out.

Your last login date and time was 19 Jun 2018, 17:17:51.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	GX3673D	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	19 Jun 2018 / 17:20:18
2	Vehicle	SJH9594H	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	19 Jun 2018 / 17:19:09