

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

Term:

Not Authorized
2 b/c
h/s
Take into other rep.
10/5/18
20 day.

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID <i>bad</i>	1.0	957.40	20	765.92
2	BOOTLID HINGE LH <i>bad</i>	1.0	145.40	20	116.32
3	BOOTLID HINGE RH <i>bad</i>	1.0	145.40	20	116.32
4	BOOTLID LOCK <i>tw</i>	1.0	177.30	20	141.84
5	BOOTLID CABLE <i>11</i>	1.0	55.10	20	44.08
6	BOOTLID RUBBER <i>tw</i>	1.0	129.30	20	103.44
7	BOOTLID EMBLEM <i>new</i>	1.0	74.40	20	59.52
8	BOOTLID LOGO - MAZDA 3 <i>new</i>	1.0	53.40	20	42.72
9	BOOTLID - SKYACTIV <i>new</i>	1.0	63.60	20	50.88
10	BOOTLID LAMP RH	1.0	265.00	20	212.00
11	BOOTLID LAMP LH	1.0	265.00	20	212.00
12	BOOTLID SWITCH <i>11</i>	1.0	164.00	20	131.20
13	TAIL LAMP RH <i>one</i>	1.0	509.40	20	407.52
14	TAIL LAMP LH	1.0	509.40	20	407.52
15	TAIL LAMP PANEL RH	1.0	377.80	20	302.24
16	TAIL LAMP PANEL LH	1.0	377.80	20	302.24
17	TAIL LAMP CLIP <i>11</i>	8.0	5.00	20	32.00
18	REAR FENDER RH <i>301510/3uc</i>	1.0	1,175.30	20	940.24
19	REAR FENDER LH <i>2</i>	1.0	1,175.30	20	940.24
20	REAR FENDER INNER PANEL GARNISH RH	1.0	235.60	20	188.48
21	REAR FENDER INNER PANEL GARNISH LH	1.0	235.60	20	188.48
22	REAR WINDSCREEN MOULDING <i>new</i>	1.0	73.30	20	58.64
23	END PANEL <i>bad</i>	1.0	505.10	20	404.08
24	END PANEL TOP GARNISH	1.0	85.10	20	68.08
25	SPARE TYRE PANEL <i>2</i>	1.0	524.70	20	419.76
26	SPARE TYRE PANEL TRIMBOARD	1.0	350.10	20	280.08
27	SPARE TYRE PANEL BRACKET <i>11</i>	1.0	70.40	20	56.32
28	SPARE TYRE PANEL SCREW	1.0	138.00	20	110.40
29	REAR BUMPER <i>dis</i>	1.0	925.10	20	740.08
30	REAR BUMPER REFLECTOR RH <i>gnc</i>	1.0	50.40	20	40.32
31	REAR BUMPER REFLECTOR LH <i>11</i>	1.0	50.40	20	40.32
32	REAR BUMPER RETAINER RH <i>bad</i>	1.0	36.10	20	28.88
33	REAR BUMPER RETAINER LH <i>bad</i>	1.0	36.10	20	28.88
34	REAR BUMPER BRACKET RH	1.0	72.20	20	57.76

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL: FAX:
PH: 96528596
ATTN:

ESTIMATE BILL

Number: EB00004820
Date: 08/05/2018
Case No: AD00009719
Vehicle No: SKP9164L
Chassis: JM6BM42A8F0150535
Year of Mfr: 2014
Policy No: 5074725906-02
Model: MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	REAR BUMPER BRACKET LH	1.0	72.20	20	57.76
36	REAR BUMPER TOWING COVER LH <i>To.1</i>	1.0	16.20	20	12.96
37	REAR BUMPER TOWING COVER RH <i>To.1</i>	1.0	16.20	20	12.96
38	SPARE TYRE LOWER BRACKET PANEL CENTER <i>NS</i>	1.0		20	
39	EXHAUST BOX <i>Self/1m1</i>	1.0	1,075.80	20	860.64
40	EXHAUST CENTER PIPE	1.0	1,433.40	20	1,146.72
41	EXHAUST MOUNTING <i>To.1</i>	4.0	33.30	20	106.56
42	EXHAUST SHIELD <i>Self</i>	1.0	270.40	20	216.32
43	SPARE TYRE SPONGE LH	1.0		20	
44	SPARE TYRE SPONGE RH	1.0		20	
45	REAR AXLE	1.0	828.20	20	662.56
46	REAR LOWER ARM LH <i>NS</i>	1.0	250.20	20	200.16
47	REAR LOWER ARM RH <i>NS</i>	1.0	250.20	20	200.16
48	REAR SHOCK ABSORBER RH	1.0	344.70	20	275.76
49	REAR SHOCK ABSORBER LH	1.0	344.70	20	275.76
50	REAR WHEEL BEARING LH	1.0	414.40	20	331.52
51	REAR WHEEL BEARING RH	1.0	414.40	20	331.52
52	BONNET <i>Self</i>	1.0	1,067.30	20	853.84
53	BONNET HINGE RH <i>Self</i>	1.0	41.10	20	32.88
54	BONNET HINGE LH <i>Self</i>	1.0	41.10	20	32.88
55	BONNET GRILLE <i>one</i>	1.0	335.00	20	268.00
56	BONNET RUBBER <i>Self</i>	2.0	63.60	20	101.76
57	BONNET LOCK <i>1m1</i>	1.0	197.10	20	157.68
58	SUPPORT PANEL <i>one</i>	1.0	469.70	20	375.76
59	SUPPORT PANEL AIR DUCT LH <i>7m1</i>	1.0	35.60	20	28.48
60	SUPPORT PANEL TOP GARNISH <i>one</i>	1.0	33.40	20	26.72
61	SUPPORT PANEL TOP PANEL <i>NS</i>	1.0	140.00	20	112.00
62	SUPPORT PANEL CENTER GARNISH <i>Dis</i>	1.0	469.70	20	375.76
63	SUPPORT PANEL AIR DUCT RH	1.0	35.60	20	28.48
64	SUPPORT GRILLE LOWER INNER GARNISH	1.0	92.70	20	74.16
65	BRACE PANEL	1.0	38.80	20	31.04
66	AIR CON CONDENSER	1.0	1,063.00	20	850.40
67	RADIATOR	1.0	1,064.90	20	851.92
68	RADIATOR COWLING, FAN & MOTOR	1.0	1,356.80	20	1,085.44

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr 2014
Policy No 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
69	RADIATOR BOTTOM HOSE	1.0	65.60	20	52.48
70	RADIATOR TOP HOSE	1.0	65.60	20	52.48
71	RADIATOR SPARE TANK	1.0	65.80	20	52.64
72	HEADLAMP ASSEMBLY LH <i>one</i>	1.0	773.30	20	618.64
73	HEADLAMP ASSEMBLY RH <i>one</i>	1.0	773.30	20	618.64
74	HEADLAMP BRACKET RH	1.0	15.10	20	12.08
75	HEADLAMP BRACKET LH	1.0	15.10	20	12.08
76	HEADLAMP CLIP <i>17</i>	4.0	8.00	20	25.60
77	FRONT GRILLE INNER GARNISH <i>one</i>	1.0	119.60	20	95.68
78	FRONT GRILLE CHROME RH <i>one</i>	1.0	176.70	20	141.36
79	FRONT GRILLE CHROME LH <i>one</i>	1.0	176.70	20	141.36
80	FRONT GRILLE EMBLEM <i>one</i>	1.0	44.20	20	35.36
81	FRONT BUMPER CENTER BRACKET <i>2.5</i>	2.0	15.10	20	24.16
82	FRONT BUMPER NUMBER GARNISH <i>one</i>	1.0	51.70	20	41.36
83	FRONT BUMPER CENTER GARNISH	1.0	335.80	20	268.64
84	FRONT BUMPER LOWER INNER GARNISH	1.0	102.40	20	81.92
85	FRONT BUMPER RETAINER RH <i>one</i>	1.0	18.70	20	14.96
86	FRONT BUMPER RETAINER LH <i>one</i>	1.0	18.70	20	14.96
87	FRONT BUMPER REINFORCEMENT <i>one</i>	1.0	565.10	20	452.08
88	FRONT BUMPER INNER CENTER BRACKET RH	1.0	35.60	20	28.48
89	FRONT BUMPER INNER CENTER BRACKET LH	1.0	35.60	20	28.48
90	FRONT GRILLE INNER BRACKET LH	1.0	15.10	20	12.08
91	FRONT BUMPER INNER BRACKET RH	1.0	15.10	20	12.08
92	FRONT BUMPER <i>one</i>	1.0	925.10	20	740.08
93	FRONT BUMPER LOWER GRILLE	1.0		20	
94	FRONT BUMPER LOWER GARNISH	1.0	83.70	20	66.96
95	FRONT BUMPER FOG LAMP LH	1.0	50.40	20	40.32
96	FRONT BUMPER FOG LAMP RH	1.0	50.40	20	40.32
97	FRONT BUMPER FOG LAMP COVER LH	1.0	42.50	20	34.00
98	FRONT BUMPER FOG LAMP COVER RH	1.0	42.50	20	34.00
99	FRONT BUMPER TRIANGLE COVER LH	1.0	28.00	20	22.40
100	FRONT BUMPER TRIANGLE COVER RH	1.0	28.00	20	22.40
101	ENGINE LOWER DUST COVER	1.0	95.70	20	76.56
102	FRONT FENDER RH <i>one</i>	1.0	333.90	20	267.12

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis : JM6BM42A8F0150535
Year of Mfr : 2014
Policy No : 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
103	FRONT FENDER LH <i>Ref/Buc</i>	1.0	333.90	20	267.12
104	FRONT FENDER INNER SHIELD LH <i>11</i>	1.0	129.30	20	103.44
105	FRONT FENDER INNER SHIELD RH <i>FORN</i>	1.0	129.30	20	103.44
106	FRONT BUMPER TOWING COVER <i>FORN</i>	1.0	28.60	20	22.88
107	FRONT BUMPER INNER CENTER BRACKET LH	1.0	15.10	20	12.08
108	FRONT BUMPER INNER CENTER BRACKET RH	1.0	15.10	20	12.08
109	STEERING AIR BAG <i>Ref/Buc</i>	1.0	1,082.50	20	866.00
110	STEERING CLOCK SENSOR <i>Ref/Buc</i>	1.0	192.90	20	154.32
111	DASHBOARD AIRBAG <i>Ref/Buc</i>	1.0	1,169.60	20	935.68
112	DASHBOARD <i>To 11</i>	1.0	1,429.10	20	1,143.28
113	FRONT SEAT BELT RH <i>Ref/Buc</i>	1.0	1,022.10	20	817.68
114	FRONT SEAT BELT LH <i>Ref/Buc</i>	1.0	1,022.10	20	817.68
115	FRONT SEAT BELT BUCKLE RH <i>11</i>	1.0	94.80	20	75.84
116	FRONT SEAT BELT BUCKLE LH <i>11</i>	1.0	94.80	20	75.84
117	FRONT SEAT BELT INNER GARNISH RH <i>11</i>	1.0		20	
118	FRONT SEAT BELT INNER GARNISH LH <i>11</i>	1.0		20	
119	AIR BAG ECU <i>Ref/Buc</i>	1.0	1,444.40	20	1,155.52
120	AIR BAG IMPACT SENSOR <i>Ref/Buc</i>	1.0	145.90	20	116.72
121	CONTROL ECU (BELOW HEADLAMP LH) <i>11</i>	1.0	2,867.10	20	2,293.68
List Price - Parts Sub Total					31,172.40
122	CERAMIC COATING	1.0	700.00	0	700.00
123	WINDSCREEN SEALANT <i>Ref</i>	2.0	24.00	0	48.00
124	SPARE TYRE SEAL <i>11</i>	1.0	80.00	0	80.00
125	REVERSE SENSOR <i>Ref/Buc</i>	1.0	280.00	0	280.00
126	REAR NUMBER PLATE <i>Ref/Buc</i>	1.0	30.00	0	30.00
127	REAR NUMBER PLATE HOLDER <i>Ref/Buc</i>	1.0	30.00	0	30.00
128	FRONT NUMBER PLATE <i>Ref/Buc</i>	1.0	30.00	0	30.00
129	REAR CHASSIS LH - REPAIR <i>Ref/Buc</i>	1.0			
130	REAR CHASSIS RH - REPAIR <i>Ref/Buc</i>	1.0			
131	FRONT DOOR LH - REPAIR <i>Ref/Buc</i>	1.0			
132	FRONT DOOR RH - REPAIR <i>Ref/Buc</i>	1.0			
133	REAR DOOR RH - REPAIR <i>Ref/Buc</i>	1.0			
134	REAR DOOR LH - REPAIR <i>Ref/Buc</i>	1.0			

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S1130299H
LEE ENG HUAT
NO 4 SEA BREEZE WALK

SINGAPORE 487392
TEL : FAX :
PH : 96528596
ATTN :

ESTIMATE BILL

Number : EB00004820
Date : 08/05/2018
Case No : AD00009719
Vehicle No : SKP9164L
Chassis: JM6BM42A8F0150535
Year of Mfr 2014
Policy No 5074725906-02
Model : MAZDA 3

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
Special Nett Price - Parts Sub Total					1,198.00
Parts Total					32,370.40
135	LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR)	1.0	2,500.00	0	2,500.00
136	SPRAY PAINT ON THE AFFECTED AREAS (REAR)	1.0	1,800.00	0	1,800.00
137	ANTI-RUST COATING (REAR)	1.0	300.00	0	300.00
138	WIRING (REAR)	1.0	80.00	0	80.00
139	TO REMOVE & REFIT WINDSCREEN (REAR)	1.0	180.00	0	180.00
140	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	350.00	0	350.00
141	TO REMOVE & REFIT FUEL TANK	1.0	350.00	0	350.00
142	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
143	TO REMOVE & REFIT UNDERCARRIAGE (REAR)	1.0	500.00	0	500.00
144	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
Labour 1 Sub Total					6,390.00
145	LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT)	1.0	1,200.00	0	1,200.00
146	SPRAY PAINT ON THE AFFECTED AREAS (FRONT)	1.0	1,200.00	0	1,200.00
147	ANTI-RUST COATING (FRONT)	1.0	250.00	0	250.00
148	WIRING (FRONT)	1.0	80.00	0	80.00
149	TO SERVICE & TOP-UP AIR-CON GAS	1.0	180.00	0	180.00
150	TO REMOVE & REFIT DASHBOARD	1.0	450.00	0	450.00
Labour 2 Sub Total					3,360.00
SINGAPORE DOLLARS : FORTY-FIVE THOUSAND SIXTY-EIGHT AND CENTS EIGHTY-THREE ONLY			Less Excess		0.00
			SUBTOTAL		42,120.40
			GST 7.00%		2,948.43
			TOTAL		45,068.83

Date of accident : 05/05/2018 10:45 PM. Place : PIE AFTER LORNIE ROAD > CHANGI

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE