

ASS. REC. BY:

REF:

C/EG118008511/U9b n2

Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

From (Person):

Pei Li

of

EG1

Date/Time:

9/5/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDA1766P

Insured:

SGY1841T

at Workshop m/s

Tan Chong Motor

Tel:

67638914

of

913 Bukit Timah Rd

Policy No:

Claim No:

DSMPC18D0865

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/4/2018

(Client's Record)

14/5/2018 After 10am

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9/5

Person Contacted:

Lawrence

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SDA1766P-X

SGY1841T-X

15/5/18 @ 4.31pm revised to Rohani by email.

(08/11/13) wef

REF:

ER1

ASS. REC. BY: MORIS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDA1766Pat Workshop m/s Tan Choy

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: 131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

8511F

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDA1766PYr Regn: 8 / 15Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Nissan QashqaiC.C. 1197Colour: Grey

A/C: Insured / Std / Nil / NA

Sp. Reading: 71324

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: SJNFEAJ1141425345

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 28/4/18D.O.I. 14/5/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 5100720/8/18 @ 1993.96, confirmed with Norsipah by email.
Used \$3420.40, 637%

Date/Time, File Pass to?

☐

: Preli. Report

120/8/18/18☐

: Final Report

Date/Time, File Return to?

2)

Report Format: TPLump Sum / I.B.I.: (\$ 1993.96)Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1800865

Date: 15th May 2018

Our Ref: CS/EGI8008511/Uqb

The Motor Claims Department
ERGO Insurance

Attn: Pei Li

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SDA 1766P

We thank you for the instruction on 09/05/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/05/2018 at the premises of M/s TAN CHONG MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,414.40</u>
Revised Estimate Amount	: S\$ <u>1,973.96</u>
"Check" Items Amount	: S\$ <u>898.08</u>
Lump Sum Repair Estimate Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages consistent.
Days of repair: 3 days.
We have NOT authorize repair.

Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 9 May, 2018 4:20 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SGY1841T / TP : SDA1766P/LKK / DOA : 28/04/2018 (DSMPC1800865)
Attachments: SGY1841T - SAS.pdf; SDA1766P - SAS.pdf; SDA1766P - PRS FORM.pdf; Re: (DSMPC1800865) ACCIDENT INVOLVING SDA1766P & SGY1841T ON 28.04.2018 ... (15.3 KB)

Dear Ashley,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TAN CHONG MOTOR SALES PTE LTD**,

ADDRESS : 913 BUKIT TIMAH ROAD
SINGAPORE 589622

PERSON TO CONTACT : LAWRENCE TEO @ 6703 8914 / 6466 7711

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

14/5/18

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 09.05.2018
Our Reference: DSMPC1800865/RH/pl
Your Reference: SDA 1766P

To: TAN CHONG MOTOR SALES PTE LTD

Sent via Fax

or

Email

lawrenceteo@tanchong.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SDA 1766P
Insured's Vehicle: SGY 1841T
Date Of Accident: 28.04.2018


We acknowledge receipt of your request for PRS on: 08.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - ROHAINI

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 20 August 2018 1:42 PM
To: Norsipah; SUR
Subject: RE: COR Final SDA1766P DOA 28.04.2018

Dear Sipah,

WITHOUT PREJUDICE

Confirm final fig \$1,993.96 before GST and 3 repair days.

Kindly send the relevant documents to ERGO Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah <norsipah@tanchong.com>
Sent: Monday, 20 August 2018 9:08 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: COR Final SDA1766P DOA 28.04.2018

Hi Shiau,

As per attached.

Best Regards,
Sipah

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: 20 August 2018 08:54
To: Norsipah <norsipah@tanchong.com>; SUR <sur@lkkauto.com>
Subject: RE: COR Final SDA1766P DOA 28.04.2018

Dear Sipah,

Kindly provide us the before paint photos of above vehicle.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah <norsipah@tanchong.com>
Sent: Friday, 17 August 2018 10:48 AM
To: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: COR Final SDA1766P DOA 28.04.2018

Hi

Please refer attach for finalization.

Thank you.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: norsipah@tanchong.com D:+6567038915

Website: www.tanchong.com :: www.nissan.com.sg

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 15 May 2018 4:31 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; Rohaini Bte Hussain
Cc: SUR
Subject: RE: OI : SGY1841T / TP : SDA1766P/LKK / DOA : 28/04/2018 (DSMPC1800865)
Attachments: CSEGI18008511Uqb.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of SDA 1766P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Wednesday, 9 May 2018 4:20 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: OI : SGY1841T / TP : SDA1766P/LKK / DOA : 28/04/2018 (DSMPC1800865)

Dear Ashley,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TAN CHONG MOTOR SALES PTE LTD.**

ADDRESS : 913 BUKIT TIMAH ROAD
SINGAPORE 589622

PERSON TO CONTACT : LAWRENCE TEO @ 6703 8914 / 6466 7711

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8511F
Vehicle Details	
Vehicle No.:	SDA1766P
Vehicle to be Exported:	No
Intended De-registration Date:	15 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	HRA2152285A
Chassis No.:	SJNFEAJ11U1425345
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$19,084.00
Original Registration Date:	11 Aug 2015
First Registration Date:	11 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$14,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2025
PARF Rebate Amount:	\$10,563.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,889.00
COE Rebate Amount:	\$40,444.00
Total Rebate Amount:	\$51,007.00

The information contained herein is correct as at 15 May 2018

OK



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

ULTIMATE CAR PROTECTOR-PREMIER Comprehensive

Certificate No. S 28794247 SMF

Excess : SGD500

1. Index Mark and Registration Number of Vehicle
SDA1766P
2. Name of Policyholder
Chng King Cher
3. Effective Date of the Commencement of Insurance for the purposes of the Act
11/08/2016
4. Date of Expiry of Insurance
10/08/2017
5. Persons or Classes of Persons entitled to drive*
Chng King Cher
Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.
* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*
Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1228511F



Name
CHNG KING CHER

莊錦書

Race
CHINESE

Date of Birth
27-12-1957

Sex
M

Country of Birth
SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Number S1228511F

CHNG KING CHER

Date of Birth 27 Dec 1957

Issue Date 14 Jan 2003




000104559D

1598993



NRIC No: S1228511F



Blood Group B+ Date of issue 17-01-1994

APT BLK 56 CHOA CHU KANG NORTH 6 #16-33
SINGAPORE 689577

NRIC No: S1228511F Date: 09-08-2006 No: 5477683


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE 30 May 1980

NP 428A

Licence No: S1228511F



TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0162/2018
DATE : 07-MAY-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832 FAX : 64697472

OWNER'S NAME : MR CHNG KING CHER
ADDRESS : 56 CHOA CHU KANG NORTH 6
#16-33
S(689577)
TELEPHONE NO : 67607989/91257751

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SGV1841T
VEHICLE NO : SDA1766P
MODEL CODE : FRLARBEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2152285A
CHASSIS NO : SJNFEAJ11U1425345
MILEAGE : 1 KM
DATE IN : 07/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 28/04/2018

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

not authorized

LKK

marcus

Tel: 62563561

Fax 62564315

3 day

14/5/18

Take photo before painting

*LKK
C. Teo*

*an
14/05/18
(m)
9-12*

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDA1766P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	11 360.00	X
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 02	11 200.00	X
4	22/001	REPAIR TAILGATE, END PANEL AND RENEW REAR BUMPER	1400.00	585
5	22/002	S/PAINT REAR BUMPER (2 TONE), END PANEL, TAILGATE	1400.00	350
TOTAL LABOUR CHARGES			3470.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/S/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO EDA1766P

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140		shut	210.00 ✓
2	SUNDRIES	NPN		re	100.00 20
3	EMBLEM	90892-4EA0A	X 17 87.00	X	
4	EMBLEM-REAR	90890-4EA0A	X 17 59.70	X	
5	GROMMET BUMPER \$2.20 EA X 02	01281-00111		re	4.40 ✓
6	RETAINER-BUMPER LH	79185-4EA0A	re 23.80		
7	RETAINER-BUMPER RH	79184-4EA0A	re 23.80		
8	BRACKET-BUMPER RH	85220-4EA0A	re 35.90		
9	BRACKET-BUMPER LH	85221-4EA0A	re 35.90		
10	STAY ASSY-REAR RH	H5210-4EAMA	17 126.00	2	
11	STAY ASSY-REAR LH	H5211-4EAMA	17 126.00	2	
12	REINF-BUMPER RR	H5030-4EAMA	17 619.20	2	
13	ENERGY ABSORBER	85090-4EA0B	17 126.40	2x	
14	CLIP BUMPER \$7.40 EA X 03	85284-JD00A	re 22.20		
15	CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	re 13.00		
16	CLIP BUMPER \$1.20 EA X 04	01553-05933	re 4.80		
17	FINISHER-REAR BUMPER TOW	85071-4EA0A	re 16.80		
18	FASCIA-RR BUMPER	85022-4EA0H	717.00	717.00	
SUB TOTAL			2037.50	0.00	314.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			407.50	0.00	0.00
GRAND TOTAL			1630.00	0.00	314.40
OVERALL TOTAL			1944.40		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDA1766P

TOTAL LABOUR CHARGES	3470.00
TOTAL SPARE PARTS CHARGES	1944.40
GRAND TOTAL	5414.40 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0162/2018
DATE : 07-MAY-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : MR CHNG KING CHER
ADDRESS : 56 CHOJA CHU KANG NORTH 6
#16-33
S(689577)
TELEPHONE NO : 67607989/91257751

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SGY1841T
VEHICLE NO : SDA1766P
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2152205A
CHASSIS NO : SJNFEAJ11U1425345
MILEAGE : 71324 KM
DATE IN : 07/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 28/04/2018

msrcs *Lee*

DIS

low

#50x03

= #150/-

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDA1766P

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	.00
2 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 02	200.00	.00
4 ZZ/001	REPAIR TAILGATE, END PANEL AND RENEW REAR BUMPER	1400.00	585.00
5 ZZ/002	S/PAINT REAR BUMPER (2 TONE), END PANEL, TAILGATE	1400.00	350.00
	TOTAL LABOUR CHARGES	3470.00	1045.00

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDA1766P

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00	OK
2	HUNDRIES	NPN			20.00	OK
3	EMBLEM	90892-4EA0A	87.00			X
4	EMBLEM-REAR	90890-4EA0A	59.70			X
5	GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40	OK
6	RETAINER-BUMPER LH	79185-4EA0A	23.80			OK
7	RETAINER-BUMPER RH	79184-4EA0A	23.80			OK
8	BRACKET-BUMPER RH	85220-4EA0A	35.90			OK
9	BRACKET-BUMPER LH	85221-4EA0A	35.90			OK
10	STAY ASSY-REAR RH	H5210-4EAMA	126.00			X
11	STAY ASSY-REAR LH	H5211-4EAMA	126.00			X
12	REINF-BUMPER RR	H5030-4EAMA	619.20			X
13	ENERGY ABSORBER	85090-4EA0B	126.40			X
14	CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20			OK
15	CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00			OK
16	CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80			OK
17	FINISHER-REAR BUMPER TOW	85071-4EA0A	16.80			OK
18	PASCIA-RR BUMPER	85022-4EA0H	717.00			OK
SUB TOTAL			893.20	0.00	234.40	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			178.64	0.00	0.00	
GRAND TOTAL			714.56	0.00	234.40	
OVERALL TOTAL			948.96			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SDA1766P

NETT ITEM	893.20
LESS 20.00%)	-178.64
NETT AMOUNT	714.56
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	234.40
LESS .00%)	0.00
SPECIAL NETT AMOUNT	234.40
TOTAL LABOUR CHARGES	1045.00
TOTAL SPARE PARTS CHARGES	948.96
TOTAL CHARGES	1993.96
ADD 7 % GST	139.58
GRAND TOTAL	2133.54




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18008511/Uqbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 21-08-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGY 1841T	Veh. Inspected	SDA 1766P	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1800865	Excess (\$)	0.00	
Assign From	PEI LI	Assign Date	09/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1425345	Colour	GREY	
Odometer	71324	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	MICHELIN	7 mm	
L/H Front Tyre	215/60 R17	MICHELIN	7 mm	
R/H Rear Tyre	215/60 R17	MICHELIN	7 mm	
L/H Rear Tyre	215/60 R17	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/04/2018	Inspection Date	14/05/2018	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDA 1766P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	EMBLEM (N)	NOT NECESSARY	87.00	-
1	EMBLEM-REAR (N)	NOT NECESSARY	59.70	-
1	RETAINER-BUMPER LH (N)	NECESSARY	23.80	23.80
1	RETAINER-BUMPER RH (N)	NECESSARY	23.80	23.80
1	BRACKET-BUMPER RH (N)	NECESSARY	35.90	35.90
1	BRACKET-BUMPER LH (N)	NECESSARY	35.90	35.90
1	STAY ASSY-REAR RH (N)	NOT NECESSARY	126.00	-
1	STAY ASSY-REAR LH (N)	NOT NECESSARY	126.00	-
1	REINF-BUMPER RR (N)	NOT NECESSARY	619.20	-
1	ENERGY ABSORBER (N)	NOT NECESSARY	126.40	-
3	CLIP BUMPER @\$7.40 (N)	NECESSARY	22.20	22.20
2	CANOE RIVET BUMPER @\$6.50 (N)	NECESSARY	13.00	13.00
4	CLIP BUMPER @\$1.20 (N)	NECESSARY	4.80	4.80
1	FINISHER-REAR BUMPER TOW (N)	DEFORMED	16.80	16.80
1	FASCIA-RR BUMPER (N)	TORN	717.00	717.00
	LESS 20% DISCOUNT		-407.50	-178.64
			1,630.00	714.56
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (J11 & T32)(SN)	SHORTED	210.00	210.00
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
2	GROMMET BUMPER @\$2.20 (SN)	NECESSARY	4.40	4.40
			314.40	234.40
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	NOT NECESSARY	360.00	-
	SUPPLY & INSTALL REVERSE SENSOR		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	NOT NECESSARY	200.00	-
	REPAIR TAILGATE,END PANEL AND RENEW REAR BUMPER		1,400.00	585.00

Report Ref No. CS/EGI18008511/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	S/PAINT REAR BUMPER (2 TONE),END PANEL, TAILGATE.		1,400.00	350.00
			3,470.00	1,045.00
GRAND TOTAL			5,414.40	1,993.96
RECOMMENDED COST OF REPAIRS				1,993.96

Report Ref No. CS/EG18008511/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.