

ASS. REC. BY: Surveyor REF: CG118DOES13/Uvbn2 Special Instruction:

ASSIGNMENT (Office)

From (Person): Pei Li of EG1 Date/Time: 9/5/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XDS128C Insured: XE425Y

at Workshop m/s Li's Brother Tel: 67411730 Susan

of Nol Kaki Bukit #01-01

Policy No: Claim No: XE425Y / SE/p1

Sum Insured: Excess:

Make of Veh: D.O.A. 7/5/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: Person Contacted: Susan Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	<u>XDS128C-X</u>
	<u>XE425Y-X</u>
<u>11/5/18</u>	<u>Informal Pei Li pending workshop est by email</u>
<u>17/5/18</u>	<u>Email preli revised to Pei Li</u>

(08/11/13) waf
ASS. REG. BY: Marcus

REF:

ER1/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: XDS-128c
at Workshop m/s lurs
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £42k
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % S Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XDS-128c Yr Regn: 11 / 11
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (m)
Make: HINO SHIEERA c.c. 12913
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 220184 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SHIEER10035
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Insider / Jammed / Leaked / Burnt or
Brake: Insider / Jammed / Leaked / Burnt or
Modi: MT / S/Rim / STD A/Rim or
Tyre Size: F: 295/60R22.5
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Triangle

Front 6 mm Rear 6/6 mm
R/Bal. 6 mm R/Bal. 6/6 mm
L/Bal. 6 mm L/Bal. 6/6 mm
D.O.A. 7/5/18 D.O.I. 7/5/18

Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S H.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction MTA 11922

17/5/18 continued 2/5 & 9500 with Susan. (Red 11,460-440, 5510)

RECEIVED 17 MAY 2018

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 17/5 - typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
Photos _____
Others _____

Report Format: TP
Lump Sum / I.B.I. (\$) 9500/2

TOTAL

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XE425Y/SE/pl
Our Ref: CS/EGH18008513/Uvb

Date: 17/5/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. XD 5128C


We thank you for your instruction on 9/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 9/5/2018 at the premises of M/s LIU'S BROTHER AUTO ENGINEERING WORKSHOP and have the following to report:-

Workshop Estimate Amount	: S\$20,962.40
Revised Estimate Amount	: S\$9,500.00 LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 17 May 2018 10:35 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; SUR
Subject: RE: XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018
Attachments: XD 5128C PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle XD 5128C
Date of survey: 9/5/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 11 May 2018 9:29 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle XD 5128C on 9/5/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 9 May 2018 12:37 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Wednesday, 9 May, 2018 12:07 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Subject: OI : XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6
#01-01 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUSAN @ 6741 1730

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you,

Yee Pei Li

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Tel.: 65 6829 9199 DID: 65 6829 9194

Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 11 May 2018 9:29 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; SUR
Subject: RE: XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle XD 5128C on 9/5/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 9 May 2018 12:37 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 9 May, 2018 12:07 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6

#01-01 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUSAN @ 6741 1730

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 9 May, 2018 12:07 PM
To: 'admin-d@lkkauto.com'
Subject: OI : XE425Y / TP : XD5128C/LKK / DOA : 07/05/2018
Attachments: XE425Y - SAS.pdf; XD5128C - SAS.pdf; XD5128C - PRS FORM.pdf; Re: Request for 3rd party survey XD5128C Claims against XE425Y (20.0 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6
#01-01 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUSAN @ 6741 1730

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ln

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 09.05.2018
Our Reference: XE 425Y/SE/pl
Your Reference: XD 5128C

To: LIU'S BROTHER AUTO

Sent via Fax

or

Email

liusbro@ymail.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: XD 5128C
Insured's Vehicle: XE 425Y
Date Of Accident: 07.05.2018


We acknowledge receipt of your request for PRS on: 08.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

ERGO

Date: 09.05.2018
Our Reference: XE 425Y/SE/pl
Your Reference: XD 5128C

To: LIU'S BROTHER AUTO

Sent via Fax
or
Email liusbro@ymail.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: XD 5128C
Insured's Vehicle: XE 425Y
Date Of Accident: 07.05.2018


We acknowledge receipt of your request for PRS on: 08.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:	<u>Pei Li</u>	6829 9194	claims@ergo.com.sg
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:


Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out](#)

HINO

Price Range ▾

Depreciation ▾

Year Reg ▾

Vehicle Type ▾

[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Hino SH1EEKA \(COE till 03/2023\)](#)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.

Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale?

[Click here to see all Auspicious Numbers!](#)

Hino SH1EEKA (COE till 03/2023)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)

Car Details

Price	\$57,000	
Depreciation	\$11,660 /yr	?
Reg Date	31-Mar-2008 (4yrs 10mths 20days COE left)	
Lifespan	30-Mar-2028	
Manufactured	2008	?
Mileage	220,000 km (21.7k /yr)	
Transmission	Manual	
Engine Cap	12,913 cc	?
Curb Weight	6,780 kg	
Fuel type	Diesel	
Features	-	
Accessories	Radio CD.	
Description	Well Maintain, Newly Spray Paint. 1 Owner Only. View To Appreciate.	
COE	\$20,115	?
OMV	\$70,748	?
ARF	\$3,538	?
Dereg Value	\$19,674 as of today (change)	?
No. of Owners	2	?
Type of Veh	Truck	
Category	COE Car, Direct Owner Sale	
Availability	Available	

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
DIRECT OWNER


100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Seller Infor

[Contact Person](#)
[Contact No.](#)
[Enquiry](#)
[USEFUL FOR](#)
[» Indemnity](#)
[» Receipt](#)
[» M01](#)

Instruction
consumer de

Regardless of
your paperw

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1196N

Vehicle Details

Vehicle No.:	XDS128C
Vehicle to be Exported:	No
Intended De-registration Date:	08 May 2018
Vehicle Make:	HINO
Vehicle Model:	SH1EERA 13L MANUAL ABS TURBO
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	E13CUN16046
Chassis No.:	SH1EER10035
Maximum Power Output:	-
Open Market Value:	\$87,764.00
Original Registration Date:	11 Nov 2011
First Registration Date:	11 Nov 2011
Transfer Count:	1
Actual ARF Paid:	\$4,389.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	10 Nov 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$34,009.00
COE Rebate Amount:	\$11,922.00
Total Rebate Amount:	\$11,922.00

The information contained herein is correct as at 08 May 2018

OK



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-069681

Date of Request: 08/05/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 08/05/2018
Enquiry By Susan Low Siew Yian
TP Vehicle No. XE425Y
Accident Date 07/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
XE425Y	ERGO Insurance Pte. Ltd.	03/03/2018-02/03/2019	6829 9199

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-069681
Date of Request: 08/05/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 08/05/2018
Enquiry By: Susan Low Siew Yian
TP Vehicle No: XE425Y
Accident Date: 07/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto-Reg in Kaki Bukit Singapore 417883

ROB No: N2W17931 Tel: 6744-1730 / 731 Fax: 6744-5746 Email: lsbw@gmail.com

Invoice/Ref No: XD5128C180507

Estimate

Customer

Name: ERGO Insurance Pte Ltd

Date: 08-05-18

Address: Motor Claims Department

Vehicle No: XD5128C

5 Temasek Boulevard #04-01

Model/Make: Hino SH1EERA

Suntec Tower Five

Singapore 038985

13L Manual ABS Turbo

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Door <i>Dis 3611.42</i>	\$ 5,639.70	
2	Door Hinge 02 pcs (@ \$145.00) <i>best/cur</i>	\$ 290.00	
3	Door Signal Lamp <i>11</i>	\$ 170.00	X
4	Door Rubber <i>10.1</i>	\$ 275.00	
5	Door Lock <i>11/12</i> <i>#25-15</i>	\$ 630.00	
6	Door Handle <i>11</i>	\$ 260.00	X
7	Door Glass <i>Shot/cur</i> <i>545.12</i>	\$ 623.00	
8	Door Glass Weatherstrip <i>Dis</i> <i>399.65</i>	\$ 570.00	
9	Door Glass Outer Garnish <i>11</i>	\$ 317.00	X
10	Door Glass Regulator <i>best/cur</i>	\$ 540.00	
11	Door Glass Panel <i>11</i>	\$ 216.00	X
12	Door Glass Motor <i>11</i> <i>645</i>	\$ 980.00	
13	Door Inner Trim Board <i>best/cur</i>	\$ 780.70	
14	Door Inner Trim Board Clip (1 set) <i>11</i>	\$ 50.00	X
15	Door Wire <i>11</i>	\$ 410.00	X
16	Door Outer Lower Protector (Garnish) <i>Dis</i>	\$ 485.20	
17	Door Garnish Inner Panel <i>11</i>	\$ 290.00	X
18	Door "2041" Emblem <i>11</i>	\$ 145.00	
19	Door "EURO 4" Emblem <i>11</i>	\$ 118.00	
20	Step Panel <i>11</i>	\$ 1,370.00	X
21	Wheel Panel <i>11</i>	\$ 845.20	X
22	Wheel Panel Outer Garnish <i>Dis</i>	\$ 374.60	
23	Corner Panel <i>11</i>	\$ 596.20	
24	Side Mirror Arm <i>best</i>	\$ 980.00	
25	Side Mirror Arm Cover <i>11</i> <i>102</i>	\$ 385.20	
26	Bumper Top Corner Panel <i>Dis</i>	\$ 560.00	
27	Bumper Side <i>11</i>	\$ 160.90	
28	Signal Lamp <i>11</i>	\$ 230.70	
29	"Corporate" Advertisement Sticker <i>11</i>	\$ 400.00	SN 2005.2
	To check all wiring & electrical component for proper function	\$ 80.00	20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 900.00	600
	To putty & spray painting & including touch up paint on accident area	\$ 1,000.00	700
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	50
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 120.00	60

Total Parts & Labour of estimate for damaged vehicle

\$ 20,962.40

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

not allowed
2/5/18 9500
9/5/18
4 dr.
take photo After repair

7-1154784
10393-01
1202308

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18008513/Uvbn2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 18-05-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 425Y	Veh. Inspected	XD 5128C
Policy No.		Coverage (\$)	0.00
Claim No.	XE 425Y/SE/pl	Excess (\$)	0.00
Assign From	PEI LI	Assign Date	09/05/2018

2. Vehicle Particulars & Condition

Make & Model	HINO SH1EERA (M)	c.c	12913
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	SH1EER10035	Colour	WHITE
Odometer	220184	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	TRIANGLE	6 mm
L/H Front Tyre	295/80 R22.5	TRIANGLE	6 mm
R/H Rear Tyre	295/80 R22.5 (D)	TRIANGLE	6/6 mm
L/H Rear Tyre	295/80 R22.5 (D)	TRIANGLE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2018	Inspection Date	09/05/2018
Survey held at	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 5128C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT LH DOOR	DISTORTED	5,639.70	3,611.42
2	DOOR HINGE @\$145.00	TWISTED / BENT	290.00	290.00
1	DOOR SIGNAL LAMP	NOT NECESSARY	170.00	-
1	DOOR RUBBER	TORN	275.00	275.00
1	DOOR LOCK	JAMMED / TWISTED	630.00	425.15
1	DOOR HANDLE	NOT NECESSARY	260.00	-
1	DOOR GLASS	SHATTERED	693.00	545.12
1	DOOR GLASS WEATHERSTRIP	DISTORTED	570.00	399.65
1	DOOR GLASS OUTER GARNISH	NOT NECESSARY	317.00	-
1	DOOR GLASS REGULATOR	BENT / TWISTED	540.00	540.00
1	DOOR GLASS PANEL	NO SUCH PARTS	216.00	-
1	DOOR GLASS MOTOR	JAMMED	980.00	645.00
1	DOOR INNER TRIM BOARD	DEFORMED / CRACKED	780.70	780.70
1	SET DOOR INNER TRIM BOARD CLIP	NOT NECESSARY	50.00	-
1	DOOR WIRE	NOT NECESSARY	410.00	-
1	DOOR OUTER LOWER PROTECTOR (GARNISH)	DISTORTED	485.20	485.20
1	DOOR GARNISH INNER PANEL	TO REPAIR SEE LABOUR	290.00	-
1	DOOR "204I" EMBLEM	NECESSARY	145.00	145.00
1	DOOR "EURO 4" EMBLEM	NECESSARY	118.00	118.00
1	STEP PANEL	TO REPAIR SEE LABOUR	1,370.00	-
1	WHEEL PANEL	TO REPAIR SEE LABOUR	845.20	-
1	WHEEL PANEL OUTER GARNISH	DISTORTED	374.60	374.60
1	CORNER PANEL	CRACKED	596.20	596.20
1	SIDE MIRROR ARM	BENT	980.00	980.00
1	SIDE MIRROR ARM COVER	BROKEN	385.20	385.20
1	BUMPER TOP CORNER PANEL	DISTORTED	560.00	560.00
1	BUMPER SIDE	MISSING	160.90	160.90
1	SIGNAL LAMP	SCRATCHED	230.70	230.70

Report Ref No. CS/EGI18008513/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-1,154.78
			18,362.40	10,393.06
	SPECIAL NETT ITEMS			
1	"CORPORATE" ADVERTISEMENT STICKER (SN)	NECESSARY	400.00	200.00
			400.00	200.00
	LABOUR			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	20.00
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF DOOR GARNISH INNER PANEL,STEP PANEL AND WHEEL PANEL.		900.00	600.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT .		1,000.00	700.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		100.00	50.00
	TO REMOVE,REPLACE AND TRANSFER DOOR PANEL,FITTING AND MECHANISMS.		120.00	60.00
			2,200.00	1,430.00
	GRAND TOTAL		20,962.40	12,023.06
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,500.00

Report Ref No. CS/EGI18008513/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.