

ASS. SEC. BY:

REF:

CS / FCL18008528 / Arbuz

Special Instruction:

SURVIVOR:

ASSIGNMENT (Office)

From (Person): WS Mary Chua of FCL Date/Time: 08052018 3:47pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 5867L Insured: SHD3630Xat Workshop m/s Jack Cus Tel: 67488824of 3007 Ubi Rd 1 #01-480Policy No: _____ Claim No: D1800357MF5H

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07052018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp' 07052018 @ after 2pm H.O.D. Endorsement: _____Date/Time: 08052018 4:02pm Person Contacted: Thura Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	Revert thru email pending est from repairer.
	Revert thru email
	confirm \$2015.20, 3 days
	Red: \$1934.80, 49%.

REF:

Fcl

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 5867L

at Workshop n/s Jack Cars

of 2007 Ubi Rd 1 #01-450.

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9/5/2018 After 2pm.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKC5867L

Yr Regn:

2011 Sept

Type: ☒ M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra.

cc 1591CC

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp Reading

124898

T/Radio

Insured / Std / NI / NA

Eng/No:

KMH DHA1CMCU219904

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size

F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

09/05/18

Survey held at

Jack Cars.

Des. of Damages: Frt / Rear / ☒ O/S / NIS / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

) S+PS 34

) Piles

) Other

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Week end (\$

136

50

50

29

259

Report Format :

Lump Sum / I.B.I. (\$



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003571MFSH

Our Ref: CS/FCI18008528/Arb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKC 5867L .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.05.2018 at the premises of M/s JACK CARS ENTERPRISE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,950.00</u> .
Revised Estimate Amount	: S\$ <u>2,015.20</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at o/s body.



Yours faithfully
ADRIAN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-05-2018	Our Ref No. D18003571MFSH
Accident Date	07-05-2018	Claim Type. Third Party
Insured Vehicle	SHD3630X	Third Party Vehicle. SKC5867L
Survey Location	Blk 3007 Ubi Road 1 #01-450	
Contact Person.	MS S.THANALETCHUMI	
Contact No.	67488824/ 67488824	Fax No. 00
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	JACK CARS ENTERPRISE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

ESTIMATE

TP 1st Cap Janice

DATE OF ACCIDENT : 07/05/2018

VEHICLE : SKC5867L

MAKE & MODEL : HYUNDAI ELANTRA

KMH DHA1CMCU219904

INSURANCE : FIRST CAPITAL INSURANCE LTD

SURVEYOR : LKK AUTO ADRIAN - 96893735

PARTS		CONDITION	COST
1.	REAR RIGHT DOOR <i>Distorted</i>	<i>1381.50</i>	\$ 1750
2.	SIDESKIRT <i>Repair</i>	REPAIR	
		<i>1381.50</i>	
	LABOUR	<i>1105.20</i>	
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 1330 <i>400</i>
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS		\$ 950 <i>400</i>
3.	TO CHECK WIRING & REWIRE	<i>910</i>	\$ 120 <i>30</i>
4.	TO REMOVE AND REINSTALL REAR RIGHT DOOR <i>ittings</i>		\$ 150 <i>80</i>
	PARTS - 20%:	\$ 1,400	
	LABOUR :	\$ 2,550	
	TOTAL :	\$ 3,950	
	7% GST :	\$ 276.50	
	GRAND TOTAL :	\$ 4,226.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2015.20
(P/P) 03 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18008528/Arbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3630X	Veh. Inspected	SKC 5867L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003571MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	08/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHDH41CMCU219904	Colour	SILVER	
Odometer	124898	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KUMHO	6 mm	
L/H Front Tyre	205/55 R16	KUMHO	6 mm	
R/H Rear Tyre	205/55 R16	KUMHO	6 mm	
L/H Rear Tyre	205/55 R16	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2018	Inspection Date	09/05/2018	
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 5867L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR RIGHT DOOR	DISTORTED TO REPAIR SEE LABOUR	1,750.00	1,381.50
1	SIDSKIRT (NPA)		-	-
	LESS 20% DISCOUNT		-350.00	-276.30
			1,400.00	1,105.20
	LABOUR			
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		1,330.00	400.00
	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF SIDESKIRT.		950.00	400.00
	TO CHECK WIRING & REWIRE.		120.00	30.00
	TO REMOVE AND REINSTALL REAR RIGHT DOOR.		150.00	80.00
			2,550.00	910.00
	GRAND TOTAL		3,950.00	2,015.20
RECOMMENDED COST OF REPAIRS				2,015.20

Report Ref No. CS/FCI18008528/Arbn2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.