



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT BONNET	X Repair	1 PC	2,600.00	
2 FRONT BONNET HINGE LH	X } repair	1 PC	95.00	
3 FRONT BONNET HINGE RH	X }	1 PC	95.00	
4 FRONT BONNET INSULATOR	- TN	1 PC	240.00	
5 FRONT BONNET INSULATOR CLIPS	- MC	17 PC	59.50	
6 FRONT BONNET HINGE BDS ACTUATOR SENSOR LH	X - SACT	1 PC	850.00	
7 FRONT BONNET HINGE BDS ACTUATOR SENSOR RH	X - SACT	1 PC	850.00	
8 FRONT BONNET LOCK CATCH OPENING CTR - CHECK PRICE	X NN	1 PC	0.0000	
9 FRONT BONNET LOCK CATCH OPENING SIDE STOPPER WITH SPRING - CHECK PRICE	X NN	1 PC	0.0000	
10 FRONT GRILLE	- CAA	1 PC	560.00	
11 FRONT GRILLE OUTER CHROME MOULDING	- BR	1 PC	840.00	
12 FRONT GRILLE EMBLEM - CHECK PRICE	- MC	1 PC	0.0000	
13 HEADLAMP WITH HID LH	- CAA	1 PC	1,850.00	
14 HEADLAMP WITH HID RH	?	1 PC	1,850.00	
15 HEADLAMP HID BULB LH - CHECK PRICE	?	1 PC	0.0000	
16 HEADLAMP HID MODULE LH - CHECK PRICE	??	1 PC	0.0000	
17 HEADLAMP LOWER BEAM - CHECK PRICE	??	2 PC	0.0000	
18 HEADLAMP CLIPS - CHECK PRICE	?	4 PC	0.0000	
19 HEADLAMP WASHER NOZZLE LH	?	1 PC	130.00	
20 HEADLAMP WASHER NOZZLE MOTOR LH	?	1 PC	180.00	
21 FRONT BUMPER	- ee	1 PC	1,650.00	
22 FRONT BUMPER SIDE RETAINER LH	- SACT	1 PC	40.00	
23 FRONT BUMPER SIDE RETAINER RH	- SACT	1 PC	40.00	
24 FRONT BUMPER LOWER GRILLE CTR	?	1 PC	220.00	
25 FRONT BUMPER REINFORCEMENT	?	1 PC	750.00	
26 FRONT BUMPER REINFORCEMENT BRACKET - CHECK PRICE	?	2 PC	0.0000	
27 FRONT BUMPER SPONGE	?	1 PC	220.00	
28 FRONT BUMPER CTR PARKING SENSOR	- M's	2 PC	290.00	
29 FRONT BUMPER CTR PARKING SENSOR HOLDER	- MC	2 PC	72.00	
30 FRONT BUMPER SIDE PARKING SENSOR	LH - M's, RH X NN	2 PC	72.00	
31 FRONT BUMPER SIDE PARKING SENSOR HOLDER	- MC	2 PC	290.00	
32 FOGLAMP COVER	LH - ee, RH X NN	2 PC	280.00	
33 FOGLAMP OUTER CHROME MOULDING	LH - BR, RH X NN	2 PC	360.00	
34 FRONT FENDER LH	X NN	1 PC	1,250.00	
35 FRONT FENDER COWLING LH	X NN	1 PC	235.00	
36 FRONT FENDER COWLING CLIPS	X NN	10 PC	35.00	
37 AIR CON CONDENSER ASSY	?	1 PC	1,150.00	
38 NO PLATE GARNISH	- ee	1 PC	45.00	





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Description	U/Price	Quantity	Cost S\$	Amount S\$
				17,198.50
Special Nett				
39 NUMBER PLATE / cut		1 PC	35.00	
40 RADIATOR COOLANT ?		1 PC	50.00	
				85.00
LABOUR				
41 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	30
42 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	120.00	?
43 TO RESET FRONT BONNET HINGE BDS ACTUATOR SENSOR, HEADLAMP, FRT BUMPER PARKING SENSOR, FRONT BUMPER SIDE PARKING SENSOR.		1 PC	120.00	80 100
44 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	160.00	40
45 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT & BRACKET. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	800.00	400
46 TO SPRAY FRONT BONNET, FRONT FENDER LH & RH, FRONT BUMPER REINFORCEMENT & BRACKET, RADIATOR SUPPORT PANEL.		1 PC	800.00	400
				2,040.00

5 Days.

part by part

before paint photos.

Excess \$600.

Not Authorised

05/5/18. GmoQiaf - 8248028

LKK Auto Consultants notice to notify the Repairer of the following

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Amount Before Excess	S\$ 19,323.50
Add GST @ 7%	1,352.65
Total Amount payable	S\$ 20,676.15

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SIX HUNDRED SEVENTY SIX AND CENTS FIFTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

