

ASS. REC. BY:

REF:

CS/NSM18008531/Gvbez

Special Instruction:

SURVIVOR

ASSIGNMENT (Office)

Smart claim
From (Person):

Kathy Too

of

Asm

Date/Time:

08/05/2018 4:06pm

Estimated Cost:

Bill to:

① TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC8818J

Insured:

at Workshop m/s

Ah Lim Motor

Tel:

64831244

of

AMK

Policy No:

Claim No:

S8M00G0N

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A.

08/05/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 8818J - x
10/5/18	Revert by SMART claim
10/5/18	Reauthorize repair at \$13,707.50 ex \$600
10/5/18	Informed Zila c/A ex \$600 by email
11/5/18	@1008am GUO Qiang informal Zila NV: \$21K
20/8/18	Final fig \$10,923 confirmed by email (Red 9403.50, 4613 (No LS)

The U/C / Chassis frame / Body Structure affected due to collision

300

20/8/2018.



Service Request Details

Claim

58M00G0N

Reference

None 

Loss Date

May 3, 2018

LKK AUTO CONSULTANTS PTE LTD (OD) ▾

Request Date

May 8, 2018

Due Date

May 15, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKC8818J

Make

JAGUAR

Service Address

10 Ang Mo Kio Ind. Park 2A, , 568047

Primary Contact/Insured

TAN JEOK PENG

20 CANBERRA DRIVE, #15-01 YISHUN EMERALD, 768425, Singapore

98711707

SMMINS@YAHOO.COM.SG

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

EXCESS \$600

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

5/8/18 4:07 PM

FROM

TEO Kitty

SUBJECT

SKC8818J - VEH @ AH LIM(AMK)

BODY

Hi Please survey WP and get estimate from worksho...



New Message

Type *

☒ Message

Subject *

Message *

Dear Sir/Madam,

We have received supplementary of \$760/- from repairer .Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.IA has submitted. Best Regards Veron Chen

Immediate Advice

To : AXA Insurance Pte Ltd

Date:20/8/2018

Survey details

Date of loss	3/5/2018
Date of appointment	8/5/2018
Date of survey	9/5/2018
Location of survey	AH LIM MOTOR COMPANY

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKC 8818J
Make and Model	JAGUAR XJ 5.0L
Date of registration	31/3/2011
Excess	\$600.00
Market Value	\$90,000.00
Part Rebate	\$68,095.00
Nett Loss	\$21,905.00

Repair details

Initial Estimate	\$20,326.50 (INCL.SUPPLEMENTARY \$760)
------------------	--

Proposed/Revised repair cost:

Parts	\$9,873.00
"Check items (Estimated)	
Labour	\$1,050.00
Total	\$10,923.00 (INCL.SUPPLEMENTARY \$760)
Lump Sum (Estimated)	

Number of days of repair	5 DAYS (EST)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the front portion.

Damages Consistent
Repair Cost Economical

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 10 May 2018 2:44 PM
To: SUR; Zila - Ah Lim Motor Co (AMK) (zila@ahlimmotor.com.sg)
Subject: SKC 8818J-DOA: 3/5/2018 (AXA OD)

Dear Zila,

As instructed by our client , please proceed to repair the insured vehicle **SKC 8818J on part by part (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Re:IA SUBMITTED FOR SKC 8818J - 10/5/18

Type

🔔 Question

Message

Hi Veron, Please authorise at \$13,707.50 before excess of \$600. Thanks.

Reply



IA SUBMITTED FOR SKC 8818J

Type

🔍 Question

Message

Dear Sir/Madam, Please be informed that IA submitted. We have Not Authorize repair. Kindly let us have your approval please.Thanks Veron Chen

Reply



Auto
Consultants
Pte Ltd

33 UBI AVE E, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (65) 62563561 FAX : (65) 62564318

Immediate Advice

To : AXA Insurance Pte Ltd

Date:10/5/2018

Survey details

Date of loss	3/5/2018
Date of appointment	8/5/2018
Date of survey	9/5/18 @4.30PM
Location of survey	AH LIM MOTOR COMPANY

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKC 8818J
Make and Model	JAQUAR XJ 5.0
Date of registration	31/3/2011
Excess	\$600
Market Value	\$90,000.00
Part Rebate	\$68,095.00
Nett Loss	\$21,905.00

Repair details

Initial Estimate	\$19,323.50
------------------	-------------

Proposed/Revised repair cost:

Parts	\$8,067.50
"Check items (Estimated)	\$4,670.00
Labour	\$970.00
Total	\$13,707.50
Lump Sum (Estimated)	

Number of days of repair	5 DAYS (EST)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the front portion.

Damages Consistent

Repair Cost Economical

Some of the parts pending for parts prices

We have Not authorize repair.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6098E
Vehicle Details	
Vehicle No.:	SKC8818J
Vehicle to be Exported:	No
Intended De-registration Date:	10 May 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XJ 5.0L AT ABS D/AB 2WD 4DR GAS/D SR
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	10111109314508PN
Chassis No.:	SAJAC22F4BLV16034
Maximum Power Output:	283.0 kW (379 bhp)
Open Market Value:	\$87,797.00
Original Registration Date:	31 Mar 2011
First Registration Date:	31 Mar 2011
Transfer Count:	0
Actual ARF Paid:	\$87,797.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2021
PARF Rebate Amount:	\$52,678.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$53,400.00
COE Rebate Amount:	\$15,417.00
Total Rebate Amount:	\$68,095.00

The information contained herein is correct as at 10 May 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 6098E

Vehicle Details

Vehicle No.: SKC8818J
Vehicle to be Exported: No
Intended De-registration Date: 03 May 2018
Vehicle Make: JAGUAR
Vehicle Model: XJ 5.0L AT ABS D/AB 2WD 4DR GAS/D SR
Primary Colour: Grey
Manufacturing Year: 2010
Engine No.: 10111109314508PN
Chassis No.: SAJAC22F4BLV16034
Maximum Power Output: 283.0 kW (379 bhp)
Open Market Value: \$87,797.00
Original Registration Date: 31 Mar 2011
First Registration Date: 31 Mar 2011
Transfer Count: 0
Actual ARF Paid: \$87,797.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Mar 2021
PARF Rebate Amount: \$52,678.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$53,400.00
COE Rebate Amount: \$15,517.00
Total Rebate Amount: \$68,195.00

The information contained herein is correct as at 03 May 2018

OK

► Jaguar XJ Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Available
Jaguar XJ Diesel 3.0A LWB (Diesel - Euro 5 Engine and Above)	\$98,000	\$21,760 /yr	03-Jan-2011	2,993 cc	104,000 km	Motor-Way Credit Pte Ltd	Available
Excellent Condition. Well Maintained. Easy In House Financing Available. Call Our Friendly Sales Consultant For Viewing.Price Inclusive Of GST.							
Jaguar XJ 5.0A	\$90,999	\$15,830 /yr	23-Feb-2011	5,000 cc	68,000 km	66 Pte Ltd	Available
Super Well Maintain, Lowest Mileage, Owner Spend Money To Replace All Wear And Tear, Engine Mounting, Gear Box Mounting Changed, Lowest Depreciation, Most Value For Money. Regular Servicing And Groomi...							
Office No. - 67434333							
Ong - 91868133 Yong - 82991743 Keene Ong - 90914333 Benjamin Teng - 83237600							
Jaguar XJ Diesel 3.0A Premium Luxury LWB (Diesel - Euro 5 Engine and Above)	\$103,000	\$21,970 /yr	31-Mar-2011	2,993 cc	86,000 km		Available
Attention All Car Lovers, Rare Diesel LWB Model, Low Mileage As Used In City Only, Owner's 3rd Car Living In Orchard. Immaculate Interior And Exterior, Showroom Condition, Upgrading For Another Car, D...							
Office No. - -							
Mr Koh - 92338800							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for C cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brand carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & C results.

© 2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/05/2018 15:26
Date Of Accident	03/05/2018 07:00
Exact Location Of Accident	YISHUN EMERALD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC8818J
Insured/Policyholder	
Name Of Registered Owner	TAN JEOK PENG
NRIC No	S0166098E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96327928
Alternative Phone No	OTHERS-96327928

Vehicle Particulars

Manufacturer	JAGUAR
Model	XJ-5.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------


Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA098722
Cover Note Number	04/04/2018 - 03/04/2019

Driver

Name of Driver	TAN JEOK PENG
NRIC No	S0166098E
Date Of Birth	25/12/1954
Occupation	INDOOR
Date Of Driving Pass	07/06/1977
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96327928
Fax Number	
Contact Number	OTHERS-96327928
Email Address	NOEMAIL

SKETCH PLAN



1 Accidentally press onto the accelerator > hit onto the parked vehicle in front

Remarks : Please forward a copy of my efile accident report to :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

I/We declare the foregoing particulars are true in every respect.


 Kellyholder's Signature
 Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

NRIC/FIN No.:

ANALYST MOTOR COMPANY



redefining / insurance

TAN JEON PENG
20 CANBERRA DRIVE
#15-01 TISHUN EMERALD
SINGAPORE 756425

AXA Insurance Pte Ltd
1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
(65) 6880 4740
customer.care@axa.com.sg
www.axa.com.sg

Renewal

date
20/04/2018

your servicing distributor
SPEEDO CAPITAL PTE LTD / 04139

your servicing distributor contact
6684 7757-YUKI

Policy Schedule

Your SmartDrive Comprehensive Private

Your policy snapshot

Policyholder name	TAN JEON PENG	Policy number	VA1 / GA098722
Cover	Comprehensive	FIN / NRIC	S0158098E
Period of insurance	from 04/04/2018 to 03/04/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 1,917.47
Total Discounts	- SGD 100.23
7% GST	SGD 127.07
Final Premium	SGD 1,942.31

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Private Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Loss or Damage
- Legal Liability
- Workshop of your Choice
- Daily Transport Allowance of \$50 per day maximum of five (5) days
- Medical and dental expenses up to \$500 per person for either you as the driver or your authorised driver and a passenger
- Personal accident benefit of up to \$10,000 for you and your named drivers
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess.

Add-on Benefits

- No Claim Discount Protector

Vehicle details

Make & Model of Vehicle	JAGUAR XJ 5.0	Year of manufacture	2010
Vehicle registration number	SKC981EJ	Type of Use	Private use
Body type	SALOON	Engine capacity (cc.)	5000
Seating capacity (excl driver)	4	Engine number	10111109314508FN
Off-Peak car	No	Chassis number	BAJAC22F4BLV15034

Insured's Estimated Market Value	Market value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	MAYBANK

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 600.00
Windscreen Excess	SGD 200.00

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

1 of 2

Sketch Plan Pg. 5



redefining / insurance

Date: 03/05/18

To: Owner of Vehicle Number: SK 481 BJ

The following has been advised to you via your workshop, Ah Lim Motor Company through their staff Zila Eileen / Mui Hong.

Please tick the applicable box if you had been advice on the content as seen below:

☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

☐ You had been advised by the workshop on the liability and merits of the case accordingly.

☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.

☒ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.

☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.

☒ The estimated waiting time for the spare parts to arrive is TBA. The estimated arrival time does not include the repair period.

☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.

☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.


For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.

☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.

☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

☒ Others claim own Damage

Signed and acknowledge by:


Name and signature of policyholder/authorised driver


Name and signature of workshop personnel including company stamp





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlime@singnet.com.sg
GST: M9-0009639-E RCB NO: 06470300B

SURVEYOR COPY

M/S: AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
SPARE PARTS				
1 FRONT BONNET X Repair		1 PC	2,600.00	
2 FRONT BONNET HINGE LH BT		1 PC	95.00	✓
3 FRONT BONNET HINGE RH		1 PC	95.00	✓
4 FRONT BONNET INSULATOR		1 PC	240.00	✓
5 FRONT BONNET INSULATOR CLIPS - 14PCS		17 PC	59.50	✓ 49
6 FRONT BONNET HINGE BDS ACTUATOR SENSOR LH		1 PC	850.00	✓
7 FRONT BONNET HINGE BDS ACTUATOR SENSOR RH		1 PC	850.00	✓
8 FRONT BONNET LOCK CATCH OPENING CTR - CHECK PRICE X NN		1 PC	0.0000	
9 FRONT BONNET LOCK CATCH OPENING SIDE STOPPER WITH SPRING - CHECK PRICE BT ✓		1 PC	0.0000	✓ 65
10 FRONT GRILLE - CRA		1 PC	560.00	✓
11 FRONT GRILLE OUTER CHROME MOULDING - BK		1 PC	840.00	✓
12 FRONT GRILLE EMBLEM - CHECK PRICE - MC		1 PC	0.0000	✓ 60
13 HEADLAMP WITH HID LH - CRA		1 PC	1,850.00	✓
14 HEADLAMP WITH HID RH		1 PC	1,850.00	
15 HEADLAMP HID BULB LH - CHECK PRICE		1 PC	0.0000	
16 HEADLAMP HID MODULE LH - CHECK PRICE		1 PC	0.0000	
17 HEADLAMP LOWER BEAM - CHECK PRICE		2 PC	0.0000	
18 HEADLAMP CLIPS - CHECK PRICE		4 PC	0.0000	
19 HEADLAMP WASHER NOZZLE LH		1 PC	130.00	
20 HEADLAMP WASHER NOZZLE MOTOR LH		1 PC	180.00	
21 FRONT BUMPER - ee		1 PC	1,650.00	✓
22 FRONT BUMPER SIDE RETAINER LH - 1/2 ac		1 PC	40.00	✓
23 FRONT BUMPER SIDE RETAINER RH		1 PC	40.00	✓
24 FRONT BUMPER LOWER GRILLE CTR		1 PC	220.00	✓
25 FRONT BUMPER REINFORCEMENT		1 PC	750.00	✓
26 FRONT BUMPER REINFORCEMENT BRACKET - CHECK PRICE X NN		2 PC	0.0000	X
27 FRONT BUMPER SPONGE		1 PC	220.00	✓
28 FRONT BUMPER CTR PARKING SENSOR		2 PC	290.00	✓
29 FRONT BUMPER CTR PARKING SENSOR HOLDER		2 PC	72.00	X
30 FRONT BUMPER SIDE PARKING SENSOR LH RH X NN		1 2PC	72.00	✓ 145
31 FRONT BUMPER SIDE PARKING SENSOR HOLDER		2 PC	290.00	X
32 FOGLAMP COVER LH - ee, RH X NN		1 2PC	280.00	145
33 FOGLAMP OUTER CHROME MOULDING LH - BK, RH X NN		2 PC	360.00	180
34 FRONT FENDER LH X NN		1 PC	1,250.00	X
35 FRONT FENDER COWLING LH X missing		1 PC	235.00	2350 ✓
36 FRONT FENDER COWLING CLIPS X NN		10 PC	35.00	34 ✓
37 AIR CON CONDENSER ASSY		1 PC	1,150.00	X
38 NO PLATE GARNISH - ee		1 PC	45.00	40 ✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Description	U/Price	Quantity	Cost	Amount
			SS	SS
			17,444.50	17,198.50
			17,386.50	
Special Nett				
39 NUMBER PLATE / cut		1 PC	35.00 ✓	
40 RADIATOR COOLANT X NN		1 PC	50.00 X	
				85.00
LABOUR				
41 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00 30 ✓	
42 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	120.00 2 X NN	
43 TO RESET FRONT BONNET HINGE BDS ACTUATOR SENSOR, HEADLAMP, FRT BUMPER PARKING SENSOR, FRONT BUMPER SIDE PARKING SENSOR.		1 PC	120.00 20 100 ✓	
44 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	160.00 40 ✓	
45 TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD FRONT BUMPER REINFORCEMENT & BRACKET, TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	800.00 400 ✓	
46 TO SPRAY FRONT BONNET, FRONT FENDER LH & RH, FRONT BUMPER REINFORCEMENT & BRACKET, RADIATOR SUPPORT PANEL.		1 PC	800.00 400 ✓	
				2,040.00

5 Days.

part by part

before paint photos.

Excess \$600.

Not Authorised

05/5/18. Gao Qia - 82480282

LIK Auto Consultants Advice notify the Repairer of the following:

- To resurvey before repair spray paint
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: **SKC8818J**

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

20,326.50

Amount Before Excess

S\$ 19,323.50

Add GST @ 7%

1,352.65

Total Amount payable

S\$ 20,676.15

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SIX HUNDRED SEVENTY SIX AND CENTS FIFTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

19711.50

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

20071.50



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

Need assessment
 Return for
 supply key

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

DRAFT FINALISATION

Claim No: MC0913079

Ref No: MF0911230

Date: 07 Aug 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKC8818J

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET HINGE LH		1 PC	95.00	
2 FRONT BONNET HINGE RH		1 PC	95.00	
3 FRONT BONNET INSULATOR		1 PC	240.00	
4 FRONT BONNET INSULATOR CLIPS		14 PC	49.00	
5 FRONT BONNET HINGE BDS ACTUATOR SENSOR LH		1 PC	850.00	
6 FRONT BONNET HINGE BDS ACTUATOR SENSOR RH		1 PC	850.00	
7 FRONT BONNET LOCK CATCH OPENING SIDE STOPPER WITH SPRING		1 PC	65.00	
8 FRONT GRILLE		1 PC	560.00	
9 FRONT GRILLE OUTER CHROME MOULDING		1 PC	840.00	
10 FRONT GRILLE EMBLEM		1 PC	60.00	
11 HEADLAMP WITH HID LH		1 PC	1,850.00	
12 FRONT BUMPER		1 PC	1,650.00	
13 FRONT BUMPER SIDE RETAINER LH		1 PC	40.00	
14 FRONT BUMPER SIDE RETAINER RH		1 PC	40.00	
15 FRONT BUMPER LOWER GRILLE CTR		1 PC	220.00	
16 FRONT BUMPER REINFORCEMENT		1 PC	750.00	
17 FRONT BUMPER SPONGE		1 PC	220.00	
18 FRONT BUMPER CTR PARKING SENSOR		2 PC	290.00	
19 FRONT BUMPER SIDE PARKING SENSOR		1 PC	145.00	
20 FOGLAMP COVER LH		1 PC	145.00	
21 FOGLAMP OUTER CHROME MOULDING LH		1 PC	180.00	
22 FRONT FENDER COWLING LH		1 PC	280.00	
23 FRONT FENDER COWLING CLIPS		8 PC	24.00	
24 NO PLATE GARNISH		1 PC	40.00	
25 BUMPER LOWER COVER		1 PC	260.00	(A)
				9,838.00
Special Nett				
26 NUMBER PLATE		1 PC	35.00	
				35.00
LABOUR				
27 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	30.00	
28 TO RESET HEADLAMP,FRONT BUMPER PARKING SENSOR, FRONT BUMPER SIDE PARKING SENSOR.		1 PC	100.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmo@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Claim No: MC0913079

Ref No: MF09H1230

Date: 07 Aug 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKC8818J

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
29 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	40.00	
30 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT BUMPER REINFORCEMENT & BRACKET.TO KNOCK & REPAIR RADIATOR SUPPORT PANEL,FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	400.00	
31 TO SPRAY FRONT BONNET,FRONT FENDER LH & RH, FRONT BUMPER REINFORCEMENT & BRACKET, RADIATOR SUPPORT PANEL.		1 PC	400.00	
32 TO RESET BONNET HINGE ACTUATOR		1 PC	500.00	
				1,470.00

Amount Before Excess	SS 11,343.00
Less Excess	SS 600.00
Amount Before GST	SS 10,743.00
Add GST @ 7%	752.01
Total Amount payable	SS 11,495.01

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FOUR HUNDRED NINETY FIVE AND CENTS ONE ONLY

The above vehicle was surveyed by GUO XIANG - LKK on 09/05/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
AUTHORISED SIGNATURE
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate Repair Cost to Vehicle No :SKC8818J

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 FRONT BONNET X Repair		1 PC	2,600.00	
2 FRONT BONNET HINGE LH X repair		1 PC	95.00	
3 FRONT BONNET HINGE RH X repair		1 PC	95.00	
4 FRONT BONNET INSULATOR - TN		1 PC	240.00	
5 FRONT BONNET INSULATOR CLIPS - MC		17 PC	59.50	
6 FRONT BONNET HINGE BDS ACTUATOR SENSOR LH 10 SACT		1 PC	850.00	
7 FRONT BONNET HINGE BDS ACTUATOR SENSOR RH 10 SACT		1 PC	850.00	
8 FRONT BONNET LOCK CATCH OPENING CTR CHECK PRICE X NA		1 PC	0.0000	
9 FRONT BONNET LOCK CATCH OPENING SIDE STOPPER WITH SPRING - CHECK PRICE X NN		1 PC	0.0000	
10 FRONT GRILLE - CRA		1 PC	560.00	
11 FRONT GRILLE OUTER CHROME MOULDING - BK		1 PC	840.00	
12 FRONT GRILLE EMBLEM - CHECK PRICE - MC		1 PC	0.0000	
13 HEADLAMP WITH HID LH - CRA		1 PC	1,850.00	
14 HEADLAMP WITH HID RH - ?		1 PC	1,850.00	
15 HEADLAMP HID BULB LH CHECK PRICE - ?		1 PC	0.0000	
16 HEADLAMP HID MODULE LH CHECK PRICE - ?		1 PC	0.0000	
17 HEADLAMP LOWER BEAM CHECK PRICE - ?		2 PC	0.0000	
18 HEADLAMP CLIPS CHECK PRICE - ?		4 PC	0.0000	
19 HEADLAMP WASHER NOZZLE LH - ?		1 PC	130.00	
20 HEADLAMP WASHER NOZZLE MOTOR LH - ?		1 PC	180.00	
21 FRONT BUMPER - ee		1 PC	1,650.00	
22 FRONT BUMPER SIDE RETAINER LH - SACT		1 PC	40.00	
23 FRONT BUMPER SIDE RETAINER RH - ?		1 PC	40.00	
24 FRONT BUMPER LOWER GRILLE CTR - ?		1 PC	220.00	
25 FRONT BUMPER REINFORCEMENT - ?		1 PC	750.00	
26 FRONT BUMPER REINFORCEMENT BRACKET CHECK PRICE - ?		2 PC	0.0000	
27 FRONT BUMPER SPONGE - ?		1 PC	220.00	
28 FRONT BUMPER CTR PARKING SENSOR - M's		2 PC	290.00	
29 FRONT BUMPER CTR PARKING SENSOR HOLDER - MC		2 PC	72.00	
30 FRONT BUMPER SIDE PARKING SENSOR LH - RH X NN		1/2 PC	72.00	
31 FRONT BUMPER SIDE PARKING SENSOR HOLDER - MC		2 PC	290.00	
32 FOGLAMP COVER LH - ee, RH X NN		1/2 PC	280.00	
33 FOGLAMP OUTER CHROME MOULDING LH - BK, RH X NN		1/2 PC	360.00	
34 FRONT FENDER LH - X NN		1 PC	1,250.00	
35 FRONT FENDER COWLING LH - X		1 PC	235.00	
36 FRONT FENDER COWLING CLIPS - X		10 PC	35.00	
37 AIR CON CONDENSER ASSY - ?		1 PC	1,150.00	
38 NO PLATE GARNISH - ee		1 PC	45.00	





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Description	U/Price	Quantity	Cost SS	Amount SS
				17,198.50
Special Nett				
39 NUMBER PLATE / cut		1 PC	35.00	
40 RADIATOR COOLANT ?		1 PC	50.00	
				85.00
LABOUR				
41 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	30
42 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	120.00	?
43 TO RESET FRONT BONNET HINGE BDS ACTUATOR SENSOR, HEADLAMP, FRT BUMPER PARKING SENSOR, FRONT BUMPER SIDE PARKING SENSOR.		1 PC	120.00	200
44 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	160.00	40
45 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD FRONT BUMPER REINFORCEMENT & BRACKET TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	800.00	400
46 TO SPRAY FRONT BONNET, FRONT FENDER LH & RH, FRONT BUMPER REINFORCEMENT & BRACKET, RADIATOR SUPPORT PANEL.		1 PC	800.00	400
				2,040.00

5 Days.

put by put

before paint photos.

Excess \$600.

Not Authorised

09/5/18. GmQiaf - 82880282





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 08 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Amount Before Excess	S\$ 19,323.50
Add GST @ 7%	1,352.65
Total Amount payable	S\$ 20,676.15

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SIX HUNDRED SEVENTY SIX AND CENTS FIFTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M00G0N

Claim Type: Own Damage

Accident Date: 03/05/2018

Estimate No: MC0913079

Date: 16 May 2018

Policy No: GA098722

Veh Reg No: SKC8818J

Make/Model: JAGUAR XJ 5.0

Estimate Repair Cost to Vehicle No :SKC8818J

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
SPARE PARTS				
1 BUMPER LOWER COVER		1 PC	260.00	260.00
LABOUR				
2 TO RESET BONNET HINGE ACTUATOR		1 PC	500.00	500.00

Amount Before Excess S\$ 760.00
GST Amount S\$ 53.20
Total Amount payable S\$ 813.20

The above vehicle was surveyed by GUO XIANG - LKK on 09/05/2018

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

實利基機件(私人)有限公司 SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887
Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270
Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISE IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s ah Lim motor co.

Tax Invoice

AMK 01-09

SSP No. 41257

Order No. 新

Date 14/5/18 20

Item	Quantity	Description	Unit Price	Amount
✓ 1	1p	C20 5386xx Front Pump		1650 00 ✓
✓ 2	1	C20 43335 Side Retainer		40 00 ✓
✓ 3	1	C20 4333 RH Side Retainer		40 00 ✓
✓ 4	9/1	C20 52851/52850 bonnet Hinge	95/	190 00 ✓
✓ 5	1/1	C20 32 3555 Radiator Grille		560 00 ✓
✓ 6	1/1	C20 3 554 GRILLE Surround		840 00 ✓
✓ 7	1/1	C22 31124 Radiator Hose		60 00 ✓
✓ 8	1/1	C20 3179 LH Head Lamp		1850 00 ✓
✓ 9	3/1	C22 22810 Parking Sensor	145/	435 00 ✓
✓ 10	1p	C20 3571 Side Moulding		180 00 ✓
✓ 11	1/1	C20 3580 Lower GRILLE	220/	220 00 ✓
✓ 12	1/1	C20 3553 Underbody Cover		✓ 260 00 SUPX
✓ 13	1/1	C20 51923 Front bumper beam		750 00 ✓
✓ 14	1/1	C20 3577 Front Bumper Foam		220 00 ✓

Sub Total

7295.00



Add GST @ 7%

510.65

Total Amount

7805.65

Delivered by _____ Received by _____
N. B. Goods are not returnable after two days.

E. & O. E.

實利基機件(私人)有限公司
SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s Ah Lim Motor Co.

AMF 01-09

Tax Invoice

SSP No. 41258

14.5.18

Order No. _____ Date: _____ 20 _____

Item	Quantity	Description	SSP	Unit Price	Amount
1	1	C2D 23552 AIR bag M2ER			1700 ✓
2	14	C2C 29479 clip	3/50		49 00 ✓
3	1	C2C 34879 bonnet 1st 2nd 240L			2410 ✓
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					

Page 2

Sub Total

1989. 00

Add GST @ 7%

139. 23

Total Amount

2128. 23

Delivered by _____ Received by _____

N. B. Goods are not returnable after two days.

E. & O. E.

實利基機件(私人)有限公司 SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s ah Lim Motor

Tax Invoice

SSP No. 41302

22/5/18

Order No.

Date: 20

Item	Quantity	Description	Unit Price	Amount
1	1/	C2P5871 GRILLE		145 00 /
2	1/	c2p 30836 FINISKE		40 00 /
3	1/	3D 17929 Latch		65 00 /
4				
5				
6				
7				
8				
9				
10				
11				
12		姜德		
13				
14				

Sub Total	250 00
Add GST @ 7%	17 50
Total Amount	267 50

Delivered by Received by

N. B. Goods are not returnable after two days.

E. & O. E.

CUSTOMER'S COPY

新中汽配有限公司

XINZHONG AUTOPARTS LLP

HQ : 33 Tyrwhitt Road Singapore 207535

Tel : (65) 6291 6051 (5 Lines) Fax : (65) 6291 6052

Branch : 25 Kaki Bukit Rd 4 #01-41 Synergy @ KB, Singapore 417800

Tel : (65) 3157 2377 Fax : (65) 6702 3855

E-mail : info@xinzhongautoparts.com

Website : http://www.xinzhongautoparts.com

Tax Invoice No. : CE177576 - 66630
 Date : 14-05-2018
 Your Reference No. :
 Payment Term :
 Currency : SGD
 Page No. : 1/1
 GST Registration No. : M903614826
 Sales Order No. : 5940-617e - 25553

TAX INVOICE

VOLKSWAGEN, AUDI, SEAT, SKODA, PORSCHE, BENTLEY, VOLVO, LAND ROVER, JAGUAR & VARIOUS OTHER LEADING EUROPEAN CAR BRANDS.

Customer

Merlin Motor Works
 10 AMK Ind Park 2A Autopoint Building
 #03-13
 Singapore 568047

Delivery Address

Merlin Motor Works
 10 AMK Ind Park 2A Autopoint Building
 #03-13
 Singapore 568047
 Singapore 568047

ITEM NO.	PART NO.	DESCRIPTION	LOG	QTY	UNIT PRICE	AMOUNT
1	JC2D34723	fender shield-10 days	XZ SALE S	1 PCS	280.00 ✓	280.00
2	JC2Z3858	clip 10 days	XZ L4E- SALE Q7 S	8 PCS	3.00 ✓	24.00
3	JC259354020	MOQ * 20PCS - clip 10 days	XZ SALE S	20 PCS (GR)	2.00 ✓ X	40.00
4	JXR854810	clip-10 days	XZ SALE S	2 PCS (GR)	3.00 ✓ X	6.00

Pass invoice

Remarks:

Vehicle No. :
 Chassis No. :
 Ordered By :
 Salesperson : KB
 Time : 09/05/2018 13:51 PM
 Zone Code :

Payment Collection

Cash ☐ Cheque ☐ NETS ☐

Amount SGD _____

Name _____

Date & Time _____

Bank Details:

Bank Name: United Overseas Bank Limited

Account Number:

UOB, Singapore 379 301 364 5 (SGD)

UOB, Singapore 379 900 273 4 (EUR)

UOB, Singapore 379 900 040 5 (USD)

SWIFT NUMBER

SUB-TOTAL	350.00
GST	24.50
TOTAL	374.50

Chia Wei Ann
 HP: 8209 2211
 Tel: 6291 6051

Checked and Received By

Goods sold are not refundable for cash.

Specialty and Electrical Parts cannot be returned

For and On Behalf of
 XINZHONG AUTOPARTS LLP

C/O: NEW TOLL ROAD

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 20 August 2018 2:56 PM
To: 'muihong@ahlimmotor.com.sg'
Cc: SUR
Subject: RE: Draft Finalisation - SKC8818J - S8M00G0N

Dear Mui Hong,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg <muihong@ahlimmotor.com.sg>
Sent: Monday, 20 August 2018 2:13 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: Draft Finalisation - SKC8818J - S8M00G0N

Dear Veron,

We will accept and amend as such and submit accordingly

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: Veron Chen (LKKAUTO)
Sent: Monday, August 20, 2018 2:10 PM
To: muihong@ahlimmotor.com.sg ; Guo Qiang (LKKAUTO)
Cc: SUR
Subject: RE: Draft Finalisation - SKC8818J - S8M00G0N

Dear Mui Hong,

Please close at \$10,923 before excess \$600 @ 5 working days.

Labour To reset bonnet hinge actuator,surveyor recommended \$80/-

Kindly confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg <muihong@ahlimmotor.com.sg>

Sent: Monday, 20 August 2018 1:29 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Re: Draft Finalisation - SKC8818J - S8M00G0N

Dear Veron,

My colleague has called Guo Qiang and clarified with him already.

Pls do check with Guo Qiang.

Thanks

Regards

Kee Mui Hong

Ah Lim Motor @ AMK

No. 10 Ang Mo Kio Ind Pk 2A

#01-09 AMK Autopoint

Singapore 568047

Tel : 64831244 Fax : 64836170

From: [Veron Chen \(LKKAuto\)](mailto:Veron Chen (LKKAuto))

Sent: Monday, August 20, 2018 11:57 AM

To: muihong@ahlimmotor.com.sg ; [Guo Qiang \(LKKAuto\)](mailto:Guo Qiang (LKKAuto))

Cc: SUR

Subject: RE: Draft Finalisation - SKC8818J - S8M00G0N

Dear Mui Hong,

Please provides us photo for Front fender cowling LH.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg <muihong@ahlimmotor.com.sg>

Sent: Friday, 17 August 2018 3:30 PM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>

Subject: Re: Draft Finalisation - SKC8818J - S8M00G0N

Dear Veron,

Thanks. I have typed supplementary and shared back.

Pls assist to advise on the draft finalisation amount soonest

Regards

Kee Mui Hong

Ah Lim Motor @ AMK

No. 10 Ang Mo Kio Ind Pk 2A

#01-09 AMK Autopoint

Singapore 568047

Tel : 64831244 Fax : 64836170

From: Veron Chen (LKKAUTO)

Sent: Friday, August 17, 2018 2:30 PM

To: muihong@ahlimmotor.com.sg ; Guo Qiang (LKKAUTO)

Subject: RE: Draft Finalisation - SKC8818J - S8M00G0N

Dear Mui Hong,

We have shared back.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg <muihong@ahlimmotor.com.sg>

Sent: Friday, 17 August 2018 2:04 PM

To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Subject: Draft Finalisation - SKC8818J - S8M00G0N

Dear Guo Qiang / Veron

Pls see attached the Draft Finalisation - SKC8818J - S8M00G0N

Aside to Admin – Pls share back assessment for us to key in the supplementary. Pls let us know when you have shared back

Pls advise.

Regards

Kee Mui Hong

Ah Lim Motor @ AMK

No. 10 Ang Mo Kio Ind Pk 2A

#01-09 AMK Autopoint

Singapore 568047

Tel : 64831244 Fax : 64836170



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18008531/Gvbe2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN : KITTY TEO

Date : 10-10-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKC 8818J
Policy No.	GA098722	Coverage (\$)	0.00
Claim No.	S8M00G0N	Excess (\$)	600.00
Assign From	KITTY TEO	Assign Date	08/05/2018

2. Vehicle Particulars & Condition

Make & Model	JAGUAR XJ 5.0L	c.c	5000
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	SAJAC22F4BLV16034	Colour	GREY
Odometer	226816	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/40 R19	PIRELLI	6 mm
L/H Front Tyre	275/40 R19	PIRELLI	6 mm
R/H Rear Tyre	275/40 R19	PIRELLI	6 mm
L/H Rear Tyre	275/40 R19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/05/2018	Inspection Date	09/05/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE MARKET VALUE IS S\$90,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 8818J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	2,600.00	-
1	FRONT BONNET HINGE LH (CONSISTENT)	BENT	95.00	95.00
1	FRONT BONNET HINGE RH (CONSISTENT)	BENT	95.00	95.00
1	FRONT BONNET INSULATOR (CONSISTENT)	TORN	240.00	240.00
17	FRONT BONNET INSULATOR CLIPS (CONSISTENT)	NECESSARY-14PCS ONLY	59.50	49.00
1	FRONT BONNET HINGE BDS ACTUATOR SENSOR LH (CONSISTENT)	ACTIVATED	850.00	850.00
1	FRONT BONNET HINGE BDS ACTUATOR SENSOR RH (CONSISTENT)	ACTIVATED	850.00	850.00
1	FRONT BONNET LOCK CATCH OPENING CTR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BONNET LOCK CATCH OPENING SIDE STOPPER WITH SPRING (CONSISTENT)	BENT	65.00	65.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	560.00	560.00
1	FRONT GRILLE OUTER CHROME MOULDING (CONSISTENT)	BROKEN	840.00	840.00
1	FRONT GRILLE EMBLEM (CONSISTENT)	NECESSARY	60.00	60.00
1	HEADLAMP WITH HID LH (CONSISTENT)	CRACKED	1,850.00	1,850.00
1	HEADLAMP WITH HID RH (CONSISTENT)	NOT NECESSARY	1,850.00	-
1	HEADLAMP HID BULB LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	HEADLAMP HID MODULE LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	HEADLAMP LOWER BEAM (NPA) (CONSISTENT)	NOT NECESSARY	-	-
4	HEADLAMP CLIPS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	HEADLAMP WASHER NOZZLE LH (CONSISTENT)	NOT NECESSARY	130.00	-
1	HEADLAMP WASHER NOZZLE MOTOR LH (CONSISTENT)	NOT NECESSARY	180.00	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,650.00	1,650.00
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER LOWER GRILLE CTR (CONSISTENT)	BROKEN	220.00	220.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	750.00	750.00
2	FRONT BUMPER REINFORCEMENT BRACKET (NPA) (CONSISTENT)	NOT NECESSARY	-	-

Report Ref No. CS/ASM18008531/Gvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	220.00	220.00
2	FRONT BUMPER CTR PARKING SENSOR (CONSISTENT)	MISSING	290.00	290.00
2	FRONT BUMPER CTR PARKING SENSOR HOLDER (CONSISTENT)	NOT NECESSARY	72.00	-
2	FRONT BUMPER SIDE PARKING SENSOR (CONSISTENT)	N/S MISSING / O/S NOT NECESSARY	290.00	145.00
2	FRONT BUMPER SIDE PARKING SENSOR HOLDER (CONSISTENT)	NOT NECESSARY	290.00	-
2	FOGLAMP COVER (CONSISTENT)	N/S DEFORMED / O/S NOT NECESSARY	280.00	145.00
2	FOGLAMP OUTER CHROME MOULDING (CONSISTENT)	N/S BROKEN / O/S NOT NECESSARY	360.00	180.00
1	FRONT FENDER LH (CONSISTENT)	NOT NECESSARY	1,250.00	-
1	FRONT FENDER COWLING LH (CONSISTENT)	MISSING	280.00	280.00
10	FRONT FENDER COWLING CLIPS (CONSISTENT)	NECESSARY-8PCS ONLY	35.00	24.00
1	AIR CON CONDENSER ASSY (CONSISTENT)	NOT NECESSARY	1,150.00	-
1	NO PLATE GARNISH (CONSISTENT)	DEFORMED	45.00	40.00
1	BUMPER LOWER COVER (ADDITIONAL) (CONSISTENT)	CUT	260.00	260.00
			17,846.50	9,838.00
SPECIAL NETT ITEMS				
1	NUMBER PLATE (SN) (CONSISTENT)	CUT	35.00	35.00
1	RADIATOR COOLANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			85.00	35.00
LABOUR				
TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.			40.00	30.00
TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		NOT NECESSARY	120.00	-
TO RESET FRONT BONNET HINGE BDS ACTUATOR SENSOR, HEADLAMP, FRT BUMPER PARKING SENSOR, FRONT BUMPER SIDE PARKING SENSOR.			120.00	100.00

Report Ref No. CS/ASM18008531/Gvbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS.		160.00	40.00
	TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD FRONT BUMPER REINFORCEMENT & BRACKET. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF FRONT BONNET.		800.00	400.00
	TO SPRAY FRONT BONNET, FRONT FENDER LH & RH, FRONT BUMPER REINFORCEMENT & BRACKET, RADIATOR SUPPORT PANEL.		800.00	400.00
	TO RESET BONNET HINGE ACTUATOR. (ADDITIONAL)		500.00	80.00
			2,540.00	1,050.00
GRAND TOTAL			20,471.50	10,923.00
RECOMMENDED COST OF REPAIRS				10,923.00
LESS EXCESS				-600.00
NETT LIABILITY				10,323.00

Report Ref No. CS/ASM18008531/Gvbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.