



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: **SPM00GFE**

Claim Type: Own Damage

Accident Date: 04/05/2018

Estimate No: **MC0913066**

Date: 05 May 2018

Policy No: GA015886

Veh Reg No: **SGK5613H**

Make/Model: TOYOTA WISH 1.8 A

Estimate Repair Cost to Vehicle No :SGK5613H

Description	U Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 FRONT BONNET / Bul		1 PC	160.00	
2 FRONT BONNET HINGE LH / BT		1 PC	22.00	
3 FRONT BONNET HINGE RH / BT		1 PC	22.00	
4 FRONT BONNET INSULATOR / Re		1 PC	125.00	
5 FRONT BONNET INSULATOR CLIPS X 10 / MC		10 PC	15.00	
6 FRONT BONNET CHROME MOULDING / BR		1 PC	90.00	
7 FRONT BONNET RUBBER / Twi		1 PC	15.00	
8 FRONT BONNET INNER LOCK / BT		1 PC	30.00	
9 FRONT BONNET LOCK CABLE / ?		1 PC	22.00	
10 FRONT BONNET STAND HOLDER / Mis		1 PC	5.00	
11 FRONT GRILLE / CRA		1 PC	45.00	
12 FRONT GRILLE CLIPS X 6 / MC		6 PC	9.00	
13 HEADLAMP LH - CHECK PRICE / CRA		1 PC	0.0000	
14 HEADLAMP RH - CHECK PRICE / CRA		1 PC	0.0000	
15 HEADLAMP CLIPS X 4 / MC		4 PC	6.00	
16 FRONT BUMPER / CRA		1 PC	165.00	
17 FRONT BUMPER SIDE RETAINERS LH / MC		1 PC	22.00	
18 FRONT BUMPER SIDE RETAINERS RH / MC		1 PC	22.00	
19 FRONT BUMPER CLIPS X 15 / ?		15 PC	15.00	
20 FRONT BUMPER LOWER AIR GRILLE / ?		1 PC	45.00	
21 FRONT BUMPER REINFORCEMENT / ?		1 PC	75.00	
22 FRONT BUMPER REINFORCEMENT BRACKET LH / ?		1 PC	20.00	
23 FRONT BUMPER REINFORCEMENT BRACKET RH / ?		1 PC	20.00	
24 FRONT BUMPER SPONGE / ?		1 PC	35.00	
25 ENGINE UNDER COVER LH / CRA		1 PC	55.00	
26 ENGINE UNDER COVER RH / CRA		1 PC	55.00	
27 ENGINE UNDER COVER CLIPS X 10 / MC		10 PC	10.00	
28 FRONT FENDER LH / Bul		1 PC	185.00	
29 FRONT FENDER COWLING LH / Re		1 PC	60.00	
30 FRONT FENDER COWLING CLIPS X 8 / MC		8 PC	8.00	
31 FRONT FENDER RH / Bul		1 PC	185.00	
32 FRONT FENDER COWLING RH / ?		1 PC	60.00	
33 FRONT FENDER COWLING CLIPS X 8 / MC		8 PC	8.00	
34 FRONT FENDER SIGNAL LAMP RH / BT		1 PC	28.00	
35 RADIATOR SUPPORT PANEL / BT		1 PC	250.00	
36 RADIATOR SUPPORT PANEL TOP GARNISH / Lt		1 PC	65.00	
37 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS X 8 / MC		8 PC	14.40	
38 BRACE PANEL / BT		1 PC	35.00	
39 AIR CON CONDENSER / BT		1 PC	450.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahliminc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 04/05/2018

Estimate No: MC0913066

Date: 05 May 2018

Policy No: GA015886

Veh Reg No: SGK5613H

Make/Model: TOYOTA WISH 1.8 A

Estimate Repair Cost to Vehicle No :SGK5613H

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 AIR CON CONDENSER PIPE (FROM COND TO COMP) ?		1 PC	120.00	
41 AIR CON CONDENSER PIPE (FROM COND TO VALVE) ?		1 PC	200.00	
42 AIR CON CONDENSER PIPE (FROM COMP TO VALVE) ?		1 PC	170.00	
43 RADIATOR ASSY / BT		1 PC	450.00	
44 RADIATOR FAN MOTOR ?		1 PC	100.00	
45 RADIATOR FAN BLADE ?		1 PC	45.00	
46 RADIATOR FAN COWLING		1 PC	68.00	
47 RADIATOR AIR GUIDE LH		1 PC	30.00	
48 RADIATOR AIR GUIDE RH		1 PC	30.00	
49 RADIATOR SPARE TANK		1 PC	70.00	
50 RADIATOR TOP BRACKET LH		1 PC	18.00	
51 RADIATOR TOP BRACKET RH		1 PC	18.00	
52 RADIATOR TOP BUSH LH		1 PC	12.00	
53 RADIATOR TOP BUSH RH		1 PC	12.00	
54 RADIATOR BOTTOM BUSH LH		1 PC	15.00	
55 RADIATOR BOTTOM BUSH RH		1 PC	15.00	
56 RADIATOR TOP HOSE / Tui		1 PC	25.00	
57 RADIATOR BOTTOM HOSE ?		1 PC	28.00	
58 HORN X 2 ?		2 PC	70.00	
59 AIR FILTER BOX ASSY ?		1 PC	250.00	
60 AIR DUCT ?		1 PC	55.00	
61 FUSE RELAY BOX HOUSING TOP ?		1 PC	70.00	
62 FUSE RELAY BOX HOUSING BOTTOM ?		1 PC	80.00	
63 BATTERY TRAY ?		1 PC	50.00	
64 BATTERY TOP BRACKET X		1 PC	45.00	
65 BATTERY ROD X 2 X		2 PC	50.00	
66 INTAKE FAN FOLD ?		1 PC	320.00	
67 ENGINE MOUNTNG FRONT ?		1 PC	45.00	
68 ENGINE MOUNTING RH ?		1 PC	75.00	
69 ENGINE MOUNTING REAR ?		1 PC	70.00	
70 GEARBOX MOUNTING LH ?		1 PC	80.00	
71 ABS PUMP X NN		1 PC	1,600.00	

6,739.40

Special Nett

72 COOLANT / MCL	1 PC	30.00
73 BATTERY / Om	1 PC	180.00
74 NUMBER PLATE / Cut	1 PC	35.00
75 BRAKE OIL X NN	1 PC	30.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage

Accident Date: 04/05/2018

Estimate No: MC0913066

Date: 05 May 2018

Policy No: GA015886

Veh Reg No: SGK5613H

Make/Model: TOYOTA WISH 1.8 A

Estimate Repair Cost to Vehicle No :SGK5613H

Description	U/Price	Quantity	Cost S\$	Amount S\$
LABOUR				
76 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	40
77 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	/
78 TO REPLACE INTAKE MANIFOLD		1 PC	80.00	?
79 TO REMOVE & REPLACE ENGINE MOUNTING & GEAR BOX MOUNTING		1 PC	120.00	?
80 TO REPLACE ABS PUMP		1 PC	180.00	X
81 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	280.00	X \$NN
82 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,600.00	1200
83 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR LH & RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH, FRONT DOOR PILLAR LH		1 PC	1,600.00	1200

4,000.00

Excess \$750

Authorised

80 Days

part by part / before paint photos

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND SEVEN HUNDRED EIGHTY FIVE AND CENTS FORTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

Can Q: ang - 82880282

09/5/18.

Amount Before Excess S\$ 11,014.40

Add GST @ 7% 771.01

Total Amount to be paid S\$ 11,785.41

the surveyor of the following:

- Surveyed before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: AUTHORISED SIGNATURE