



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlime@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S8M006AA

Claim Type: Own Damage/Third Party

Accident Date: 07/05/2018

Estimate No: MC0913075

Date: 08 May 2018

Policy No: GA242377

Veh Reg No: SJS2845Y

Make/Model: TOYOTA VIOS E AUTO

Estimate Repair Cost to Vehicle No :SJS2845Y

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 HEADLAMP LH - Cut		1 PC	130.00	
2 FRONT BUMPER - Re		1 PC	140.00	
3 FRONT BUMPER SIDE RETAINER LH = 1/2 MC		1 PC	22.00	
4 FRONT BUMPER SIDE RETAINER RH = 1/2 MC		1 PC	22.00	
5 FRONT BUMPER CLIPS X 15 = 1/2 MC		15 PC	15.00	
6 FRONT BUMPER EMBLEM = 1/2 MC		1 PC	25.00	
7 FRONT BUMPER LOWER SPOILER - CHECK PRICE X Repair		1 PC	0.0000	
8 FRONT BUMPER BEAM ?		1 PC	105.00	
9 FOGLAMP LH X NN		1 PC	95.00	
10 FRONT FENDER LH - Bul		1 PC	120.00	
11 FRONT FENDER COWLING LH ?		1 PC	40.00	
12 FRONT FENDER COWLING CLIPS X 8 - MC		8 PC	8.00	
13 FRONT FENDER COWLING RH ?		1 PC	40.00	
14 FRONT FENDER COWLING CLIPS X 8 ?		8 PC	8.00	
15 FRONT FENDER VVT-I LOGO LH - MC		1 PC	10.00	
16 SIDE MIRROR ARM LH - BR		1 PC	220.00	
17 SIDE MIRROR COVER LH - mis		1 PC	28.00	
18 FRONT DOOR PROTECTOR LH - MC		1 PC	35.00	
				1,063.00

Special Nett

19 TYRE LHF - CHECK PRICE - car	1 PC	0.0000	(- 50%)
20 SPORT RIM LHF - CHECK PRICE - Cut	1 PC	0.0000	

0.00

LABOUR

21 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	30
22 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60
23 TO REMOVE AND REPLACE SIDE MIRROR LH	1 PC	80.00	40
24 TO DISMANTLE ALL DAMAGED PARTS, TO KNOCK & REPAIR FRONT DOOR LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	400
25 TO SPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, FRONT FENDER LH, FRONT DOOR LH	1 PC	800.00	600



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO.06470300B

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Own Damage/Third Party

Accident Date: 07/05/2018

Estimate No: MC0913075

Date: 08 May 2018

Policy No: GA242377

Veh Reg No: SJS2845Y

Make/Model: TOYOTA VIOS E AUTO

Estimate Repair Cost to Vehicle No :SJS2845Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
				1,600.00

Amount Before Excess S\$ 2,663.00

Add GST @ 7% 186.41

Total Amount payable S\$ 2,849.41

TOTAL: SINGAPORE DOLLAR TWO THOUSAND EIGHT HUNDRED FORTY NINE AND CENTS FORTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

5 Days .

part by part .

before paint photos .

Guo Qiang - 82880282

09/5/18.

Authorized

Excess \$300 .

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
6483 1244 / 6483 6170
AUTHORISED SIGNATURE

CHK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage - part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: