



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 TOYOTA VIOS 1.5 (SJS2845Y)

Date of Loss

7 May 2018

Time of Loss

10.45

Loss Description

SJS2845Y (INSD) C/W FY9524T (TP)

Comment

Workshop Details

Total Rebate Amount

8767

Nett Loss Amount

\$5,233.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

30/07/2018



Days of work completion *

80



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJS2845Y

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

07/08/2009



Mileage

269273

Age of Vehicle

8

Driver Details

CATEGORY

Manufacturing Year

CATEGORY

Driver Name

POLICY INFORMAT... 2009

FNOL INFORMATI...

LEOW BOON HONG

ASSESSMENT INFO...

2009

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... VIOS 1.5

ASSESSMENT INFO... VIOS E AUTO

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO... ▼

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MR053HY9305125431

CATEGORY Date of Birth

FNOL INFORMATI... 24 December 1962

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 55

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 1NZX947164

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 38

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI...183D RIVERVALE CRESCENT, #12-213,
544183, Singapore

POST SURVEY INF...

CATEGORYAddress type

FNOL INFORMATI...Residential

POST SURVEY INF...

CATEGORYGender

FNOL INFORMATI...Male

POST SURVEY INF...

CATEGORYMarital status

FNOL INFORMATI...Married

POST SURVEY INF...

CATEGORYIdentification #

FNOL INFORMATI...S1566397I

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/05/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

300

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/60R15

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

195/60R15

Front left side

FALKEN5mm

Front right side

FALKEN5mm

Rear left side

FALKEN5mm

Rear right side

FALKEN5mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			HEADLAMP LH			Cut	130				130	Reviewing
☐		2	1			FRONT BUMPER			Deformed	140				140	Reviewing
☐		3	1			FRONT BUMPER SIDE RETAINER LH			Necessary	22				22	Reviewing
☐		4	1			FRONT BUMPER SIDE RETAINER RH			Necessary	22				22	Reviewing
☐		5	15			FRONT BUMPER CLIPS X 15			Necessary	1				15	Reviewing
☐		6	1			FRONT BUMPER EMBLEM			Necessary	25				25	Reviewing
☐		7	1			FRONT BUMPER LOWER SPOILER (NPA)			Repair	0	0	0	0	0	Deny
☐		8	1			FRONT BUMPER BEAM			Serviceable	0	0	0	0	0	Deny
☐		9	1			FOGLAMP LH			Serviceable	0	0	0	0	0	Deny
☐		10	1			FRONT FENDER LH			Buckled	120				120	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		11	1			FRONT FENDER COWLING LH			Serviceable	0	0	0	0	0	Deny
		12	8			FRONT FENDER COWLING CLIPS X 8			Necessary	1				8	Reviewing
		13	1			FRONT FENDER COWLING RH			Serviceable	0	0	0	0	0	Deny
		14	8			FRONT FENDER COWLING CLIPS X 8			Serviceable	0	0	0	0	0	Deny
		15	1			FRONT FENDER VVT-I LOGO LH			Serviceable	0	0	0	0	0	Deny
		16	1			SIDE MIRROR ARM LH			Broken	220				220	Reviewing
		17	1			SIDE MIRROR COVER LH			Missing	28				28	Reviewing
		18	1			FRONT DOOR PROTECTOR LH			Necessary	35				35	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	30	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVI
		2		TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	60	0	0	Reviewing		
		3		TO REMOVE AND REPLACE SIDE MIRROR LH	40	0	0	Reviewing		
		4		TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR FRONT DOOR LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	400	0	0	Reviewing		
		5		TO SPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,FRONT FENDER LH, FRONT DOOR LH	600	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		DAYS OF REPAIR : 5 DAYS	Reviewing			
☐	2	TYRE LHF (NPA)	Deny	0	NOT NECESSARY	
☐	3	SPORT RIM LHF	Reviewing	150	CUT	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary	
Claim Amount		\$1,745.00		Claim Amount		\$1,745.00							

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,130.00	\$1,130.00
Miscellaneous	\$150.00	\$150.00
Excess	-\$300.00	-\$300.00

Submit for Review