

ASS. REC. BY:

REP:

CS/AG118008541/BAH

Special Instruction:

Surveyor

Action.

ASSIGNMENT (Office)

From (Person): Albert Hong of AG1 Date/Time: 9/5/2018

Estimated Cost: _____ Bill to: _____

GD / TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLC1121U Insured: 85W 2322Tat Workshop n/s Sam Yick Han Tel: 6744 1373of 1 Kaki Bukit Ave 6 #01-70Policy No: _____ Claim No: C10001587

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/5/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLC1121U-X</u>
	<u>85W 2322T-X.</u>
	<u>lump sum \$7500 (Red: 10435.72 : 58%)</u>

REF: AGL

ASSIGNMENT

From:

Date:

10052018.

Veh No:

SLC121U.

Yr Regn:

2016 April

Estimated Cost:

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

SLC 121U

Make:

Mazda 3

cc

1496.

at Workshop n/s

Sam Yick Lian

Colour:

Red.

A/C: Insured / Std / NI / NA

of

1 Kaki Bukit Ave 6 # 01-70

Sp. Reading

68/85

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

JM6BM42A8E0341053

Policy No:

C/No:

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size:

F: 205/60R16-

R: 205/60R16.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

06

mm

R/Bal.

06

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

06

mm

L/Bal.

06

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I.

10/05/18

Lump Sum:

%

3 Val: Yes or No

Survey held at

Sam Yick Lian.

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget Direct.

RECEIVED 1-2 JUL 2018

Date/Time: File Pass to?



Prel. Report

12/7 Typist



Final Report

Date/Time: File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

3

Survey Fee:

250

Transportation

1. S + P: \$

2. Prices

3. Other

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Report Format:

TP

Lump Sum / I.B.L: (\$ 7500)

Catherine Chong (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Wednesday, 9 May, 2018 5:14 PM
To: assignments
Cc: SUR
Subject: Appoint LKK to conduct TP survey; Our Ref: C10001587
Attachments: TP PRI.pdf

Hi Team,

Kindly accept survey assignment and liaise with TP workshop.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

*Veh In.
Marcus*

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: soon siew kheng <sskheng@yahoo.com.sg>
Sent: Wednesday, 9 May, 2018 3:30 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: TP PRI - Acc Invlg SLC 1121U & SJW 2322T on 07.05.18

Hi

Reference to the above accident, kindly arrange for PRI of our client's Veh No. SLC 1121U which was damaged due to the negligence of your insured driver of Veh No. SJW 2322T.

Vehicle is now lying in our workshop.

Attached herein our Estimate and necessary documents for your action.

Awaits your prompt attention.

SAM YICK LIAN

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

MSME18059521 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 07/05/2018 17:09
SUBMITTED BY: Chia Pui Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/05/2018 17:09
Date Of Accident 07/05/2018 14:15
Exact Location Of Accident JOO SENG ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLC1121U
Insured/Policyholder
Name Of Registered Owner DING SIEW CHOON ANGELA
NRIC No S1736537A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96711121
Alternative Phone No OFFICE-96711121

Vehicle Particulars

Manufacturer MAZDA
Model 3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number D17MTPV01008789
Cover Note Number

Driver

Name of Driver DING SIEW CHOON ANGELA
NRIC No S1736537A
Date Of Birth 28/06/1966
Occupation INDOOR
Date Of Driving Pass 20/10/1993
Driving Experience 24 YEARS AND 6 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-96711121
Fax Number
Contact Number OFFICE-96711121
Email Address NOEMAIL

Address	BLK 121 PASIR RIS ST 11 #05-469
Postcode	510121
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING AONG 132 JOO SENG ROAD. I WAS ABOUT TO TURN LEFT INTO MY OFFICE. VEHICLE B TRY TO OVERTAKE MY VEHICLE FROM LEFT AND HIT ONTO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW2322T
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to invalidate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (All insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

132

WAS DRIVING ALONG JOO SENG RI, I WAS ABOUT TO TURN
LEFT INTO MY OFFICE UTILITY B TRY TO OVERTAKE MY
VEHICLE FROM LEFT AND HIT ONTO MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SAM YICK LIAN

1 Kaki Bukit Ave 6,
#01-70 Autobay@Kaki Bukit
Singapore 417883
Tel: 67441373. Fax: 67417138
Reg No: 01939300L

M/s Auto & General Insurance (Singapore) Pte Ltd
Singapore Shopping Centre
190 Clemenceau Avenue #03-01
Singapore 239924
Tel: 62212111
Fax: 67250611
Email: claims@budgetdirect.com.sg

ESTIMATE

Date : 08.05.18
Veh No : SLC 1121U
Make/Model : Mazda 3
Chassis No :
Acc Date : 07.05.18
Your Ref : SJW 2322T

S/No.	Qty	Particular	Unit Price	Amount
MATERIALS				
1	1	Bonnet <i>Buckled</i>		\$ 1,142.00 ✓
2	1	Bonnet Rubber, Outer <i>Zone A</i>		\$ 27.70 ✓
3	1	Bonnet Rubber, Inner		\$ 45.90 ✓
4	2	Headlamp L/R <i>LH cracked</i>	\$ 2,402.00	\$ 4,804.00 <i>2402</i>
5	1	Frt Grille		\$ 622.00 ✓
6	1	Frt Grille Top apron <i>Zone A</i>		\$ 358.45 ✓
7	1	Frt Grille Chrome		\$ 188.90 ✓
8	1	Frt Grille Badge		\$ 47.30 ✓
9	1	Frt Bumper <i>Distorted</i>		\$ 1,103.90 ✓
10	10	Frt Bumper Clips <i>new</i>	\$ 3.00	\$ 30.00 ✓
11	6	Frt Bumper Rivets <i>new</i>	\$ 8.70	\$ 52.20 ✓
12	1	Frt Bumper Sensor <i>new</i>		\$ 320.00 <i>200</i>
13	1	Frt Bumper Wiper Motor <i>new</i>		\$ 259.30 ✓
14	1	Frt Bumper Wiper Nozzle Cover <i>Missing</i>		\$ 29.90 ✓
15	1	Frt Bumper Reinforcement <i>Best</i>		\$ 475.60 ✓
16	1	Frt Bumper Side Bracket LH <i>new</i>		\$ 16.10 ✓
17	1	Frt Bumper Sport Light LH <i>new</i>		\$ 727.60 ✓
18	1	Frt Bumper Sport Light Cover LH <i>new</i>		\$ 49.60 ✓
19	1	Frt Bumper Signal Lamp LH <i>new</i>		\$ 167.90 ✓
20	1	Frt Fender LH <i>Distorted</i>		\$ 357.20 ✓
21	1	Frt Fender Liner LH <i>new</i>		\$ 138.30 ✓
22	10	Frt Fender Liner Clips <i>new</i>	2.8	\$ 28.00 ✓
23	1	Frt Road Rim LH <i>new</i>		\$ 1,080.00 <i>680 (new)</i>
24	1	Frt Shock Absorber LH <i>Best</i>		\$ 367.60 ✓
25	1	Frt Absorber Top Mounting LH <i>new</i>		\$ 98.30 ✓
26	1	Frt Absorber Sponge LH <i>new</i>		\$ 47.10 ✓
27	1	Frt Absorber Bearing LH <i>new</i>		\$ 56.80 ✓
28	1	Frt Knuckle Arm LH <i>Best</i>		\$ 410.20 ✓
29	1	Frt Wheel Hub LH <i>new</i>	8219.90	\$ 679.60 <i>35030</i>
30	1	Frt Wheel Shaft LH <i>new</i>		\$ 1,429.10 ✓
31	1	Frt Lower Arm LH <i>Best</i>		\$ 518.60 <i>484.70</i>
32	1	Frt Anti Roll Bar Linkage <i>new</i>		\$ 69.20 ✓
33	1	Steering Rack & Pinion <i>new</i>		\$ 826.20 ✓
34	1	Steering Linkage LH <i>new</i>		\$ 126.70 ✓
35	1	Steering Bsl Joint LH <i>new</i>		\$ 152.10 ✓
36	1	Steering Cross Member <i>new</i>		\$ 1,916.30 ✓
Tyre <i>new</i>				\$ 18,669.65
			Discount 20%	\$ 3,733.93
			Parts Total :	\$ 14,935.72

LABOUR

1	Towing Fees	\$	80.00	60
2	To remove, rearrange electrical wirings.	\$	80.00	30
3	To remove, replace frt suspension undercarriage parts.	\$	480.00	2 320.
4	To reset side slip	\$	60.00	
5	Panel knocking, repair & replace damaged parts.	\$	1,000.00	700
2	To putty and respray painting on affected areas.	\$	1,100.00	700
Labour Total :		\$	3,000.00	

Total Parts & Labour : \$ 17,935.72


for SAM YICK LIAN

Adrian Ling. total 9375.92
h/s 10/05/18. h/s: 7.5K
06 Aug.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

7.5K

SAM YICK LIAN

1 Kaki Bukit Ave 6,
#01-70 Autobay@Kaki Bukit
Singapore 417883
Tel: 67441373. Fax: 67417138
Reg No: 01939300L

M/s **Auto & General Insurance (Singapore) Pte Ltd**
Singapore Shopping Centre
190 Clemenceau Avenue #03-01
Singapore 239924
Tel: 62212111
Fax: 67250611
Email: claims@budgetdirect.com.sg

ESTIMATE

Date : 08.05.18
Veh No : **SLC 1121U**
Make/Model : Mazda 3
Chassis No :
Acc Date : 07.05.18
Your Ref : SJW 2322T

S/No.	Qty	Particular	Unit Price	Amount
MATERIALS				
1	1	Bonnet		\$ 1,142.00
2	1	Bonnet Rubber, Outer		\$ 27.70
3	1	Bonnet Rubber, Inner		\$ 45.90
4	2	Headlamp L/R	\$ 2,402.00	\$ 4,804.00
5	1	Frt Grille		\$ 622.00
6	1	Frt Grille Top apron		\$ 358.45
7	1	Frt Grille Chrome		\$ 188.90
8	1	Frt Grille Badge		\$ 47.30
9	1	Frt Bumper		\$ 1,103.90
10	10	Frt Bumper Clips	\$ 3.00	\$ 30.00
11	6	Frt Bumper Rivets	\$ 8.70	\$ 52.20
12	1	Frt Bumper Sensor		\$ 320.00
13	1	Frt Bumper Wiper Motor		\$ 259.30
14	1	Frt Bumper Wiper Nozzle Cover		\$ 29.90
15	1	Frt Bumper Reinforcement		\$ 475.60
16	1	Frt Bumper Side Bracket LH		\$ 16.10
17	1	Frt Bumper Sport Light LH		\$ 727.60
18	1	Frt Bumper Sport Light Cover LH		\$ 49.60
19	1	Frt Bumper Signal Lamp LH		\$ 167.90
20	1	Frt Fender LH		\$ 357.20
21	1	Frt Fender Liner LH		\$ 138.30
22	10	Frt Fender Liner Clips	2.8	\$ 28.00
23	1	Frt Road Rim LH		\$ 1,080.00
24	1	Frt Shock Absorber LH		\$ 367.60
25	1	Frt Absorber Top Mounting LH		\$ 98.30
26	1	Frt Absorber Sponge LH		\$ 47.10
27	1	Frt Absorber Bearing LH		\$ 56.80
28	1	Frt Knuckle Arm LH		\$ 410.20
29	1	Frt Wheel Hub LH		\$ 579.60
30	1	Frt Wheel Shaft LH		\$ 1,429.10
31	1	Frt Lower Arm LH		\$ 518.60
32	1	Frt Anti Roll Bar Linkage		\$ 69.20
33	1	Steering Rack & Pinion		\$ 826.20
34	1	Steering Linkage LH		\$ 126.70
35	1	Steering Bsl Joint LH		\$ 152.10
36	1	Steering Cross Member		\$ 1,916.30
				\$ 18,669.65
Discount 20%				\$ 3,733.93
Parts Total :				\$ 14,935.72



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI18008541/Atbq2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 19-07-2018	
			Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 2322T	Veh. Inspected	SLC 1121U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001587	Excess (\$)	0.00	
Assign From	ALBERT HONG	Assign Date	09/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0341053	Colour	RED	
Odometer	68185	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2018	Inspection Date	10/05/2018	
Survey held at	SAM YICK LIAN 1, KAKI BUKIT AVE 6 #01-70 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1121U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	1,142.00	1,142.00
1	BONNET RUBBER ,OUTER	NOT NECESSARY	27.70	-
1	BONNET RUBBER ,INNER	NOT NECESSARY	45.90	-
2	HEADLAMP L/R @\$2402.00	N/S CRACKED	4,804.00	2,402.00
1	FRT GRILLE	NOT NECESSARY	622.00	-
1	FRT GRILLE TOP APRON	NOT NECESSARY	358.45	-
1	FRT GRILLE CHROME	NOT NECESSARY	188.90	-
1	FRT GRILLE BADGE	NOT NECESSARY	47.30	-
1	FRT BUMPER	DISTORTED	1,103.90	1,103.90
10	FRT BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
6	FRT BUMPER RIVETS @\$8.70	NECESSARY	52.20	52.20
1	FRT BUMPER SENSOR	DAMAGED	320.00	200.00
1	FRT BUMPER WIPER MOTOR	DAMAGED	259.30	259.30
1	FRT BUMPER WIPER NOZZLE COVER	MISSING	29.90	29.90
1	FRT BUMPER REINFORCEMENT	BENT	475.60	475.60
1	FRT BUMPER SIDE BRACKET LH	NECESSARY	16.10	16.10
1	FRT BUMPER SPORT LIGHT LH	NOT NECESSARY	727.60	-
1	FRT BUMPER SPORT LIGHT COVER LH	CUT	49.60	49.60
1	FRT BUMPER SIGNAL LAMP LH	CRACKED	167.90	167.90
1	FRT FENDER LH	DISTORTED	357.20	357.20
1	FRT FENDER LINER LH	DEFORMED	138.30	138.30
10	FRT FENDER LINER CLIPS @\$2.80	NECESSARY	28.00	28.00
1	FRT SHOCK ABSORBER LH	BENT	367.60	367.60
1	FRT ABSORBER TOP MOUNTING LH	DAMAGED	98.30	98.30
1	FRT ABSORBER SPONGE LH	NOT NECESSARY	47.10	-
1	FRT ABSORBER BEARING LH	NECESSARY	56.80	56.80
1	FRT KNUCKLE ARM LH	BENT	410.20	410.20
1	FRT WHEEL HUB LH	DAMAGED	579.60	350.30
1	FRT WHEEL SHAFT LH	NOT NECESSARY	1,429.10	-
1	FRT LOWER ARM LH	BENT	518.60	484.70
1	FRT ANTEROLL BAR LINKAGE	NOT NECESSARY	69.20	-
1	STEERING RACK & PINION	NOT NECESSARY	826.20	-
1	STEERING LINKAGE LH	NOT NECESSARY	126.70	-
1	STEERING BALL JOINT LH	NOT NECESSARY	152.10	-

Report Ref No. CS/AGI18008541/Atbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING CROSS MEMBER	NOT NECESSARY	1,916.30	-
	LESS 20% DISCOUNT		-3,517.93	-1,643.98
			14,071.72	6,575.92
1	FRT ROAD RIM LH (SN)	CUT	1,080.00	680.00
	LESS 20% DISCOUNT		-216.00	-
			864.00	680.00
	SPECIAL NETT ITEMS			
1	TYRE (SN)	CUT	350.00	250.00
			350.00	250.00
	LABOUR			
	TOWING FEES.		80.00	60.00
	TO REMOVE, REARRARRANGE ELECTRICAL WIRINGS.		80.00	30.00
	TO REMOVE, REPLACE FRT SUSPENSION UNDERCARRIAGE PARTS.		680.00	320.00
	TO RESET SIDE SLIP.		60.00	60.00
	PANEL KNOCKING, REPAIR & REPLACE DAMAGED PARTS.		1,000.00	700.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,100.00	700.00
			3,000.00	1,870.00
	GRAND TOTAL		18,285.72	9,375.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00

Report Ref No. CS/AGI18008541/Atbq2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M,MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or form, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.