

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29760

Your Reference : GA325161
Accident Date : 08-May-2018

Date : 09-May-2018

Our Ref : 180313 / SHUMAN

PAGE : 1

METEORITE LOGISTICS SERVICES PTE LTD
C/O AXA INSURANCE PRIVATE LIMITED
8 SHENTON WAY
#24-01 AXA TOWER
Singapore 068811

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER 2998cc (2016) YP5718A

1 pc	front bumper	- BT	480.00	c
1 pc	front bumper side garnish (lh)	- CAA	200.00	c
1 pc	front bumper side garnish (rh)	- CAA	200.00	c
1 pc	front bumper bracket (lh)	- BT	110.00	c
1 pc	front bumper bracket (rh)	- BT	110.00	c
1 pc	front grille	- cut	495.00	c
1 pc	front grille logo	- MC	45.00	c
1 pc	front grille 'canter' emblem	- MC	55.00	c
10 pcs	front grille clips	- MC @ S\$ 4.50	45.00	c
1 pc	headlamp (lh)	- cut	300.00	c
1 pc	headlamp (rh)	- cut	300.00	c
1 pc	front signal lamp (lh)	- cut	160.00	c
1 pc	front signal lamp (rh)	- cut	160.00	c
2 pcs	front side lamp	LH x NN, RH CAA @ S\$110.00	220.00	c
2 pcs	front corner panel	LH? RH cut @ S\$250.00	500.00	c
1 pc	front panel	- MC	540.00	c
1 pc	front wiper panel garnish	- MC	440.00	c
1 pc	front windscreen glass	- CAA	780.00	c
1 pc	front windscreen glass rubber	- MC	195.00	c
1 pc	n/s wingmirror - big	- mis.	75.00	c
1 pc	o/s wingmirror stay	- BT	190.00	c
1 pc	o/s wingmirror stay cap cover	- cut	18.00	c
1 pc	o/s wingmirror stay inner cover	- mis.	45.00	c
1 pc	front wiper arm (lh)	- cut	265.00	c
1 pc	front wiper arm (rh)	- cut	265.00	c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : GA325161
Our Ref : 180313

Page : 2
No. : 29760

1 pc front wiper blade (lh) — <i>Cut</i>	165.00 c
1 pc front wiper blade (rh) <i>X NN</i>	165.00 c
1 pc air con blower ?	<i>No stock 23005W</i>
1 pc air con cooling coil ?	
1 pc heater unit ?	40.00 sn
1 pc front number plate — <i>BT</i>	26.00 sn
1 pc ERP bracket — <i>MC</i>	

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

800.00 *600*

To remove aircon condenser, pipes and driers. Vaccum and recharge gas

100.00 */*

To remove and renew front wind-screen glass and conduct water leak test.

120.00 *100*

To remove front instrument panel assy and rewiring to facilitate repair works.

300.00 *250*

To putty and respray on affected portions.

900.00 *800*

To focus headlamps. To check front wiring and lighting operation.

50.00

Total : S\$ 8,859.00

=====
11, 159

Singapore Dollars Eight Thousand Eight Hundred and Fifty Nine Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Excess \$1900

Authorised

Guo Qiang - 82880282

10/5/18

6 Days.

part by part / before paint photo S.