

ASS. REC. BY:

REF:

CE/MSG18008546/Tlvber

Special Instruction:

Surveyor

Tauflich

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

9/5/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH4888U

Insured:

RTY4667A

at Workshop m/s

Performance Motor

Tel:

63190174 Caroline

of

303 Alexandra Rd

Policy No:

2TSG2673QMY

Claim No:

557790

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/5/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

eds

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time	Action/Instruction ( ) Estimate
	SLH4888U-X
	RTY4667A-X
14/5/18	Send preli revised by merimen
10/10/18	Final fig \$ 16,038.75 confirmed by email (Ref 486640, 237)

Signature

Tanaka

REF:

MS16

ASSIGNMENT

SLH 48884

29

2016 Oct.

From: Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Merina

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216D.

c.c 1496

Colour: white

A/C Insured / Std / NI / NA

Sp. Reading: 47463.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA2B32010V791415.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

205/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

10/5/180/pw

Survey held at

PMI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 OCT 2018

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

10/10- typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS St

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week-end (\$

Report Format:

merimen

Lump Sum / I.B.I: (\$ 16,038.75

TOTAL

200

10

210

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2018		09 May 2018 16:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHAN KOK WENG WYMAN, ID: S7339046Z		
Main Claimant:	ANG WEI TIONG RONALD, ID: S7715606B		
Vehicle Reg. No.:	SLH4888U	Date of Loss:	08/05/2018 00:00 - :59 [18 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 557790	Policy/Cover Note No.:	27562673QMY Coverage: 03/09/2017 - 02/09/2018
Vehicle Reg. No. (Insured):	SJY4667A	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/05/2018]		
Adj Asg. Remarks:	TP agree to use LKK. Non Reporting Case. Chain Collission, OI is the centre vehicle. Under Bola, we are liable.		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 14 May 2018

**Preliminary Advice**

Insured Vehicle No	: SJY4667A		
TP Vehicle No	: SLH4888U	Accident Date	: 08/05/2018
Make	: BMW 216D	Assignment Date	: 09/05/2018
Date of Inspection	: 14/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,299.85
Revised Amount	:S\$	6,662.90
Check Items (Estimated)	:S\$	7,390.25
Total	:S\$	14,053.15

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/05/2018 15:31
Date Of Accident	08/05/2018 11:25
Exact Location Of Accident	MOULMEIN FLYOVER TWDS CTE (CITY)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH4888U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ANG WEI TIONG RONALD
NRIC No	S7715606B
Email Address	RONALD.ANG@INCOME.COM.SG
Mobile Phone No	(LOCAL) +65-96911141
Alternative Phone No	OTHERS-98893141

### Vehicle Particulars

Manufacturer	BMW
Model	216D-1.5 D ACTIVE TOURER (F45) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095356296
Cover Note Number	27/10/2017 - 26/10/2018

### Driver

Name of Driver	NEO LI TING
NRIC No	S8828895E
Date Of Birth	21/07/1988
Occupation	INDOOR
Date Of Driving Pass	16/12/2008
Driving Experience	9 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98893141
Fax Number	
Contact Number	
EMail Address	NEO_LITING@HOTMAIL.COM

Address	BLK 138C YUAN CHING ROAD #14-147
Postcode	613138
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY VEHICLE WAS TRAVELLING ALONG THE RIGHT LANE OF MOULMEIN FLYOVER TOWARDS CTE(CITY). TRAFFIC WAS MODERATE. VEHICLES INFRONT STOPPED AND I STOPPED IN TIME. A FEW SECONDS LATER, I FELT AN IMPACT ON MY VEHICLE REAR PORTION AND VEHICLE B HAD HIT ONTO MY VEHICLE. I FELT TWO IMPACTS FROM MY VEHICLE REAR. UPON ALIGHT, IT WAS A CHAIN COLLISION INVOLVING THREE VEHICLES. NO ONE WAS INJURED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJY4667A
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	FRONT AND REAR PORTIONS
Vehicle Category	PRIVATE CAR
Name of Driver	WYMAN CHAN KOK WENG
NRIC/Passport Number	S7339046Z
Contact Number	92298982
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKW4687R
Vehicle Make/Model/Colour	PEUGEOT
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	MUKHTIAR KHAN S/O ALI HASSAN
NRIC/Passport Number	S1326008G
Contact Number	96783510
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

## Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No. M1

D.O.A.

Vehicle No.

Make Model

Report Date: 5/8/2018 Start Time: 4:02 PM

Reporting Type: TP

End Time:


### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, law or court orders.

  
 Policyholder's Signature  
 Date & Time: 5/8/2018 15:59

  
 Driver's Signature (If driver is not the policyholder)  
 Date & Time: 5/8/2018 15:59

  
 Reporting Centre Personnel's Signature  
 Name: Chen JunLiang  
 NRIC/ Fin No: S990765



## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180

Tel. 63190888 (AfterSales)  
Fax 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

09 MAY 2018

Estimate No. : b1 46874  
Date Estimated : 09/05/2018  
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -  
Ang Wei Tiong Ronald (Weng Weizhong  
138C Yuan Ching Road  
#14-147

Singapore 613138

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH4888U	V791415	27/10/2016	216d AT	0

## DESCRIPTION

To replace rear bumper, bootlid including attachments etc and to knock out dented area caused by accident

	VALUE
✓ 1700	2,550.00

To paint rear bumper and bootlid

✓ 1730 1,923.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

✓ 230. 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

✓ 150. 177.00

To carry out body cavity preservation.  
(Per panel).

✓	100	118.00
---	-----	--------

To replace rear exhaust silencer including alignment system and conduct checks for leak.

✓ 4517 photo 531.00

Sundries. *NM*

✓? 150.00

Total Labour 1:	<u>5,720.00</u>
-----------------	-----------------

## DESCRIPTION

Screw  
EXCHANGE EXHAUST PIPE CATALYST  
REAR SILENCER  
TAILPIPE TRIM CHROME  
TRUNK LID  
TRUNK LID RH HINGE  
REAR BUMPER PANEL PRIMED (PDC)  
RR BUMPER LH SIDE GUIDE  
RR BUMPER RH SIDE GUIDE  
REAR BUMPER CARRIER  
SUPPORT  
RR BUMPER LH INNER SIDE GUIDE  
RR BUMPER RH INNER SIDE GUIDE

QTY	PRICE
3	0.75
1	1,849.15
1	1,167.45
1	107.85
1	1,174.95
1	75.90
1	966.25
1	47.85
1	47.85
1	423.80
1	37.35
1	58.55
1	58.55

	VALUE
bt	2.25
bt	1,849.15
bt	1,167.45
act	107.85
bt	1,174.95
Re	75.90
del	966.25
?	47.85
?	47.85
?	423.80
me	37.35
he	58.55
de	58.55

[illegible]

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 46874  
Date Estimated : 09/05/2018  
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH4888U	V791415	27/10/2016	216d AT	0

DESCRIPTION	QTY	PRIC	VALUE
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	69.50	69.50
SPINDLE DRIVE	2	307.35	614.70
STRIKER BOOT LID	1	55.75	55.75
LOCK TRUNK LID	1	189.10	189.10
ACTUATION UNIT	1	586.65	586.65
REAR FLAP TOWING EYE PRIMED	1	41.80	41.80
REAR WINDOW ESG	1	632.25	632.25
TRUNK LID SEALING	1	97.85	97.85
THIRD STOPLAMP	1	176.70	176.70
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
ULTRASONIC SENSOR ALPINWEISS (U300)	2	380.65	761.30
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

Total Parts : 9,579.85

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date 10/5/18 pm Excess \$ \_\_\_\_\_

Surveyor's Name Tanfua Sign \_\_\_\_\_

Surveyor's Tel 97495149 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_

Surveyor's E-mail tanfua@meant.com

No. of Working Days Recommend 5 days

*Signature*  
30/5/18

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour 1	:	5,720.00
Parts	:	9,579.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,070.99
Grand Total	:	16,370.84

20,905.15

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : **b1 46874**  
Date Estimated : **09/05/2018**  
Prepared By : **Merina Chia San San**

Page No. :

### REPAIR FOR -

**Ang Wei Tiong Ronald (Weng Weizhong**  
**138C Yuan Ching Road**  
**#14-147**

**Singapore 613138**

### - ACCOUNT - 66

**MSIG Insurance (S) Pte Ltd**  
**4 Shenton Way**  
**#21-01 SGX Centre 2**  
**Singapore 068807**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH4888U	V791415	27/10/2016	216d AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, trunk lid and attachments include knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint rear bumper and bootlid	1730.00		1,730.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
* To replace rear exhaust silencer including alignment system and conducting checks for leak	451.00		451.00	
# To replace exch diesel particulate filter EU5 include alignment and conducting checks for leak	664.00		664.00	} (A)
# To replace boot lid smart opener control unit include programming and conducting checks for proper function	661.00		661.00	
# To conduct water leak tests	75.00		75.00	
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.90	4.00		11.60
# CLAMPING BUSH *	54.30	1.00		54.30
# V BAND CLAMP *	41.80	1.00		41.80
# GASKET *	8.25	1.00		8.25
EXCHANGE EXHAUST PIPE CATALYST	1,849.15	1.00		1,849.15
REAR SILENCER	1,167.45	1.00		1,167.45
# EXCH DIESEL PARTICULATE FILTER EU5 *	3,550.20	1.00		3,550.20
# HOLDER EXHAUST SYSTEM *	27.20	1.00		27.20

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

TAILPIPE TRIM CHROME	107.85	1.00	107.85
TRUNK LID	1,174.95	1.00	1,174.95
REAR BUMPER PANEL PRIMED (PDC)	966.25	1.00	966.25
SUPPORT	37.35	1.00	37.35
RR BUMPER LH INNER SIDE GUIDE	58.55	1.00	58.55
RR BUMPER RH INNER SIDE GUIDE	58.55	1.00	58.55
# EMBLEM GROMMET *	0.80	2.00	1.60
PLAQUE 74MM	69.50	1.00	69.50
# BUMP STOP *	3.25	10.00	32.50
TRUNK LID SEALING	97.85	1.00	97.85
# PLUG BLACK D=5MM *	0.90	10.00	9.00
# CONTROL UNIT SMART OPENER *	468.85	1.00	468.85
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00	20.20
(DG) CLEANER R1 (100ML)	23.85	1.00	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85

### # SUPPLEMENTARY ITEMS

Total Labour :	5,911.00
Total Parts :	10,127.75
Total Labour & Parts :	16,038.75
Deduction for Excess :	0.00
Total Repair Costs less Excess:	16,038.75
GST @7%:	1,122.71
Grand Total :	17,161.46

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 46874  
Date Estimated : 09/05/2018  
Prepared By : Merina Chia San San

Page No. :

**REPAIR FOR -**  
**Ang Wei Tiong Ronald (Weng Weizhong**  
**138C Yuan Ching Road**  
**#14-147**

**- ACCOUNT - 66**  
**MSIG Insurance (S) Pte Ltd**  
**4 Shenton Way**  
**#21-01 SGX Centre 2**  
**Singapore 068807**

**Singapore 613138**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH4888U	V791415	27/10/2016	216d AT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To replace exch diesel particulate filter EU5 include alignment and conducting checks for leak	664.00		664.00	
# To replace boot lid smart opener control unit include programming and conducting checks for proper function	661.00		661.00	
# To conduct water leak tests	75.00		75.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.90	4.00		11.60 <i>new</i>
# CLAMPING BUSH *	54.30	1.00		54.30 <i>new</i>
# V BAND CLAMP *	41.80	1.00		41.80 <i>dis</i>
# GASKET *	8.25	1.00		8.25 <i>new</i>
# EXCH DIESEL PARTICULATE FILTER EU5 *	3,550.20	1.00		3,550.20 <i>new</i>
# HOLDER EXHAUST SYSTEM *	27.20	1.00		27.20 <i>new</i>
# EMBLEM GROMMET *	0.80	2.00		1.60 <i>new</i>
# BUMP STOP *	3.25	10.00		32.50 <i>new</i>
# PLUG BLACK D=5MM *	0.90	10.00		9.00 <i>new</i>
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85 <i>new</i>

Total Labour : 1,400.00  
Total Parts : 4,205.30  
Total Labour & Parts : 5,605.30



## FACSIMILE MESSAGE

(INCLUSIVE OF THIS PAGE

TEL NO. \_\_\_\_\_

If this fax is not received in order, please do call us. Thank you.

216

any model

1781115

---

Supplementary Parts to be replaced:	Price (nett)
Labour :	
1) To replace boot cial smart opener control unit and top of button sensor (inc include programming and check for proper function	\$ 661.00
2) To replace diesel particulate filter incold alignment	\$ 664.00
Parts	
1) Control unit smart	\$ 466.85
2) Brmp stop x 10	\$ 32.50
3) Support	\$ 9.00
4)	\$ 3550.20
kindly revert :	

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 10 October 2018 2:43 PM  
**To:** 'Keith Leo Chi Yung'; Taufikh (LKKAUTO); PBSP  
**Cc:** SUR  
**Subject:** RE: RESEND: FINAL REPORT / SLH4888U

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$16,038.75 before GST @ 5 working days.

**Kindly send Final invoice and all supporting documents to MSIG**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>  
**Sent:** Thursday, 4 October 2018 10:56 AM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; PBSP <pml-pbsp@sime-darby.com.sg>  
**Cc:** SUR <sur@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** RE: RESEND: FINAL REPORT / SLH4888U

Warm Regards

Keith Leo  
Body & Paint  
DDI: 6319 0172  
FAX: 6479 4601



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising

from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

---

**From:** Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]  
**Sent:** Thursday, 04 October, 2018 10:43 AM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>  
**Cc:** 'SUR' <sur@lkkauto.com>; 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>  
**Subject:** RE: RESEND: FINAL REPORT / SLH4888U

Hi Keith,

Can forward the resurvey photos for the check and supplementary items?

Thank you.

Regards  
Taufikh  
Lkk Auto

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Tuesday, 18 September 2018 12:40 PM  
**To:** PBSP; Keith Leo Chi Yung  
**Cc:** SUR; Taufikh (LKKAuto)  
**Subject:** FW: RESEND: FINAL REPORT / SLH4888U

Dear Keith,

Please forward us check items and supplementary photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 13 September 2018 4:38 PM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** FW: RESEND: FINAL REPORT / SLH4888U

Dear Keith,

Please forward us check items and supplementary photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315



**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Wednesday, 12 September 2018 4:22 PM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RESEND: FINAL REPORT / SLH4888U

Dear Sirs

Resending to include supplementary attachment.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** PBSP  
**Sent:** Wednesday, 12 September 2018 4:20 PM  
**To:** [taufikh@lkkauto.com](mailto:taufikh@lkkauto.com); SUR  
**Subject:** FINAL REPORT / SLH4888U

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 5,911.00  
Total Parts : 10,127.75  
Total Labour & Parts : 16,038.75

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2018		09 May 2018 16:31 <a href="#">Edit Adj Rpt</a>	<b>S\$16,038.75</b> <a href="#">Edit Estimates</a>	<b>S\$16,038.75</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured: <b>CHAN KOK WENG WYMAN</b> , ID: S7339046Z									
Main Claimant: <b>ANG WEI TIONG RONALD</b> , ID: S7715606B									
Vehicle Reg. No.: <b>SLH4888U</b>		Date of Loss: 08/05/2018 00:00 - :59 <b>[18 Months and 11 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / 557790</b>		Policy/Cover Note No.: 27562673QMY Coverage: 03/09/2017 - 02/09/2018							
Vehicle Reg. No. (Insured): <b>SJY4667A</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 08/06/2018]</b>									
Adj Asg. Remarks: TP agree to use LKK. Non Reporting Case. Chain Collision, OI is the centre vehicle. Under Bola, we are liable.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLH4888U (557790)  
[SJY4667A]  
TP  
ANG WEI TIONG RONALD  
May 8 2018 12:00AM  
[CHAN KOK WENG WYMAN]  
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	14/05/18 08:43	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
2	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
3	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
4	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
5	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
6	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
7	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
8	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
9	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
10	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
11	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
12	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
13	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
14	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
15	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
16	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
17	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
18	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
19	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
20	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
21	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
22	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
23	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
24	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
25	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
26	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
27	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
28	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
29	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
30	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
31	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
32	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
33	14/05/18 08:44	General View						Load JPG	<input checked="" type="checkbox"/>	
34	14/05/18 08:44	General View						Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	14/05/18 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/05/18 08:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/10/18 14:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/05/18 12:50	Email frm TP - PRI	 Load PDF	
2	09/05/18 12:53	Estimate	 Load PDF	
3	09/05/18 12:56	SLH4888U GIA Rpt	 Load PDF	
4	09/05/18 14:50	Email to TP our SJE list & TP agree to use LKK	 Load PDF	
5	09/05/18 15:42	TP Vehicle photo 1	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	09/05/18 15:42	TP Vehicle photo 2		Load JPG	<input checked="" type="checkbox"/>
7	09/05/18 15:42	TP Vehicle photo 3		Load JPG	<input checked="" type="checkbox"/>
8	09/05/18 15:42	TP Vehicle photo 4		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/10/18 14:27	Supplementary		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008546/T1VBE2

Date: 22/10/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27562673QMY

Claimant Vehicle  
No: SLH4888U

Insured Vehicle No: SJY4667A

Date of Loss: 08/05/2018

Nature of Claim: TP

Claim No: 557790

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLH4888U

Make &amp; Model: BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A)

Engine No: HIDDEN

Reg. Date: 27/10/2016 (Man. Year: 2016)

Chassis No: WBA2B32010V791415

Colour: White

Odometer: 47463 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R15

Rear Tyre Size: 205/60 R15

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,935.15	10,277.75	3,657.40	26.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,970.00	5,761.00	1,209.00	17.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,905.15</b>	<b>16,038.75</b>	<b>4,866.40</b>	<b>23.28</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,463.36</b>	<b>1,122.71</b>	<b>340.65</b>	<b>23.28</b>
<b>Nett Amount (S\$)</b>	<b>22,368.51</b>	<b>17,161.46</b>	<b>5,207.05</b>	<b>23.28</b>

## INSPECTION

Date of Assignment: 09/05/2018

Date Inspected: 10/05/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2018)
<b>Parts:</b>	M1-MPV	BMW 216D 1.5 D Active Tourer (F45) D/AB LED (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLH4888U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	3		*SCREW	Not Necessary	2.25 FS	*- FS
3	1		*EXCHANGE EXHAUST PIPE CATALYST	Bent	1,849.15 FS	*1,849.15 FS
4	1		*REAR SILENCER	Bent	1,167.45 FS	*1,167.45 FS
5	1		*TAILPIPE TRIM CHROME	Cut	107.85 FS	*107.85 FS
6	1		*TRUNK LID	Bent	1,174.95 FS	*1,174.95 FS
7	1		*TRUNK LID RH HINGE	Repair	75.90 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	966.25 FS	*966.25 FS
9	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	47.85 FS	*- FS
10	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	47.85 FS	*- FS
11	1		*REAR BUMPER CARRIER	Not Necessary	423.80 FS	*- FS
12	1		*SUPPORT	Necessary	37.35 FS	*37.35 FS
13	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	58.55 FS	*58.55 FS
14	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	58.55 FS	*58.55 FS
15	2		*GROMMET	Not Necessary	1.50 FS	*- FS
16	1		*PLAQUE 74MM	Necessary	69.50 FS	*69.50 FS
17	2		*SPINDLE DRIVE	Not Necessary	614.70 FS	*- FS
18	1		*STRIKER BOOT LID	Not Necessary	55.75 FS	*- FS
19	1		*LOCK TRUNK LID	Not Necessary	189.10 FS	*- FS
20	1		*ACTUATION UNIT	Not Necessary	586.65 FS	*- FS
21	1		*REAR FLAP TOWING EYE PRIMED	Repair	41.80 FS	*- FS
22	1		*REAR WINDOW ESG	Not Necessary	632.25 FS	*- FS
23	1		*TRUNK LID SEALING	Necessary	97.85 FS	*97.85 FS
24	1		*THIRD STOPLAMP	Not Necessary	176.70 FS	*- FS
25	4		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
26	2		*ULTRASONIC SENSOR ALPINWEISS (U300)	Not Necessary	761.30 FS	*- FS
27	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
28	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
29	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
30	4		*BLIND RIVET NUT M6	Necessary	11.60 FS	*11.60 FS
31	1		*CLAMPING BUSH	Bent	54.30 FS	*54.30 FS
32	1		*V BAND CLAMP	Distorted	41.80 FS	*41.80 FS
33	1		*GASKET	Necessary	8.25 FS	*8.25 FS
34	1		*EXCH DIESEL PARTICULATE FILTER EU5	Bent	3,550.20 FS	*3,550.20 FS
35	1		*HOLDER EXHAUST SYSTEM	Bent	27.20 FS	*27.20 FS
36	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
37	10		*BUMP STOP	Necessary	32.50 FS	*32.50 FS
38	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
39	1		*CONTROL UNIT SMART OPENER	Cracked	468.85 FS	*468.85 FS

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					13,935.15	10,277.75

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER, BOOTLID INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	2,550.00	1,700.00
2	TO PAINT REAR BUMPER AND BOOTLID	New	1,923.00	1,730.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
6	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
7	TO REPLACE EXCH DIESEL PARTICULATE FILTER EU5 INCLUDE ALIGNMENT AND CONDUCTING CHECKS FOR LEAK	New	664.00	664.00
8	TO REPLACE BOOT LID SMART OPENER CONTROL UNIT INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	661.00	661.00
9	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,970.00</b>	<b>5,761.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >