

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T**AAD1805-066***Not Authorized
21 Pny & 25501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7874T

KL1LA69RJBB106353

CHEVROLET

EPICA 2.0

4.5.2018

CHINA TAIPING**PART****LIST**

1	1	Front Bumper	\$	Sm	1,202.00	}	X
2	1	Front Bumper Lower Absorber	\$	Sm	180.00		
3	1	Front Bumper Reinforcement	\$	N	356.00		
4	1	Front Bumper Retainer RH	\$	Sm	102.00		
5	1	Front Bumper Retainer LH	\$	Sm	102.00		
6	1	Front Bumper Lower Grille	\$	Sm	78.00		
7	1	Front Bumper Lower Stiffener	\$	N	134.37		
8	1	Front Bumper Bracket LH	\$	N	10.00		
9	1	Front Bumper Bracket RH	\$	N	10.00		
10	1	Bumper Fog Lamp Cover RH	\$	Sm	32.40		
11	1	Bumper Fog Lamp Cover LH	\$	Sm	32.40	}	X
12	1	Headlamp LH	\$	Sm	816.00		
13	1	Headlamp LH inner panel	\$	N	611.16		
14	1	Front Fender LH	\$	Not An	837.60		
15	1	Front Fender Liner LH	\$	Sm	47.00		
16	1	Front Fender Inner Wheel House Panel LH	\$	N	1,437.00		
17	1	Front Shock Absorber Assy LH	\$	Sm	216.17		
18	1	Front Shock Absorber Top Mounting LH	\$	Sm	48.32		
19	1	Front Lower Arm LH	\$	Sm	283.00		
20	1	Front Knuckle Arm LH	\$	Sm	230.00		
21	1	Front Door LH	\$	N	1,133.00	}	X
22	1	Front Door Glass Guide RH Chrome Moulding	\$	Sm	60.00		
23	1	Front Door Outer Moulding	\$	Sm	220.00		
24	1	Front Door Outer Handle	\$	Sm	125.00		
25	1	Front Door Handle Support	\$	Sm	3.00		
26	1	Front Door outer handle inner seal	\$	Sm	89.15		
27	1	Front Door outer key lock	\$	Sm	25.00		
28	1	Front Door Hinge Upper	\$	N	65.00		

Trans-cab Auto Services Pte Ltd**AAD1805-066**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T

29	1	Front Door Hinge Lower	\$	R	65.00	}	X
30	1	Front Door inner lock	\$	R	586.00		
31	1	Front Door Inner Lock Latch LH	\$	R	206.00		
32	1	Front Door Check / Arrestor	\$	SL	67.50		
33	1	Front Door Weatherstrip LH	\$	SL	138.79		
34	1	Front Door glass channel weatherstrip	\$	SL	160.00		
35	1	Front Door inner trim board	\$	SL	455.69		
36	1	Front Door window glass	\$	SL	456.12		
37	1	Front Door Power Window Motor (Master) LH	\$	SL	284.97		
38	1	Front Door power window motor switch	\$	SL	145.00		
39	1	Front Door Window Regulator Gear LH	\$	SL	84.58	}	X
40	1	Front Door Outer Pillar Panel LH	\$	R	715.00		
41	1	Front Door Pillar Inner Panel LH	\$	R	850.00		
42	1	Front Door Center Pillar Panel LH	\$	R	698.15		
43	1	Front Side View Mirror Assy LH	\$	Null	1,191.00	}	X
44	1	Rear Door LH (Panel A-RR DR LH)	\$	R	1,133.00		
45	1	Rear door weatherstrip - Inner	\$	SL	41.40		
46	1	Rear door weatherstrip - 2nd Frame	\$	SL	25.90		
47	1	Rear door top hinge	\$	R	35.00		
48	1	Rear door bottom hinge	\$	R	35.00		
49	1	Rear door inner lock	\$	R	425.00		
50	1	Rear door check / arrestor	\$	SL	65.00		
51	1	Rear door lock striker / latch	\$	R	120.00		
52	1	Rear door outer weatherstrip moulding	\$	SL	85.00		
53	1	Side Rocker Panel Garnish LH	\$	SL	236.40	}	X
54	1	Rear Fender LH	\$	R	1,145.00		
55	1	Rear Fender Inner Trim LH	\$	SL	418.44		
56	1	Front Side Rocker Panel Garnish LH	\$	SL	236.40		
57	1	Front Side Rocker Panel Outer LH	\$	R	600.00		
58	1	Front Side Rocker Panel Inner LH	\$	R	519.30		
59	1	Rear Bumper	\$	SL	1,202.00		

TOTAL	\$	20,912.21
10%	\$	2,091.22
	\$	18,820.99

Trans-cab Auto Services Pte Ltd

AAD1805-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T

Specical Nett

1 Set Front Bumper Fastener Clip	\$	24.00	}
1 Set Front licence plate with holder	\$	192.00	
1 Set Radiator Grille clip	\$	35.00	
1 Set Front Fender Liner clip	\$	30.00	
1 Front Fender RR Bracket LH	\$	7.10	
1 Rear Wheel Rim Hub Cap LH	\$	166.30	
1 Rear Tyre LH	\$	180.00	
1 Rear Tyre Rim RLH	\$	126.00	
1Set Rear Fender Inner Trim Clip LH	\$	30.00	

TOTAL \$ 790.40**TOTAL PARTS \$ 19,611.39****LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	501
Putty and spray painting of the affected portion.	\$	4,000.00	801
Towing Fees.	\$	120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1805-066**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T

To rust-proofing of the affected areas.	\$	170.00	301
To check steering geometry and computer wheel alignment	\$	220.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	~ X
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00	~ X

TOTAL	\$	10,460.00
--------------	-----------	------------------

Over All Total	\$	30,071.39
-----------------------	-----------	------------------

Repair Days (Lump Sum)~~15 days~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: