

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T

AAD1805-066

Not Authorised
21 May @ 25501

Vehicle No.:	SHB 7874T
Chassis No.:	KL1LA69RJB106353
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	4.5.2018
Third Party Insurer :	CHINA TAIPING

PART		LIST
1	1 Front Bumper	\$ Sin 1,202.00
2	1 Front Bumper Lower Absorber	\$ Sin 180.00
3	1 Front Bumper Reinforcement	\$ N 356.00
4	1 Front Bumper Retainer RH	\$ Sin 102.00
5	1 Front Bumper Retainer LH	\$ Sin 102.00
6	1 Front Bumper Lower Grille	\$ Sin 78.00
7	1 Front Bumper Lower Stiffener	\$ N 134.37
8	1 Front Bumper Bracket LH	\$ N 10.00
9	1 Front Bumper Bracket RH	\$ N 10.00
10	1 Bumper Fog Lamp Cover RH	\$ Sin 32.40
11	1 Bumper Fog Lamp Cover LH	\$ Sin 32.40
12	1 Headlamp LH	\$ Sin 816.00
13	1 Headlamp LH inner panel	\$ N 611.16
14	1 Front Fender LH	\$ <i>Del An</i> 837.60 ✓
15	1 Front Fender Liner LH	\$ Sin 47.00 X
16	1 Front Fender Inner Wheel House Panel LH	\$ N 1,437.00
17	1 Front Shock Absorber Assy LH	\$ Sin 216.17
18	1 Front Shock Absorber Top Mounting LH	\$ Sin 48.32
19	1 Front Lower Arm LH	\$ Sin 283.00
20	1 Front Knuckle Arm LH	\$ Sin 230.00
21	1 Front Door LH	\$ N 1,133.00
22	1 Front Door Glass Guide RH Chrome Moulding	\$ Sin 60.00
23	1 Front Door Outer Moulding	\$ Sin 220.00
24	1 Front Door Outer Handle	\$ Sin 125.00
25	1 Front Door Handle Support	\$ Sin 3.00
26	1 Front Door outer handle inner seal	\$ Sin 89.15
27	1 Front Door outer key lock	\$ Sin 25.00
28	1 Front Door Hinge Upper	\$ N 65.00

Trans-cab Auto Services Pte Ltd

AAD1805-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T

29	1	Front Door Hinge Lower	\$	R	65.00	}
30	1	Front Door inner lock	\$	R	586.00	
31	1	Front Door Inner Lock Latch LH	\$	R	206.00	
32	1	Front Door Check / Arrestor	\$	S ₂	67.50	
33	1	Front Door Weatherstrip LH	\$	S ₂	138.79	
34	1	Front Door glass channel weatherstrip	\$	S ₂	160.00	
35	1	Front Door inner trim board	\$	S ₂	455.69	
36	1	Front Door window glass	\$	S ₂	456.12	
37	1	Front Door Power Window Motor (Master) LH	\$	S ₂	284.97	
38	1	Front Door power window motor switch	\$	S ₂	145.00	
39	1	Front Door Window Regulator Gear LH	\$	S ₂	84.58	
40	1	Front Door Outer Pillar Panel LH	\$	R	715.00	
41	1	Front Door Pillar Inner Panel LH	\$	R	850.00	
42	1	Front Door Center Pillar Panel LH	\$	R	698.15	
43	1	Front Side View Mirror Assy LH	\$	Null	1,191.00	
44	1	Rear Door LH (Panel A-RR DR LH)	\$	R	1,133.00	}
45	1	Rear door weatherstrip - Inner	\$	S ₂	41.40	
46	1	Rear door weatherstrip - 2nd Frame	\$	S ₂	25.90	
47	1	Rear door top hinge	\$	R	35.00	
48	1	Rear door bottom hinge	\$	R	35.00	
49	1	Rear door inner lock	\$	R	425.00	
50	1	Rear door check / arrestor	\$	S ₂	65.00	
51	1	Rear door lock striker / latch	\$	R	120.00	
52	1	Rear door outer weatherstrip moulding	\$	S ₂	85.00	
53	1	Side Rocker Panel Garnish LH	\$	S ₂	236.40	
54	1	Rear Fender LH	\$	R	1,145.00	
55	1	Rear Fender Inner Trim LH	\$	S ₂	418.44	
56	1	Front Side Rocker Panel Garnish LH	\$	S ₂	236.40	
57	1	Front Side Rocker Panel Outer LH	\$	R	600.00	
58	1	Front Side Rocker Panel Inner LH	\$	R	519.30	
59	1	Rear Bumper	\$	S ₂	1,202.00	

TOTAL	\$	20,912.21
10%	\$	2,091.22
	\$	18,820.99

Trans-cab Auto Services Pte Ltd

AAD1805-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T

Special Nett

1 Set Front Bumper Fastener Clip	\$	<i>un</i>	24.00	}
1 Set Front licence plate with holder	\$	<i>Sn</i>	192.00	
1 Set Radiator Grille clip	\$	<i>un</i>	35.00	
1 Set Front Fender Liner clip	\$	<i>un</i>	30.00	
1 Front Fender RR Bracket LH	\$	<i>R</i>	7.10	
1 Rear Wheel Rim Hub Cap LH	\$	<i>Sn</i>	166.30	
1 Rear Tyre LH	\$	<i>Sn</i>	180.00	
1 Rear Tyre Rim RLH	\$	<i>Sn</i>	126.00	
1Set Rear Fender Inner Trim Clip LH	\$	<i>un</i>	30.00	

TOTAL	\$	790.40
--------------	-----------	---------------

TOTAL PARTS	\$	19,611.39
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>5001</i>
Putty and spray painting of the affected portion.	\$	4,000.00	<i>8001</i>
Towing Fees.	\$	<i>un</i> 120.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>un</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>un</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>un</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1805-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7874T

To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To check steering geometry and computer wheel alignment	\$	<i>220.00</i>	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>170.00</i>	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>170.00</i>	<i>X</i>
To transfer of fender fittings, attachment and perform water seepage test.	\$	<i>170.00</i>	<i>X</i>

TOTAL \$ 10,460.00

Over All Total \$ 30,071.39

Repair Days (Lump Sum)

15 days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: