

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1061G

DATE 9/5/2018 14:32

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Detorant</i>			\$ 603.60	
	Rear Bumper Reinforcement <i>Xm</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Xm</i>		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket <i>Xm</i>			\$ 49.00	
	Rear Bumper Clips <i>me</i>			\$ 22.00	
	Rear Bumper Sponge <i>Xm</i>			\$ 143.40	
	Rear Bumper Under Cover <i>cl</i>			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor <i>X me</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat <i>me</i>			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 280.00 ²⁰⁰	
	Spray Painting Charge			\$ 200.00 ¹⁶⁰	
	Wiring Charge			\$ 50.00 ^{X 17}	
	R/Refix Reverse Sensor			\$ 120.00 ²⁰	
	Towing Fee			\$ 60	
	TOTAL LABOUR			\$ 650.00	
	ESTIMATE TOTAL			\$ 2,361.58	
<div> <p><i>Kahin (C/C)</i></p> <p><i>9/5/8 1515h</i></p> <p><i>2012</i></p> <p><i>P/P</i></p> <p><i>Baton Paul phh</i></p> </div> <div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305158385

Date : 10/05/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

: SHC1061G

Date of Accident : 08/05/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBF743J
###

2. The finalized amount shall be:

(a) Spare Parts after List discount \$730.48

(b) Labour Charges ### \$480.00

Total for Part-By-Part Repair Cost \$1,190.48

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : KALVIN

Date : 10/5/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 10.05.2018
Time: 12:37:07
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305158385
REGN NO : SHC1061G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.01.2017
DATE/TIME IN : 08.05.2018 18:45
ACCIDENT DATE : 08.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00

SUB-TOTAL : 730.48

JOB NATURE

0000 23-01	TOWING FEE	60.00
0001 L	PANEL BEATING- REAR	200.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	180.00
0003 L	REMOVE/REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 460.00

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 10.05.2018
Time: 12:37:07
Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305158385
REGN NO : SHC1061G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.01.2017
DATE/TIME IN : 08.05.2018 18:45
ACCIDENT DATE : 08.05.2018

JOB/PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,190.48

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 30 May, 2018 8:25 AM
To: Lucas Lee; claimsdept@sg.cntaiping.com
Cc: 'jowyn.tay@sg.cntaiping.com'; Angie Foo; Joy Irene (LKKAUTO); Hsiao Tong (LKKAUTO); Asher Sng (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBF743J (OI : CAI - SNM18D02574C02) and SHC1061G (TP : LKK REF - CC3/CTI18008564/K1ja3) on 08/05/2018
Attachments: LeeSZ_SNM18D02574C01-GBF743J-LKKDirectSettlementAccidentNotReportedLtr_clcr96.523.pdf
Categories: HMK

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]
Sent: Wednesday, 23 May, 2018 2:22 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBF743J (OI : CAI - SNM18D02574C02) and SHC1061G (TP : LKK REF - CC3/CTI18008564/K1ja3) on 08/05/2018

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Jowyn Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #18-00 Springleaf Tower Singapore 079908
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D02574/C01/3**

Date : **23 MAY 2018**

via Ordinary & Registered Mail

**KENBUILD ENGINEERING PTE LTD
57 UBI AVENUE 1
#05-01 UBI CENTRE
SINGAPORE 408936**

Dear Sir / Madam

**ACCIDENT INVOLVING GBF743J AND SHC1061G ON 08 MAY 2018
ALONG FERNVALE ROAD TOWARDS SENGKANG WEST**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC1061G**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY
Ref : CC3/CT118008564/K1JA3
Contact No : 68412409
via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0421A) - VITESSE SOLUTIONS

F02/LKKDSANR-2013



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI18008564/K1ja3

01st Jun 2018

KENBUILD ENGINEERING PTE LTD

57 UBI AVENUE 1
#05-01 UBI CENTRE
SINGAPORE 408936

Dear Sir / Madam,

**ACCIDENT INVOLVING GBF 743J AND SHC 1061G ON 08/05/2018 ALONG/ AT
FERNVALE ROAD TOWARDS SENGKANG WEST**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from CHINA TAIPING INSURANCE SINGAPORE PTE LTD dated **23rd May 2018**.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter (by **08th Jun 2018**).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Joy

Claims

Tel : 6841 2409

Fax: 6741 4108

Email : Joyirene@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)*

ARC Repair TP(CLS0)1

JOB CARD Sales Order: 3823239 JC NO: 305158385

COMFORT TRANSPORTATION PTE LTD 7010045 83 SIN MING DRIVE Singapore SINGAPORE 575717 5508755 (0)	REG NO: SHC1061G	MILEAGE
	MAKE HYUNDAI	FUEL E 1/2 F
	MODEL I-40	DATE/TIME IN 08.05.2018 18:45
	YR OF MANU 25.01.2017	TARGET DATE
	CHASSIS NO: R410B41UMHU098552	COMPLETION DATE/TIME:

nt Date: 08.05.2018
: 3P 08.05.18

JOB DESCRIPTION

LABOR CODE	DESCRIPTION
23-01	TOWING FEE

ASSED OUT BY: _____

SERVICE ADVISOR _____ CUSTOMER'S SIGNATURE _____

it Slip	Exit Pass
SHC1061G JU CHINA	Vehicle No.: SHC1061G
Advisor: _____	Name of Service Advisor: _____
Signature/Date: _____	Date: _____
Service Reception upon collection	To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 1061G

DATE 9/5/2018 14:32

MAKE :

MODEL : HYUNDAI i40

CHINA
LRL
JH

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 280.00 200	
	Spray Painting Charge			\$ 200.00 160	
	Wiring Charge			\$ 50.00 X	
	R/Refix Reverse Sensor			\$ 120.00 20	
	Towing Fee			\$ 60	
	TOTAL LABOUR			\$ 650.00	
	ESTIMATE TOTAL			\$ 2,361.58	
<p>Kalish (C/C)</p> <p>9/5/8 1515h</p> <p>2012</p> <p>P/P</p> <p>Beton Paul phh</p> <div> <p>LK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>					
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: _____ Time Received: _____		3. Vehicle Type:	
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>CHONG</u> Contact No. : <u>96641118</u> Vehicle No. : <u>SHC10616</u> Make / Model / Colour : <u>J40</u> Email : _____		<input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	
		4. Type of Towing:	
		<input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	
		5. Nature of Service:	
		<input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	
7. Location: <u>FERNVALE Rd</u>		6. Parts Replaced/Remarks:	
9. Preferred Workshop:		8. Vehicle Tow - In Workshop:	
<input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others: _____		<input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
10. Odometer Reading : <u>252862km</u>		11. Radio / CD Player	
Fuel Level : <u>F 1/4 1/2 3/4 E</u>		<input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	
Job Attended			
12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input checked="" type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS		 # : Cracked X : Dented / : Scratched O : Missing	
Name of Driver : <u>GAO X J</u>			
Vehicle No. : <u>Y108450P</u>			
Time Dispatch : <u>19:19</u>			
Time of Arrival : <u>20:00</u>			
Time Completed : _____		Signature of Customer	
Cash Invoice Details (if applicable)			
13. Cash Invoice No. : _____			
Customer Acknowledgement			
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
<u>8/5/2018</u>		<u>20:00</u>	
Date		Time	
		Signature of Customer	
14. WORKSHOP			
Name of Attending Staff/Guard		Date & Time of Arrival	
		Signature of Attending Staff/Guard	

COMFORTDELGRO ENGINEERING

Our Ref : T0518/SHC1061G/WT(ck)
Date : 22.5.18

China Taiping Insurance Co (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
c/o LKK Auto Consultants

CDGE Taxi Claims
59 Loyang Drive
4th Floor
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Maintline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 195889049W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 758732

Without Prejudice

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC1061G **YOUR INSURED** GBF743J
OTHERS ON 8.5.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd and CityCab Pte Ltd, the owner of motor taxi SHC1061G which was involved in the captioned accident with your insured's vehicle. The taxi owner and driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the taxi.

As the accident was caused by the negligent act of your insured driving GBF743J we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

- 1) Cost of Repair
- 2) 2.5 days Loss of Rental @ \$ 117.00 per day
- 3) Surveyor Report fees
- 4) LTA search fees
- 5) Accident Search/Report fees
- 6) Towing/Medical/Transportation/Misc Fees

\$ 1,273.81

\$ 292.50

\$ 7.49

Sub-Total \$ 1,573.80

HIRER'S CLAIM

- 1) 2.5 days Loss of Income @ \$ 80.00 per day

\$ 200.00

\$ 1,773.80

TOTAL CLAIM

We enclosed herewith the following documents to support the claims: -

- a) Original repair/survey bill/report/photographs _____ pcs
- b) LTA search slip/s of GBF743J
- c) Accident/Police report/s of SHC1061G
- d) Letter of authority from owner/ hirer/operator
- e) Rental rate letter/Mileage record
- f) Scene Photographs 9 pcs

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

Motor Claims Specialist

CDGE Claims Department

Tel: 62148737 Fax: 62141843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Thursday, 22 November 2018 3:53 PM
To: 'info@republicbe.com'
Cc: Admin A
Subject: ATTENTION: MS. MAY (ACCIDENT INVOLVING GBF 743J AND SHC 1061G ON 08/05/18)

Our ref: CC3/CTI18008564/K1ja3

REPUBLIC BUILDER & ENGINEERING PTE LTD/ KENBUILD ENGINEERING PTE LTD
Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING GBF 743J AND SHC 1061G ON 08/05/18

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONGi 40 SHC1061G , GBF743J
FERNVALE ROAD X TWDS SENGKANG WEST.

ON 08-May-18 18:45

I / We

KAY POH PHAY

(Hirer) NRIC No.: S7536438E

and/or

CHONG WOEI LIEH

(Relief) NRIC No.: S7626097D

Taxi Number

SHC1061G

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

09-May-2018

Name of Hirer

KAY POH PHAY

Hirer NRIC

S7536438E

Signature :



Address

406C FERNVALE ROAD #23-63
793406

Contact No.

96640392

Name of Relief

CHONG WOEI LIEH

Relief NRIC

S7626097D

Signature :



Address

411B FERNVALE ROAD 04-62
792411

Contact No.

96641118

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMCVSN1639291701
Claimant : COMFORT TRANSPORTATION PTE LTD

Claim No : SNM18D02574/C01/3

Amount : S\$1,615.00
SINGAPORE DOLLARS ONE THOUSAND SIX HUNDRED FIFTEEN ONLY.

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHC 1061G
Insured Vehicle No. : GBF 743J

Date of Loss : 08/05/2018
Place of Accident : FERNVALE ROAD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : REPUBLIC BUILDER & ENGINEERING PTE LTD
Driver Name : ROKNUZZAMAN

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum	S\$ 1,615.00
	=====
TOTAL	S\$ 1,615.00
	=====

COMFORT DELGRO ENGINEERING PTE LTD
51 CORMORANT DRIVE
SINGAPORE 439588
Claimant Name : _____ NRIC No : _____

Signature :  Date : 26.11.18

"The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

Please forward your cheque made payable to
COMFORTDELGRO ENGINEERING PTE LTD

TAX INVOICE

(COMPANY REG. NO.: 199506048W
Page: 1

8010012

CHINA TAIPING INSURANCE CO(S) PTE L,
SPRINGLAP TOWER

3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO
SHC1061G

MARK
HYUNDAI

MODEL
I-40

DATE OF REG
25.01.2017

CHASSIS CODE
KMH1B41UMHU098552

INV. NO/DATE
91373072 17.05.2018

JOB NO.
305158385

DIRECTION READING

DATE/TIME IN
08.05.2018 18:45

Description : 3P 08.05.18

S/No	Part No.		Qty	Unit Price	Disc	Net
PART REQUISITION						
0001	04-01-0103-0579	140VC COVER ASSY-RR BUMPER	1	603.60	20.00	482.88
0002	04-01-0103-0738	140VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0003	04-01-0101-0111	HYUNDAI BUMPER COVER (LIP	10	2.20	20.00	17.60
0004	04-01-0103-1150	140VC PROTECTOR MAT	1	50.00	0.00	50.00
SUB-TOTAL:			:			730.48

JOB NATURE

0001	23-01	TOWING FEE	60.00	60.00
0002	I,	PANEL READING- REAR	200.00	200.00
0003	23-502	SPRAYPAINT (ON APPLICABLE AREA	180.00	180.00
0004	I,	REMOVE/REPTX REVERSE SENSOR	20.00	20.00

omfortDelGro Engineering Pte Ltd
member of COMFORTDELGRO

Head Office:
15 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No
8010012	91373072	1,273.81	

TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO(S) PTE L
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO
SHC1061G

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
25.01.2017

CHASSIS CODE
KMHT841UMHU098552

INV. NO/DATE
91373072 17.05.2018

JOB NO.
305158385

ODOMETER READING

DATE/TIME IN
08.05.2018 18:45

S/No	Part No.	Qty	Unit Price	%Disc	Net
SUB-TOTAL :					460.00

Items total	1,190.48
Add GST @ 7.000 %	83.33
Invoice amount	1,273.81

Issued by : KATHERINETAN 17.05.2018 17:03:27
Repair type : CSO/57/57
Payment type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO
8010012	91373072	1,273.81	

Our Ref: CT18050205



Date: 17 May 2018

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON
ALONG
INVOLVING

08/05/2018 @ 18:45 hrs
FERNVALE ROAD X TWDS SENGKANG WEST.
GBF743J

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC1061G** (the "Taxi"). The Taxi was hired to **KAY POH PHAY IC NO S7536438E** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$117.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SAC 10619

DATE	NAME OF DRIVER	MILEAGE READING				MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
		2	5	2	0		FROM	TO
6/5/18	Rogers	2	5	2	0	323	0700	1826
6/5/18	Chen	2	5	2	3	248	7PM	1826
4/8/18	Rogers	2	5	2	4	155	07-11P	1717
7/15/18	Chen	2	5	2	6	196	530PM	0408
8/5/18	Chen	2	5	2	8	198	0715	1745
		2	5	2	8	3		
080518	Accident	127	2	5	2	UN	1845	-
100518	Repair	127	2	5	2	041	1045	-

MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
		FROM	TO
9497	325	1930	0625
19685	188	0920	1750
9922	236	1841	0545
0110	188	0700	1750
0238	128	1815	0615
0435	197	0705	1825
0757	322	0628	0611
0997	240	0700	1812
1250	252	1200	0545
1469	219	0700	1614
1761	241	1659	003

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
GBF743J	08 May 2018 / 18:45:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#) [OK](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18008564/K1ja3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-12-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 743J	Veh. Inspected	SHC 1061G
Policy No.	DMCVSN1639291701	Coverage (\$)	0.00
Claim No.	SNM18D02574/C01/3	Excess (\$)	0.00
Assign From		Assign Date	09/05/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU098552	Colour	BLUE
Odometer	252882	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/05/2018	Inspection Date	09/05/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1061G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	49.00	-
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER	CUT	225.00	225.00
	LESS 20% DISCOUNT		-381.47	-170.12
			1,525.88	680.48
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			185.70	50.00
<u>LABOUR</u>				
	PANEL BEATING.		280.00	200.00
	SPRAY PAINTING CHARGE.		200.00	180.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	R/REFIX REVERSE SENSOR .		120.00	20.00
	TOWING FEE.		60.00	60.00
			710.00	460.00
GRAND TOTAL			2,421.58	1,190.48
RECOMMENDED COST OF REPAIRS				1,190.48

Report Ref No. CC3/CT18008564/K1ja3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.