COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 1061G

1AKE

DATE 9/5/2018 14:32

CHNA LKK JU

Parts Description/ Labour	Type	Unit Price		Amount
Rear Bumper De torus			\$	603.60
Rear Bumper Reinforcement			\$	504.35
Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$	360.00
Rear Bumper Side Bracket			\$	49.00
Rear Rumper Clips			\$	22.00
Rear Bumper Sponge			\$	143.40
Rear Bumper Under Cover			\$	225.00
SUB TOTAL			\$	1,907.35
LESS 20%			\$	381.47
DISCOUNTED TOTAL			\$	1,525.88
Rear Rumper Reverse Sensor & M			8	135.70
Rear Rumper Rubber Mat				50.00
Real Bumper Rubber Wat			"	30.00
			\$	185.70
Labour Charge				2
			8	28900
				200.00
				20 0.00
				120.00
				120.00
			_	
TOTAL LABOUR			\$	650.00
ESTIMATE TOTAL			\$	2,361.58
Kahi (ClCk) LKK Ault the Rep. • To resure • To display a Parts pi	airer of the vey before/after by damaged po ces are subjects	following: er spray painting art(s) during resurvey of to confirmation		
9/5/8 1515/ms • Third pa • No illega • Supple	rty survey is o	a "Without Prejudice basis		
2 // Acknowle	edged by Rep			
Befor Paul pht Date:	* ;		-	
This is an initial actimate based on a visual inspection of the	e above w	ehicle. The final repair	mant	tum will
	Rear Bumper Reinforcement Bracket (LH/RH) Ken Rear Bumper Side Bracket Rear Bumper Clips Rear Bumper Sponge Kum Rear Bumper Sponge Kum Rear Bumper Under Cover Great Bumper Under Cover Great Bumper Under Cover Great Bumper Reverse Sensor Rear Bumper Reverse Sensor Rear Bumper Rubber Mat Labour Charge Panel Beating Spray Painting Charge Wiring Charge R/Refix Reverse Sensor Total LABOUR ESTIMATE TOTAL Kaki (Clay Total LABOUR ESTIMATE TOTAL LABOUR Beating Spray Painting Charge Total LABOUR ESTIMATE TOTAL ACKNOWN Signature Date:	Rear Bumper Reinforcement Bracket (LH/RH) Ken Rear Bumper Side Bracket Rear Bumper Clips Rear Bumper Sponge Rear Bumper Under Cover SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Reverse Sensor Rear Bumper Rubber Mat Labour Charge Panel Beating Spray Painting Charge Wiring Charge R/Refix Reverse Sensor Total Labour ESTIMATE TOTAL LKK Aulo Consultat the Repairer of the *To essurely before/aft *To display damaged p *Parts pices are subje *Third party survey is of *No illegal modification *Supplementary item(is subject to final app Acknowledged by Rep Signature: Date:	Rear Bumper Reinforcement Bracket (LH/RH) Ker Rear Bumper Side Bracket Rear Bumper Sponge Rear Bumper Clips Rear Bumper Under Cover SUB TOTAL LESS 20% DISCOUNTED TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Reverse Sensor Rear Bumper Rubber Mat Labour Charge Panel Beating Spray Painting Charge Wiring Charge R/Refix Reverse Sensor Total LABOUR ESTIMATE TOTAL LKK Aub Consultants hence notify the Repairer of the following: To resurvey beforalder parpy spainting To display damaged parties during resurvey Parts pices are subject to confirmation Timp drays urvey is de a "Without Prejudice" basis No illegal modifications) is allowed Supplementary items of must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature: Date:	Rear Bumper Reinforcement Bracket (LH/RH) Star Rear Bumper Reinforcement Bracket (LH/RH) Star Rear Bumper Side Bracket Star Rear Bumper Side Bracket Star Rear Bumper Clips Rear Bumper Sponge Star Star Star Bumper Under Cover Star Bumper Under Cover Star Bumper Under Cover Star Bumper Under Cover Star Bumper Reverse Sensor Star Rear Bumper Reverse Sensor Star Bumper Reve



A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline +65 6383 6280 Facsimile +65 6280 9755

Service Centres

205 Braddell Boad Singapore 579701

45 Pandan Road Singapore 609286

75 Sungel Kadut Way Singapore 728791

24 Senoko Loop Singapore 758156





JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

lah Pagulaitian							
Job Requisition	2.44.1		4.7	upo of Tourism			
1. Date: Time Received: 2. New SPARK Kakis Name of Customer : Chong Contact No. : 96641118 Vehicle No. : SHC15616 Make/Model/Colour: 143 Email :	F. Nature	3. Vehicle Type: Private Taxi (CTPL/CCPL) Fleet STK (Boon Lay) 5. Nature of Service: Jumpstart Recovery Change Tyre / Battery		4. Type of Towing: Normal Tow King Dolly Flat Bed Crane-up 6. Parts Replaced/Remarks:			
7. Location: FERNVALE Rd		8	Vehicle Tow - Ir		eel Jammed		
9. Preferred Workshop: Braddell Loyang Sin Ming Sungei Kadut Senoko Komoco (UBI / Leng Ke	Pandan Ubi Cycle & C	carriage (PD)	Smoky Ext Overheatin Brake Faul Starting Pr Accident Return Tax	ng Stee Ity Alte oblem Los Eng	ering Faulty ernator Faulty s Power ine Stalled		
10. Odometer Reading : 2526 Fuel Level : F 1/4 1/2	82Km.	11. Radio / CD Plance OK Faulty Not test		FIGURE			
Job Attended				3005	PAGHT.		
12. Tow Truck / Recovery Van : VRS	19	YISHUN TOWING	OTHERS	#: Cracked /: Scatched	X : Dented O : Missing		
Cash Invoice Details (if applicable)		I tall to the					
13. Cash Invoice No. :							
Customer Asknowledges							
Customer Acknowledgement a. I have been advised to remove all valuable items in my cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own c. Surcharge: Towing fee will be levied if the customer de Date	risk and SPARK Car Care™	will not be held liab	le for such losses.		carpark coupor		
14. WORKSHOP					- 14		
Name of Attending Staff/Guard	Date & Time of Arrival		Signature of A	Attending Staff/Guar			
				WC	DRKSHOP CO		