

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7599M*Not Notarised
11 Sep @ 2800***AAD1805-060**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7599M

KL1LA69RJBB077941

CHEVROLET

EPICA 2.0

6.5.2018

*1A14***PART****LIST**

1	1	Front Fender RH	\$	<i>N</i>	837.60	<i>X</i>
2	1	Front Fender Liner RH	\$	<i>Sn</i>	47.00	<i>X</i>
3	1	Fender Insulation RH	\$	<i>Sn</i>	39.00	<i>X</i>
4	1	Front Fender Inner Wheel House Panel RH	\$	<i>N</i>	1,437.00	<i>X</i>
5	1	Front Door RH	\$	<i>N</i>	1,133.00	<i>X</i>
6	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>Sn</i>	60.00	<i>X</i>
7	1	Front Door Outer Moulding	\$	<i>Sn</i>	220.00	
8	1	Front Door Outer Handle	\$	<i>Sn</i>	125.00	
9	1	Front Door Handle Support	\$	<i>Sn</i>	3.00	
10	1	Front Door outer handle inner seal	\$	<i>Sn</i>	89.15	
11	1	Front Door outer key lock	\$	<i>Sn</i>	25.00	
12	1	Front Door Hinge Upper	\$	<i>N</i>	65.00	
13	1	Front Door Hinge Lower	\$	<i>N</i>	65.00	
14	1	Front Door inner lock	\$	<i>N</i>	586.00	
15	1	Front Door Inner Lock Latch RH	\$	<i>N</i>	206.00	
16	1	Front Door Check / Arrestor	\$	<i>Sn</i>	67.50	
17	1	Front Door Weatherstrip RH	\$	<i>Sn</i>	138.79	
18	1	Front Door glass channel weatherstrip	\$	<i>Sn</i>	160.00	
19	1	Front Door inner trim board	\$	<i>Sn</i>	455.69	
20	1	Front Door window glass	\$	<i>Sn</i>	456.12	
21	1	Front Door Power Window Motor (Master) RH	\$	<i>Sn</i>	284.97	
22	1	Front Door power window motor switch	\$	<i>Sn</i>	145.00	
23	1	Front Door Window Regulator Gear RH	\$	<i>Sn</i>	84.58	
24	1	Front Door Outer Pillar Panel RH	\$	<i>N</i>	715.00	
25	1	Front Door Pillar Inner Panel RH	\$	<i>N</i>	850.00	
26	1	Front Door Center Pillar Panel RH	\$	<i>N</i>	698.15	
27	1	Front Side View Mirror Assy RH	\$	<i>Sn</i>	1,191.00	

Trans-cab Auto Services Pte Ltd

AAD1805-060

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7599M

28	1	Rear Door RH (Panel A-RR DR LH)	\$	<i>Rollwrap</i>	1,133.00	✓
29	1	Rear door weatherstrip - Inner	\$	<i>Sn</i>	41.40	}
30	1	Rear door weatherstrip - 2nd Frame	\$	<i>Sn</i>	25.90	
31	1	Rear door top hinge	\$	<i>n</i>	35.00	
32	1	Rear door bottom hinge	\$	<i>n</i>	35.00	
33	1	Rear door inner lock	\$	<i>n</i>	425.00	
34	1	Rear door check / arrestor	\$	<i>Sn</i>	65.00	
35	1	Rear door lock striker / latch	\$	<i>n</i>	120.00	
36	1	Rear door outer weatherstrip moulding	\$	<i>Sn</i>	85.00	
37	1	Side Rocker Panel Garnish RH	\$	<i>Sn</i>	236.40	
38	1	Rear Fender RH	\$	<i>n</i>	1,145.00	
39	1	Rear Fender Inner Trim RH	\$	<i>Sn</i>	418.44	}
40	1	Front Side Rocker Panel Garnish RH	\$	<i>Sn</i>	236.40	
41	1	Front Side Rocker Panel Outer RH	\$	<i>n</i>	600.00	
42	1	Front Side Rocker Panel Inner RH	\$	<i>n</i>	519.30	
43	1	Rear Bumper	\$	<i>Sn</i>	1,202.00	

TOTAL	\$	16,507.39
10%	\$	1,650.74
	\$	14,856.65

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>nn</i>	24.00	}
1 Set	Front licence plate with holder	\$	<i>Sn</i>	192.00	
1 Set	Radiator Grille clip	\$	<i>nn</i>	35.00	
1 Set	Front Fender Liner clip	\$	<i>nn</i>	30.00	
1	Front Fender RR Bracket RH	\$	<i>n</i>	7.10	
1	Rear Wheel Rim Hub Cap RH	\$	<i>Sn</i>	166.30	
1	Rear Tyre RH	\$	<i>Sn</i>	180.00	
1	Rear Tyre Rim RH	\$	<i>Sn</i>	126.00	
1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i>	30.00	

TOTAL	\$	783.30
--------------	-----------	---------------

TOTAL PARTS	\$	16,917.10
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd**AAD1805-060**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7599M

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	501
Putty and spray painting of the affected portion.	\$	4,000.00	801
Towing Fees.	\$	120.00	nr X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	nr X
To check steering geometry and computer wheel alignment	\$	220.00	nr X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nr X
To rust-proofing of the affected areas.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	220.00	nr X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nr X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00	nr X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 10,460.00**Over All Total \$ 25,577.10****Repair Days (Lump Sum)****15 days****4 days**