

7/03/2002

ASS. REC. BY:

REF:

CB/ICS18008569/Aqb72

Special Instruction:

ASSIGNMENT (Office)

SUNATON
merman

From (Person):

Claims

of

ICS

Date/Time:

09052018 2.06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 6846R

Insured:

SGK 8514R

at Workshop m/s

Borneo Motor

Tel:

66311687

of

17 Ubi Road 4

Policy No:

Claim No:

0mpc1800145H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10042018

CA / REV / REP. / REV 24 HRS. 'DS'

14052018 @ after 8:30am

H.O.D. Indorsement:

Date/Time:

10052018 3:14pm

Person Contacted:

Sam

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 6846R - X
	SGK 8514R - X
12/11/18 @ 4.55pm	confirmed with Sam final fig \$5841.10, 4 days. (Red \$4279.65, 42%)

REF: TCS

ASSIGNMENT

From:-

Date:

14/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKV 6846R

at Workshop m/s

Borneo Motor

of

17 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Sum

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS '09

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

TP ECICS.

RECEIVED 12 NOV 2018

Veh No

SKV 6846R

Yr Regn

2015 Sept

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota AHB

CC 1598

Colour

Red

A/C

Insured / Std / NI / NA

Sp. Reading

46251

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104538600

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/05/18

Survey held at

Borneo Motor (ubi)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to?

☐

: Prel. Report

1) 12/10/2018

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

Y S+R S

Y Photos

Y Other

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

MER-TP

Lump Sum / L.B.I. (\$

5841.10

TOTAL

350
10

360

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Date: 18 Sep 2018

Attn:

Preliminary AdviceInsured Vehicle No : SGK8514R
TP Vehicle No : SKV6846R
Make : TOYOTA COROLLA ALTIS
Date of Inspection : 14/05/2018
Inspection At : BORNEO MOTORAccident Date : 10/04/2018
Assignment Date : 15/05/2018
Est. Duration of Repair : 4**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,120.75
Revised Amount	:S\$	5,841.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,841.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ASSIST TO UPDATE THE INSURED'S INFORMATION.

Catherine Chong (LKK Auto)

From: Sam San Joi UBI <SanJoi.Sam@borneomotors.com.sg>
Sent: Thursday, 10 May, 2018 3:10 PM
To: assignments@lkkauto.com
Subject: Fw: Liability Status: SKV6846R
Attachments: SKV6846R 10042018_Est Inv.pdf; SKV6846R 10042018_SAS_Damaged Photos.pdf

From: Siti Nabilah PTCBC
Sent: Thursday, 10 May 2018 10:28 AM
To: Sam San Joi UBI
Cc: Siti Nabilah PTCBC
Subject: Liability Status: SKV6846R

Hi Sam,

Liability is clear.
Please proceed with LOR @\$100/day as per surveyor recommendation.

Thank you,
Nabilah

Sent: Wednesday, 9 May 2018 2:06 PM
To: Siti Nabilah PTCBC <Siti.Nabilah@inchcape.com.sg>
Cc: ECICS Claims <claims@ecics.com.sg>;
Subject: RE: Direct Settlement(SAM) - Accident Involving SKV6846R and SGK8514R DOA 10/04/2018 ; Our ref DMPC1800145H

Without Prejudice

Dear Siti

Thank you for your email.

We agree to settle your client's claim under third party direct settlement arrangement with Car Rental of @ \$100 per day x no. of days as recommended by our appointed surveyor.

Please be advised that we will arrange our surveyor to conduct survey of your client's vehicle and kindly quantify the claim with supporting documents after finalizing the cost of repairs

Thank you.

Aside to LKK

Please assist to arrange survey for the above TP's vehicle.

Our claim no DMPC1800145H.

Thank you.

Regards,
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 12 November 2018 4:55 PM
To: Sam San Joi UBI; SUR
Subject: RE: FINALIZE SKV6846R

Dear Sam,

WITHOUT PREJUDICE

Confirm final fig \$5,841.10 before GST and 4 repair days.

Kindly send the relevant documents to ECICS insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam San Joi UBI <SanJoi.Sam@borneomotors.com.sg>

Sent: Tuesday, 9 October 2018 2:40 PM

To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: Re: FINALIZE SKV6846R

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Sent: Monday, 8 October 2018 11:56:49 AM

To: Sam San Joi UBI; Adrian Ling (LKKAUTO); SUR

Subject: RE: FINALIZE SKV6846R

Dear Sam,

Any updates?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)

Sent: Wednesday, 26 September 2018 8:45 AM

To: Sam San Joi UBI <SanJoi.Sam@borneomotors.com.sg>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: FINALIZE SKV6846R

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/04/2018 17:14
Date Of Accident	10/04/2018 15:20
Exact Location Of Accident	SLIP RD OF PIE INTO EUNOS LINK TWDS HOUGANG
Country/State of Loss	SINGAPORE
VEHICLE INFORMATION	
Vehicle Registration Number	SKV6846R
Insured/Policyholder	
Name Of Registered Owner	LILY LIM
NRIC No	S2533991F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96182298
Alternative Phone No	OFFICE-96182298
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPAP1973397
Cover Note Number	
Driver	
Name of Driver	TAN PHEE AN
NRIC No	S1846044J
Date Of Birth	04/01/1953
Occupation	INDOOR
Date Of Driving Pass	18/01/1974
Driving Experience	44 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90230186
Fax Number	
Contact Number	
Email Address	JEFFREY.TAN22@YAHOO.COM.SG

Address BLK 135 BEDOK RESERVOIR ROAD #09-1241
 Postcode 470135
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF DRIVER OF PROPERTY

Vehicle Registration Number SGK8514R
 Vehicle Make/Model/Colour TOYOTA VIOS GREY
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAN MUI KIME
 NRIC/Passport Number S1411004F
 Contact Number 97958318
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

AS 10-04-2018 4:30pm
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident


Whilst stopping at The Slip Road of PJE toward Eunos
link toward Hongkong M/car SGK8514R Toyota Vios
Grey knock into my rear of vehicle SKV6846R.
Damage to SKV6846R rear bumper damage and the boot
cannot closed properly.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

 10-04-2018 4:30pm
Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel



POLICY INFORMATION		Policy No. : VPA/P1973397
Source	: (01) 14888 INCH-AXA RN(EP)	
Insured	: LIM LILY	
Address	: BLK 135 BEDOK RESERVOIR ROAD #09-1241 SINGAPORE 470135	
Business/Profession	: OTHER OCCUPATION Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.	
Period of Insurance	: From 29/09/2017 To 28/09/2019 (Both Dates Inclusive)	
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.		
PREMIUM		
Premium After 50.00% NCD	: SGD 765.55	
GST 7.00%	: SGD 53.58	
Annual Premium	: SGD 819.13	
Total Payable	: SGD 1,638.28	
RISK DETAILS THE MOTOR VEHICLE		
Type Of Cover	: Comprehensive	
Regn No.	: SKV6846R	
Type Of Use	: Private Car	
Make/Model	: TOYOTA COROLLA ALTIS 1.6	
Year of Manufacture	: 2015	Seating Capacity (excl. Driver) : 05
Body Type	: SALOON	Engine C.C. : 1598
Engine No.	: 1ZRX529826	Chassis No. : MR053REH104538600
Insured's Estimated Market Value	: Market Value At The Time Of Loss (including Accessories and Spare Parts)	
Limitations as to Use : As specified in Certificate of Insurance		
<u>Extra Coverage(Premium Breakdown)</u>	<u>Limits (SGD)</u>	<u>Premium (SGD)</u>
NCD Protector		: SGD 500.00
Basic Own Damage Excess		
<u>Named Drivers</u>		
1 LIM LILY		
MEMORANDA, CLAUSES, WARRANTIES & ENDORSEMENTS		
Subject to the Memoranda, Clauses, Warranties & Endorsements attached hereto:		
BTR NCDF		
BTR - The supplementary clauses forms parts of the Schedule :		

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S1846044J**

Name: **TAN PHEE AN**

Birth Date: **04 Jan 1953**

Issue Date: **16 Dec 2002**

000000363E



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1846044J**



TAN PHEE AN

陳披安

Race
CHINESE

Date of Birth
04-01-1953

Country of Birth
MALAYSIA

Sex
M



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Pass Date
Class 2B	Motorcycles not exceeding 200 cc	18 Jan 1974
Class 2A	Motorcycles between 201 cc and 400 cc	18 Jan 1974
Class 2	Motorcycles exceeding 400 cc	18 Jan 1974
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	18 Jan 1974

PASS DATE

18 Jan 1974
18 Jan 1974
18 Jan 1974
18 Jan 1974



NP 428A



NRIC No. **S1846044J**



Blood Group
O+

Date of issue
07-02-2001

Address
APT BLK 135 BEDOK RESERVOIR ROAD
#09-1241
SINGAPORE 470135

3249616



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg


Toyota Bodycare Centre,
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mdm Lily Lim 135 Bedok Reservoir Road #09-1241 Singapore 470135 Mobile: 90230186	
		Document No		
		0		
		Document Date		
		10/05/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	29/09/2015	SKV6846R	40723	16323	7DS/SKV6846R/10041
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104538600	1ZR529826	60	Sam San Joi		10/04/2018 16.57	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SGK8514R ACC DATE:10/04/2018 DRIVE IN:10/04/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				net ✓ 30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR				✓ 154.00
3	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓ 154.00
4	S	BP-SUBLET SEALANT - REAR END PANEL				nn x 80.00
5	S	BP-SUBLET REMOVE & INSTALL REAR BOOTLID CARPET, GAR NISH AND TRIMMING TO ASSIST REPAIR				✓ 308.00
6	B	BP-MECH RESET ECU AND REPROGRAMME				462 ✓ 402.00
7	S	BP-SUBLET REPLACE REAR BUMPER, REAR BUMPER REINFORC EMENT, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1323 1323 3080.00
8	S	BP-SUBLET RESPRAY JOB ON NREAR ACCIDENT AFFECTED A REAS				1518 1012 2530.00
9	1	S52159-02904 COVER, RR BUMPER	1.00	539.90		✓ 539.90
10	2	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30		x 58.30
11	3	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70		x 105.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle.	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3664614

3664614

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES:

DATE 10/05/2018
TIME 15:06

VEHICLE NO

SKV6846R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no: 6631 1188

Account Detail		Account No	Customer Detail	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026/ICECICS	Mdm Lily Lim 135 Bedok Reservoir Road #09-1241 Singapore 470135 Mobile: 90230186	
		Document No		
		0		
		Document Date		
		10/05/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	29/09/2015	SKV6846R	40723	16323	7DS/SKV6846R/10041
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104538600	12RX529826	60	Sam San Joi	10/04/2018 16.57	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	4	S52562-02250 RETAINER, RR BUMPER R <i>new</i>	1.00	58.30		✓ 58.30
13	5	S52575-02140 RETAINER, RR BUMPER R <i>new</i>	1.00	105.70		✓ 105.70
14	6	S52023-02190 REINFORCEMENT, RR <i>new</i>	1.00	386.60		✓ 386.60
15	7	S52182-02160 ARM, RR BUMPER, OUTE <i>new</i>	1.00	66.20		✓ 66.20
16	8	S52181-02190 ARM, RR BUMPER, OUTE <i>new</i>	1.00	66.20		✓ 66.20
17	9	S52161-0K040 CLIPS <i>new</i>	10.00	3.90		✓ 39.00
18	0	S58307-02380 PANEL, LAMP LOWER <i>new</i>	1.00	649.20		✓ 649.20
19	1	S75431-02090 LUGGAGE COMP EMBLEM, <i>new</i>	1.00	59.70		✓ 59.70
20	2	S75442-02330 EMBLEM, SYMBOL <i>new</i>	1.00	39.70		✓ 39.70
21	3	S75442-02340 EMBLEM, SYMBOL <i>new</i>	1.00	44.10		✓ 44.10
22	4	S58387-02240 PLATE, RR FLOOR <i>new</i>	1.00	234.30		✓ 234.30
23	5	SPZ061-12021 26 BACK SENSOR (3R3) 310A <i>new</i>	1.00	159.75		✓ 159.75

Adrian King
p/p 14/05/18
04 Days.

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

10120.75

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	9,350.65	
	Please acknowledge receipt of vehicle	Parts			
		Labour	2,612.65	GST 7.00%	654.55
		Materials	432.00	Less	0.00
		Lubrication/Fluid	6,306.00		
		Others	0.00		
			0.00	Amount Due	10,005.20

PLEASE TEAR ALONG PERFORATED LINE

3664615

3664615

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 10/05/2018
TIME 15:06

VEHICLE NO SKV6846R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1198

ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

S1000026/ICECICS

39006705

06/06/2018

Mdm Lily Lim
135 Bedok Reservoir Road
#09-1241
Singapore 470135
Mobile: 90230186

15 GEXGKZ S2 ZRE171R 29/09/2015 SKV6846R 46251 16323 7DS/SKV6846R/10041:
MR053REH104538600 12RX529826 60 Sam San Joi 10/04/2018 16.57 17/05/2018 9.13

1	Z	BP-SUNDRY	SUNDRIES	TP-DIRECT SETTLEMENT					30.00
				ACC DATE:10/04/2018					
				DRIVE IN:10/04/2018					
				DATE-IN:14/05/2018					
				DATE SURVEY:14/05/2018					
				NO OF REPAIR DAYS:4 DAYS					
				BY:ADRIAN(LKK)					
2	B	BP-MECH	RESET ECU AND REPROGRAMME						462.00
3	B	BP-LAB	DRILL HOLE & INSTALL REAR REVERSE SENSOR						154.00
4	B	BP-LAB	CHECK LIGHTING & CONDUCT WATER LEAK TEST						154.00
5	B	BP-LAB	REMOVE & INSTALL REAR BOOTLID CARPET, GAR						308.00
			NISH AND TRIMMING TO ASSIST REPAIR						
6	B	BP-LAB	REPLACE REAR BUMPER, REAR BUMPER REINFORC						1232.00
			EMENT, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED						
			AREAS						
7	B	BP-RES	RESPRAY JOB ON REAR ACCIDENT AFFECTED AR						1518.00
			EAS						
8	1	S52159-0Z904	COVER, RR BUMPER		1.00	539.90			539.90
9	2	S52562-02250	RETAINER, RR BUMPER R		1.00	58.30			58.30
10	3	S52575-02140	RETAINER, RR BUMPER R		1.00	105.70			105.70
11	4	S52161-0K040	PIECE, RR BUMPER		10.00	3.90			39.00

06/06/2018
14:57

SKV6846R

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

S1000026 / ICECICS

39006705

06/06/2018

Mdm Lily Lim
135 Bedok Reservoir Road
#09-1241
Singapore 470135
Mobile: 90230186

15 GEXGKZ S2 ZRE171R 29/09/2015 SKV6846R 46251 16323 7DS/SKV6846R/10041:
MR053REH104538600 1ZRX529826 60 Sam San Joi 10/04/2018 16.57 17/05/2018 9.13

12 5 S52023-02190
13 6 S75431-02090
14 7 S75442-02330
15 8 S75442-02340
16 9 S64401-02B71

REINFORCEMENT, RR
EMBLEM, LUGGAGE COMP
PLATE, LUGGAGE DOOR
PLATE, LUGGAGE DR
PANEL, LUGGAGE DR HG *included.*

1.00	386.60	386.60
1.00	59.70	59.70
1.00	39.70	39.70
1.00	44.10	44.10
1.00	710.10	710.10 (18)

COPY DOCUMENT

1,983.10	GST 7.00%	5,841.10
3,858.00		408.88
0.00		0.00
0.00		
0.00		6,249.98

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

06/06/2018
14:57

SKV6846R

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18008569/AQBN2
Date: 13/11/2018

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant: SKV6846R Insured Vehicle No: SGK8514R
Vehicle No: Nature of Claim: TP Claim No: DMPC1800145H
Date of Loss: 10/04/2018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV6846R Engine No: 1ZRX529826
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Chassis No: MR053REH104538600
Reg. Date: 29/09/2015 (Man. Year: 2015) Odometer: 46251 km
Colour: Red
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Price: Market Value/New Car Price
Sum Insured (\$\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,432.75	2,013.10	1,419.65	41.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,688.00	3,828.00	2,860.00	42.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,120.75	5,841.10	4,279.65	42.29
+ GST 7.00/7.00% (\$\$)	708.45	408.88	299.57	42.29
Nett Amount (\$\$)	10,829.20	6,249.98	4,579.22	42.29

INSPECTION

Date of Assignment: 09/05/2018 Inspected At: Borneo Motors (S) Pte Ltd (Ubi)
Date Inspected: 14/05/2018 17 Ubi Road 4
Singapore 408611

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKV6846R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,RR BUMPER	Deformed	539.90 FS	*539.90 FS
2	1		*RETAINER,RR BUMPER L	Not Necessary	58.30 FS	*- FS
3	1		*RETAINER,RR BUMPER L	Not Necessary	105.70 FS	*- FS
4	1		*RETAINER,RR BUMPER R	Necessary	58.30 FS	*58.30 FS
5	1		*RETAINER,RR BUMPER R	Necessary	105.70 FS	*105.70 FS
6	1		*REINFORCEMENT,RR	Bent	386.60 FS	*386.60 FS
7	1		*ARM,RR BUMPER,OUTE	Not Necessary	66.20 FS	*- FS
8	1		*ARM,RR BUMPER,OUTE	Not Necessary	66.20 FS	*- FS
9	10		*CLIPS	Necessary	39.00 FS	*39.00 FS
10	1		*PANEL,LAMP LOWER	Repair	649.20 FS	*- FS
11	1		*LUGGAGE COMP EMBLEM	Necessary	59.70 FS	*59.70 FS
12	1		*EMBLEM,SYMBOL	Necessary	39.70 FS	*39.70 FS
13	1		*EMBLEM,SYMBOL	Necessary	44.10 FS	*44.10 FS
14	1		*PLATE,RR FLOOR	Not Necessary	234.30 FS	*- FS
15	1		*BACK SENSOR (3R3) 310A	Not Necessary	159.75 FS	*- FS
16	1		*PANEL LUGGAGE DR HG	Buckled	710.10 FS	*710.10 FS
17	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
18	1		*SEALANT-REAR END PANEL	Not Necessary	80.00 FS	*- FS
Total Parts (S\$)					3,432.75	2,013.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE & INSTALL REAR REVERSE SENSOR	New	154.00	154.00
2	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	154.00	154.00
3	REMOVE & INSTALL REAR BOOTLID CARPET,GARNISH AND TRIMMING TO ASSIST REPAIR	New	308.00	308.00
4	RESET ECU AND REPROGRAMME	New	462.00	462.00
5	REPLACE REAR BUMPER,REAR BUMPER REINFORCEMENT,ETC,STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	New	3,080.00	1,232.00
6	RESPRAY JOB ON NREAR ACCIDENT AFFECTED AREAS	New	2,530.00	1,518.00
Gross Labour Cost (\$\$)			6,688.00	3,828.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >