

Trans-cab Auto Services Pte Ltd

AAD1805-039

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9934R*Not Authorised
11/1/2018*

Vehicle No.:

SHB 9934R

Chassis No.:

VF1ABL15AUC273104

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

5.5.2018

Third Party Insurer :

AIG

PART		LIST	
1	FENDER PANEL FRT LH	\$	783.83
1	WHEELARCH FRT LH	\$	278.84
1	FENDER BRACKET LOWER LH	\$	15.79
1	FENDER INSULATOR LH	\$	130.84
1	DOOR PANEL FRT LH	\$	2,844.66
1	DOOR HINGE UPPER LH L70Y	\$	261.28
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK FRT LH	\$	194.77
1	DOOR CHECK BOLT	\$	22.69
1	DOOR LOCK FRT LH	\$	908.75
1	DOOR CATCH FRT LH	\$	131.23
1	DOOR HANDLE OUTER FRT LH	\$	477.76
1	DOOR HANDLE COVER FRT LH	\$	13.22
1	DOOR HANDLE MODULE FRT LH	\$	133.60
1	DOOR REGULATOR FRT LH	\$	505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97
1	DOOR PANEL REAR LH L70Y	\$	2,844.66
1	DOOR GUIDE REAR LH L70Y	\$	176.82
1	DOOR GUIDE SCREW	\$	10.85
1	DOOR HINGE UPPER LH L70Y	\$	274.50
1	DOOR HINGE LOWER L70Y	\$	300.55
1	DOOR HINGE BOLT	\$	10.85
1	DOOR HINGE NUT L70Y	\$	14.60
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06
1	DOOR CHECK BOLT	\$	22.69
1	DOOR CHECK NUT	\$	3.75
1	DOOR LOCK REAR LH L70Y	\$	908.75
1	DOOR LOCK SCREW L70Y	\$	6.12

Trans-cab Auto Services Pte Ltd**AAD1805-039**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9934R

1	DOOR CATCH SCREW L70Y	\$	10.06
1	DOOR HANDLE OUTER REAR LH L70Y	\$	126.49
1	DOOR HANDLE CAP REAR LH L70Y	\$	35.52
1	DOOR HANDLE SEAL REAR LH L70Y	\$	7.89
1	DOOR HANDLE COVER REAR LH L70Y	\$	13.22
1	DOOR HANDLE MODULE REAR LH L70Y	\$	133.60
1	DOOR REGULATOR REAR LH L70Y	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH L70Y	\$	423.10
1	DOOR MOULDING REAR LH L70Y	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH L70Y	\$	1,509.06
1	DOOR WATER SHIELD REAR LH L70Y	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH L70Y	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR GRAB HANDLE REAR LH L70Y	\$	210.96
1	DOOR BLIND REAR LH L70Y	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH L70Y	\$	410.66
1	DOOR SEAL REAR LH L70Y	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH L70Y	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH L70Y	\$	115.64
1	FENDER PANEL REAR LH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR LH	\$	543.47
1	BUMPER COVER REAR	\$	1,108.46
1	BUMPER LOWER REAR	\$	768.84
1	BUMPER BRACKET CTR REAR	\$	113.47
1	BUMPER RETAINER LH REAR	\$	44.99
1	BUMPER BEAM REAR	\$	777.52

Trans-cab Auto Services Pte Ltd

AAD1805-039

No. 2, Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9934R

1	BUMPER BEAM BRACKET LH REAR	\$	225.95	} X
1	DOOR MIRROR ASSY LH	\$	1,483.40	
1	TAILLAMP LH	\$	552.55	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	
1	ROCKER PANEL INNER LH	\$	1,024.79	
1	ROCKER PANEL CENTER LH	\$	990.25	

\$	31,992.86
----	------------------

10% \$	3,199.29
--------	-----------------

\$	28,793.57
----	------------------

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	WHEELARCH CLIP FRT LH	\$	30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	6000
1	FRONT DOOR STICKER 'Chassis'	\$	50.00	1500
1	REAR DOOR STICKER '6555 3333'	\$	80.00	6000

TOTAL	\$	518.00
--------------	----	---------------

TOTAL PARTS	\$	29,311.57
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	6000
----	----------	------

Putty and spray painting of the affected portion.

\$	4,000.00	11000
----	----------	-------

To rust-proofing of the affected areas.

\$	170.00	300
----	--------	-----

Trans-cab Auto Services Pte Ltd

AAD1805-039

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9934R

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	601 380.00
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	na 380.00 X
To replace, refix and top up coolant for radiator	\$	na 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	na 170.00 X

TOTAL	\$	10,710.00
--------------	-----------	------------------

Over All Total	\$	40,021.57
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15 DAYS~~

4 days

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--