

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBC2796J

TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA

Claim Type: Third Party

Accident Date: 10/05/2018

Estimate No: ES1890514

Date: 10 May 2018

Policy No: 5073860219-02

Veh Reg No: GBC2796J

Make/Model: NISSAN NV200 VAN

Chassis No: VSKYBAM20U0024348

Engine No: K9KF276D123048

Reg. Date: 27/10/2011

Estimate Repair Cost to Vehicle No :GBC2796J

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Net Price	
1 REAR BUMPER	624.80	1 PC	624.80	—
2 REAR BUMPER INNER SPONGE	133.80	1 PC	133.80	—
3 REAR BUMPER REFLECTOR	66.60	2 PC	133.20	—
4 REAR BUMPER CLIP	2.60	6 PC	15.60	—
5 TAILLAMP	258.70	2 PC	517.40	—
6 REAR TAILGATE LH	1,470.40	1 PC	1,470.40	—
7 LH TAILGATE LOGO	66.40	1 PC	66.40	—
8 LH TAILGATE EMBLEM-MV200	106.70	1 PC	106.70	—
9 LH TAILGATE OUTER GARNISH	336.00	1 PC	336.00	—
10 LH TAILGATE INNER RUBBER	96.40	1 PC	96.40	508.00
11 LH TAILGATE INNER LOCK BOTTOM	101.70	1 PC	101.70	—
12 LH TAILGATE INNER LOCK UPP	101.70	1 PC	101.70	—
13 LH TAILGATE INNER LOCK CENTRE	167.70	1 PC	167.70	—
14 LH TAILGATE BOTTOM HINGE	107.10	1 PC	107.10	—
15 LH TAILGATE INNER TRIM BOARD	210.00	1 PC	210.00	—
16 RH TAILGATE	960.90	1 PC	960.90	—
17 RH TAILGATE LOWER HINGE	107.10	1 PC	107.10	—
18 RH TAILGATE EMBLEM "Dci"	56.20	1 PC	56.20	—
19 RH TAILGATE INNER LOCK -BOTTOM,	101.70	1 PC	101.70	—
20 RH TAILGATE INNER LOCK UPP	101.70	1 PC	101.70	—
21 RH TAILGATE INNER LOCK CENTRE	116.70	1 PC	116.70	—
22 RH TAILGATE INNER RUBBER	96.40	1 PC	96.40	508.00
23 RH TAILGATE INNER TRIM BOARD	152.50	1 PC	152.50	—
24 RH TAILGATE FRAME RUBBER	101.40	1 PC	101.40	—
25 REAR END PANEL OUTER	264.20	1 PC	264.20	—
26 REAR WIPER ARM	79.60	1 PC	79.60	—
			6,327.30	
		Less 10%	632.73	5,694.57
Special Net				
27 LH TAILGATE GLASS SEALANT	40.00	1 PC	40.00	—
28 RHTAILGATE GLASS SEALANT	40.00	1 PC	40.00	—
29 REVERSE SENSOR	200.00	1 PC	200.00	—
30 TAILGATE STICKER - 70KM/H	10.00	1 PC	10.00	—
31 TAILGATE STICKER - 3PAX	10.00	1 PC	10.00	—
			300.00	300.00
Labour				
32 REMOVE AND REFIX REAR LH TAILGATE GLASS	80.00	1 LA	80.00	60.00
33 REMOVE AND REFIX REAR RH TAILGATE GLASS	80.00	1 LA	80.00	60.00
34 TO PANEL BEATING	1,350.00	1 PCS	1,350.00	900.00
35 TO PUTTY AND RESPRAY ON REAR AFFECTED AREAS	1,100.00	1 LA	1,100.00	900.00
36 RUSTPROOFING	90.00	1 LA	90.00	—
			2,700.00	2,700.00
		Total		SS 8,694.57
		Add GST @ 7%		608.62
		Total Amount Payable		SS 9,303.19

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd