

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/05/2018 09:44
Date Of Accident	06/05/2018 08:30
Exact Location Of Accident	MARISLING DR TWDS ADMIRALTY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8656U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	KWA CHOON ENG
NRIC No	S2538738D
Date Of Birth	11/09/1954
Occupation	OUTDOOR
Date Of Driving Pass	02/03/1974
Driving Experience	44 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91152413
Fax Number	
Contact Number	
EMail Address	JOHNSTONKWA@YAHOO.COM.SG

Address	BLK 339 BUKIT BATOK STREET 34 #07-306
Postcode	650339
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD9566J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ABAS BIN OTHMAN
NRIC/Passport Number	S1794458D
Contact Number	
Address	
Postcode	
Insurance Company Name	AXA INSURANCE PTE LTD
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO REG. NO. 199303821R

6/5/18
Reporting Centre Personnel

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On. 6 May 2018 @ 08:30 hr I Veh A
 was driving along Marking Br. Tuks. Admiralty Rd
 along the way I veh A stop to pick up
 passenger the passenger about to open the
 door. Suddenly veh B from rear hit veh A
 Rear - No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


COMFORT TRANSPORTATION PTE LTD
 CO REG NO 199303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

615/18
 600501
 COA
 Jherka



A member of COMFORTDELGRO

Date/Time: 07.05.2018 11:15 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305157281

CUSTOMER COMFORT TRANSPORTATION PTE LTD MS 7010045 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO. SHC8656U	MILEAGE
	MAKE TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4)06.05.2018	DATE/TIME IN 11:10
	YR OF MANU 05.07.2017	TARGET DATE
	CHASSIS CODE JTDKB3FU103561417	COMPLETION DATE/TIME:

AXA

JOB DESCRIPTION

Accident Date: 06.05.2018
 NATURE: 3P 06.05.2018

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

Vehicle No.: SHC8656U LKE

Vehicle No.: SHC8656U

Signature/Date of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE

VEHICLE NO : SHC 8656U

7/5/2018 11:43

MAKE :

MODEL : TOYOTA PRIUS

Lice

PbyP
AXA

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER X			\$ 922.50
REAR TRUNK LID LOCK X			\$ 447.70
REAR TRUNK LID GLASS (BLACK COLOR) X			\$ 721.30
REAR TRUNK LID LOGO(PRIUS) /			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) /			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) /			\$ 52.90
REAR BUMPER /			\$ 458.60
REAR BUMPER RE-INFORCEMENT /			\$ 318.80
REAR BUMPER UNDER COVER /			\$ 552.60
REAR BUMPER SIDE RETAINER ?			\$ 112.70
REAR BUMPER UNDER SIDE COVER (LH)(RH) /			\$ 232.00
REAR BUMPER CLIPS /			\$ 22.00
TAIL LAMP ASSY (UPPER) (RH) ?			\$ 557.90
TAIL LAMP ASSY (LOWER) (RH) /			\$ 548.40
REAR END PANEL X <i>repair</i>			\$ 602.10
REAR END PANEL GARNISH ?			\$ 121.60
REAR FENDER, RH X			\$ 817.50
REAR FENDER SHEILD (RH) X			\$ 134.20
SUB TOTAL			\$ 6,736.00
LESS 25%			\$ 1,684.00
DISCOUNTED TOTAL			\$ 5,052.00
REAR TRUNK LID APPS STICKER /			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STCIKER /			\$ 60.00
REAR BUMPER REVERSE SENSOR /			\$ 135.70
REAR BUMPER RUBBER MAT X			\$ 50.00
			\$ 285.70
LABOUR CHARGE			\$ 600
Panel Beating <i>Kalvin (KKA)</i>			\$ 850.00
Spray Painting Charge <i>9/5/18 1x35hr</i>			\$ 5x0 600.00
Wiring Charge <i>3 Days</i>			\$ 20 50.00
Tuff Kote <i>P/P</i>			\$ X 50.00
Front Chassis Alignment Charge <i>Before Panel photo</i>			\$ X 400.00
Remove/Refix Cushion & Upholstery Rear			\$ X 150.00
Remove/Refix Rear Windscreen Glass			\$ X 120.00
Remove/Refix Reverse Sensor			\$ 20 120.00
TOTAL LABOUR			\$ 2,340.00
ESTIMATE TOTAL			\$ 7,677.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.

REPAIR ESTIMATE

VEHICLE NO : SHC 8656U

7/5/2018 11:43

MAKE :

Lice

PbyP
AXA

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER X <i>sc</i>			\$ 922.50
REAR TRUNK LID LOCK X <i>sc</i>			\$ 447.70
REAR TRUNK LID GLASS (BLACK COLOR) X <i>sc</i>			\$ 721.30
REAR TRUNK LID LOGO(PRIUS) - <i>sc</i>			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) - <i>sc</i>			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) - <i>sc</i>			\$ 52.90
REAR BUMPER - <i>sc</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT - <i>sc</i>			\$ 318.80
REAR BUMPER UNDER COVER - <i>sc</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>sc</i>			\$ 112.70
REAR BUMPER UNDER SIDE COVER (LH)(RH) - <i>sc</i>			\$ 232.00
REAR BUMPER CLIPS - <i>sc</i>			\$ 22.00
TAIL LAMP ASSY (UPPER) (RH) <i>sc</i>			\$ 557.90
TAIL LAMP ASSY (LOWER) (RH) - <i>sc</i>			\$ 548.40
REAR END PANEL X <i>sc</i>			\$ 602.10
REAR END PANEL GARNISH <i>sc</i>			\$ 121.60
REAR FENDER, RH X <i>sc</i>			\$ 817.50
REAR FENDER SHEILD (RH) X <i>sc</i>			\$ 134.20
<i>Rear Bumper towing cost - cut \$14.90</i>			
SUB TOTAL			\$ 6,736.00
LESS 25%			\$ 1,684.00
DISCOUNTED TOTAL			\$ 5,052.00
REAR TRUNK LID APPS STICKER - <i>sc</i>			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STCIKER - <i>sc</i>			\$ 60.00
REAR BUMPER REVERSE SENSOR - <i>sc</i>			\$ 135.70
REAR BUMPER RUBBER MAT X <i>sc</i>			\$ 50.00
			\$ 285.70
LABOUR CHARGE			\$ 600
Panel Beating			\$ 850.00
Spray Painting Charge			\$ 500.00
Wiring Charge			\$ 20 50.00
Tuff Kote			\$ 20 X 50.00
Front Chassis Alignment Charge			\$ 20 X 400.00
Remove/Refix Cushion & Upholstery Rear			\$ 20 X 150.00
Remove/Refix Rear Windscreen Glass			\$ 20 X 120.00
Remove/Refix Reverse Sensor			\$ 20 120.00
TOTAL LABOUR			\$ 2,340.00
ESTIMATE TOTAL			\$ 7,677.70

Kalvin (K14)
9/5/18 1435hrs
3 Days
PIP
Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508999
Fax: 6546 8156

Our Job Ref No 305157281
Date : 12/05/18

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr KALVIN ANG
Vehicle Reg No. SHC8656U CTPL 06.05.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA --- SHD9566J
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$1,970. ⁶⁰</u>
(b) Labour Charges	<u>\$1,180.00</u>
Total for Part-By-Part Repair Cost	<u>\$3,150. ⁶⁰</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	_____
Final Lumpsum Repair cost	_____

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Calvin
Date : 14/5/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.05.2018

REPAIR ESTIMATE

Time: 13:26:29

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305157281
 REGN NO : SHC8656U
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 05.07.2017
 DATE/TIME IN : 06.05.2018 11:10
 ACCIDENT DATE : 06.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1 L	458.60	25.00	343.95
0002	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1 L	552.60	25.00	414.45
0003	04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1 L	318.80	25.00	239.10
0004	09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1 N	135.70	2.50-	135.70
0005	04-01-0302-2267-G	PRIVC BUMPER PIECE	10 L	22.00	25.00	16.50
0006	04-01-0302-0795-G	PRIG4 LENS AND BODY REAR	1 L	548.40	25.00	411.30
0007	04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1 L	14.70	25.00	11.02
0008	04-01-0302-2965-G	PRIG4 FILLER-REAR BUMPER	1 L	232.00	25.00	174.00
0009	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1 L	60.80	25.00	45.60
0010	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1 L	52.40	25.00	39.30
0011	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1 L	52.90	25.00	39.67
0012	28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1 N	40.00	2.50-	40.00
0013	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1 N	30.00	0.25	30.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.05.2018

REPAIR ESTIMATE

Time: 13:26:29

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305157281
REGN NO : SHC8656U
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 05.07.2017
DATE/TIME IN : 06.05.2018 11:10
ACCIDENT DATE : 06.05.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0014 28-01-0302-0006-A PRIVC REAR BOOT 65521111	1	N		30.00	0.03-	30.00

SUB-TOTAL : 1,970.59

JOB NATURE

0000 L	PANEL BEATING	600.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	540.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-22	REMOVE/REFIX REVERSE SENSOR	20.00
SUB-TOTAL :		1,180.00
TOTAL :		3,150.59

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
COMFORTDELGRO ENGINEERING PTE LTD		Ref : CS/QW18008582/K1qbs2	
59 LOYANG DRIVESINGAPORE 508969		Date : 17-05-2018	
		Code : QW007	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	Veh. Inspected	SHC 8656U
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	09/05/2018
2. Vehicle Particulars & Condition			
	Make & Model	TOYOTA PRIUS	c.c 1798
	Engine No.	HIDDEN	Year of Reg. 2017
	Chassis No.	JTDKB3FU103561417	Colour BLUE
	Odometer	122916	Steering IN ORDER
	Brakes	IN ORDER	Modification STANDARD ALLOY RIM
	General	FAIR	
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	195/65R15	BRIDGESTONE
	L/H Front Tyre	195/65R15	BRIDGESTONE
	R/H Rear Tyre	195/65R15	BRIDGESTONE
	L/H Rear Tyre	195/65R15	BRIDGESTONE
			Balance
			7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	06/05/2018	Inspection Date 09/05/2018
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969	
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8656U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TRUNK LID COVER	SERVICEABLE	922.50	-
1	REAR TRUNK LID LOCK	SERVICEABLE	447.70	-
1	REAR TRUNK LID GLASS (BLACK COLOUR)	SERVICEABLE	721.30	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	CRACKED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER UNDER SIDE COVER (RH)	CRACKED	232.00	232.00
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	TAIL LAMP ASSY (UPPER) (RH)	SERVICEABLE	557.90	-
1	TAIL LAMP ASSY (LOWER) (RH)	CRACKED	548.40	548.40
1	REAR END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	REAR END PANEL GARNISH	SERVICEABLE	121.60	-
1	REAR FENDER, RH	SERVICEABLE	817.50	-
1	REAR FENDER SHIELD (RH)	SERVICEABLE	134.20	-
1	REAR BUMPER TOWING COVER	CUT	14.70	14.70
	LESS 25% DISCOUNT		-1,687.67	-578.30
			5,063.03	1,734.90
<u>SPECIAL NETT ITEMS</u>				
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
			285.70	235.70
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		850.00	600.00
	SPRAY PAINTING CHARGE.		600.00	540.00
	WIRING CHARGE.		50.00	20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.	NOT NECESSARY	50.00	-
	FRONT CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	NOT NECESSARY	150.00	-
	REMOVE / REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX REVERSE SENSOR.		120.00	20.00
			2,340.00	1,180.00
	GRAND TOTAL		7,688.73	3,150.60
	RECOMMENDED COST OF REPAIRS			3,150.60

Report Ref No. CS/QW18008582/K1qbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.