

ASS. REC. BY:

REP: CS / FCL10008584 / Kltbmr Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWB Soren Ler of FCL Date/Time: 10052018 1022am

Estimated Cost: Bill to:

OD /  WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 9951Y Insured: SHD 3259K

at Workshop m/s Premier Tel: 6344 6689

of 23 Chungi South Ave 2 #03-02

Policy No: Claim No: D18003711MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 08052018 (Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 10052018 11:20am Person Contacted: Vincent Vehicle  IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 9951Y - x
	SHD 3259K - 003 / ATH / 80051132 / Riebs DAF - 190318
11/5-4:24pm	revert via preli advise.





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 6

Your Ref: D18003711MFSH

Date: 11/5/2

Our Ref: CS/FC18008584/K1tb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8951Y.**

Please be informed that we had conducted the inspection of the abovementioned  
10/5/18 at the premises of M/s Premier and have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,179.40</u>
Revised Estimate Amount	: S\$ <u>3,191.30</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>          </u>
LTA Reimbursement Value	: S\$ <u>          </u>
Nett Value	: S\$ <u>          </u>

**Description of Damage:**

The vehicle sustained damages at the  
n/s body portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	09-05-2018	<b>Our Ref No.</b> D18003711MFSH
<b>Accident Date</b>	08-05-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD3259K	<b>Third Party Vehicle.</b> SHB8951Y
<b>Survey Location</b>	23 CHANGI SOUTH AVENUE 2 #03-02	
<b>Contact Person.</b>	VINCENT CHUA	
<b>Contact No.</b>	65446676/ 65446689	<b>Fax No.</b> 62141511
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 11 May 2018 4:24 PM  
**To:** Admin-D (LKKAuto); 'Claim Workflow System'; assignment  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18003711MFSH/1  
**Attachments:** PRELI ADVISED SHB 8951Y.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 8951Y**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 10 May 2018 11:12 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assign  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18003711MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 10 May, 2018 10:32 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SERENELER@MSFIRSTCAPITAL.COM.SG](mailto:SERENELER@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18003711MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	25 Apr 2014 / 09:25:10	Receipt No.:	AACCK001-AX239-140425-000006
Asset Type:	Vehicle	Transaction Amount:	\$72,769.00
Asset ID:	SHB8951Y	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140425092510464155		
Vehicle No.:	SHB8951Y		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	25 Apr 2014		
Original Registration Date:	25 Apr 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5462558		
Engine No.:	D4FDDH307943		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$20,184.00		
Minimum PARF Benefit:	\$7,654.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	25 Apr 2014 09:25:10		
COE No.:	2014042501000980K		
COE Expiry Date:	24 Apr 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$59,871.00		
Lifespan Expiry Date:	24 Apr 2022		
Owner ID Type:	Company		

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

9-May-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8951 Y

1 pc	Front n/s fender — <i>Def</i>	\$	384.00
1 pc	Front n/s fender inner shield — <i>cm</i>	\$	120.00
1 pc	Front n/s headlamp X <i>see</i>	\$	1,028.00
1 pc	Front bumper — <i>Rehd</i>	\$	531.00
1 pc	Front bumper emblem — <i>see</i>	\$	44.00
1 pc	Front bumper n/s side retainer — <i>cm</i>	\$	16.00
1 pc	Front bumper n/s upper bracket — <i>see</i>	\$	16.00
1 pc	Front bumper n/s support bracket — <i>see</i>	\$	16.00
1 pc	Front n/s wheel cover X <i>see</i>	\$	116.00
1 pc	n/s mirror assy — <i>see</i>	\$	590.00
1 pc	Front n/s door X <i>repair</i>	\$	765.00
	<i>Front Bumper</i> — <i>see</i>	\$ 979	
	<i>Front n/s Door moulding</i> — <i>see</i>	\$ 87	
	<i>Front n/s Door handle</i> — <i>see</i>	\$ 40	
		Less 10%	
		<u>\$</u>	<u>3,262.00</u>
			<u>\$ 3,263.40</u>

**S/NETT**

1 set	Front n/s fender inner shield clips — <i>see</i>	\$	28.00
1 set	Front bumper clips — <i>see</i>	\$	48.00
1 pc	Front n/s fender sticker X <i>see</i>	\$	30.00
1 set	n/s door stickers — <i>see</i>	\$	100.00
	Sundry <i>see</i>	\$	<del>50.00</del> 20
	To check wheel alignment	\$	<del>80.00</del> + 19
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> + 20
	To dismantle and refit the inner component of the front n/s door into new shell door	\$	<del>150.00</del> + 60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bonnet, etc.	\$	<del>750.00</del> 600
	To putty and spray painting on bonnet, front bumper, front n/s fender, n/s side mirror, front n/s door, rear n/s door, rear bumper X <i>see</i>	\$	<del>800.00</del> 700
	To apply rustproofing on the repaired and replaced panels.	\$	<del>200.00</del> 50
	<i>Kabin (1600)</i>	\$	<u>6,179.40</u>
	<i>10/5/18 1115hrs.</i>		
	<i>4 Days.</i>		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
*45 Repair After Repair photo*

7174.80



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18008584/K1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3259K	Veh. Inspected	SHB 8951Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18003711MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	10/05/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5462558	Colour	SILVER
Odometer	490948	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/05/2018	Inspection Date	10/05/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8951Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT N/S FENDER	DENTED	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	CRACKED	120.00	120.00
1	FRONT N/S HEADLAMP	SERVICEABLE	1,028.00	-
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER N/S SIDE RETAINER	CRACKED	16.00	16.00
1	FRONT BUMPER N/S UPPER BRACKET	CRACKED	16.00	16.00
1	FRONT BUMPER N/S SUPPORT BRACKET	CRACKED	16.00	16.00
1	FRONT N/S WHEEL COVER	SERVICEABLE	116.00	-
1	N/S MIRROR ASSY	CRACKED	590.00	590.00
1	FRONT N/S DOOR	TO REPAIR SEE LABOUR	765.00	-
1	FRONT BONNET	DENTED	979.00	979.00
1	FRONT N/S DOOR MOULDING	CUT	87.00	87.00
1	FRONT N/S DOOR HANDLE	CRACKED	40.00	40.00
	LESS 10% DISCOUNT		-473.20	-282.30
			4,258.80	2,540.70
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET N/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			256.00	196.00
<b><u>LABOUR</u></b>				
	TO CHECK WHEEL ALIGNMENT	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF THE FRONT N/S DOOR INTO NEW SHELL DOOR.	NOT NECESSARY	150.00	-

Report Ref No. CS/FC118008584/K1tbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE BONNET, ETC. INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR.		750.00	600.00
	TO PUTTY AND SPRAY PAINTING ON BONNET, FRONT BUMPER, FRONT N/S FENDER, N/S SIDE MIRROR, FRONT N/S DOOR, REAR N/S DOOR, REAR BUMPER, REAR N/S DOOR HANDLE.		1,300.00	800.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	50.00
			2,660.00	1,450.00
	<b>GRAND TOTAL</b>		<b>7,174.80</b>	<b>4,186.70</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,350.00</b>

Report Ref No. CS/FCI18008584/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.