

INS. CASE OWNER:

CC 4/ASM1800

8585

1/11/18

LKK:

IDAC:

44368

S' rveyor:

DOI:

ASSIGNMENT

10/5/18

Date / Time :

9/5/2018.

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

YP 6494M

"VIRTUAL"

Claim No. :

SSM006LB

Name of Insured :

SPM SERVICES

Policy No. :

VCA/P1947320

Insured Tel No. :

HP:

Make / Model :

Isuzu

Excess Sec II :SS

D.O.A :

9/5/2018

Place of Accident :

Tan Boek Sang Corp

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

K HORAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

82303062

(V/L: YES / NO)

Insured Liability :

%

Final ? Yes / No

YP 6494M

SHC 6393R

PC 232E



INSRS:

WSP:

Tel :

Liability :

RMKS:

01



INSRS:

WSP:

Tel :

Liability :

RMKS:

Premium

Tp



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date / Time

20/5/18

SHC 6393R - X; YP 6494M - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

14/5

Sent By:

Hm

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Ruk

Repair Cost:

46 SS 13,500

(0 days)

Reduction:

30 %

Email

Call

FINAL SETTLEMENT

Date/Time: 26-2-19

Confirm with GARY

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 37

If NO or B 28, Ass. Lia :

Repair Cost:

10/4/18 SS 13,315.00

OLD REPAIR ENDED TP

Loss of Rental (LOR):

SS 811.52

(8 days)

X * 101.44

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TW

3) Survey fee:

*350

Total:

SS 14,188.52

Global Sum SS: 10,000

FINAL PAYMENT

Date/Time: 26-2-19

Confirm with: GARY

Email

Call

Payee 1:

SS 10,000.00

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

(08/11/13)

REF:

Surveyor: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6393R Yr Regn: 27 Feb 2015Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Tra~~ / Prime Mover /

Truck / Trailer or

Make: KIA Optima C.C. 1685Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 287827 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH M414MF557827

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt orBrake: Insured / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD SR / Rim orTyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 9/5/8 D.O.I. 10/5/8Survey held at PRAIR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt / Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>21/5/8</u>	<u>Insured 45 \$12501 / 8 Rep.</u>
	<u>Canal finish</u>
	<u>AXA</u>
	<u>43</u>
	<u>Virtual</u>
	<u>(RED: 95,417-50 30%)</u>

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

9-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6393 R

1 pc	Bonnet	Repl	\$	979.00	✓
1 pc	Bonnet insulator	X su	\$	219.00	X
1 pc	Bonnet lock	X su	\$	36.00	X
1 pc	Bonnet lifter	X su	\$	70.00	X
1 pc	Bonnet lock base	X su	\$	13.00	X
2 pc	Bonnet hinge o/s & n/s @ \$23.00	X su	\$	46.00	X
1 pc	Bonnet weatherstrip	X su	\$	58.00	X
1 pc	Bonnet lock cover	X su	\$	15.00	X
1 pc	Bonnet cable long	X su	\$	25.00	X
1 pc	Bonnet cable short	X su	\$	15.00	X
1 pc	Bonnet grille	Repl	\$	385.00	✓
1 pc	Support panel	Repl	\$	645.00	✓
1 pc	Front bumper	Repl	\$	531.00	✓
1 pc	Front bumper emblem	Repl	\$	44.00	✓
1 pc	Front bumper centre grille	X su	\$	174.00	X
1 pc	Front bumper lower stiffer	X su	\$	134.00	X
1 pc	Front bumper tow hook cover	X su	\$	14.00	X
1 pc	Front bumper lip	X su	\$	52.00	X
1 pc	Front bumper inner sponge	✓ fin	\$	110.00	✓
1 pc	Front bumper reinforcement	✓ fin	\$	328.00	✓
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	X su	\$	32.00	X
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	X su	\$	32.00	X
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	X su	\$	32.00	X
2 pcs	n/s & o/s headlamp @ \$1028.00	Repl	\$	2,056.00	✓
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00	X su	\$	132.00	X
2 pcs	Front bumper o/s & n/s protector @ \$51.00	X su	\$	102.00	X
1 pc	Air con condenser	Repl	\$	805.00	✓
1 pc	Radiator	Repl	\$	669.00	✓
1 pc	Washer tank motor	X su	\$	48.00	X
1 pc	Washer tank	X su	\$	47.00	X
1 pc	Air duct	Repl	\$	210.00	✓
1 pc	Boot lid	Repl	\$	1,119.00	✓
1 pc	Boot lid lock	Repl	\$	99.00	✓
1 pc	Bootlid lock cable	X su	\$	35.00	X
1 pc	Bootlid striker	X su	\$	21.00	X
1 pc	Bootlid emblem	Repl	\$	27.00	✓
1 pc	Bootlid CRDi	Repl	\$	29.00	✓
1 pc	Boot lid rubber weatherstrip	✓ fin	\$	96.00	✓
1 pc	Boot lid lower garnish	Repl	\$	290.00	✓
2 pcs	Bootlid hinge @ \$66.00	Repl	\$	132.00	✓
2 pcs	Bootlid hinge torsion bar @ \$33.00	X su	\$	66.00	X
1 pc	Bootlid inner trim	Repl	\$	190.00	✓

8744

9-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6393 R

1 pc	End panel <i>✓ Ant</i>	\$	250.00 ✓
1 pc	End panel garnish <i>✓ cr</i>	\$	74.00 ✓
1 pc	Towing hook bracket <i>✓ su</i>	\$	68.00 X
1 pc	Spare tyre clamp <i>✓ cr</i>	\$	6.00 ✓
2 pcs	Rear o/s & n/s tail lamp @ \$421.00 <i>— cr</i>	\$	842.00 ✓
2 pcs	Bootlid n/s & o/s reflector @ \$350.00 <i>— cr</i>	\$	700.00 ✓
1 pc	Rear bumper <i>— Ant</i>	\$	696.00 ✓
1 pc	Rear bumper lower cover <i>— Ant</i>	\$	206.00 ✓
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>✓ or</i>	\$	58.00 ✓
1 pc	Rear bumper inner sponge <i>✓ Ant</i>	\$	114.00 ✓
1 pc	Rear bumper reinforcement <i>✓ cr</i>	\$	607.00 ✓
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>✓ cr</i>	\$	108.00 ✓
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>✓ cr</i>	\$	36.00 ✓
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>✓ cr</i>	\$	36.00 ✓
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>X su</i>	\$	92.00 X
		\$	14,055.00
		Less 10%	\$ 1,405.50
			\$ 12,649.50

S/NETT

1 set	Rear bumper clips <i>— su</i>	\$	48.00 ✓
1 set	End panel inner garnish clips <i>X su</i>	\$	30.00 X
1 set	Bootlid inner trim clips <i>X su</i>	\$	52.00 X
1 set	Bootlid lower garnish clips <i>X su</i>	\$	60.00 X
1 set	Bootlid stickers <i>— su</i>	\$	100.00 ✓
1 set	Reverse sensor <i>— Ant</i>	\$	280.00 200 ✓
1 set	Floorboard compartment insulating paddings <i>X su</i>	\$	120.00 X
1 pc	Front no. plate with casing <i>— Ant</i>	\$	50.00 35 ✓
1 pc	Front bumper clips <i>— su</i>	\$	48.00 ✓
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 <i>— su</i>	\$	12.00 ✓
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 <i>— su</i>	\$	6.00 ✓
1 set	Bonnet insulator clips <i>X su</i>	\$	52.00 X
1 PC	Rear bumper top protector <i>— su</i>	\$	80.00 ✓

9-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6393 R

Towing Fee	\$	50.00	/
Sundry	ncl \$	50.00	20
To check for wiring and to focus head lamps	\$	80.00	20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50
3360			
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, front n/s & o/s fender etc, Rear LH, RH taillamp panel	\$	1,600.00	1400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, front bumper, bonnet grille, bonnet, front n/s & o/s fender, rear LH, RH taillamp panel.	\$	2,000.00	1700
To apply rustproofing on the repaired and replaced panels.	\$	250.00	100
	\$	17,917.50	

18953.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka/ha 10/5/18
10/5/18 1025h
8 Days.
L/S
After Repair p/ha.

21/5/18
control 45812500/8h
N

PREMIER AUTOMOTIVE SERVICES PTE LTD


23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

19-May-18

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6393 R

1 pc	Blower Assy		\$	596.00
			Less 10%	\$ 59.60
				<u>\$ 536.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

*THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.*



PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

9-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6393 R

1 pc	Bonnet	\$	979.00
1 pc	Bonnet insulator X	\$	219.00
1 pc	Bonnet lock X	\$	36.00
1 pc	Bonnet lifter X	\$	70.00
1 pc	Bonnet lock base X	\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 X	\$	46.00
1 pc	Bonnet weatherstrip X	\$	58.00
1 pc	Bonnet lock cover X	\$	15.00
1 pc	Bonnet cable long X	\$	25.00
1 pc	Bonnet cable short X	\$	15.00
1 pc	Bonnet grille	\$	385.00
1 pc	Support panel	\$	645.00
1 pc	Front bumper	\$	531.00
1 pc	Front bumper emblem	\$	44.00
1 pc	Front bumper centre grille X	\$	174.00
1 pc	Front bumper lower stiffer X	\$	134.00
1 pc	Front bumper tow hook cover X	\$	14.00
1 pc	Front bumper lip X	\$	52.00
1 pc	Front bumper inner sponge ?	\$	110.00
1 pc	Front bumper reinforcement ?	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 X	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 X	\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 X	\$	102.00
1 pc	Air con condenser ?	\$	805.00
1 pc	Radiator ?	\$	669.00
1 pc	Washer tank motor ?	\$	48.00
1 pc	Washer tank ?	\$	47.00
1 pc	Air duct ?	\$	210.00
1 pc	Boot lid	\$	1,119.00
1 pc	Boot lid lock	\$	99.00
1 pc	Bootlid lock cable ?	\$	35.00
1 pc	Bootlid striker ?	\$	21.00
1 pc	Bootlid emblem	\$	27.00
1 pc	Bootlid CRDi	\$	29.00
1 pc	Boot lid rubber weatherstrip ?	\$	96.00
1 pc	Boot lid lower garnish ?	\$	290.00
2 pcs	Bootlid hinge @ \$66.00	\$	132.00
2 pcs	Bootlid hinge torsion bar @ \$33.00	\$	66.00
1 pc	Bootlid inner trim	\$	190.00

9-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6393 R

1 pc	End panel ?	\$	250.00
1 pc	End panel garnish ?	\$	74.00
1 pc	Towing hook bracket ?	\$	68.00
1 pc	Spare tyre clamp ?	\$	6.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00 ✓	\$	842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00 ✓	\$	700.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✕	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 ✕	\$	92.00
		\$	14,055.00
		Less 10%	\$ 1,405.50
		\$	12,649.50

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	End panel inner garnish clips ?	\$	30.00
1 set	Bootlid inner trim clips ?	\$	52.00
1 set	Bootlid lower garnish clips ?	\$	60.00
1 set	Bootlid stickers ✓	\$	100.00
1 set	Reverse sensor ✓	\$	280.00 200
1 set	Floorboard compartment insulating paddings ✕	\$	120.00
1 pc	Front no. plate with casing ✓	\$	50.00 35
1 pc	Front bumper clips ✓	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 ✓	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 ✓	\$	6.00
1 set	Bonnet insulator clips ✕	\$	52.00
1 PC	Rear bumper top protector ✓	\$	80.00

9-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6393 R

Towing Fee	\$	50.00	/
Sundry	\$	50.00	20
To check for wiring and to focus head lamps	\$	80.00	20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, front n/s & o/s fender etc	\$	1,600.00	1400
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, front bumper, bonnet grille, bonnet, front n/s & o/s fender	\$	2,000.00	1700
To apply rustproofing on the repaired and replaced panels.	\$	250.00	100
	\$	17,917.50	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka/ha 10/11/14
11 10/5/18 1025km
8 Days.
L/s
After Repair plz.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Victory Recovery (Business Reg No.: 53096358B)
65 Teban Gardens Rd #23-617, Singapore 600065.
Mobile: 9618 0311 Fax: 6267 8996

CASH /
W.O. No. 93055

TOW JOB WORKS ORDER

M Premier Taxi Svc Date 9/5/18
Car Make/Model Kia Vehicle No. SHC6393R
M'ship/NRIC No./Card No. _____ Contact No. _____
Time - Rec'd 12.30 Arrived 12.50 Completed 13.25
Amount Charge S\$ _____ Tow Truck No. Y48128
Destination (from) Tan Tuck Seng Link (to) Changi L1
Remark (if any) _____

Tow Driver's Signature  Member's Signature _____

- ☐ Change Tyres & Towing
- ☐ Basement / Multi Carpark
- ☐ Causeway / 2nd Link

- ☐ Using King Dolley
- ☐ Low Spoiler / Low Oil Sump
- ☐ Accident / Over-turn

- ☐ Use Car Carrier
- ☐ Release Brake / Shaft
- ☐ Loaded

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.



SERVICE REQUESTS

MESSAGES

CLAIMS

**Re:RE: Re:RE: Re:RE: VIRTUAL CASE, DO NOT FINALISE ON COR.**

Type

Question

Message

Hi We are looking at around \$5K. VO

[Reply](#)



**RE: Re:RE: Re:RE: Re:RE: Re:RE: VIRTUAL CASE, DO NOT
FINALISE ON COR.**

Type

🔔 Question

Message

Hi Vale, TP disagreed with our offer and counter propose G/S \$11,500. (Asher Sng - 29/01/19)

Reply



Re:: VIRTUAL CASE, DO NOT FINALISE ON COR.

Type

🔔 Question

Message

Hi Pls counter offer global sum of S\$10k (all in)-VO

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YP 6494M (Insd veh)	Model:	KIA OPTIMA
	SHC 6393R (TP veh)		
Date of Accident:	09/05/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	19,745.67
Final Repair Cost	:	\$	13,375.00
Loss of Token Sum	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	811.52 8 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum (GLOBAL SUM)	:	\$ 10,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100 _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	PREMIER AUTOMOTIVE SERVICES PTE LTD	\$ 10,000.00

NUR SHAQILAH BTE ABDOL
WAHAB

06/03/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008585/K1ea3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: VALE OH		Date : 06-03-2019 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 6494M	Veh. Inspected	SHC 6393R	
Policy No.	VCA/P1947320	Coverage (\$)	0.00	
Claim No.	S8M00GLB	Excess (\$)	0.00	
Assign From	VALE OH	Assign Date	09/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5578217	Colour	SILVER	
Odometer	287827	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65R16	MAXXIS	7 mm	
L/H Front Tyre	205/65R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/05/2018	Inspection Date	10/05/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6393R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET (CONSISTENT)	DENTED	979.00	979.00
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	219.00	-
1	BONNET LOCK (CONSISTENT)	SERVICEABLE	36.00	-
1	BONNET LIFTER (CONSISTENT)	SERVICEABLE	70.00	-
1	BONNET LOCK BASE (CONSISTENT)	SERVICEABLE	13.00	-
2	BONNET HINGE O/S & N/S @ \$23.00 (CONSISTENT)	SERVICEABLE	46.00	-
1	BONNET WEATHERSTRIP (CONSISTENT)	SERVICEABLE	58.00	-
1	BONNET LOCK COVER (CONSISTENT)	SERVICEABLE	15.00	-
1	BONNET CABLE LONG (CONSISTENT)	SERVICEABLE	25.00	-
1	BONNET CABLE SHORT (CONSISTENT)	SERVICEABLE	15.00	-
1	BONNET GRILLE (CONSISTENT)	CRACKED	385.00	385.00
1	SUPPORT PANEL (CONSISTENT)	BENT	645.00	645.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM (CONSISTENT)	NECESSARY	44.00	44.00
1	FRONT BUMPER CENTRE GRILLE (CONSISTENT)	SERVICEABLE	174.00	-
1	FRONT BUMPER LOWER STIFFENER (CONSISTENT)	SERVICEABLE	134.00	-
1	FRONT BUMPER TOW HOOK COVER (CONSISTENT)	SERVICEABLE	14.00	-
1	FRONT BUMPER LIP (CONSISTENT)	SERVICEABLE	52.00	-
1	FRONT BUMPER INNER SPONGE (CONSISTENT)	TORN	110.00	110.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	328.00	328.00
2	FRONT BUMPER O/S & N/S SIDE RETAINER @ \$16.00 (CONSISTENT)	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S UPPER BRACKET @ \$16.00 (CONSISTENT)	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @ \$16.00 (CONSISTENT)	SERVICEABLE	32.00	-
2	N/S & O/S HEADLAMP @ \$1028.00 (CONSISTENT)	CRACKED	2,056.00	2,056.00
2	FRONT BUMPER O/S & N/S FOG LAMP COVER @ \$66.00 (CONSISTENT)	SERVICEABLE	132.00	-
2	FRONT BUMPER O/S & N/S PROTECTOR @ \$51.00 (CONSISTENT)	SERVICEABLE	102.00	-
1	AIR CON CONDENSER (CONSISTENT)	BENT	805.00	805.00

Report Ref No. CC4/ASM18008585/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR (CONSISTENT)	BENT	669.00	669.00
1	WASHER TANK MOTOR (CONSISTENT)	SERVICEABLE	48.00	-
1	WASHER TANK (CONSISTENT)	SERVICEABLE	47.00	-
1	AIR DUCT (CONSISTENT)	CRACKED	210.00	210.00
1	BOOT LID (CONSISTENT)	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK (CONSISTENT)	BENT	99.00	99.00
1	BOOTLID LOCK CABLE (CONSISTENT)	SERVICEABLE	35.00	-
1	BOOTLID STRIKER (CONSISTENT)	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM (CONSISTENT)	NECESSARY	27.00	27.00
1	BOOTLID CRDI (CONSISTENT)	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP (CONSISTENT)	TORN	96.00	96.00
1	BOOT LID LOWER GARNISH (CONSISTENT)	CRACKED	290.00	290.00
2	BOOTLID HINGE @ \$66.00 (CONSISTENT)	BENT	132.00	132.00
2	BOOTLID HINGE TORSION BAR @ \$33.00 (CONSISTENT)	SERVICEABLE	66.00	-
1	BOOTLID INNER TRIM (CONSISTENT)	CRACKED	190.00	190.00
1	END PANEL (CONSISTENT)	DENTED	250.00	250.00
1	END PANEL GARNISH (CONSISTENT)	CRACKED	74.00	74.00
1	TOWING HOOK BRACKET (CONSISTENT)	SERVICEABLE	68.00	-
1	SPARE TYRE CLAMP (CONSISTENT)	CRACKED	6.00	6.00
2	REAR O/S & N/S TAIL LAMP @ \$421.00 (CONSISTENT)	CRACKED	842.00	842.00
2	BOOTLID N/S & O/S REFLECTOR @ \$350.00 (CONSISTENT)	CRACKED	700.00	700.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER (CONSISTENT)	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @ \$29.00 (CONSISTENT)	CRACKED	58.00	58.00
1	REAR BUMPER INNER SPONGE (CONSISTENT)	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S @ \$53.00 (CONSISTENT)	CRACKED	108.00	108.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00 (CONSISTENT)	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00 (CONSISTENT)	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @ \$46.00 (CONSISTENT)	SERVICEABLE	92.00	-

Report Ref No. CC4/ASM18008585/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BLOWER ASSY (CONSISTENT) (ADDITIONAL)	CRACKED	596.00	596.00
	LESS 10% DISCOUNT		-1,465.10	-1,307.30
			13,185.90	11,765.70
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	SET FLOORBOARD COMPARTMENT INSULATING PADDINGS (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT NO. PLATE WITH CASING (SN) (CONSISTENT)	DENTED	50.00	35.00
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	48.00	48.00
2	FRONT N/S & O/S HEAD LAMP LOWER CLIP @ \$6.00 (SN) (CONSISTENT)	NECESSARY	12.00	12.00
2	FRONT N/S & O/S HEAD LAMP SIDE CLIP @ \$3.00 (SN) (CONSISTENT)	NECESSARY	6.00	6.00
1	SET BONNET INSULATOR CLIPS (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	REAR BUMPER TOP PROTECTOR (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	SUNDRY (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			988.00	549.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.		80.00	20.00
	TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE / REFIT INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00

Report Ref No. CC4/ASM18008585/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT / WELD, CUT-OFF THE THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FLOORBOARD COMPARTMENT, FRONT N/S & O/S FENDER ETC, REAR LH, RH TAILLAMP PANEL.		1,600.00	1,400.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL, FRONT BUMPER, BONNET GRILLE, BONNET, FRONT N/S & O/S FENDER, REAR LH, RH TAILLAMP PANEL.		2,000.00	1,700.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	100.00
			4,280.00	3,340.00
GRAND TOTAL			18,453.90	15,654.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,500.00

Report Ref No. CC4/ASM18008585/K1ea3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.