

22/03/2012

ASS. REC. BY:

REF:

CS/SM018008587/Drbn2

Special Instruction:

Surveyor:

Bryan

ASSIGNMENT (Office)

From (Person):

Grace Leo

of

SMO

Date/Time:

08052018 331pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 4768Y

Insured:

- PC 1419P

at Workshop m/s

Teamwork

Tel:

of

53 ubi Rd 1 #01-24

Policy No:

Claim No:

OM101801948 / NSW

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07052018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpt

H.O.D. Endorsement:

Date/Time:

08052018

11:55pm

Person Contacted:

Daren

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKQ 4768Y - NA / CT18008344 / zh

DCA: 07052018

PC 1419P - CS/SM017006304 / Mlg302

DCA: 29032017

21/1/19

Email preli. revised to Grace

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKQ 4768 Y Regn: 2014 Dec
 Type: M.CAR / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Mercedes Benz B180 C.G. 1595
 Colour: Grey A/C Insured / Std / NI / NA
 Sp. Reading: 43668 T/Radio: Insured / Std / NI / NA
 Eng/No: 27091030501322
 C/No: WDD24624225287807
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55 R16
 R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Michelin

Front	Rear
R/Bal. <u>S</u> mm	R/Bal. <u>S</u> mm
L/Bal. <u>S</u> mm	L/Bal. <u>S</u> mm
D.O.A. <u>07/05/2018</u>	D.O.I. <u>09/05/2018</u>

Survey held at Teamwork Paya ubi

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sompo PC 1419P01/02/19 jinan 4/5 5200/- with 4 days of rep. (Red 11,670, 6910)

RECEIVED 02 JAN 2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation:

21 - typistAdd Fee: ☐ Site Insp (\$

) S+R5 \$

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Others

☐ Weekend (\$

)

Report Format:

TP

Lump Sum / I.B.I. (\$

5200/-450

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1801948/NSW

Our ref: CS/SMO18008587/Dvb

Date: 2/1/2019

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKQ 4768Y


We thank you for your instruction on 8/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 9/5/2018 at the premises of M/s TEAMWORK GARAGE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$16,870.00
Revised Estimate Amount	: S\$5,200.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 2 January 2019 11:25 AM
To: 'Teo, Grace'
Cc: 'Ngo, Sau Wei Shawn'; 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD1801948/NSW - SUV(LKK)/ PC1419P & SKQ4768Y ACC ON 07.05.18
Attachments: SKQ 4768Y PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SKQ 4768Y
Date of survey: 9/5/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 8 May 2018 4:29 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801948/NSW - SUV(LKK)/ PC1419P & SKQ4768Y ACC ON 07.05.18

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Tuesday, 8 May, 2018 3:31 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: TEAMWORK GARAGE CLAIMS <claims@teamworkgarage.com>; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1801948/NSW - SUV(LKK)/ PC1419P & SKQ4768Y ACC ON 07.05.18

Our Reference: CMTD1801948/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for SKQ4768Y.

Please be informed that Shawn Ngo the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: TEAMWORK GARAGE CLAIMS [<mailto:claims@teamworkgarage.com>]

Sent: Tuesday, May 08, 2018 2:36 PM

To: Teo, Grace

Cc: Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; claims@teamworkgarage.com

Subject: RE: CMTD1801948/NSW - PRI/ PC1419P & SKQ4768Y ACC ON 07.05.18

Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop.

Darren Ng

Teamwork Garage Pte Ltd

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Tuesday, May 08, 2018 1:31 PM
To: Teamwork Garage Pte Ltd <claims@teamworkgarage.com>
Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1801948/NSW - PRI/ PC1419P & SKQ4768Y ACC ON 07.05.18

Our Reference: CMTD1801948/NSW
Your Reference: 1805-08

Without Prejudice

Date: 8th May 2018

Attention:
M/S TEAMWORK GARAGE PTE LTD

Dear Alison,

ACCIDENT INVOLVING PC1419P & SKQ4768Y ON 07.05.2018

We refer to your Notice of Accident dated 08/05/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teamwork Garage Pte Ltd [<mailto:claims@teamworkgarage.com>]

Sent: Tuesday, May 08, 2018 11:03 AM

To: Claims - Motor Survey

Cc: claims@teamworkgarage.com

Subject: PRE-REPAIR INSPECTION FOR SKQ4768Y (1805-08)

Importance: High

WITHOUT PREJUDICE

OUR REF: 1805-08

YOUR REF: PC1419P

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SKQ4768Y

ACCIDENT INVOLVING SKQ4768Y & PC1419P ON 07.05.2018

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.

Thank you.

Regards,

Alison
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 8 May, 2018 3:31 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: TEAMWORK GARAGE CLAIMS; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin
Subject: CMTD1801948/NSW - SUV(LKK)/ PC1419P & SKQ4768Y ACC ON 07.05.18
Attachments: 20180508110009314.pdf

Our Reference: CMTD1801948/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for SKQ4768Y.

Please be informed that Shawn Ngo the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: TEAMWORK GARAGE CLAIMS [mailto:claims@teamworkgarage.com]
Sent: Tuesday, May 08, 2018 2:36 PM
To: Teo, Grace
Cc: Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; claims@teamworkgarage.com
Subject: RE: CMTD1801948/NSW - PRI/ PC1419P & SKQ4768Y ACC ON 07.05.18
Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop.

Darren Ng
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Tuesday, May 08, 2018 1:31 PM
To: Teamwork Garage Pte Ltd <claims@teamworkgarage.com>
Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1801948/NSW - PRI/ PC1419P & SKQ4768Y ACC ON 07.05.18

Our Reference: CMTD1801948/NSW
Your Reference: 1805-08

Without Prejudice

Date: 8th May 2018

Attention:
M/S TEAMWORK GARAGE PTE LTD

Dear Alison,

ACCIDENT INVOLVING PC1419P & SKQ4768Y ON 07.05.2018

We refer to your Notice of Accident dated 08/05/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	

		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teamwork Garage Pte Ltd [<mailto:claims@teamworkgarage.com>]

Sent: Tuesday, May 08, 2018 11:03 AM

To: Claims - Motor Survey

Cc: claims@teamworkgarage.com

Subject: PRE-REPAIR INSPECTION FOR SKQ4768Y (1805-08)

Importance: High

WITHOUT PREJUDICE

OUR REF: 1805-08

YOUR REF: PC1419P

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SKQ4768Y

ACCIDENT INVOLVING SKQ4768Y & PC1419P ON 07.05.2018

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.

Thank you.

Regards,

Alison
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax: 6844 2474

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/05/2018 19:21
Date Of Accident	07/05/2018 09:50
Exact Location Of Accident	DEPOT RD TWDS BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ4768Y
Insured/Policyholder	
Name Of Registered Owner	TAN HONG KAI, RINO (CHEN HONGKAI, RINO)
NRIC No	S8340844H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90127987
Alternative Phone No	OFFICE-90127987
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	B180 (R16 BI)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3003581700
Cover Note Number	
Driver	
Name of Driver	TAN HONG KAI, RINO (CHEN HONGKAI, RINO)
NRIC No	S8340844H
Date Of Birth	02/12/1983
Occupation	OUTDOOR
Date Of Driving Pass	06/05/2004
Driving Experience	14 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90127987
Fax Number	
Contact Number	OFFICE-90127987
Email Address	NOEMAIL

Address	BLK 417 EUNOS ROAD 5
	#08-06
Postcode	400417
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	PC1419P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	INNASI VELANGANNI SURESH
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN HONG KAI, RINO (CHEN HONGKAI, RINO)
------	---

Accident Sketch Plan

REPORT NO.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was completely stationary along Depot Rd towards
 Bullet road, with a safe distance and no contact with the
 front stationary vehicle, at the right most lane. All of a
 sudden, I felt an impact from the rear portion of my
 car. I got off my car and found that veh B had hit onto
 my rear rear portion.

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/TIN No.:

Accident File No.:



Teamwork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 ROC number : 201015366H
3RD PARTY CLAIM ESTIMATION

Sompo Insurance Pte Ltd
 50 Raffles Place , #05-01/06
 Singapore Land Tower
 Singapore 048623

Vehicle number	SKQ4768Y
Make / Model	MERCEDES/BENZ B180
Chassis number	WDD2462422J287807
Accident date	07 May 2018
Reference	1805-08

Qty	Particulars	Unit Price - SGD \$
-----	-------------	---------------------

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>distorted mounting crack</i>	1432.00 1835.00 ✓
1	REAR BUMPER TOP GUARD PLATE <i>Nuc</i>	175.00 470.00 ✓
2	REAR BUMPER CHROME MOULDING <i>S/C</i>	350.00 X
1	REAR BUMPER REINFORCEMENT <i>Dented</i>	456.00 599.00 ✓
1	END PANEL <i>new</i>	1051.00 X
1	END PANEL TOP GARNISH <i>NH</i>	291.00 X
1	REAR BUMPER INNER BRACKET <i>NH</i>	218.00 X
1	TAILGATE <i>Dented</i>	1790.00 2500.00 ✓
2	TAILGATE ABSORBER <i>NH</i>	318.00 X
2	TAILGATE INNER HINGE <i>NH</i>	188.00 X
1	TAILGATE OUTER GARNISH <i>chrome mounting crack</i>	257.00 1519.00 ✓
1	TAILGATE WEATHERSTRIP <i>NH</i>	297.00 X
1	TAILGATE LOCK ASSY <i>NH</i>	397.00 X
1	TAILGATE LOCK STRIKER <i>NH</i>	53.00 X
1	TAILGATE INNER TRIM <i>NH</i>	352.00 X
1	TAILGATE LOGO <i>Nuc</i>	61.00 ✓
1	TAILGATE EMBLEM - B180 <i>Nuc</i>	92.00 ✓
2	TAILGATE INNER LAMP <i>o/s crack mounting n/s NH</i>	448.50 897.00 LL
2	TAILLAMP <i>o/s crack mounting n/s NH</i>	544.00 1088.00 LL
4	PDC SENSOR <i>Dom 2 pc NH 2 pc</i>	450.00 1224.00 LL
		13800.00
		Less 10 % 1380.00
		Subtotal 12420.00
		Balance C/F 12420.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
		Balance B/F 12420.00
1 SET	REAR BUMPER CLIP <i>Nuc</i>	60.00 30/-
1	REAR NUMBER PLATE <i>NH</i>	80.00 X
1	WINDSCREEN SEALANT <i>Nuc</i>	150.00 40/-
1	JOINT SEALANT <i>NH</i>	150.00 X
		Subtotal 440.00
		Balance C/F 12860.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
		Balance B/F 12860.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-

4	REMOVE AND REFIT REAR WINDSCREEN	150.00	80/-
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00	214
6	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00	60/-
7	PANEL BEATING ON AFFECTED AREAS	1200.00	500/-
8	SPRAY PAINTING ON AFFECTED AREAS	1400.00	500/-
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00	40/-
09/05/2023 C 1100WS		Subtotal	4010.00
KIA Nuthurst		Grand total	16870.00
2/5mm 4 days.			

ryan
LKK Auto

6534.95
4/5 5200/-

KK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Notified by Repairer

Signature:

1:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18008587/Dvbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 04-01-2019



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 1419P	Veh. Inspected	SKQ 4768Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801948/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	08/05/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2462422J287807	Colour	GREY
Odometer	43668	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	5 mm
L/H Front Tyre	205/55 R16	MICHELIN	5 mm
R/H Rear Tyre	205/55 R16	MICHELIN	5 mm
L/H Rear Tyre	205/55 R16	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2018	Inspection Date	09/05/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 4768Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED / MOUNTING CRACKED	1,835.00	1,432.00
1	REAR BUMPER TOP GUARD PLATE	NECESSARY	470.00	175.00
2	REAR BUMPER CHROME MOULDING	SERVICEABLE	350.00	-
1	REAR BUMPER REINFORCEMENT	DENTED	599.00	456.00
1	END PANEL	NOT NECESSARY	1,051.00	-
1	END PANEL TOP GARNISH	NOT NECESSARY	291.00	-
1	REAR BUMPER INNER BRACKET	NOT NECESSARY	218.00	-
1	TAILGATE	DENTED	2,500.00	1,790.00
2	TAILGATE ABSORBER	NOT NECESSARY	318.00	-
2	TAILGATE INNER HINGE	NOT NECESSARY	188.00	-
1	TAILGATE OUTER GARNISH CHROME	MOUNTING CRACKED	1,519.00	257.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	297.00	-
1	TAILGATE LOCK ASSY	NOT NECESSARY	397.00	-
1	TAILGATE LOCK STRIKER	NOT NECESSARY	53.00	-
1	TAILGATE INNER TRIM	NOT NECESSARY	352.00	-
1	TAILGATE LOGO	NECESSARY	61.00	61.00
1	TAILGATE EMBLEM-B180	NECESSARY	92.00	92.00
2	TAILGATE INNER LAMP	O/S MOUNTING CRACKED / N/S NOT NECESSARY	897.00	448.50
2	TAILLAMP	O/S MOUNTING CRACKED / N/S NOT NECESSARY	1,088.00	544.00
4	PDC SENSOR	DAMAGED (2 PCS) / NOT NECESSARY (2 PCS)	1,224.00	450.00
	LESS 10% DISCOUNT		-1,380.00	-570.55
			12,420.00	5,134.95
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00

Report Ref No. CS/SMO18008587/Dvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	JOINT SEALANT (SN)	NOT NECESSARY	150.00	-
			440.00	70.00
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	80.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	80.00
	DIAGNOIS CHECK AND CLEAR FAULT CODE.	NOT NECESSARY	500.00	-
	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.		1,200.00	500.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,400.00	500.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			4,010.00	1,330.00
GRAND TOTAL			16,870.00	6,534.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CS/SMO18008587/Dvbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.