



Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Estimate To Repair

Vehicle No :

Chassis No :

HONDA VEZEL HYBRID 1.5X AUTO

SLR3048G

RU3242354

GST / ROC Company No :

201101753C

Third Party Insurer :

AIG

Insured's Veh No :

SLF5895C

Date of accident :

24/04/2018

Quotation No : AR/QO18/04-1079

Quotation Date : 25/04/2018

Pages :

1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	FRT BUMPER DIS	\$861.00
2	1PC	FRT BUMPER RETAINER LH 3rd	\$40.00
3	10PC	FRT BUMPER CLIPS neu	\$55.00
4	1PC	FRT BUMPER BEAM (BELOW HEADLAMP) LH	\$42.00
5	1PC	FRT BUMPER REINFORCEMENT	\$381.00
6	1PC	FRT FOG LAMP GARNISH LH Twi	\$68.00
7	1PC	FRT HEADLAMP LH one	\$1,985.00
8	1PC	FRT FENDER LH 3rd	\$429.00
9	1PC	FRT FENDER INNER COWLING LH	\$165.00
10	10PC	INNER COWLING CLIPS neu	\$55.00
11	1PC	FRT BUMPER LOWER SPOILER	\$431.00
12	1PC	FRT FENDER PROTECTOR LH To. 1	\$198.00
13	1PC	FRT FENDER "HYBRID" PLATE neu	\$105.00
			\$4,815.00
LESS 20%			\$963.00
			\$3,852.00
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$20.00
2		LABOUR CHARGE	\$500.00
3		SPRAY PAINTING	\$600.00
Total			\$1,120.00
Sub Total			\$4,972.00
GST (7.00%)			\$348.04
Total			\$5,320.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418