

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TP/AIG.
SKL3344U

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 09/05/2018

TP Veh Reg No: SLJ1345D

Estimate No: ES1890506/WS

Date: 09 May 2018

Policy No: 5018026086-11

Veh Reg No: SKL3344U

Make/Model: NISSAN SUNNY 1.6EXM

Chassis No: JN1CFAN16Z0105331

Engine No: QG16418704

Reg. Date: 21/12/2006

Estimate Repair Cost to Vehicle No :SKL3344U

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 REAR BUMPER	452.50	1 PC	452.50	✓
2 REAR BUMPER MOULDING	175.20	1 PC	175.20	✓
3 REAR BUMPER SPONGE	126.20	1 PC	126.20	✓
4 REAR BUMPER SIDE RETAINER	33.30	1 PC	33.30	✓
5 REAR BUMPER CLIPS	3.90	6 PC	23.40	✓
6 REAR BUMPER RH BRACKET	86.60	1 PC	86.60	✓
7 REAR BOOT	674.60	1 PC	674.60	✓
8 REAR BOOT LOGO	46.10	1 PC	46.10	✓
9 REAR BOOT EMBLEM 'EX SALOON'	85.70	1 PC	85.70	✓
10 REAR BOOT EMBLEM 'SUNNY'	95.70	1 PC	95.70	✓
11 REAR BOOT TOP MOULDING	369.10	1 PC	369.10	✓
12 REAR BOOT LOWER MOULDING	208.30	1 PC	208.30	✓
13 REAR BOOT INNER RUBBER	80.30	1 PCS	80.30	50% in
14 REAR BOOT INNER LOCK	54.50	1 PCS	54.50	✓
15 REAR BOOT RH HINGE	81.30	1 PC	81.30	✓
16 TAIL LAMPS	329.80	2 PCS	659.60	✓
17 TAIL LAMP LOWER GARNISH	33.60	2 PCS	67.20	✓
18 REAR PANEL	335.60	1 PC	335.60	✓
19 REAR PANEL INNER TOP GARNISH	66.50	1 PC	66.50	✓
20 REAR PANEL INNER CLIPS	5.00	2 PCS	10.00	✓
21 REAR FENDER INNER GARNISH	233.30	2 PC	466.60	✓
22 REAR FENDER INNER GARNISH CLIPS	3.90	10 PC	39.00	✓
23 REAR BOOT INNER SPONGE	3.90	8 PC	31.20	✓
24 REAR SPARE TYRE TOP BOARD	452.30	1 PC	452.30	?
			4,720.80	
			Less 10%	472.08
				4,248.72
Special Net				
25 REAR BOOT EMBLEM 'CVTC'	70.00	1 PC	70.00	✓
26 REAR BOOT EMBLEM 'E-THROTTLE'	70.00	1 PC	70.00	✓
			140.00	140.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 09/05/2018

TP Veh Reg No: SLJ1345D

Estimate No: ES1890506/WS

Date: 09 May 2018

Policy No: 5018026086-11

Veh Reg No: SKL3344U

Make/Model: NISSAN SUNNY 1.6EXM

Chassis No: JN1CFAN16Z0105331

Engine No: QG16418704

Reg. Date: 21/12/2006


Estimate Repair Cost to Vehicle No :SKL3344U

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
27 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS, REAR BOOT, LOCK ASSY, MOULDING. TO CUTTING, WELDING AND RENEW REAR PANEL, TO STRAIGHEN. KNOCK AND REPAIR REAR FENDERS, REAR SPARE TYRE COMPARTMENT AND REALIGN THE SAME	1,000.00	1 LA	1,000.00	900
28 PUTTY AND RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR BUMPER, REAR FENDERS, REAR PANEL AND REAR AFFECTED AREA	900.00	1 LA	900.00	800
29 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,960.00	1,960.00

Total S\$ 6,348.72

Add GST @ 7% 444.41

Total Amount Payable S\$ 6,793.13



For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE