

27/03/2007

ASS REC BY:

REF:

CS/SMD18008608/Ttbn2

Special Instruction:

Surveyor:

Taufik.

ASSIGNMENT (Office)

From (Person):

Mehin Ye

of

SMD

Date/Time: 08052018 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 5080Y

Insured:

SKR 285U

at Workshop m/s

Zhong Cheng

Tel:

of

Blk 6399J Woodlands Rd

Policy No:

Claim No:

CMTD1801902 / AGC

Sum Insured:

Excess:

D.O.A.

04052018

Make of Veh:

(Client's Record)

09-052018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS Wp

Date/Time:

08052018 4:18pm

Person Contacted:

Sini

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJR 5080Y - CS/RES18008781/46

DIA: 04052018

SKR 285U - X

Confirm Lump Sum \$6500 (Red: 12462.20 :65%)

Tan Jiah

REF:

SMD

ASSIGNMENT

2019 June

2009 June

From:

Date:

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJR5080y

Yr Regn:

2009 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Lancer 1.6V

C.C. 1584

Colour:

Grey

A/C

Insured / Std / NI / NA

Sp. Reading

125108

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSTC33A94005667

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

10/5/18 @ 1715

Survey held at

Zhang Chen

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Report limit 4546500, 10 days

RECEIVED 13 DEC 2010

Date/Time. File Pass to?



Prel. Report



Final Report

Date/Time. File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation

\$ + RS \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / L.B.I. (\$

6500/-

450

Catherine Chong (LKK Auto)

From: Janice Kee <janice.kee@ksteoptr.com>
Sent: Tuesday, 8 May, 2018 4:06 PM
To: Catherine Chong (LKK Auto)
Subject: Fwd: Pre Repair Survey for SJR 5080 Y (Your Ref: SKR 285 U Our Ref: TKS/Z422-ACC-40272.18/sf)
Attachments: PRS.pdf

----- Forwarded message -----

From: **Ye, Yong Kang Melvin** <melvin.ye@sompo.com.sg>
Date: Mon, May 7, 2018 at 3:03 PM
Subject: RE: Pre Repair Survey for SJR 5080 Y (Your Ref: SKR 285 U Our Ref: TKS/Z422-ACC-40272.18/sf)
To: Janice Kee <janice.kee@ksteoptr.com>
Cc: "Chan, Shu Hui Agnes" <agnes.chan@sompo.com.sg>, "Teo, Grace" <grace.teo@sompo.com.sg>

Our Reference: CMTD1801902/AGC

Dear LKK AUTO,

Please make arrangement to conduct the survey for SJR 5080Y.

Please be informed that Ms Agnes Chan is the handler of this case.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Janice Kee [mailto:janice.kee@ksteoptr.com]

Sent: Monday, 7 May, 2018 2:12 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>; Zhong Cheng <zhongchengauto@gmail.com>

Subject: Re: Pre Repair Survey for SJR 5080 Y (Your Ref: SKR 285 U Our Ref: TKS/Z422-ACC-40272.18/sf)

Dear Sir

Our client has agree to the usage of LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,

Janice Kee

c/o, Teo Keng Siang LLC

111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

On Mon, May 7, 2018 at 9:35 AM, Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Reference: CMTD1801902/AGC

Your Reference: TKS/Z422-ACC-40272.18/sf(mc)

Without Prejudice

Date: 4 May 2018

Attention:

M/S TEO KENG SIANG LLC

Dear Janice,

ACCIDENT INVOLVING SJR 5080Y & SKR285U ON 04.05.2018

We refer to your Notice of Accident dated 04/05/2018.

Please be informed that Ms Agnes Chan is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Janice Kee [mailto:janice.kee@ksteoptr.com]

Sent: Friday, 4 May, 2018 5:52 PM

To: Teo, Grace <grace.teo@sompo.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Zhong Cheng <zhongchengauto@gmail.com>

Subject: Pre Repair Survey for SJR 5080 Y (Your Ref: SKR 285 U Our Ref: TKS/Z422-ACC-40272.18/sf)

Dear Sir

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you.

Regards,

Janice Kee

c/o Teo Keng Siang LLC

111 North Bridge Road,
#29-07/08 Peninsula Plaza,

Singapore 179098

Tel: 6333 4222 Fax: 6333 5676

Denise Tay (LKKAUTO)

From: zhong xiong Tan <zhongchengenterprise@hotmail.com>
Sent: Wednesday, 12 December 2018 3:19 PM
To: Taufikh (LKKAUTO)
Cc: Denise Tay (LKKAUTO)
Subject: Re: SJR5080Y repair limit
Attachments: SJR5080Y after.zip

Hi Taufikh,

Ok to accept. Attached pictures fyi.

Thanks

Best Regards
Sini Tan
Zhong Cheng Enterprise Pte Ltd
Blk 6, 399J
Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

From: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Sent: Wednesday, December 12, 2018 3:10 PM
To: 'zhong xiong Tan'
Cc: Denise Tay (LKKAUTO)
Subject: RE: SJR5080Y repair limit

Hi Sini,

As per our teleconversation, COR I/s \$6500 , 10 days.

Regards
Taufikh
Lkk Auto

From: zhong xiong Tan [mailto:zhongchengenterprise@hotmail.com]
Sent: Wednesday, 26 September 2018 6:39 PM
To: Taufikh (LKK Auto)
Subject: Re: SJR5080Y repair limit

Dear Taufikh,

Appreciate you can let me know this readjust limit.

Thank you

Sent from my iPhone

On 11 May 2018, at 10:14 AM, Taufikh (LKK Auto) <taufikh@lkkauto.com> wrote:

Hi Sini,

Sharing
&
Serving

COME VOLUNTEER WITH US!

If you are 40 years old and above and are able to spend half a day every month to contribute your talents and skills in many meaningful ways, we want you!



Mitsubishi Lancer 1.6

Price Range

Depreciation

2009

Vehicle Type



Search

Advanced
Search

Home » Used Cars » 1axis » Mitsubishi Lancer 1.6A GLX

Resources

Car Buying

Car Selling


Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Rental



Mitsubishi Lancer 1.6A GLX

Overview Financial Accessories Similar Research Photos Map

1axis

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$14,800

Depreciation \$7,970 /yr

View models with similar depreciation

Reg Date 30-Apr-2009
(11mths 18days COE left)

Manufactured 2008

Mileage 117,000 km (12.9k /yr)

Transmission Auto

Engine Cap 1,584 cc

Road Tax \$734 /yr

Power 79.0 kW (105 bhp)
View specs of the Mitsubishi Lancer (2006-2008)

Curb Weight 1,162 kg

Features 1.6L Inline 4 Cylinders 16 Valves Engine, 5 Speed CVT
Auto Transmission, Airbags, ABS.Accessories Sports Rim, Black Leather Seats, CD/Radio Player, Side
Indicator, Parking Sensor.Description Cheapest In Town With New Road Tax Till 29 OCT
2018. Sporty White LANCER. Nicely Done Up By
Previous Owner. View To Believe It. Act Now For
Appointment Test Drive This Beauty White Lancer.

COE \$7,326

OMV \$14,189

ARF \$14,189

Dereg Value \$7,803 as of today (change)

No. of Owners 3

Type of Veh Mid-Size Sedan

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note



Seller Information

Company

1axis

• dealer's price list
• 48 vehs sold | 32 vehs available

Address

5 Yishun Industrial Street 1 #01-18
Search cars nearby this location

Location

North Spring Bizhub

Contact Person(s)

Kervin Chia	88113768
Jack	84306433
Viki	90270337
Edward Chen	81800536

Posted on: 04-May-2018 | Last Updated on: 10-May-2018

Tags: Mitsubishi Lancer, 2009 Mitsubishi Lancer, Mitsubishi Lancer, Used Mitsubishi

Upfront Payment

* more financial info

Transfer Fee \$25

Down Payment \$4,440 (change)

Maximum 70% Loan

1st Instalment \$968

Total Upfront Payment \$5,433 (excluding insurance)

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Mitsubishi Lancer

* View All

Audio Panel Console
\$120Carbon Air Charger
\$180

Compare

Website

Company Profile

Used Car List

Make sure of this car condition
with STA Evaluation

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9959I
Vehicle Details	
Vehicle No.:	SJR5080Y
Vehicle to be Exported:	No
Intended De-registration Date:	11 May 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	4G18KC6716
Chassis No.:	JMYSTCS3A9U005667
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,024.00
Original Registration Date:	26 Jun 2009
First Registration Date:	26 Jun 2009
Transfer Count:	2
Actual ARF Paid:	\$13,024.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2019
PARF Rebate Amount:	\$7,163.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$1,447.00
Total Rebate Amount:	\$8,610.00

The information contained herein is correct as at 11 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/05/2018 12:26
Date Of Accident	04/05/2018 13:20
Exact Location Of Accident	ALONG CTE TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR5080Y
Insured/Policyholder	
Name Of Registered Owner	JAVE JASMINE LIM JAY MIN
NRIC No	S9049959I
Email Address	WJJCOOPER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87829826
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00602800
Cover Note Number	

Driver

Name of Driver	JAVE JASMINE LIM JAY MIN
NRIC No	S9049959I
Date Of Birth	23/12/1990
Occupation	INDOOR
Date Of Driving Pass	08/09/2009
Driving Experience	8 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87829826
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	WJJCOOPER@GMAIL.COM

Address	BLK 101 GANGSA ROAD #05-11
Postcode	670101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : LOW YEE SHIEN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to sketch plan.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR285U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG KOK KEONG
NRIC/Passport Number	
Contact Number	96795382
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SDD8992R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLG5870T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A 23R 5080Y
B 2KR 285U
C 2DD 8992R
D 26G 5890T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At mentioned details, I was driving along CTE on E 2nd lane. Suddenly vehicles ahead E-braked & I followed suit. Seconds later I heard & felt bang (impact) on my rear vehicle. When I got down, I realised it was chained collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJR5080Y

Adjustment of Spare Parts Costs for Repairs			Condition / Remark	Estimated by workshop
Item	Qty	Vehicle parts description		
1	1	rear bumper		672.00 <i>de</i> ✓
2	1	rear bumper centre retainer		160.00 <i>de</i> ✓
3	2	rear bumper side retainer @S\$36.00		72.00 <i>de</i> ✓
4	1set	rear bumper fasteners		36.00 <i>de</i> ✓
5	1	rear bumper lower skirt		660.00 <i>x un</i>
6	1set	rear bumper lower skirt fasteners		34.00 <i>x un</i>
7	1	bootlid		590.00 <i>bt</i> ✓
8	1	bootlid inner lock		85.00 <i>bt</i> ✓
9	1	bootlid lock striker		21.00 <i>x un</i>
10	1	bootlid garnish		125.00 <i>Ry</i>
11	1set	bootlid garnish fasteners		16.00 <i>x un</i>
12	1	bootlid logo emblem		38.00 <i>de</i> ✓
####	2	bootlid rubber damper @S\$24.00		48.00 <i>de</i> ✓
####	2	taillamp assy @S\$360.00		720.00 <i>un</i> ✓
####	2set	taillamp fasteners @S\$16.00		32.00 <i>de</i> ✓
####	2	taillamp inner panel @S\$59.00		118.00 <i>Ry</i>
####	1	rear end panel		420.00 <i>Ry</i>
21	1	rear end panel top garnish		118.00 <i>x un</i>
22	1set	rear end panel top garnish fasteners		25.00 <i>x un</i>
25	3	rear exhaust rubber mouting@S\$25.00		75.00 <i>x un</i>
26	1	rear exhaust muffler		478.00 <i>Ry</i>
28	1	RH rear fender		620.00 <i>Ry</i>
29	1	rear fender inner sheild RH		230.00 <i>x</i>
30	1 set	rear fender inner sheild fasteners		32.00 <i>x</i>
31	1	rear fender inner trim		214.00 <i>x</i>
32	1	rear fender inner trim fasteners		32.00 <i>x</i>
50	1	LH front fender		450.00 <i>bt</i> ✓
51	1	LH front fender fasteners		20.00 <i>de</i> ✓
52	1	LH front fender inner shield		115.00 <i>de</i> ✓
53	1	LH front fender inner shield fasteners		32.00 <i>de</i> ✓
54	1	LH front fender signal lamp		42.00 <i>de</i> ✓
64	1	front bumper		760.00 <i>de</i> ✓
65	1	front bumper reinforcement		140.00 <i>bt</i> ✓
66	2	front bumper side retainer		116.00 <i>de</i> ✓
67	1	front bumper logo emblem		45.00 <i>de</i> ✓
68	1set	front bumper fasteners		35.00 <i>de</i> ✓
69	1	front bumper center grille		80.00 <i>de</i> ✓
70	1	front bumper center lower grille garnish		60.00 <i>de</i> ✓
71	1set	front bumper clips		30.00 <i>de</i> ✓
72	1	front bumper lower skirt		570.00 <i>x un</i>
73	1set	front bumper lower skirt fasteners		32.00 <i>x un</i>
74	1	front upper grille		220.00 <i>un</i> ✓
75	2	front upper grille LH&RH garnish		180.00 <i>un</i> ✓

76	1set	front upper grille garnish fasteners
77	2	headlamps
78	2	fog lamps
79	2	fog lamps garnish
80	1	bonnet
81	1	bonnet inner lock
82	1	bonnet rubber seal
83	1	front support panel
84	1	radiator assy
85	1	radiator upper mouding w bracket
86	1	radiator lower mouding w bracket
87	1	air con condensor
88	1	air cleaner box assy
89	1	air intake duct
90	1	wiper washer tank
91	1	wiper washer motor
92	1	battery tray W bolt & bracket
93	1	front windscreen moudling
94	1	wiper panel garnish
95	1set	wiper panel garnish fasteners

20.00	ne	490
980.00	LH-8 RH-2	
770.00	x n	
84.00	x n	
590.00	bt	
75.00	bt	
37.00	ne	
580.00	bt	
750.00	bt	
36.00	bt	
36.00	bt	
980.00	bt	
320.00	one	
65.00	de	
97.00	x n	
120.00	x	
110.00	x	
140.00	x	
135.00	x	
35.00	x	

Less 10%

14558.00	8757
1455.80	
13102.20	7881.30

Special nett item

1	front number plate W frame casing
1	rear windscreen sealant
1	rear end panel sealant
1	reverse sensor
1	battery

50.00	we	45
60.00	x n	
60.00	200 n w	
250.00	200 n w	
200.00	x n	
620.00	245	

Adjustment of Labour Costs for Repairs

To remove and replaced damaged parts including straightening and repositioning replacement parts.

1400/1600.
2000.00

Supply paint material and necessary items. To respray replaced and other affected panels.

1600
1800.00

to remove and reinstall bootlid components

60.00 40.

To check wiring system for proper functions.

60.00 30

to remove and reinstall rear boot upholstery

80.00 40

To carry out front and rear anti rust treatment.	160.00 80
to remove and reinstall reverse sensor	80.00 30
to remove and reinstall and realign rear exhaust muffler	100.00 60
to remove and reinstall front windscreen	150.00 X n
to remove and reinstall fuel tank	80.00 X n
to straighten and realign chassis member	250.00 X n
to remove and refix radiator and condensor	100.00 ✓
to top up coolant and air con gas	60.00 ✓
towing services	120.00 80
to realign headlamps focus	40.00 20.
to do 4 wheel alignment	100.00 X n

18962.20

3740.

Total labour 5240.00

11866.30
 Taupin 97495749
 - up
 10/5/18 @ 1715
 11/5/18 @ 6500
 10 days
 10 days
 Resurvey after repair
 Sw@lkhauto.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18008608/T1tbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 20-12-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 285U	Veh. Inspected	SJR 5080Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801902/AGC	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	08/05/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER 1.6 A	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JMYSTCS3A9U005667	Colour	GREY
Odometer	125108	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/05/2018	Inspection Date	10/05/2018
Survey held at	ZHONG CHENG ENTERPRISE BLK 4 YEW TEE IND 393-H WOODLANDS ROAD SINGAPORE 677969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5080Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	672.00	672.00
1	REAR BUMPER CENTRE RETAINER	DEFORMED	160.00	160.00
2	REAR BUMPER SIDE RETAINER @\$36.00	NECESSARY	72.00	72.00
1	SET REAR BUMPER FASTENERS	NECESSARY	36.00	36.00
1	REAR BUMPER LOWER SKIRT	NOT NECESSARY	660.00	-
1	SET REAR BUMPER LOWER SKIRT FASTENERS	NOT NECESSARY	34.00	-
1	BOOTLID	BENT	590.00	590.00
1	BOOTLID INNER LOCK	BENT	85.00	85.00
1	BOOTLID LOCK STRIKER	NOT NECESSARY	21.00	-
1	BOOTLID GARNISH	TO REPAIR SEE LABOUR	125.00	-
1	SET BOOTLID GARNISH FASTENERS	NOT NECESSARY	16.00	-
1	BOOTLID LOGO EMBLEM	NECESSARY	38.00	38.00
2	BOOTLID RUBBER DAMPER @\$24.00	NECESSARY	48.00	48.00
2	TAILLAMP ASSY @\$360.00	CRACKED	720.00	720.00
2	SET TAILLAMP FASTENERS @\$16.00	NECESSARY	32.00	32.00
2	TAILLAMP INNER PANEL @\$59.00	TO REPAIR SEE LABOUR	118.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	420.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	118.00	-
1	SET REAR END PANEL TOP GARNISH FASTENERS	NOT NECESSARY	25.00	-
3	REAR EXHAUST RUBBER MOUTING @\$25.00	NOT NECESSARY	75.00	-
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	478.00	-
1	RH REAR FENDER	TO REPAIR SEE LABOUR	620.00	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	230.00	-
1	SET REAR FENDER INNER SHIELD FASTENERS	NOT NECESSARY	32.00	-
1	REAR FENDER INNER TRIM	NOT NECESSARY	214.00	-
1	REAR FENDER INNER TRIM FASTENERS	NOT NECESSARY	32.00	-
1	LH FRONT FENDER	BENT	450.00	450.00

Report Ref No. CS/SMO18008608/T1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH FRONT FENDER FASTENERS	NECESSARY	20.00	20.00
1	LH FRONT FENDER INNER SHIELD	DEFORMED	115.00	115.00
1	LH FRONT FENDER INNER SHIELD FASTENERS	NECESSARY	32.00	32.00
1	LH FRONT FENDER SIGNAL LAMP	DISTORTED	42.00	42.00
1	FRONT BUMPER	DEFORMED	760.00	760.00
1	FRONT BUMPER REINFORCEMENT	BENT	140.00	140.00
2	FRONT BUMPER SIDE RETAINER	NECESSARY	116.00	116.00
1	FRONT BUMPER LOGO EMBLEM	NECESSARY	45.00	45.00
1	SET FRONT BUMPER FASTENERS	NECESSARY	35.00	35.00
1	FRONT BUMPER CENTER GRILLE	DEFORMED	80.00	80.00
1	FRONT BUMPER CENTER LOWER GRILLE GARNISH	DEFORMED	60.00	60.00
1	SET FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
1	FRONT BUMPER LOWER SKIRT	NOT NECESSARY	570.00	-
1	SET FRONT BUMPER LOWER SKIRT FASTENERS	NOT NECESSARY	32.00	-
1	FRONT UPPER GRILLE	CRACKED	220.00	220.00
2	FRONT UPPER GRILLE LH & RH GARNISH	CUT	180.00	180.00
1	SET FRONT UPPER GRILLE GARNISH FASTENERS	NECESSARY	20.00	20.00
2	HEADLAMPS	O/S CRACKED / N/S NOT NECESSARY	980.00	490.00
2	FOG LAMPS	NOT NECESSARY	770.00	-
2	FOG LAMPS GARNISH	NOT NECESSARY	84.00	-
1	BONNET	BENT	590.00	590.00
1	BONNET INNER LOCK	BENT	75.00	75.00
1	BONNET RUBBER SEAL	NECESSARY	37.00	37.00
1	FRONT SUPPORT PANEL	BENT	580.00	580.00
1	RADIATOR ASSY	BENT	750.00	750.00
1	RADIATOR UPPER MOULDING W BRACKET	BENT	36.00	36.00
1	RADIATOR LOWER MOULDING W BRACKET	BENT	36.00	36.00
1	AIR CON CONDENSOR	BENT	980.00	980.00
1	AIR CLEANER BOX ASSY	CRACKED	320.00	320.00
1	AIR INTAKE DUCT	DEFORMED	65.00	65.00
1	WIPER WASHER TANK	NOT NECESSARY	97.00	-
1	WIPER WASHER MOTOR	NOT NECESSARY	120.00	-

Report Ref No. CS/SMO18008608/T1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BATTERY TRAY W BOLT & BRACKET	NOT NECESSARY	110.00	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	140.00	-
1	WIPER PANEL GARNISH	NOT NECESSARY	135.00	-
1	SET WIPER PANEL GARNISH FASTENERS	NOT NECESSARY	35.00	-
	LESS 10% DISCOUNT		-1,455.80	-875.70
			13,102.20	7,881.30
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE W FRAME CASING (SN)	NECESSARY	50.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	BATTERY (SN)	NOT NECESSARY	200.00	-
			620.00	245.00
	LABOUR			
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID GARNISH,TAILLAMP INNER PANEL,REAR END PANEL,REAR EXHAUST MUFFLER AND RH REAR FENDER.		2,000.00	1,600.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS.TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		1,800.00	1,600.00
	TO REMOVE AND REINSTALL BOOTLID COMPONENTS.		60.00	40.00
	TO CHECK WIRING SYSTEM FOR PROPER FUNCTIONS.		60.00	30.00
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY.		80.00	40.00
	TO CARRY OUT FRONT AND REAR ANTI RUST TREATMENT.		160.00	80.00
	TO REMOVE AND REINSTALL REVERSE SENSOR.		80.00	30.00
	TO REMOVE AND REINSTALL AND REALIGN REAR EXHAUST MUFFLER.		100.00	60.00
	TO REMOVE AND REINSTALL FRONT WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE AND REINSTALL FUEL TANK.	NOT NECESSARY	80.00	-
	TO STRAIGHTEN AND REALIGN CHASSIC MEMBER.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX RADIATOR AND CONDENSOR.		100.00	100.00

Report Ref No. CS/SMO18008608/T1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TOP UP COOLANT AND AIR CON GAS.	NOT NECESSARY	60.00	60.00
	TOWING SERVICES.		120.00	80.00
	TO REALIGN HEADLAMP FOCUS.		40.00	20.00
	TO DO 4 WHEEL ALIGNMENT.		100.00	-
			5,240.00	3,740.00
GRAND TOTAL			18,962.20	11,866.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CS/SMO18008608/T1tbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.