REF: NIA /741018	6008615 / S56 nz
	- CONTRACT
40	Voh No. S 115 (475) Yr Regn: 11/7/2014 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Date:	Veh No. Salis (413) Yr Regn.
From:	Type. m.car.
Estimated Cost. OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or C.c. 105/8
	Make: Insured / Std / NI / NA
To Inspect Vehicle No:	Colour Mult. (Oka-
at Workshop m/s	Sp.Reading 266198
of Insured SJK 51478	Eng/No: WMAH 22276 1= 7007199
- 2011 0117 - NO DL10-17 - 23-1	(0.18 C/No: Gen. Cond: Good / Fair / Poor / Burnt
Policy No. 50 39469311 00 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Gen. Cond: Good / Fair / Pool / Burnt Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	. A I I sawed I Burnt Or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	Tyre Size: F: 275/70822-5
	Pr ()
(Policy Condition)	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /
Remark: The veh had commenced its	TOYO/YOKO or Files &
repair at the time of inspection.	Rear Rear
Ball, or Market Value: Consistent?: Yes or No	R/Bal. R/Bal. 0/6
Consistent? · Yes or No	UBal. U/Bal. 6/6 mm
GIA / PR Section Res.: Yes or No	D.O.A. /// 4//8
Est. Repairs:	Survey held at SMRT
Lum Sum:	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: II	N / OUT The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted:	And the same of th
Date / Time Action / Instruction	
SJK 51478 - X	The second secon
JA 5416	1 2 Palm - 33%
21/05/18 (\$4,813.92 - \$3,200	0/- 7 Reduc - 33/6
	₩AY-2018 · · · · · · · · · · · · · · · · · · ·
-RECEIVED 2-1	MAY-2010
	and the second s
Daie/Time. File Pass to? : Prell. Report	Days Of Repair: 2
Beleffine File Pass to? : Prell. Report	Resurvey No. of Trip: O Survey Fee:
1995	- A SARS SI
Date/Type Pac Notation 5	Add Fee: Sito Insp (\$)S + RS or
P40	Tech. Invs (\$) Others
Report Format :	Week sind is
Report Format: Lump Sum / I.B.I: (S 3.200/-	TOTAL [60



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTU	JC INCOME INSU	RANCE CO-OPERATIVE LTD	Ref:	NS/INC180086	15/Ss3b	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	10-05-2018		
			Code:	INC4		
1.		Policy Particulars	:- THIR	D PARTY CLAIM		
	Insured Veh.	SJK 5147B	Veh. Ir	nspected	SMB 1473Y	
	Policy No.	5039469312-08	Cover	age (\$)	0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From		Assign Date		04/05/2018	
2.		Vehicle Parti	culars 8	Condition		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year o	f Reg.		
	Chassis No.	is No. Colour				
	Odometer -			Steering		
	Brakes		Modification			
	General			×=====================================		
3.		Conditi	ons of	Tyres		
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
		Description	on of Da	mages		
5.		Genera	Inform	ation		
	Accident Date	16/04/2018	A STATE OF S	tion Date	04/05/2018	
	Survey held at	SMRT AUTOMOTIVE SERVICE			0-700/2010	
		NO. 28 KIAN TECK DRIVE SINGAPORE 628845				
ia.	(Werestein 2)	Remarks				

eBao Tech							GeneralClaim			
Hello, NAC_PAYA_UBI_800601						Change La	nguage	· Change Passwor	rd + Log Out	
My Desktop	Policy Query									
Notice of Loss	Policy No.					Date of Acc	ident	16/04	/2018 19:06	
	Vehicle	No.(For Motor)	SJK5147B							
						Search				
	Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5039469312-08	CHIEW CHENG SAN	S1267709Z	GPC	drivo CLASSIC	SJK51478	SJK5147B	24/10/2017	23/10/2018
					- 1	Continue				

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0939315-003	SMRT BUSES LTD	SMB 1472A	SKJ 7179P	29/03/2017
2	MT/0995090-001	SMRT BUSES LTD	SMB 342Z	PC 8808D	14/09/2017
3	MT/0980389-002	SMRT BUSES LTD	SMB 5893S	PA 4137T	26/01/2018
4	MT/0939257-002	SMRT BUSES LTD	SMB 1582R	PA 8425K	25/03/2017
2	MT/0987666-002	SMRT BUSES LTD	SMB 1484R	SHB 8685R	27/2/2018
9	MT/0990787-002	SMRT BUSES LTD	SMB 1473Y	SJK 5147B	16/4/2018
7	MT/0985497-002	SMRT BUSES LTD	SMB 1515K	SGK454H	9/3/2018
	MT/0989067-002	SMRT BUSES LTD	SMB 61J	SJH 4630U	2/4/2018
6	MT/0991323-002	SMRT BUSES LTD	SG 1721J	EN 59Z	20/4/2018

Shirley Hiew (LKK Auto)

From: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>

Sent: Monday, 21 May 2018 9:07 AM

To: Shirley Hiew (LKK Auto)

Subject: FW: Finalisation - SMB1473Y (BUS/04/18/5018) - IDAC

Attachments: SMB_1473_Y_ESTIMATE_REPLY.pdf

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax; 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sebastian Yeang (LKK Auto) Sent: Thursday, 17 May 2018 4:04 PM

To: Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svs/AR & SC); AutoSvs-ARC (Bus)

Subject: RE: Finalisation - SMB1473Y (BUS/04/18/5018) - IDAC

Dear Catherine

Please refer to attachment for the finalization.

Thank You

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [mailto:catherineleesc@smrt.com.sg]

Sent: Wednesday, 16 May 2018 2:57 PM

To: Sebastian Yeang (LKK Auto)

Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svs/AR & SC); AutoSvs-ARC (Bus)

Subject: Finalisation - SMB1473Y (BUS/04/18/5018) - IDAC

Hi Sebastian,

Attached herewith our copy of the bus repair estimate for the case.

Our finalised amount is \$3,200/- @ 2 working days under lump sum repair.

Please confirm the COR by return email ASAP.

Thank you

Best Regards Catherine Lee SMRT Automotive Services Pte Ltd



Moving People, Enhancing Lives

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT				
Date Of Report	17/04/2018 11:47			
Date Of Accident	16/04/2018 08:25			
Exact Location Of Accident JUNC OF UPPER BKT TIMAH RD WITH CHUN TIN RD				

SINGAPORE

DETAILS OF	OWN V	EHICLE

Vehicle Registration Number SMB1473Y

Insured/Policyholder

Country/State of Loss

Name Of Registered Owner SMRT BUSES LTD

Co Reg No 198202292D Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-NOPHONE

Vehicle Particulars

Manufacturer MAN
Model MAN A22

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

BUS

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage THIRD PARTY

Fleet Policy YES

Policy Number D-18090224MFBP

Cover Note Number

Driver

Name of Driver EDMUND KONG

 NRIC No
 G7071355T

 Date Of Birth
 10/05/1983

 Occupation
 OUTDOOR

 Date Of Driving Pass
 25/04/2016

Driving Experience 1 YEAR AND 11 MONTHS

Gender MALE

Mobile Number Fax Number

Contact Number

EMail Address NOEMAIL

Address

NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

0

Insurance Company of Driver's Own Vehicle

į

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

5

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I was travelling straight on lane 2 of Upper Bukit Timah Road towards Bus Stop 42091 (Opp Bukit Timah Shopping Centre). As I was approaching the bus stop, I had to pass by Chun Tin Road. There was a private car approaching the stop line of Chun Tin Road. As my bus passed by Chun Tin Road, the pte car from drove out, turn left hence collided onto the left rear portion of my bus. The pte car had damages on the front right portion. No injury reported

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

PENDING DOWNLOAD

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJK5147B

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

CHIEW CHENG SAN

NRIC/Passport Number

S1267709Z

Contact Number

96277183

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

\$250 B

Policyholder's Signature Date & Time: 15

Driver's Signature (If driver is not the policyholder) Date & Time: The state of the s

Reporting Centre Personnel's Signature Name: BALQISH

NRIC/FIN No.: S8340325Z

Sketch Plan Pg. 2

SKETCH PLAN (MB14)	212				
B CJK514			LOCATION .		
0 40.00		JUNCTION OF UPIER BUKIT TIMAH ROAD MITH CHUN TIN ROAD CTOWARDS BUKIT PANJANG INTERCHANGE)			
~	~	•	E _		
	←	·	- OAON HAMIT TIMMA MISTU		
	-	·	Ka 1 2 4		
KIT TIMBH	2 2 1 4 9 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	PICK UP BAY	O LINE THE STATE OF THE STATE O		
SESCRIBE CIRC	CUMSTANCES C	OF THE ACCIDENT) B £ 1		
REFER TO	O REPORT				
-		-112111-1-1-1-1-1-1			
ECLARATION		#11/4/50/E012 - 4/7/2013 - 6/7/2013	(Color		
We declare the	foregoing particu	alars are true in every respect.	ALLION BALLON		
Policyholder's Sign Date & Time:	nature	Driver's Signature (If driver is not the policyh Date & Time:	Reporting Centre Personnel's Signature older) Name: BALQISH NRIC/FIN No.: S8340325Z		

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	C14D4473V
Vehicle No.:	SMB1473Y
Vehicle to be Exported:	No
Intended De-registration Date:	07 May 2018
Vehicle Make:	MAN
Vehicle Model:	NL 320F (A22) 11L AUTO ABS TURBO
Primary Colour:	Multi-Colour
Manufacturing Year:	2014
Engine No.:	50338061143798
Chassis No.:	WMAA22ZZ6E7002199
Maximum Power Output:	And the state of t
Open Market Value:	\$257,053.00
Original Registration Date:	11 Sep 2014
First Registration Date:	11 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	MO
PARF Eligibility:	No
PARF Eligibility Expiry Date:	***
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	to 00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 07 May 2018

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

1.590.00

0.00

Total Spray Painting Charges

1,200.00

0.00

Total Material Charges

2,023.92

2,023.92

Other Charges

0.00

0.00

TOTAL **Lum Sum Total** 4,813.92

0.00

0.00

0.00

No. of Repair Days

3.00

0.00

Prepared / Adjusted By

I gails

Arc / Surveyor Sing Off Date

01/01/1900 12:00:00 AM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 04/05/2018 03:10:26 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount

Prepared Date:

LKK Auto Consultants hence notify

the Repairer of the following:

. To resurvey before/after spray painting

. To display damaged pertis) during resurvey

* Parts prices are subject to confirmation.

. That purpy is on a "Without Prejudice" basis

* W. liegal modification(s) is allowed.

. This prementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Skillefolds

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor if applicable	
TO REPAIR LH PORTION	1,590.00	0.00_ 1060	
Total Labour	1,590.00	0.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,200.00	0.00 892
Total Spray Painting & Panel Beating	1,200.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Page:

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SMB1473Y

Ref. No

BUS/04/18/5018

Reg. Date

11/09/2014

Vehicle Type

: BUS -12M

Make Model MAN

Name of Driver

: MAN

: Edmund Kong

Type of Accident

: HEAD TO REAR

Date / Time of Accident

16/04/2018 08:24:00 AM

Accident Reported Date / Time :

17/04/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

IDAC

Vehicle is Towed Back?

No

Towed Back Date/Time

01/01/2000

Replacement Vehicle issued? :

Accident Repair Job Card No : 000024096030


Special Instruction to ARC, if any :

SMB1473Y - LEFT REAR PORTION (CORNER)

SJK5147B (TP) - INSURED WITH NTUC

Prepared Date

: 17/04/2018 11:44:52 AM



econon b - 10 be completed by certice nation, necident nepail centre

Chassis No:

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

01/01/2000

Total Labout Charges

1,590.00

1,060.00

Total Spray Painting Charges

1,200.00

892.00

Total Material Charges

1,586.75

1,619.14

Other Charges

0.00

-350.00

TOTAL

4,376.75

3,221.14

Lum Sum Total

4,400.00

3,200.00

No. of Repair Days

3.00

2.00

Prepared / Adjusted By

Sebastian

Arc / Surveyor Sing Off Date

: 09/05/2018 04:49:10 PM

09/05/2018 04:47:15 PM

Prepared / Adjusted Date

Remarks

Prepared Date : 04/05/2018 03:10:26 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No.

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

COULD - Details of Fohall Estimates

Part 1 - Labour Works

Jöb Scope	Quotation from ARC	Adjusted by Surveyor, if applicable	
TO REPAIR LH PORTION	1,590.00	1,060.00	
Total Labour	1,590.00	1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,200.00	892.00 /		
Total Spray Painting & Panel Beating	1,200.00	892.00		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor	0.00	-350.00		
Total Other Costs	0.00	-350.00		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
F01001- CW271		6010060	REAR TAIL LAMP COVER LH	1	974.70	10.00	877.23	Replace	Replace	NO CRK
88-25320 -6008		6010299	SIGNAL LAMP LED	1	1,274.10	10.00	1,146.69	Replace	Replace	No CRK
TOTAL MATERIALS								2,023.92	2,023.92	
TOTAL MATERIALS(Discounted)						illy — man		1,586.75	1,619.14	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
/	TOTAL SUPPLEMENTARY MATERIALS								

\$77.23 + 1146.69 2023.92 + 1060.00 + 892.00 3975.92 - 20% 3180.736

L/s \$ 3200

Sel 578462

5038.80



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC18008615/Ssbn2			
73 BRAS BASAH ROA #05-01 NTUC TRADE 189556	D UNION HOUSESINGAPORE	Date:	24-05-2018 INC4		
	Policy Particulars	:- THIR	D PARTY CLAIM		
Insured Veh.	SJK 5147B	Veh. li	nspected	SMB 1473Y	
Policy No.	5039469312-08	Cover	age (\$)	0.00	
Claim No.	MT/0990787-002	Exces	ss (\$)	0.00	
Assign From		Assig	n Date	04/05/2018	
	Vehicle Parti	culars &	& Condition		
Make & Model	MAN NL 320	c.c		10518	
Engine No.	HIDDEN	Year	of Reg.	2014	
Chassis No.	WMAA22ZZ6E7002199	Colou	ır	MULTI	
Odometer	260398	Steering		IN ORDER	
Brakes	IN ORDER	Modification		NIL	
General	FAIR				
NU SVENE SELECT	Condit	ions of	Tyres		
	Size	Make		Balance	
R/H Front Tyre	275/70 R22.5	FIREN	IZA	6 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA		6 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA		6/6 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA		6/6 mm	
	Descript	ion of D	amages		
THE VEHICLE SU	STAINED DAMAGES AT THE REDETAILS.	EAR N/S	PORTION.		
5.		al Inform	nation		
Accident Date	16/04/2018	Inspe	ection Date	04/05/2018	
Survey held at	SMRT AUTOMOTIVE SERVICE	ES PTE I	LTD		
11	NO. 28 KIAN TECK DRIVE SINGAPORE 628845				
5a.		Remarks			
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A"WI ICE TO YOUR INSTRUCTIONS, V	NE HAVE	E NOT AUTHORISE	S. ED REPAIRS.	
5b.		Days o	of Repair	Cartina Carta Carta	
ESTIMATED NOF	RMAL PERIOD FOR REPAIR:		2 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1473Y

(TO ITS PRE-ACCIDENT CONDITION)

(CONFIRMED)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAIL LAMP COVER LH	CRACKED	974.70	974.70
1	SIGNAL LAMP LED	CRACKED	1,274.10	1,274.10
	LESS 10% DISCOUNT		12	-224.88
			2,248.80	2,023.92
	LABOUR			
	TO REPAIR LH PORTION.		1,590.00	1,060.00
100	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		1,200.00	892.00
			2,790.00	1,952.00
	GRAND TOTAL		5,038.80	3,975.92
400	RECOMMENDED COST OF LUMP SUM REPAIRS			3,200.00

Report Ref No. NS/INC18008615/Ssbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.