

REF: NS/INC 18008617 / Ss bn2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **SKM 4429Y**
 Policy No: **50935707 25** **26.12.2017**
 Claims No: **MT/0996063-001**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Turn Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. **SHB 5105T** Yr Regn: **19/12/2017**
 Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or**
 Make: **Toyota Prius 4** C.C. **1798**
 Colour: **Maroon** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **52144** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **JTDK15314403576729**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: **In order / Jammed / Leaked / Burnt or**
 Brake: **In order / Jammed / Leaked / Burnt or**
 Modi: **Nil / S/Rim / STD A/Rim or**
 Tyre Size: F: **195/65R15**
 R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	4/5/18	D.O.I.	7/5/18

 Survey held at **SMART**
 Des. of Damages: **Frt / Rear / O/S / N/S / UIC / Rooftop or**
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
28/05/18 P/P \$2,416.91
 (\$7,131.35 - \$2,416.91) = Reduction 96%
 SKM 4429Y - X
 TAX/05/18/2024
 LKF
 NTUC
 SKM 4429Y

RECEIVED 30 MAY 2018

Date/Time. File Pass to? **28/05/18**
 1) **Typist** : Preli. Report : Final Report
 Date/Time. File Return to?
 2)
 Report Format :
 Lump Sum / I.B.I. (\$

Days Of Repair: **4 days**
 Resurvey No. of Trip: **1**

Add Fee: : Site Insp (\$
 : Interview (\$
 : Tech. Invs (\$
 : Weekend (\$

Survey Fee: **160**
 Transportation: **35**
 S + RS \$
 Photos
 Others
 TOTAL **195**



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18008617/Ss3b			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE		Date: 10-05-2018	
189556		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKM 4429Y	Veh. Inspected	SHB 5105T
Policy No.	5093570725	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/05/2018	Inspection Date	07/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Hello, NAC_PAYA_UBI_800601

[Change Language](#)
[Change Password](#)
[Log Out](#)

[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
 Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5093570725	A-SPEED HOLDINGS	53366627M	GFT	drive CLASSIC	SKM4429Y	SKM4429Y	26/12/2017	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHB5105T
Vehicle to be Exported:	No
Intended De-registration Date:	08 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8262958
Chassis No.:	JTDKB3FU403576929
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$32,494.00
Total Rebate Amount:	\$36,244.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 May 2018

OK

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/0996063-001	SMRT TAXIS PTE LTD	SHB 5105T	SKM 4429Y	4/5/2018	18:10	\$ 7,131.35	\$ 2,416.91

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 25 May 2018 3:01 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHB5105T

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: Friday, 25 May 2018 10:11 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team
Subject: RE: SHB5105T

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,
Sebastian | Automotive Assessor
LKK Auto Consultants
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 22 May 2018 8:11 AM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5105T

Hi Sebastian,

Attached herewith the repair estimate of SHB 5105T having Case No: TAX/05/18/2024.

There is no change to the approved amount of \$2,416.91 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Monday, 21 May 2018 6:05 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/05/2018 09:30
Date Of Accident	04/05/2018 18:10
Exact Location Of Accident	JURONG WEST STREET 93
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5105T
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	CHIEW FOOK KEE @ ALVIN CHIEW
NRIC No	S0230904A
Date Of Birth	28/05/1954
Occupation	OUTDOOR
Date Of Driving Pass	20/07/1979
Driving Experience	38 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	274
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG JURONG WEST STREET 93 AT THE RIGHT LANE AND HAD STOPPED AS THE VEHICLE INFRONT OF MY TAXI STOPPED. AFTER WHICH A VEHICLE SKM4429Y FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM4429Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALEX TAY BOON HUAT
NRIC/Passport Number	S7517729A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten Signature] 5/5/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

NTUK

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5105T
 Ref. No : TAX/05/18/2024
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : CHIEW FOOK KEE @ ALVIN CHIEW
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 04/05/2018 06:10:00 PM
 Accident Reported Date / Time : 05/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 04/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095907
 Special Instruction to ARC, if any :
 TOWED \$40 / SKM4429Y
 Prepared Date : 05/05/2018 10:00:55 AM



*Sebastian
 7/5/18
 - Part by part repair
 - Question Mark Item
 Photo
 - Photo Before Paint*

*[Signature]
 22/5/18*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403576929

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 918.00	0.00
Total Material Charges	: 4,319.35	4,319.35
Other Charges	: 880.00	0.00
TOTAL	: 7,131.35	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sing Off Date	: 05/05/2018 11:06:59 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/05/2018 11:06:56 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 X
TO RESPRAY REAR PANEL	180.00	0.00 7
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 50
Total Spray Painting & Panel Beating	1,098.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 20 X
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	880.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓ CRK	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓ NRC	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ✓ DT	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓	No DMG
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓	No NRC
52462470 30			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace ?	No
52462470 20			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace ?	No
52462470 10			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace ?	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace ?	No
52592470 40			SEAL, RR BUMPER , LH	1	85.20	25.00	63.90	Replace	Replace ✓	No ?
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace X	No
52566479 00			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace ✓ MS	No
81591470 10			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	10.00	438.12	Replace	Replace ?	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓	No CRK
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace ?	No
58399470 30			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.72	Replace	Replace ?	No
58398470 50			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.12	Replace	Replace ✓	No
66259470 10			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace ?	No
90467170 26A0			CLIP , FLOOR UNDER COVER , NO.1	10	2.60	25.00	19.50	Replace	Replace ?	No
90467170 27C0			CLIP , FLOOR UNDER COVER , NO.2	10	3.20	25.00	24.00	Replace	Replace ?	No
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace ✓	No
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace X	No
75441470 90			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace X	No
75442471 30			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace X	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace X	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace X	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
58307470 90			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
58415471 10C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Replace	No
65638470 60			LINER, REAR FENDER, LH	1	135.80	25.00	101.85	Replace	Replace	No
TOTAL MATERIALS								4,319.40	4,319.35	
TOTAL MATERIALS(Discounted)							4,319.35	4,319.35		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

11-5-18 / 11:34

11-5-18 / 15:34


7-5-18 / 15:34

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

11/5
OK

Reg. No : SHB5105T
 Ref. No : TAX/05/18/2024
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : CHIEW FOOK KEE @ ALVIN CHIEW
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 04/05/2018 06:10:00 PM
 Accident Reported Date / Time : 05/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 04/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095907
 Special Instruction to ARC, if any :
 TOWED \$40 / SKM4429Y NTAC P/P
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
 & Email : sebastianeang @lkkauto.com HP:90036121
 Prepared Date : 05/05/2018 10:00:55 AM



Recording Camera

Radio Antenna

1st witness M Date 7-5-18

2nd witness _____ Date _____

52144

1 1 3
4 2 4 1

QC 10/5/18
P.31 P.33

52209

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 9-5-2018

Vehicle Return Time: 17:09

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403576929 Mileage : 0

Workshop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	600.00
Total Spray Painting Charges	: 1,098.00	350.00
Total Material Charges	: 2,882.38	1,376.91
Other Charges	: 880.00	90.00
TOTAL	: 5,874.38	2,416.91
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	4.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 05/05/2018 11:06:59 AM	07/05/2018 03:34:37 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/05/2018 11:06:56 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1805-0414 Invoice No :
Quotation Date : 18/5 Invoice Date :
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00 ✓	600.00 ✓
Total Labour	1,014.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 ✓	200.00 ✓
TO RESPRAY BUMPER BEAM	180.00 ✓	100.00 ✓
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00 ✗	0.00
TO RESPRAY REAR PANEL	180.00 ✗	0.00
TO RESPRAY FILLER RR BUMPER LH	180.00 ✓	50.00 ✓
Total Spray Painting & Panel Beating	1,098.00	350.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30.00 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	800.00	90.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	✓	423.90	25.00	317.92	Replace	Replace	No ✓
5216116010			CLIPS PIECE, FRT & RR BUMPER	✓ 10	1.50	25.00	11.25	Replace	Replace	No ✓
5202347030			REAR BUMPER REINFORCEMENT	✓	318.80	25.00	239.10	Replace	Replace	No ✓
			SENSOR REVERSE	✓ 1	180.00	0.00	180.00	Replace	Replace	No ✓
			PIXEL STICKER	✓ 2	60.00	0.00	120.00	Replace	Replace	No ✓
5246247030			PAD, RR BUMPER, RH & LH , 1	X 2	3.80	25.00	5.70	Replace	Check	No X
5246247020			PAD, RR BUMPER, RH & LH , 2	X 2	3.80	25.00	5.70	Replace	Check	No X
5246247010			PAD, RR BUMPER, RH & LH , 3	X 2	3.80	25.00	5.70	Replace	Check	No X
5219147030			SEAL, RR BUMPER ARM, RH & LH	X 2	11.00	25.00	16.50	Replace	Check	No X
5259247040			SEAL, RR BUMPER , LH	X 1	85.20	25.00	63.90	Replace	Check	No X
5257647040			RETAINER, RR BUMPER, LH	X 0	111.50	25.00	0.00	Replace	Not given	No X
5256647900			FILLER, RR BUMPER , LH	✓	119.90	25.00	89.92	Replace	Replace	No ✓
8159147010			LENS & BODY ASSY , RR BUMPER , LH	X 1	486.80	10.00	438.12	Replace	Check	No X
5245347010			GUARD, RR BUMPER, LOWER	✓	558.30	25.00	418.72	Replace	Replace	No ✓
5216947020			COVER, GUARD RR BUMPER LOWER	X 1	14.80	25.00	11.10	Replace	Check	No X
5839947030			COVER, REAR FLOOR UNDER , LH	X 1	234.30	25.00	175.73	Replace	Check	No X
5839847050			COVER, REAR FLOOR UNDER , RH	X 1	169.50	25.00	127.13	Replace	Check	No X
6825947010			COVER, REAR FLOOR UNDER CENTER	X 1	222.60	25.00	166.95	Replace	Check	No X
9046717026A0			CLIP , FLOOR UNDER COVER , NO.1	X 10	2.60	25.00	19.50	Replace	Check	No X
9046717027C0			CLIP , FLOOR UNDER COVER , NO.2	X 10	3.20	25.00	24.00	Replace	Check	No X
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	X 0	891.20	25.00	0.00	Replace	Not given	No X
7540348010			EMBLEM SUB-ASSY REAR	X 0	46.30	25.00	0.00	Replace	Not given	No X
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	X 0	52.30	25.00	0.00	Replace	Not given	No X
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	X 0	52.30	25.00	0.00	Replace	Not given	No X
	COMMO N		SMRT LOGO	X 0	7.80	0.00	0.00	Replace	Not given	No
	COMMO N		STICKER DECAL 6555 8888	X 0	21.60	0.00	0.00	Replace	Not given	No

CRK
NEC
DT
DMG
NEC
NA
MS
NA
CRK
NA

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	X 1	629.80	25.00	472.35	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	X 1	37.00	0.00	37.00	Replace	Check	No X
5841547110C2			BOARD, REAR FLOOR, NO.1	X 0	502.20	25.00	0.00	Replace	Not given	No X
6563847060			LINER, REAR FENDER, LH	X 0	135.80	25.00	0.00	Replace	Not given	No X
TOTAL MATERIALS							2,946.30	1,376.91		
TOTAL MATERIALS(Discounted)							2,882.38	1,376.91		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1376.91 ✓
 + 600.00 ✓
 + 440.00 ✓

 2416.91 ✓

Sebastian
 25/5/18

8451.70.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18008617/Ssbn2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 01-06-2018	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKM 4429Y	Veh. Inspected	SHB 5105T
Policy No.	5093570725	Coverage (\$)	0.00
Claim No.	MT/0996063-001	Excess (\$)	0.00
Assign From		Assign Date	07/05/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS 4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU403576929	Colour	MAROON
Odometer	52144	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/05/2018	Inspection Date	07/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5105T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER,RR BUMPER ASSY (DISC 25%)	CRACKED	423.90	317.92
10	CLIPS PIECE,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	REAR BUMPER REINFORCEMENT (DISC 25%)	DENTED	318.80	239.10
1	FILLER,RR BUMPER,LH (DISC 25%)	MISSING	119.90	89.92
1	GUARD,RR BUMPER LOWER (DISC 25%)	CRACKED	558.30	418.72
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
2	PAD,RR BUMPER,RH & LH 1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER,RH & LH 2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER,RH & LH 3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL,RR BUMPER ARM,RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	SEAL,RR BUMPER,LH	NOT NECESSARY	85.20	-
1	RETAINER,RR BUMPER,LH	NOT NECESSARY	111.50	-
1	LENS & BODY ASSY RR BUMPER,LH	NOT NECESSARY	486.80	-
1	COVER,GUARD RR BUMPER LOWER	NOT NECESSARY	14.80	-
1	COVER,REAR FLOOR UNDER,LH	NOT NECESSARY	234.30	-
1	COVER,REAR FLOOR UNDER,RH	NOT NECESSARY	169.50	-
1	COVER,REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
10	CLIP,FLOOR UNDER COVER,NO 1 @\$2.60	NOT NECESSARY	26.00	-
10	CLIP,FLOOR UNDER COVER,NO 2 @\$3.20	NOT NECESSARY	32.00	-
1	TAILGATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	NOT NECESSARY	891.20	-
1	EMBLEM SUB-ASSY REAR	NOT NECESSARY	46.30	-
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT DOOR	NOT NECESSARY	52.30	-
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT DOOR	NOT NECESSARY	52.30	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 65558888	NOT NECESSARY	21.60	-
1	END PANEL SUB-ASSY,BODY LOWER BACK	NOT NECESSARY	629.80	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	BOARD,REAR FLOOR,NO 1	NOT NECESSARY	502.20	-

Report Ref No. NS/INC18008617/Ssbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LINER, REAR FENDER, LH	NOT NECESSARY	135.80	-
			5,539.70	1,376.91
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,654.00	690.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,098.00	350.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,912.00	1,040.00
	GRAND TOTAL		8,451.70	2,416.91
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,416.91

Report Ref No. NS/INC18008617/Ssbn2

YEANG WAI KEEN
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.