



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008620/Apa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-09-2020



ATTN:RICHARD

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGR 866R	Veh. Inspected	WWH 9682
Policy No.	GA283092	Coverage (\$)	0.00
Claim No.	S8M00G79	Excess (\$)	0.00
Assign From		Assign Date	07/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HILUX	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	PN133JV2508538202	Colour	BLACK
Odometer	298702	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/70 R16	SILVERSTONE	6 mm
L/H Front Tyre	245/70 R16	SILVERSTONE	6 mm
R/H Rear Tyre	245/70 R16	SILVERSTONE	6 mm
L/H Rear Tyre	245/70 R16	SILVERSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/05/2018	Inspection Date	07/05/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------