



新福德車廠私人有限公司 *ADDIYAN*

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

KHAN ATIQUUR RAHMAN

07/05/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 05/05/2018

Estimated repair cost for vehicle no: WWH9682 TOYOTA HILUX

S/n	Qty	Items	U/price	Amount	
1	1	Front Bonnet <i>Buckled</i>		\$980.20	✓
2	1	Front Bonnet Lock <i>Ring</i>		\$150.50	✓
3	2	Front Bonnet Hinges <i>new</i>	\$105.00	\$210.00	✗
4	1	Front Bonnet Toyota Cover <i>cracked</i>		\$265.00	✓
5	1	Front Bonnet Insulator <i>new</i>		\$288.50	✗
6	15	Front Bonnet Insulator Clips <i>new</i>	\$3.00	\$45.00	30
7	1	Front Bonnet Inner Rubber <i>new</i>		\$65.50	✗
8	2	Front Head Lamp <i>LH cracked</i>	\$456.70	\$913.40	456.70.
9	2	Front Head Lamp Lower Bracket <i>LH Damaged</i>	\$96.80	\$193.60	96.80.
10	1	Front Grille <i>cracked</i>		\$351.60	✓
11	1	Front Grille Emblem Logo <i>new</i>		\$71.60	✓
12	1	Front Grille Top Rubber <i>new</i>		\$105.00	✗
13	1	Front Grille Outer Chrome <i>cracked</i>		\$116.60	✓
14	1	Front Bumper <i>Deformed</i>		\$595.70	✓
15	2	Front Bumper Side Retainer <i>new</i>	\$44.20	\$88.40	✓
16	1	Front Bumper Number Plate <i>cracked</i>		\$50.00	✓
17	1	Front Bumper Center Garnish <i>cracked</i>		\$189.20	✓
18	1	Front Bumper Fog Lamp L/H <i>cracked</i>		\$385.80	✓
19	1	Front Bumper Fog Lamp L/H Cover <i>deformed</i>		\$61.70	✓
20	1	Front Bumper Side Cover L/H <i>new</i>		\$74.20	✗
21	1	Front Bumper Lower Reinforcement <i>Best</i>		\$373.20	✓
22	2	Front Bumper Lower Reinforcement Bracket <i>Best</i>	\$75.40	\$150.80	✓
23	10	Front Bumper Clips <i>new</i>	\$3.00	\$30.00	✓
24	1	Front Support Panel <i>Assy Buckled</i>		\$645.00	✓
25	2	Front Support Panel Side Air-Duct Cover <i>deformed</i>	\$35.00	\$70.00	✓
26	2	Front Horn <i>Not New</i>	\$48.00	\$96.00	✗
27	1	Front Air-Con Condenser <i>Best</i>		\$1,145.00	✓
28	1	Front Radiator <i>Best</i>		\$2,108.00	✓
29	1	Front L/H Fender <i>Buckled</i>		\$625.40	✓

30	1	Front L/H Fender Protector Cover <i>Del'd</i>		\$145.50 ✓
31	1	Front L/H Fender Side Mirror Assy <i>crushed</i>		\$259.40 ✓
32	1	Front L/H Fender Cowling		\$185.00 ✓
33	10	Front L/H Fender Cowling Clips <i>not new</i>	\$3.00	\$30.00 ✓
34	1	Front Wiper Tank		\$124.10 ✓
35	1	Front Wiper Tank Motor		\$85.10 X
36	1	Rear Tailgate <i>Distorted</i>		\$1,114.70 ✓
37	2	Rear Tailgate Hinges <i>Bent</i>	\$54.80	\$109.60 ✓
38	1	Rear Tailgate Toyota Logo <i>new</i>		\$68.20 ✓
39	1	Rear Tailgate Hilux Logo		\$67.40 ✓
40	1	Rear Tailgate C Logo		\$28.60 ✓
41	1	Rear Tailgate Center Lamp <i>crushed</i>		\$124.90 ✓
42	1	Rear Tailgate Outer Handle <i>Dist'd</i>		\$58.80 ✓
43	1	Rear Tailgate Outer Handle Inner Lock <i>Joined</i>		\$78.40 ✓
44	1	Rear Tailgate Inner Cover <i>Del'd</i>		\$385.00 ✓
45	2	Rear Tailgate Side Lock <i>new</i>	\$275.60	\$551.20 X
46	2	Rear Tail Lamp <i>LH crushed, RH cut</i>	\$354.00	\$708.00 ✓
47	2	Rear Tail Lamp Panel <i>Repair</i>	\$241.00	\$482.00 X
48	1	Rear Tailgate Lower Member <i>Dist'd</i>		\$777.20 ✓
49	1	Rear L/H Fender <i>Repair</i>		\$2,490.00 X
50	1	Rear Bumper <i>Distorted</i>		\$974.00 ✓
51	1	Rear Bumper Top Rubber Cover <i>Dist'd</i>		\$332.80 ✓
52	1	Rear Bumper Number Plate <i>crushed</i>		\$60.00 ✓
53	2	Rear Bumper Number Plate Lamp <i>crushed</i>	\$69.60	\$139.20 ✓
54	1	Rear Bumper Number Plate Garnish <i>Dist'd</i>		\$58.50 ✓
55	1	Rear Bumper Number Plate Cover		\$39.40 ✓
56	2	Rear Bumper Bracket <i>Bent</i>	\$140	\$280.00 ✓
57	1	Rear Floor Panel <i>Repair</i>		\$2,985.00 X
58	1	Rear Floor Panel Cover <i>new</i>		\$554.00 ✓
59	1	Rear Spare Tyre Lock		\$195.00 X
60	1	Rear Exhaust <i>new</i>		\$851.20 X
61	1	Rear Center Exhaust		\$785.00 X
62	2	Rear Fender Commonrail Turbo Sticker (set) <i>new</i>	\$30.00	\$60.00 ✓
63	2	Rear Fender Lower Sticker (set) <i>new</i>	\$20.00	\$40.00 X

14906-80

Subtotal :- \$25,672.10

118010

Labour charges

To remove & refit front air-con condenser, radiator, fan motor &

~~\$380.00~~ 120

top up gas

To remove & refit reverse sensor

\$100.00 X

To remove & refit rear & center exhaust

\$380.00 X

To remove & refit floor panel & tailgate cover

~~\$1,500.00~~ X 150

To check wiring

5090 ~~\$100.00~~ 60

Tuff kote

~~\$150.00~~ 100

Towing Fees

~~\$100.00~~ 60

Panel beating

~~\$3,800.00~~ 2400

Spray painting

~~\$2,800.00~~ 2200

Subtotal :- \$9,310.00

Total:- \$34,982.10

total ~~16270.10~~ 16270.10

2/s 13k

110 c/s

13k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: