

Stacey

CC 4 / ASM1800

8625, S WAZZ

44235

ASSIGNMENT

Surveyor:

YWK

DOI:

10/5/18

Date / Time:

9/5/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SLN 2637J

Claim No. :

S 8m00663

Name of Insured :

Leong Wei Man

Policy No. :

GA192432/1

Insured Tel No. :

HP: 9788 2614

Make / Model :

T. Avria

Excess Sec II :SS

D.O.A : 8/5/2018

Place of Accident :

PIE (TAS)

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SLN 303XP

SLN 2637J

SLN 6093B



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time

6/6  
vmbw

SLN 6093B - NS/Ins 17/11/18 / Klybnz ; 008: 28/1/17  
SLN 2637J - CC/ASM 130 215 331 / Apb3 ; 008: 8/1/17

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	13/6/18 Ch
After call ltr to OI:	6/1/18 Ch

12/6/18

called OI, oversea. will be back 13/6/18.

13/6/18

OI, Mr Leong called back confirm accident details inform TP claim. agree to settle letter send out

20/6/18

File pass to typist type report

24/8/18

Seek mandoc via SMART.

27/9/18

mandoc approve via SMART

RECEIVED - 8 SEP 2018

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input type="checkbox"/>	<input type="checkbox"/>
LTA / GIA :	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PIR:	<input type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
Others:	<input type="checkbox"/>	<input type="checkbox"/>

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm by:
---------------------------	------------	----------	-------------

<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by:
---------------------	------------	---------------	-------------

Repair Cost:	SS	( days) Reduction:	%	Email <input type="checkbox"/>	Call <input type="checkbox"/>
--------------	----	--------------------	---	--------------------------------	-------------------------------

<b>FINAL SETTLEMENT</b>	Date/Time:	Confirm with:	Email <input type="checkbox"/>	Call <input type="checkbox"/>
-------------------------	------------	---------------	--------------------------------	-------------------------------

Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 28	If NO or B 28, Ass. Lia: O.I.
Repair Cost:	SS 2125.99	OI1 involved in 3.00
Loss of Rental (LOR):	SS 735.63 ( 5-5 days) X 133.75	O2 is the 2nd
Loss of Use (LOU):	SS - ( \$ x days)	
Loss of Income (LOI):	SS - ( \$ x days)	
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>
GIA/LTA Search	SS 7.00	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle
Legal Cost	SS -	2) Report Format:
		3) Survey fee:

<b>Total:</b>	SS 2868.62	Global Sum SS: 2850.00
---------------	------------	------------------------

<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Email <input type="checkbox"/>	Call <input type="checkbox"/>
Payee 1:	SS 2850.00	Name 1: SURT TAXIS Pte Ltd		
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHD 6093B Yr Regn: 27/7/2016  
 Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Prius c.c. 1798  
 Colour: Maroon A/C: Insured / Std / NI / NA  
 Sp. Reading: 144471 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDKN 5CY 40576 8972  
 Gen. Cond: Good /  Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or  
 Brake:  Inorder / Jammed / Leaked / Burnt or  
 Modi:  Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Feilong

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>8/5/18</u>	D.O.I. <u>10/5/18</u>

Survey held at SMART

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	solble Confirm 2.B. 2 \$ 2125.99 with 3 working days
	TAX / 05/18/2043 LICK AXA
	SLN 26373
	(Red) \$ 4706.96 69.1

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

) \$ - RS, SI

) Photos

) Others

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008625/Swa3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 10-05-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLN 2637J	Veh. Inspected	SHD 6093B
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00GGS	Excess (\$)	0.00
Assign From		Assign Date	10/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/05/2018	Inspection Date	10/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

W



*Handwritten signature*

12-5-18 / 15:47

14-5-18 / 10:47

14-5-18 / 14:47

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672


### SMRT Accident Vehicle Repair Estimates

10-5-18 / 19:47

Section A - To be completed by Claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6093B  
 Ref. No : TAX/05/18/2043  
 Reg. Date : 27/07/2016  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : NG NGOH HOCK  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 08/05/2018 02:45:00 PM  
 Accident Reported Date / Time : 08/05/2018 12:00:00 AM  
 Surveyor is Required? : No  
 Survey by : Sebastian  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095958  
 Special Instruction to ARC, if any :


14/5



SLN2637J - AXA *PLP*  
 BEFORE PAINT PHOTO AND AFTER REPAIR PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email: sebastianyeang@lkkauto.com HP:90036121  
 Prepared Date : 08/05/2018 04:19:12 PM

QC 12/5/18 11:52 pass 144472

Recording Camera    
 Radio Antenna    
 1<sup>st</sup> witness    *R*    Date 10-5-18  
 2<sup>nd</sup> witness \_\_\_\_\_ Date \_\_\_\_\_



144531

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 12-5/18

Vehicle Return Time: 10:14 am

SMRT staff sign: *[Signature]*

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U405768492

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	400.00
Total Spray Painting Charges	: 1,116.00	400.00
Total Material Charges	: 1,943.56	949.11
Other Charges	: 1,136.88	376.88
<b>TOTAL</b>	<b>: 5,210.44</b>	<b>2,125.99</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	3.00
Prepared / Adjusted By	:	/
Arc / Surveyor Sign Off Date	: 08/05/2018 06:52:18 PM	10/05/2018 02:47:04 PM

F

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 06:50:43 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1805-0416

Invoice No :

Quotation Date : 18/5

Invoice Date :

Invoice Amount :

Prepared Date :

949.11 /  
+ 400.00 /  
+ 776.88 /

2125.99 /

Sebastian  
25/5/18

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	400.00
<b>Total Labour</b>	<b>1,014.00</b>	<b>400.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY REAR PANEL	180.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>400.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>1,136.88</b>	<b>376.88</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR	0	228.90	25.00	0.00	Replace	Not given	No <i>✓</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Check	No <i>X</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>✓</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>✓</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>
67005-47241			TAILGATE ASY	1	1,007.90	100.00	0.00	Replace	Repair	No <i>R</i>
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	0	29.40	25.00	0.00	Replace	Not given	No <i>X</i>
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	0	29.40	25.00	0.00	Replace	Not given	No <i>X</i>
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	0	29.40	25.00	0.00	Replace	Not given	No <i>X</i>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>X</i>
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No <i>✓</i>
69415-47020			TAILGATE LOCK, COVER	0	15.70	25.00	0.00	Replace	Not given	No <i>X</i>
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No <i>✓</i>
69431-47010			STRIKER, BACK DOOR	0	48.90	25.00	0.00	Replace	Not given	No <i>X</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>✓</i>
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Check	No <i>X</i>
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	0	46.10	25.00	0.00	Replace	Not given	No <i>X</i>
64716-47031B0			END PANEL COVER, DECK TRIM, RR	0	121.10	25.00	0.00	Replace	Not given	No <i>X</i>
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No <i>X</i>
<b>TOTAL MATERIALS</b>								<b>1,943.58</b>	<b>949.11</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>1,943.56</b>	<b>949.11</b>	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------

2298.38

## SMRT Accident Vehicle Repair Estimates

G 117

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6093B  
 Ref. No : TAX/05/18/2043  
 Reg. Date : 27/07/2016  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : NG NGOH HOCK  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 08/05/2018 02:45:00 PM  
 Accident Reported Date / Time : 08/05/2018 12:00:00 AM  
 Surveyor is Required? : No  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095958  
 Special Instruction to ARC, if any :  
 SLN2637J  
 Prepared Date : 08/05/2018 04:19:12 PM



Sebastian  
 10/5/18  
 - Part by part repair  
 - Question Mark Item  
 Photo  
 - Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U405768492

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 3,566.07	3,566.07
Other Charges	: 1,136.88	0.00
<b>TOTAL</b>	<b>: 6,832.95</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	<del>0.00</del>
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sing Off Date	: 08/05/2018 06:52:18 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 06:50:43 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	<del>0.00</del> 400
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	<del>0.00</del> 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	<del>0.00</del> 200
TO RESPRAY REAR PANEL	180.00	0.00 ?
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	<del>0.00</del> 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	<del>0.00</del> 50
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>1,136.88</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace	No
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
<b>TOTAL MATERIALS</b>								<b>3,566.13</b>	<b>3,566.07</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>3,566.07</b>	<b>3,566.07</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 3/5/2018

### Survey Details:

Date of loss	8-May-18
Date of appointment	9-May-18
Date of survey	10-May-18
Location of survey	SMRT Automotive Services Pte Ltd

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SHD 6093B
Make and Model	TOYOTA PRIUS TAXI (SMRT)
Date of registration	27-Jul-16
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

### Repair details:

Initial Estimate	6,832.95
------------------	----------

### Proposed/Revised repair cost:

Parts	\$	949.11
Check items (estimate)	\$	1,354.44
Labour	\$	1,236.88
<b>Total</b>	\$	<b>3,540.43</b>
<b>Lump Sum(if applicable)</b>	\$	<b>-</b>

<b>Number of days for repair</b>	<b>3 days</b>
----------------------------------	---------------

LKK AUTO CONSULTANTS PTE LTD (TP)

## << Service Request Details

9003 b 121

Claim

58M00GG5

Reference

None 

Smart

Loss Date

May 8, 2018

Request Date

May 9, 2018

Due Date

May 16, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Agree to perform service

Decline Work	Accept Work
--------------	-------------

### Vehicle Information

Incident Vehicle Registration #

SHD6093B

Make

TPVD TOYOTA

## Service Address

...

## Primary Contact/Insured

LEONG WEI YUAN (LIANG WEIYUAN)  
 BLK 502B YISHUN STREET, #13-432, 760502, Singapore  
 97882614  
 AH\_YUAN15@YAHOO.COM.SG

## Claim Handler

NG Stacey  
 6568804351  
 stacey.ng@axa.com.sg

## Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType



NAME

 SLN2637J INS GIA

TYPE

Reports &amp; Statement

SUB-TYPE

GIA Report

AUTHOR

Merimen

DATE UPLOADED

NAME

 EMAIL WITH TP GIA SHD6093B & ESTIMATE.msg

TYPE

Forms / Claim Documents

SUB-TYPE

Estimate / Quotation

AUTHOR

KUMAR Shailendra



**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLN 2637J (Insd veh)	Model:	TOYOTA PRIUS TAXI (SMRT)
	SHD 6093B (TP veh)		
Date of Accident:	08/05/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	7,798.38
Final Repair Cost	:	\$	2,125.99
Loss of Token Sum	:	\$	days at \$00.00 per day
Rental (if any)	:	\$	735.63 5.5 days
LTA / GIA Search Fee	:	\$	7.00

Others: : \$

: \$  
Final Settlement Sum (GLOBAL SUM) : \$ 2,850.00

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No:

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): 0 (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks  
\_\_\_\_\_  
\_\_\_\_\_

Payment Instruction: Payee's Breakdown	
1) SMRT TAXIS PTE LTD	\$ 2,850.00

NUR SHAQILAH BTE ABDOL  
WAHAB

01/10/2018

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## Service Request Details

Claim: SBM00GGG

Reference: CC4/ASM180006625/Swa3s2

Loss Date: May 8, 2018

Request Date: May 9, 2018

Due Date: May 9, 2019

Vendor Name: LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss: Third Party Vehicle Damage

Services: Pending verification - Direct Settlement

Additional Instructions

**Actions**

Next Step: Finish the work

Complete Work

More

Document Type

Document Sub Type

Upload Documents

**Vehicle Information**

Incident Vehicle Registration #: SHD6093B

Service Address

Make: TPVD TOYOTA

Model: PRIUS TAXI-1.8 (A)

Primary Contact/Insured: LEONG WEI YUAN (LIANG WEIYUAN)

Address: BLK 502B YISHUN STREET, #13-432, 760502, Singapore

Contact: 97862614

Email: AH\_YUAN15@YAHOO.COM.SG

**Claim Handler**

NG Stacey

6568804351

stacey.ng@axa.com.sg

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SLN2637J INS GIA	Reports & Statement	GIA Report	Merimen	

Messages Invoices History Documents

Assessment Metrics Notes

<< Service Request Details

Claim SBM00GGG

Reference

CC4/ASM18008625/Swa3s2  Loss Date

May 8, 2018 Request Date  
 May 9, 2018 Due Date

May 9, 2019 Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP) Type of Loss

Third Party Vehicle Damage Services

Pending verification - Direct Settlement

Actions

Next Step Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration # SHD6093B

Make

Service Address

TPVD TOYOTA

Model

PRUS TAXI-1.8 (A)

Primary Contact/Insured

LEONG WEI YUAN (LIANG WEIYUAN)  
 BLK 502B YISHUN STREET, #13-432, 760502, Singapore  
 97882614  
 AH\_YUAN15@YAHOO.COM.SG

Claim Handler

NG Stacey  
 6568804351  
 stacey.ng@axa.com.sg

Additional Instructions

Messages Invoices History Documents  
 Assessment Metrics Notes

CREATED USER VERSION DATE ESTIMATED AMOUNT APPROVED AMOUNT STATUS SHARE CLONE

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SHD6093B	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date	07/27/2006
Mileage	144471	Age of Vehicle	11
<b>Driver Details</b>			
<b>CATEGORY</b>	<b>POLICY INFORMATION</b>	<b>ASSESSMENT INFORMATION</b>	<b>POST SURVEY INFORMATION</b>
Manufacturing Year		2015	
Make	TPVD TOYOTA	TOYOTA	
Model	PRIUS TAXI-1.8 (A)	PRIUS TAXI (SMART)	
Type			
Type of Paint			
Chassis No		JTDKN36U405768492	
Engine No		2ZR6609120	
Engine Capacity		1798 cc	
		Driver Name	NG NGOH HOCK
		Date of Birth	mm/dd/yyyy
		Age	0
		Occupation	Unknown
		Education Qualification	Other
		Driving Experience	0
		Driver License #	
		License Type	

## Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

### Detailed Assessment

### Condition of Vehicle at time of survey

Inspection Date *	05/10/2018		General condition	Fair
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unn amed Driver Excess	0		Pre-accident condition	Good
Other Excess				

### Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	195/65R15	Rear Tyre Size	195/65R15
Front left side	FALKEN 6mm	Rear left side	FALKEN 6mm
Front right side	FALKEN 6mm	Rear right side	FALKEN 6mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			BUMPER CLIPS (10PCS) (DISC 25%)			Necessary	12.07		0		12.07	Reviewing	
	2	1			TAILGATE DOOR LOCK (DISC 25%)			Damaged	333.07		0		333.07	Reviewing	
	3	1			TAILGATE DOOR WEATHER STRIP (DISC 25%)			Damaged	265.05		0		265.05	Reviewing	
	4	1			NAME PLATE (HYBRID) (DISC 25%)			Necessary	38.92		0		38.92	Reviewing	
	5	1			SENSOR REVERSE (SN)			Damaged	180		0		180	Reviewing	
	6	2			PIXEL STICKER (SN)			Necessary	60		0		120	Reviewing	
	7	1			BUMPER LIP REAR			Serviceable	0		0		0	Reviewing	
	8	1			BUMPER REINFORCEMENT REAR			Serviceable	0		0		0	Reviewing	
	9	1			ARM SUB-ASSY RR BUMPER LH			Serviceable	0		0		0	Reviewing	
	10	1			ARM SUB-ASSY RR BUMPER RH			Serviceable	0		0		0	Reviewing	
	11	1			BUMPER SIDE RETAINER RR/LH			Serviceable	0		0		0	Reviewing	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR HSR	LABOUR REPAIR	PART	ACTION (LABOUR)	COMMENT	REMOVE
	2		SPRAY PAINT.	400	0	0	Reviewing		
	3		TO CHECK WIRING AND SYSTEM FUNCTION.	0	0	0	Reviewing		
	4		TO TRANSFER REAR TAILGATE MECHANISM.	0	0	0	Reviewing		
	5		TO REMOVE AND REFIX REAR WINDSCREEN.	0	0	0	Reviewing		
	6		TO TEST AND REFIX REVERSE SENSOR SYSTEM.	30	0	0	Reviewing		
	7		TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	50	0	0	Reviewing		
	8		TO REPLACE SUNDRY PARTS.	0	0	0	Reviewing		
	9		TO WASH AND VACUUM.	0	0	0	Reviewing		



### Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Buttons: Add, Approve, Deny, Submit All

EDIT SR NO NAME ACTION AMOUNT COMMENT REMOVE

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1		Reviewing		3	

DAYS OF REPAIR

### << Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous    Summary

Claim Amount    \$2,125.99

Claim Amount    \$2,125.99

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$1,245.99	\$1,245.99
Labour	\$880.00	\$880.00

Submit for Review