

G 114

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6093B
 Ref. No : TAX/05/18/2043
 Reg. Date : 27/07/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : NG NGOH HOCK
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 08/05/2018 02:45:00 PM
 Accident Reported Date / Time : 08/05/2018 12:00:00 AM
 Surveyor is Required? : No
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095958
 Special Instruction to ARC,if any :
 SLN2637J
 Prepared Date : 08/05/2018 04:19:12 PM



*Sebastian .
 10/5/18 .
 - Part by part repair .
 - Question Mark Item
 Photo
 - Photo Before Paint .*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405768492 Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 3,566.07	3,566.07
Other Charges	: 1,136.88	0.00
TOTAL	: 6,832.95	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sing Off Date	: 08/05/2018 06:52:18 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 06:50:43 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,136.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	R No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	✓ No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	X No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	✓ No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	✓ No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	✓ No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	✓ No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	✓ No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	✓ No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	✓ No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	R No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	X No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	✓ No
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	X No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	X No
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	✓ No
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace	✓ No
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	✓ No
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace	X No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	✓ No
68307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	✓ No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	X No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	✓ No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	✓ No
TOTAL MATERIALS								3,566.13	3,566.07	
TOTAL MATERIALS(Discounted)							3,566.07	3,566.07		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------