


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6093B  
Ref. No : TAX/05/18/2043  
Reg. Date : 27/07/2016  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : NG NGOH HOCK  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 08/05/2018 02:45:00 PM  
Accident Reported Date / Time : 08/05/2018 12:00:00 AM  
Surveyor is Required? : No  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024095958  
Special Instruction to ARC,if any :  
SLN2637J - AXA  
Prepared Date : 08/05/2018 04:19:12 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U405768492 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,116.00	0.00
Total Material Charges :	3,566.07	3,566.07
Other Charges :	1,136.88	0.00
<b>TOTAL :</b>	<b>6,832.95</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>0.00</b>	<b>0.00</b>
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	08/05/2018 06:52:18 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 06:50:43 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>1,136.88</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace	No
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
<b>TOTAL MATERIALS</b>								<b>3,566.13</b>	<b>3,566.07</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>3,566.07</b>	<b>3,566.07</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									