

Tanala Automotive Consultancy

My Mail Box 883230
Singapore 919191
ROB: 53240124K

Cheryl
9838 5899

Swee Seng Leasing Pte Ltd
21 Toh Guan Road East
#03-02 Toh Guan Centre
Singapore 608609
Attn: Motor Claims Department

Estimate No : ES2018/0096
Date : 09/05/2018
Vehicle No : SKG3325B
Make/Model : TOYOTA / ALLION
Date of Accident : 04/05/2018

S/N	Description List Item	Qty	Unit Amount	Amount
1	Boot Lid <i>Dented</i>	1	1,166.35	1,166.35
2	Boot Lid Hinge <i>NOT NEU</i>	2	107.00	214.00
3	Boot Lid Inner Lock <i>Damaged</i>	1	378.50	378.50
4	Boot Lid Lock Striker <i>Not new</i>	1	102.50	102.50
5	Boot Lid Inner Trim <i>Not new</i>	1	211.62	211.62
6	Boot Lid Rubber <i>lt</i>	1	136.20	136.20
7	Boot Lid "Allion" Emblem	1	68.50	68.50
8	Boot Lid "Toyota" Emblem <i>new</i>	1	68.50	68.50
9	Boot Lid "A 1.5" Emblem	1	68.50	68.50
10	Boot Lid Outer Chrome Moulding <i>not new</i>	1	311.65	311.65
11	Boot Lid Trim <i>not new</i>	1	195.00	195.00
12	Boot Lid Trim Clips <i>not new</i>	10	5.00	50.00
13	Rear Lamp, LH/RH <i>cracked</i>	2	483.61	967.22 630
14	Rear Lamp Panel <i>Repair</i>	2	283.60	567.20
15	Rear Centre Panel <i>Distorted</i>	1	862.85	862.85 655
16	Rear Centre Panel Inner Top Garnish <i>getand</i>	1	185.41	185.41
17	Rear Centre Panel Top Garnish Clips <i>new</i>	10	5.00	50.00 10
18	Rear Bumper <i>Distorted</i>	1	1,186.95	1,186.95
19	Rear Bumper Reflector <i>lt</i>	2	68.50	137.00
20	Rear Bumper Bracket <i>1 not new</i>	2	99.50	199.00
21	Rear Bumper Clips <i>new</i>	10	5.00	50.00 30
22	Rear Bumper Side Retainer <i>new</i>	2	64.43	128.86
23	Rear Bumper Side Bracket <i>not new</i>	2	81.50	163.00
24	Rear Floor Top Board <i>not new</i>	1	396.23	396.23
25	Rear Floor Panel <i>Repair</i>	1	894.65	894.65
26	Rear Vehicle Number Plate Lamp <i>not new</i>	1	48.60	48.60
27	Rear Exhaust Silencer <i>Not New</i>	1	781.62	781.62
28	Rear Exhaust Silencer Mounting <i>2 Not</i>	2	50.00	100.00
29	Rear Exhaust Silencer Chrome <i>1 New</i>	1	120.00	120.00
30	Boottlid Lock Sensor <i>Cracked</i>	195.60		
Sub-Total:				9,809.91
Less: 25%				(2,452.48)
				7,357.43

504537
less 25%: 3784.02

Nett Items				
1	Rear Vehicle Number Plate <i>Not new</i>	1 (N)	60.00	60.00
2	Rear Reverse Sensor <i>Damaged</i>	1 (N)	250.00	250.00 200
Sub-Total:				310.00
Less: 10%				(31.00)
				279.00

200

Tanala Automotive Consultancy

My Mail Box 882230
 Singapore 918191
 ROE: 53240124K

Swee Seng Leasing Pte Ltd
 21 Toh Guan Road East
 #03-02 Toh Guan Centre
 Singapore 608609
 Attn: Motor Claims Department

Estimate No : ES2018/0096
 Date : 09/05/2018
 Vehicle No : SKG3325B
 Make/Model : TOYOTA / ALLION
 Date of Accident : 04/05/2018

S/N	Description	Qty	Unit Amount	Amount
Labour Charges				
1	Towing Charges			100.00 X
2	To remove/transfer/refix bootlid fittings			80.00 60
3	To remove/repair rear exhaust silencer			120.00 X
4	To remove/refix damaged parts, align and renew replaced parts, including repair			1,200.00 1000
5	To rewire rear portion			50.00 30
6	To putty and respray on affected areas, boot lid, rear panel, rear bumper, both rear fender, floor panel			1,400.00 1000
8	To apply undersealing on replaced and repaired parts			100.00 40
8	To remove/replace reverse sensor			100.00 50
9	To remove/refix rear trims and garnishes			120.00 60
Sub-Total:				3,270.00

2240

Rental: 5 working days @ S\$120/day

TOTAL 10,906.43

total: 6,224.02
 L/s: SK
 05Days