

INS. CASE OWNER:

Shenmi

CC 4, III1800 8627, Ajably

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

8/5/18

Date / Time:

8/5/18

Registered in Merimen:

10/5/18

Pre-assign / CCU / FTE

SHD 4332A

MU18050102



Insured Vehicle No.:

SHD 4332A

Claim No.:

MU18050102

Name of Insured:

CTB

Policy No.:

MU18050102

Insured Tel No.:

HP: _____

Make / Model:

H. Sonata

Excess Sec II :SS

D.O.A.: 4/5/18

Place of Accident:

CTB 7 Ave

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHAN KENG HEE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

9148 2823 (V/L: YES/NO)

Insured Liability: %

Final ? Yes / No

SGR 1233R

SHD 4332A

SKG 3325B



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

zanala

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/5
8/5

SHD 4332A - X;
SHD 4332A - 6411116011340 / 672 X; 10/15/18
3 VC, 012ND - X: 0%

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

!!! INSTRUCTION
SUBMIT REPORT
TP PASS SOLICITORS

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ (days) Reduction: % Email Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia: 0

Repair Cost: S\$ - (days)

Loss of Rental (LOR): S\$ - (days)

Loss of Use (LOU): S\$ - (\$ x days)

Loss of Income (LOI): S\$ - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: S\$ -

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost: S\$ -

Total: S\$ Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email Call

Payee 1: S\$ - Name 1:

Payee 2: (Strike if N.A.) S\$ - Name 2:

Payee 3: (Strike if N.A.) S\$ - Name 3:

12/18/18

WP

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$350

REF: III

B.000000

ASSIGNMENT

10/10/08

From: Date: 08052018

Veh No: SKG3325B Yr Regn: 2008 Oct.

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKG 3325B
at Workshop mis: Tanala Automotive
of: 25 Kaki Bukit Rd 4 #07-56
Insured: Synergy @ KBMake: Toyota Allion cc 1496
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 170182 T/Radio: Insured / Std / NI / NA

Policy No:

Eng No:
C/No: NZT2603030057

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Chery - 9838 5899

Mod: Nil / STD A/Rim or

(Policy Condition)

Call her before go

Tyre Size: F: 185/70 R14

R: 185/70R14

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

BS / QUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Bal. or Market Value:

Front:

Rear:

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 06 mm

R/Bal. 06 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 06 mm

L/Bal. 06 mm

Est. Repairs: 5 days Res: Yes or No

D.O.A. D.O.I. 08/05/18

Lum Sum: % 3 Val: Yes or No

Survey held at: Tanala Automotive

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rdr / O/S / N/S / UIC / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP !!!

L/S \$4,650

MV: 13K
PV: 7.9K
Nett: 5.1K

P (\$6,256.43 / 577)

Date/Time: File Pass to?

: Prel. Report

Days Of Repair: 1548K

1)

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to?

2)

Add Fee:

Site Insp \$

) 0 + 01. 51

Interview \$

) Photo

Tech Insp \$

) Agent

Weekend \$

) TOTAL

Report Format :

Lump Sum / I.B.I: \$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18008627/Aja3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 10-05-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4332A	Veh. Inspected	SKG 3325B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/05/2018	Inspection Date	08/05/2018
Survey held at	TANALA AUTOMOTIVE CONSULTANCY BLK 7 SIN MING IND EST SECTOR C #01-82 SINGAPORE 575642		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Tanala Automotive Consultancy

My Mail Box 883230
Singapore 919191
ROB: 53240124K

Cheryl
9838 5899

Swee Seng Leasing Pte Ltd

21 Toh Guan Road East
#03-02 Toh Guan Centre
Singapore 608609
Attn: Motor Claims Department

Estimate No : ES2018/0096
Date : 09/05/2018
Vehicle No : SKG3325B
Make/Model : TOYOTA / ALLION
Date of Accident : 04/05/2018

S/N	Description List Item	Qty	Unit Amount	Amount	
1	Boot Lid <i>Dented</i>	1	1,166.35	1,166.35	
2	Boot Lid Hinge <i>NOT NEC</i>	2	107.00	214.00	
3	Boot Lid Inner Lock <i>Damaged</i>	1	378.50	378.50	
4	Boot Lid Lock Striker <i>NOT NEC</i>	1	102.50	102.50	
5	Boot Lid Inner Trim <i>Not new</i>	1	211.62	211.62	
6	Boot Lid Rubber <i>lt</i>	1	136.20	136.20	
7	Boot Lid "Allion" Emblem	1	68.50	68.50	
8	Boot Lid "Toyota" Emblem <i>NEC</i>	1	68.50	68.50	
9	Boot Lid "A 1.5" Emblem	1	68.50	68.50	
10	Boot Lid Outer Chrome Moulding <i>not NEC</i>	1	311.65	311.65	
11	Boot Lid Trim <i>Not NEC</i>	1	195.00	195.00	
12	Boot Lid Trim Clips <i>NOT NEC</i>	10	5.00	50.00	
13	Rear Lamp, LH/RH <i>cracked</i>	2	483.61	967.22 630	
14	Rear Lamp Panel <i>Repair</i>	2	283.60	567.20	
15	Rear Centre Panel <i>Distorted</i>	1	862.85	862.85 655	
16	Rear Centre Panel Inner Top Garnish <i>Defound</i>	1	185.41	185.41	
17	Rear Centre Panel Top Garnish Clips <i>New</i>	10	5.00	50.00 10	
18	Rear Bumper <i>Distorted</i>	1	1,186.95	1,186.95	
19	Rear Bumper Reflector <i>lt</i>	2	68.50	137.00	
20	Rear Bumper Bracket <i>1 Not new</i>	2	99.50	199.00	
21	Rear Bumper Clips <i>New</i>	10	5.00	50.00 50	
22	Rear Bumper Side Retainer <i>New</i>	2	64.43	128.86	
23	Rear Bumper Side Bracket <i>with NEC</i>	2	81.50	163.00	
24	Rear Floor Top Board <i>Not new</i>	1	396.23	396.23	
25	Rear Floor Panel <i>Repair</i>	1	894.65	894.65	
26	Rear Vehicle Number Plate Lamp <i>Not new</i>	1	48.60	48.60	
27	Rear Exhaust Silencer <i>Not New</i>	1	781.62	781.62	
28	Rear Exhaust Silencer Mounting <i>2 Not</i>	2	50.00	100.00	
29	Rear Exhaust Silencer Chrome <i>Not New</i>	1	120.00	120.00	
30	Bootlid Lock Sensor <i>Cracked</i>	1	195.60	195.60	
				Sub-Total:	9,809.91
				Less: 25%	(2,452.48)
					7,357.43

504537
less 25%: 3784.02

Nett Items					
1	Rear Vehicle Number Plate <i>Not new</i>	1 (N)	60.00	60.00	
2	Rear Reverse Sensor <i>Damaged</i>	1 (N)	250.00	250.00 200	
				Sub-Total:	310.00
				Less: 10%	(31.00)
					279.00

Tanala Automotive Consultancy

My Mail Box 882230
 Singapore 919191
 ROB: 53240124K

Swee Seng Leasing Pte Ltd
 21 Toh Guan Road East
 #03-02 Toh Guan Centre
 Singapore 608609
 Attn: Motor Claims Department

Estimate No : ES2018/0096
 Date : 09/05/2018
 Vehicle No : SKG3325B
 Make/Model : TOYOTA / ALLION
 Date of Accident : 04/05/2018

S/N	Description	Qty	Unit Amount	Amount
Labour Charges				
1	Towing Charges			100.00 X
2	To remove/transfer/refix bootlid fittings			80.00 60
3	To remove/repair rear exhaust silencer			120.00 X
4	To remove/refix damaged parts, align and renew replaced parts, including repair			1,200.00 200
5	To rewire rear portion			50.00 35
6	To putty and respray on affected areas, boot lid, rear panel, rear bumper, both rear fender, floor panel			1,400.00 200
8	To apply undersealing on replaced and repaired parts			100.00 40
8	To remove/replace reverse sensor			100.00 50
9	To remove/refix rear trims and garnishes			120.00 60
			Sub-Total:	3,270.00

1840

Rental: 5 working days @ S\$120/day

TOTAL 10,906.43

total: 5824.02

L/s: 4650
 050 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1948K
Vehicle Details	
Vehicle No.:	SKG3325B
Vehicle to be Exported:	Yes
Intended De-registration Date:	08 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	1N2D133707
Chassis No.:	NZT2603030057
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,582.00
Original Registration Date:	10 Oct 2008
First Registration Date:	10 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$14,582.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Oct 2018
PARF Rebate Amount:	\$7,291.00
Intended COE Rebate Details	
COE Expiry Date:	09 Oct 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$13,801.00
COE Rebate Amount:	\$578.00
Total Rebate Amount:	\$7,869.00

The information contained herein is correct as at 08 May 2018

OK

Joy Irene (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Thursday, 16 August 2018 12:14 PM
To: Sherini Pillai; Joy Irene (LKKAuto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: MCT18050102 (SHD 4332A, SGQ 1233R & SKG 3325B ON 4.5.18) *** LKK REF: CC4/III18008627/Aja3

From: Sherini Pillai <sherini@iii.com.sg>
Sent: Thursday, 16 August, 2018 12:11 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Subject: MCT18050102 (SHD 4332A, SGQ 1233R & SKG 3325B ON 4.5.18)
Importance: High

Dear Mei Kwan,

TP has passed the case to their solicitors therefore please upload your report urgently.
Tks.

Regards,

Sherini Pillai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6128 Fax: 6224 4174



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2018 Edit Reg		08 May 2018 00:00 Edit Adj Rpt	S\$4,650.00 Edit Estimates	S\$4,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	SWEE SENG LEASING PTE LTD , Co. Reg. No.: 201111948K								
Vehicle Reg. No.:	SKG3325B	Date of Loss:	04/05/2018 22:00 - :59 [114 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18050102	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD4332A	Policy No. (Claimant):	DMHCSN1302291805						
Repairer:	Tanala Automotive Consultancy - Kaki Bukit (HQ) 25 KAKI BUKIT ROAD 4, #07-56 SYNERGY @ KB, 417800 Kaki Bukit - Tel: 98385899								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• III_SG (15/05/2018): Alert - Adj Mandate Approved (S\$0.00) - SKG3325B - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKG3325B (MCT18050102)
 [SHD4332A]
 TP
 SWEE SENG LEASING PTE LTD
 May 4 2018 10:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Tanala Automotive Consultancy - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
68	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
69	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
70	17/08/18 17:14	General View	 Load JPG	<input checked="" type="checkbox"/>
71	17/08/18 17:14	AFTER REPAIR	 Load JPG	<input checked="" type="checkbox"/>
72	17/08/18 17:14	AFTER REPAIR	 Load JPG	<input checked="" type="checkbox"/>
73	17/08/18 17:14	AFTER REPAIR	 Load JPG	<input checked="" type="checkbox"/>
74	17/08/18 17:14	AFTER REPAIR	 Load JPG	<input checked="" type="checkbox"/>
75	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	17/08/18 17:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/18 21:05	ACKNOWLEDGEMENT EMAIL TO III DD 07.05.2018	 Load PDF	
2	14/05/18 23:36	TP GIA REPORT	 Load PDF	
3	17/08/18 17:19	INSTRUCTION TO WP	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 08:51	Singapore Accident Statement	 Load PDF	
2	06/08/18 15:08	Letter of Demand from Third Party ORACLE LAW	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18008627/AJA3Q2
Date: 23/08/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No : SKG3325B	Insured Vehicle No :	SHD4332A	
Date of Loss: 04/05/2018	Nature of Claim:	TP	Claim No: MCT18050102

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG3325B	Engine No:	1NZD133707
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603030057
Reg. Date:	10/10/2008 (Man. Year: 2008)	Odometer:	170182 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,814.13	3,984.03	3,830.10	49.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,840.00	1,430.00	43.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,084.13	5,824.03	5,260.10	47.46
Approved Total (Overridden) (S\$)		4,650.00		
Nett Amount (S\$)	11,084.13	4,650.00	6,434.13	58.05
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	08/05/2018	
Date Inspected:	08/05/2018 Inspected At:	Tanala Automotive Consultancy - Kaki Bukit (HQ) 25 KAKI BUKIT ROAD 4, #07-56 SYNERGY @ KB Singapore 417800
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2018)
Parts: 143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKG3325B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,166.35 FL	*1,166.35 FL
2	2		*BOOT LID HINGE	Not Necessary	214.00 FL	*- FL
3	1		*BOOT LID INNER LOCK	Damaged	378.50 FL	*378.50 FL
4	1		*BOOT LID LOCK STRIKER	Not Necessary	102.50 FL	*- FL
5	1		*BOOT LID INNER TRIM	Not Necessary	211.62 FL	*- FL
6	1		*BOOT LID RUBBER	Cut	136.20 FL	*136.20 FL
7	1		*BOOT LID ALLION EMBLEM	Necessary	68.50 FL	*68.50 FL
8	1		*BOOT LID TOYOTA EMBLEM	Necessary	68.50 FL	*68.50 FL
9	1		*BOOT LID A 1.5 EMBLEM	Necessary	68.50 FL	*68.50 FL
10	1		*BOOT LID OUTER CHROME MOULDING	Not Necessary	311.65 FL	*- FL
11	1		*BOOT LID TRIM	Not Necessary	195.00 FL	*- FL
12	10		*BOOT LID TRIM CLIPS	Not Necessary	50.00 FL	*- FL
13	2		*REAR LAMP ,LH/RH	Cracked	967.22 FL	*630.00 FL
14	7		*REAR LAMP PANEL	Repair	567.20 FL	*- FL
15	1		*REAR CENTRE PANEL	Distorted	862.85 FL	*655.00 FL
16	1		*REAR CENTRE PANEL INNER TOP GARNISH	Deformed	185.41 FL	*185.41 FL
17	10		*REAR CENTRE PANEL TOP GARNISH CLIPS	Necessary	50.00 FL	*10.00 FL
18	1		*REAR BUMPER	Distorted	1,186.95 FL	*1,186.95 FL
19	2		*REAR BUMPER REFLECTOR	Cut	137.00 FL	*137.00 FL
20	2		*REAR BUMPER BRACKET	Not Necessary	199.00 FL	*- FL
21	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	128.86 FL	*128.86 FL
23	2		*REAR BUMPER SIDE BRACKET	Not Necessary	163.00 FL	*- FL
24	1		*REAR FLOOR TOP BOARD	Not Necessary	396.23 FL	*- FL
25	1		*REAR FLOOR PANEL	Repair	894.65 FL	*- FL
26	1		*REAR VEHICLE NUMBER PLATE LAMP	Not Necessary	48.60 FL	*- FL
27	1		*REAR EXHAUST SILENCER	Not Necessary	781.62 FL	*- FL
28	2		*REAR EXHAUST SILENCER MOUNTING	Not Necessary	100.00 FL	*- FL
29	1		*REAR EXHAUST SILENCER CHROME	Not Necessary	120.00 FL	*- FL
30	1		*BOOTLID LOCK SENSOR	Cracked	195.60 FL	*195.60 FL
31	1		*REAR VEHICLE NUMBER PLATE	Not Necessary	60.00 FS	*- FS
32	1		*REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,315.51	5,245.37
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,501.38	1,261.34
Total Parts (\$\$)	7,814.13	3,984.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	0.00
2	TO REMOVE/TRANSFER /REFIX BOOTLID FITTINGS	New	80.00	60.00
3	TO REMOVE/REPAIR REAR EXHAUST SILENCER	New	120.00	0.00
4	TO REMOVE/REFIX DAMAGED PARTS ,ALIGN AND RENEW REPLACED PARTS ,INCLUDING REPAIR	New	1,200.00	800.00
5	TO REWIRE REAR PORTION	New	50.00	30.00
6	TO PUTTY AND RESPRAY ON AFFECTED AREAS ,BOOT LID ,REAR PANEL,REAR BUMPER,BOTH REAR FENDER ,FLOOR PANEL	New	1,400.00	800.00
7	TO APPLY UNDERSEALING ON REPLACED AND REPAIRED PARTS	New	100.00	40.00
8	TO REMOVE/REPLACE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE/REFIX REAR TRIMS AND GARNISHES	New	120.00	60.00
Gross Labour Cost (S\$)			3,270.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >