

Slame

CC6 / CTI 1800 8631, Aua3 n2

ASSIGNMENT

Surveyor:

DORIAN

DOI:

4/1/18

Date / Time:

4/1/18

Registered in Merimen:

Pre-assign / CCU / FTE

GBG 8548 Z



Insured Vehicle No.:

Name of Insured:

Lee Lum Hui & Company

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

3/1/18

Claim No.:

JNM800726502

Policy No.:

DNRN/207471700

Make / Model:

T. BYNA

Place of Accident:

WOODLANDS Ave 1

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

JNM YW
91333037

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLT 4355 C



INSRS:

WSP:

Tel:

Liability:

RMKS:

My Solution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

4/1/18
244

SLT 4355 C. X ; GBG 8548 Z. X

OI rear-ended to TP.

18.2.18

FILE PASS TO TYPST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

THIN 2315 > Division

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: WOP

Repair Cost:

SS 4,800

(6 days)

Reduction:

68 %

Email

Call

FINAL SETTLEMENT

Date/Time: 12.04.19

Confirm with: SU WONG

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

N/A

SS 5,366.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 420.00

(\$ 60

x 7 days)

Loss of Income (LOI):

SS

(\$

x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

7400

Total:

SS 5,563.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 12.04.19

Confirm with: SU WONG

Email

Call

Payee 1:

SS 5,563.45

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18008631/Aua3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 11-05-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 8548Z	Veh. Inspected	SLT 4355C	
Policy No.	DMCVSN1767471700	Coverage (\$)	0.00	
Claim No.	SNM18D02265C02	Excess (\$)	0.00	
Assign From		Assign Date	11/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/05/2018	Inspection Date	04/05/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING INSURANCE	DATE	: 04/05/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLT4355C	<i>MR053FEH 604574630</i>	
MODEL	: TOYOTA COROLLA ALTIS 1.6	<i>Thin Thin</i>	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
	DATE : 3-May-18		
	TIME : 09:55HRS		
THIRD PARTY REQUESTOR / CONTACT	:	MS HONG / SHARON	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 896.10	\$ 896.10
2	BOOTLID LOGO	1	\$ 68.60	\$ 68.60
3	BOOTLID EMBLEM 'COROLLA'	1	\$ 55.10	\$ 55.10
4	BOOTLID EMBLEM 'ALTIS'	1	\$ 55.40	\$ 55.40
5	BOOTLID LOCK <i>Damaged</i>	1	\$ 349.60	\$ 349.60
6	BOOTLID HINGE <i>new</i>	2	\$ 101.00	\$ 202.00
7	BOOTLID OUTER CHROME MOULDING <i>lt.</i>	1	\$ 380.00	\$ 380.00
8	BOOTLID LAMP <i>Cracked</i>	2	\$ 345.00	\$ 690.00
9	BOOTLID WEATHERSTRIP <i>lt</i>	1	\$ 175.10	\$ 175.10
10	REAR BUMPER <i>Deformed</i>	1	\$ 630.00	\$ 630.00
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 101.00	\$ 202.00
12	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 88.00	\$ 176.00
13	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 460.00	\$ 460.00
14	TAILLAMP <i>cracked</i>	2	\$ 480.00	\$ 960.00
15	TAILLAMP PANEL <i>Repair</i>	2	\$ 190.00	\$ 380.00
16	TAILLAMP LOWER BRACKET <i>new</i>	2	\$ 58.00	\$ 116.00
17	REAR NUMBER PLATE LAMP(SET) <i>new</i>	1	\$ 190.00	\$ 190.00

✓
✓
✓
✓
✓
x.
✓ 230.70
✓
✓
✓
✓ 486.50
✓
✓
x.
✓
780.
x.
x.

18	REAR WINDSCREEN MOULDING <i>Not in</i>	1	\$ 280.00	\$ 280.00	X
19	REAR FENDER <i>in</i>	2	\$ 1,020.00	\$ 2,040.00	+
20	REAR FENDER INNER TRIM <i>in</i>	2	\$ 340.00	\$ 680.00	+
21	REAR END PANEL <i>Distorted</i>	1	\$ 790.00	\$ 790.00	✓ 587.20
22	REAR END PANEL TOP GARNISH <i>2hd</i>	1	\$ 350.00	\$ 350.00	252.60
23	SPARE FLOOR PANEL <i>Rps</i>	1	\$ 980.00	\$ 980.00	X
24	SPARE FLOOR PANEL TOP COVER <i>in</i>	1	\$ 298.10	\$ 298.10	X
25	REAR EXHAUST PIPE <i>3 NP</i>	1	\$ 965.60	\$ 965.60	X
26	REAR EXHAUST MOUNTING <i>in</i>	4	\$ 46.20	\$ 184.80	+

5288.90

3866.67

TOTAL PRICE \$ 12,554.40

LESS 25% \$ 3,138.60

SUB TOTAL PRICE \$ 9,415.80

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>in</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS(SET) <i>in</i>	1	\$ 20.00	\$ 20.00	✓
3	REAR TAILLAMP CLIPS(SET) <i>in</i>	1	\$ 20.00	\$ 20.00	✓
4	REAR END PANEL SEALANT <i>in</i>	1	\$ 80.00	\$ 80.00	60
5	REAR END PANEL TOP GARNISH CLIPS(SET) <i>in</i>	1	\$ 20.00	\$ 20.00	10
6	REAR FLOOR PANEL SEALANT <i>in</i>	1	\$ 80.00	\$ 80.00	+
7	REVERSE SENSOR <i>Pungd</i>	1	\$ 220.00	\$ 220.00	200
8	REVERSE CAMERA <i>in</i>	1	\$ 580.00	\$ 580.00	+

310

TOTAL \$ 1,070.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL AND SPARE TYRE PANEL	\$1,800.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,400.00	800	
3	WIRING	\$50.00	30	
4	TUFF COAT	\$180.00	40	
5	TO CONDUCT WATER LEAKAGE TEST	\$250.00	+	
6	TO REMOVE AND REFIX REAR EXHAUST PIPE	\$250.00	+	
7	TO REMOVE AND REFIX REAR WINDSCREEN	\$150.00	+	

8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$120.00	SD	
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$120.00	SD	
TOTAL		\$4,320.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,485.80
 TOTAL LABOUR COST : \$ 4,320.00
 TOTAL REPAIR COST : \$ 14,805.80

1770

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lij
 H/S 4/5 04/05/18. 2/s: 4.81K.
 06 Aug
 total: 6046.67.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 11 May, 2018 11:10 AM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBG8548Z (OI : CAI - SNM18D02265C02) AND SLT4355C (TP : LKK REF - CC6/CTI18008631/Aua3) on 03/05/2018
Attachments: leeSZ_SNM18D02265C02-GBG8548Z-LKKDirectSettlementAccidentLtr_CLCR95.608.pdf; MCHM18057969-GBG8548Z.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 11 May, 2018 9:29 AM
To: Claims Dept of CTI
Cc: Irene Tay; Lucas Lee; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving GBG8548Z (OI : CAI - TBA) AND SLT4355C (TP : LKK REF - CC6/CTI18008631/Aua3) on 03/05/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SLT 4355C at M/s MG Solution Pte Ltd - Kaki Bukit.

Enclosed here with a copy of TP's GIA report for your perusal.

Please be informed that the estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D02265/C02/8**

Date : **11 MAY 2018**

via Ordinary & Registered Mail

**LEE LUM HUAT AND COMPANY
15 WOODLANDS LOOP
#01-30/31
SINGAPORE 738322**

Dear Sir / Madam

**ACCIDENT INVOLVING GBG8548Z AND SLT4355C ON 03 MAY 2018
ALONG WOODLANDS AVE 1**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLT4355C**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : THIN THIN
Ref : CC6/CTI18008631/AUA3
Contact No : 68412360
via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: LIM WEE LEE

CAR/ LORRY/CYCLE: REG NO: SLT 4355C POLICY NO: -

ACCIDENT CLAIM NO: -

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SLT 4355C from the repairers,

Messrs MG Solution Pte Ltd

And that all repairs necessary as a result of an accident in which the said vehicle was Involved on or

about the 03 day of 05 2018 have been completed to my / our satisfaction, and that

I / we have no further claim on the above company in Respect thereof.

Date: Signature: [Signature]

Co's Stamp: NRIC No:

4/5/2018 - PR1

6/5/2018 - Sunday

Vehicle In - 4/5/2018

Vehicle Out - 10/5/2018

Low - 7 days x \$80
= \$560



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18008631/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-05-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 8548Z	Veh. Inspected	SLT 4355C
Policy No.	DMCVSN1767471700	Coverage (\$)	0.00
Claim No.	SNM18D02265/C02/8	Excess (\$)	0.00
Assign From		Assign Date	04/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH604574630	Colour	BLACK
Odometer	6711	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/05/2018	Inspection Date	04/05/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4355C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED	896.10	896.10
1	BOOTLID LOGO	NECESSARY	68.60	68.60
1	BOOTLID EMBLEM 'COROLLA'	NECESSARY	55.10	55.10
1	BOOTLID EMBLEM 'ALTIS'	NECESSARY	55.40	55.40
1	BOOTLID LOCK	DAMAGED	349.60	349.60
2	BOOTLID HINGE @\$101.00	NOT NECESSARY	202.00	-
1	BOOTLID OUTER CHROME MOULDING	CUT	380.00	230.70
2	BOOTLID LAMP @\$345.00	CRACKED	690.00	690.00
1	BOOTLID WEATHERSTRIP	CUT	175.10	175.10
1	REAR BUMPER	DEFORMED	630.00	486.50
2	REAR BUMPER SIDE RETAINER @\$101.00	NECESSARY	202.00	202.00
2	REAR BUMPER REFLECTOR @\$88.00	NOT NECESSARY	176.00	-
1	REAR BUMPER REINFORCEMENT	BENT	460.00	460.00
2	TAILLAMP @\$480.00	CRACKED	960.00	780.00
2	TAILLAMP PANEL @\$190.00	TO REPAIR SEE LABOUR	380.00	-
2	TAILLAMP LOWER BRACKET @\$58.00	NOT NECESSARY	116.00	-
1	SET REAR NUMBER PLATE LAMP	NOT NECESSARY	190.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	280.00	-
2	REAR FENDER @\$1020.00	NOT NECESSARY	2,040.00	-
2	REAR FENDER INNER TRIM @\$340.00	NOT NECESSARY	680.00	-
1	REAR END PANEL	DISTORTED	790.00	587.20
1	REAR END PANEL TOP GARNISH	DEFORMED	350.00	252.60
1	SPARE FLOOR PANEL	TO REPAIR SEE LABOUR	980.00	-
1	SPARE FLOOR PANEL TOP COVER	NOT NECESSARY	298.10	-
1	REAR EXHAUST PIPE	NOT NECESSARY	965.60	-
4	REAR EXHAUST MOUNTING @\$46.20	NOT NECESSARY	184.80	-
	LESS 25% DISCOUNT		-3,138.60	-1,322.23
			9,415.80	3,966.67

Report Ref No. CC6/CTI18008631/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR TAILLAMP CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	REAR FLOOR PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	580.00	-
			1,070.00	310.00
	LABOUR			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL AND SPARE TYRE PANEL.		1,800.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	800.00
	WIRING.		50.00	30.00
	TUFF COAT.		180.00	40.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		120.00	50.00
			4,320.00	1,770.00
	GRAND TOTAL		14,805.80	6,046.67
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CC6/CT118008631/Aea3n2

ADRIAN LING WAI PING

B.Eng.AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.