

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST1800131
Date: 07 May 2018
Veh Reg No: SKS3875S
Make/Model: TOYOTA VIOSJGRADEMT
Chasis No: MHFBT9F3006028307
Reg. Date: 13/04/2015
Your Ref No: SCN63J

Claim Type: Third Party
Accident Date: 04/05/2018
TP Veh Reg No: SCN63J

Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC REAR BOOT LID <i>Distorted</i>	665.80	✓
2	1 PC REAR BOOT LID GARNISH <i>cracked</i>	161.60	✓
3	1 PC REAR BOOT LID LOGO <i>free</i>	44.80	✓
4	1 PC REAR BOOT LID "VIOS" EMBLEM	43.60	✓
5	1 PC REAR BOOT LID LOCK <i>new</i>	185.90	✓
6	1 PC REAR BOOT LID LOCK CHECKER <i>new</i>	44.40	+
7	1 PC REAR BOOT LID KEY LOCK <i>not new</i>	98.80	+
8	1 PC REAR BOOT LID RUBBER <i>cut</i>	166.40	✓
9	2 PCS REAR BOOT LID HINGES <i>Best</i>	120.40	✓
10	1 PC REAR BOOT LID TRIM <i>new</i>	178.90	+
11	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	125.80	+
12	1 PC REAR R/H FENDER <i>Buckled</i>	872.10	✓
13	1 PC REAR R/H FENDER TRIM <i>new</i>	355.90	+
14	1 PC REAR R/H TAIL LAMP <i>cut</i>	357.20	2
15	1 PC REAR R/H TAIL LAMP PANEL <i>Repair</i>	143.70	+
16	1 PC REAR L/H TAIL LAMP <i>cut</i>	357.20	2
17	1 PC REAR L/H TAIL LAMP PANEL <i>new</i>	143.70	+
18	1 PC REAR PANEL <i>Dehnd</i>	620.10	✓
19	1 PC REAR PANEL TRIM <i>Dehnd</i>	232.10	✓
20	1 PC REAR SPARE TYRE COVER <i>tom</i>	206.90	✓
21	1 PC REAR SPARE TYRE R/H SPONGE <i>cracked</i>	227.70	✓
22	1 PC REAR SPARE TYRE L/H SPONGE <i>new</i>	227.70	+
23	1 PC REAR BUMPER <i>Dehnd</i>	452.00	✓
24	1 PC REAR BUMPER REINFORCEMENT <i>Best</i>	316.00	✓
25	2 PCS REAR BUMPER SIDE RETAINERS <i>new</i>	227.80	✓
26	2 PCS REAR BUMPER SMALL RETAINERS <i>new</i>	43.60	✓
27	1 PC REAR BUMPER R/H REFLECTOR <i>cracked</i>	179.80	+
28	1 PC REAR EXHAUST PIPE <i>Best new</i>	595.20	+
29	2 PC REAR EXHAUST MOUNTING <i>new</i>	56.20	+

5481

4110.75

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST1800131
Date: 07 May 2018
Veh Reg No: SKS3875S
Make/Model: TOYOTA
VIOSJGRADEMT
Chasis No: MHFBT9F3006028307
Reg. Date: 13/04/2015
Your Ref No: SCN63J

Claim Type: Third Party
Accident Date: 04/05/2018
TP Veh Reg No: SCN63J

Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		7,451.30	
	Less 25%	1,862.83	5,588.53
	Special Net		
30	1 SET REAR BOOT LID CLIPS <i>new</i>	48.00	<i>x</i>
31	1 PC REAR NUMBER PLATE <i>Best</i>	50.00	<i>30</i>
32	1 SET REAR R/H FENDER TRIM CLIPS <i>new</i>	48.00	<i>x</i>
33	1 PC REAR R/H FENDER STICKER <i>new</i>	190.00	<i>✓</i>
34	1 PC REAR WINDSCREEN GUM <i>3 new</i>	60.00	<i>30</i>
35	1 PC REAR WINDSCREEN SEAL <i>new</i>	60.00	<i>30</i>
36	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00	<i>10</i>
37	1 PC REAR BUMPER STICKERS <i>new</i>	195.00	<i>✓</i>
38	1 SET REAR BUMPER CLIPS <i>new</i>	48.00	<i>30</i>
39	1 PC REAR BUMPER "L" PLATE BRACKET <i>new</i>	70.00	<i>✓</i>
	<i>1pc L bracket Best</i>	809.00	809.00
40	1 PC REAR BOOT LID "522" STICKER <i>new</i>	35.00	<i>✓</i>
		35.00	35.00
	Labour		
41	1 TO CHECK WIRING	50.00	<i>30</i>
	GENERIC		
42	1 TO REMOVE AND REFIT STICKERS	100.00	<i>80</i>
43	1 TO REMOVE AND REFIT WINDSCREEN GLASS	120.00	<i>✓</i>
44	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	<i>80</i>
45	1 TO REMOVE AND REFIT EXHAUST PIPE	150.00	<i>80</i>
46	1 TO SPRAY UNDER SEAL	180.00	<i>80</i>
47	1 TO SPRAY PAINT DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC. ALL	1,600.00	<i>1100</i>

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 04/05/2018
TP Veh Reg No: SCN63J

Estimate No: EST1800131
Date: 07 May 2018
Veh Reg No: SKS3875S
Make/Model: TOYOTA
VIOSJGRADEMT
Chasis No: MHFBT9F3006028307
Reg. Date: 13/04/2015
Your Ref No: SCN63J

Estimate Repair Cost to Vehicle No :SKS3875S

Quantity	Description	List Price	Amount
		SS	SS
48	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. GENERIC	1,800.00 <i>1250</i>	
		4,200.00	4,200.00
Total			SS 10,632.53
Add GST @ 7%			744.28
Total Amount Payable			SS 11,376.81

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND THREE HUNDRED SEVENTY SIX AND CENTS EIGHTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
1/s 07/05/18.
09 ays.
6K
Total 756575
1/s 6K