

TE

4 / Asm 1800

8637

Kya332

LKK:

IDAC:

44466

Surveyor:

DOT:

11/5/2018

Date / Time:

10/05/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

X07648E

Name of Insured:

Wolvo B(S) Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

2/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8m0060H

Policy No.:

Make / Model:

AXG 6X17 3

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SUW 3055J



INSRS:

WSP:

Tel:

Liability:

RMKS:

MBM



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

4/1/18

SUW 3055J-X;

A2m

X07648E-cup/AXA 27224069/Dea3; DOA: 9/1/17

File to olvio to check PA.

27.05.18 440 (AUED DID COMPANY NUMBER INVALID)

Mandate approve via SMART.

19/1/18

Mandate approve via SMART

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 27.05.18 EMAIL.

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3/1/19

Confirm with:

Email

Call

Final Liability:

% (00)

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 11920.34

OLD REPR ENDED TP

Loss of Rental (LOR):

SS 840.00

(

7

days) X

120.00

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS 2.00

Medical:

SS

Disbursement:

SS

(e.g Tow/ Independent)

Legal Cost

SS

Total:

SS 12762.34

Global Sum SS: 12700.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 12700.00

Name 1:

mbm wheel power Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
6/9/19

REF:

BSM(LAXA)

ASSIGNMENT

From: Date: 11-052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 3055J

at Workshop m/s:

MBM Wheelpower

of

60 Sin Ming Drive

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)


Make of Veh:

Daimler

(Policy Condition)

1 pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

8202k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLW 3055J Yr Regn: 02 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M

(A) Wagon GLC 250

1991

Colour:

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

7989

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDC 253 94621-3 08024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

7/5/18

D.O.A.

11/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/5 File pass to Corrine

10/9/19 Confirm 2.B.2 \$11,140.50 with 6 working days.

(Recd) - \$11278.50
50%.

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

\$ + PE \$

Phone

Other

Total

Add Fee:



Site Insp. (\$



Interview (\$



Tech Invs (\$




Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

MBM WHEELPOWER PTE LTD

Your Ref: XD7648E
Our Ref: SLW3055J



mbm wheelpower

To: AXA INSURANCE

CC

Fax

*Not Notified
1-B1
Resurvey B4 pain*

Date: 10/5/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MERCEDES GLC 250
Chassis No.: WDC2539462F308024
Engine No.: 27492031158245
Year of Make: 2017
Accident Date: 7 May 2018

ESTIMATE FOR VEHICLE NO. : SLW3055J

DESCRIPTION

QTY

List Price

TAIL GATE	1	\$ 2,700.00 ✓ 131
TAIL GATE WEATHERSTRIP	1	\$ 395.00 ✓ 0.1
TAIL GATE INNER TRIM	1	\$ 435.00 ✓ (CB) ?
TAIL GATE INNER HANDLE GARNISH	1	\$ 165.00 ✓ SUE
TAIL GATE SWITCH BUTTON	1	\$ 175.00 ✓ SUE
TAIL GATE SWITCH COVER	1	\$ 30.00 ✓ SUE
TAIL GATE BUZZER	1	\$ 185.00 ✓ SUE
REAR WINDSCREEN	1	\$ 2,080.00 ✓ NH
REAR WINDSCREEN MOULDING	1	\$ 380.00 ✓ 190
FLOOR BOARD COMPARTMENT COVER	1	\$ 950.00 ✓ NH
TAIL GATE LAMP RH	1	\$ 850.00 ✓ 430 ✓ CM
TAIL GATE LAMP LH	1	\$ 850.00 ✓ SUE
TAIL LAMP RH	1	\$ 1,350.00 ✓ 497 ✓ CM
TAIL LAMP LH	1	\$ 1,350.00 ✓ SUE
REAR BUMPER	1	\$ 1,650.00 ✓ 830 ✓ B
REAR BUMPER CLIPS	10	\$ 90.00 ✓ SUE
REAR BUMPER LOWER COVER	1	\$ 540.00 ✓ 405 ✓ B
REAR BUMPER LOWER TRIM	1	\$ 520.00 ✓ NH
TAIL PIPE COVER RH	1	\$ 465.00 ✓ 30 ✓ B
TAIL PIPE COVER LH	1	\$ 465.00 ✓ R
REAR BUMPER TOWING COVER RH	1	\$ 75.00 ✓ SUE
REAR REINFORCEMENT	1	\$ 820.00 ✓ 485 ✓ B
REAR BUMPER REFLECTOR RH	1	\$ 65.00 ✓ CM
REAR BUMPER REFLECTOR LH	1	\$ 65.00 ✓ NH

DECOUPLING RING	1	\$	SL 25.00 X
EXHUAUST PIPE TIP RH	1	\$	BT ✓ 135.00 ?
EXHUAUST PIPE TIP LH	1	\$	✓ 135.00 X
LOADING COMPARTMENT RIGHT	1	\$	CEP ✓ 410.00
LOADING COMPARTMENT FLAP	1	\$	BT ✓ 285.00
RIVET	10	\$	NEC ✓ 90.00
END PANEL	1	\$	1,362 ✓ 1,655.00 BT
END PANEL TOP GARNISH	1	\$	275 ✓ 390.00 BT
REAR BUMPER SIDE BRACKET LH & RH @ \$150 EACH	2	\$	✓ 300.00 X
TAIL GATE "MERCEDES" LOGO	1	\$	✓ 85.00 —
TAIL GATE "GLC 250" EMBLEM	1	\$	✓ 110.00 —
TAIL GATE "4 MANTIC" EMBLEM	1	\$	✓ 110.00 —
REAR WINDSCREEN WIPER	1	\$	✓ 180.00 X
REAR WIPER MOTOR	1	\$	✓ 350.00 X
Total: \$			20,910.00
LESS 10% \$			(2,091.00)
Parts Total: \$			18,819.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

WINDSCREEN SEALANT	1	\$	<i>80.00</i>	80.00
BODY SEALANT	1	\$	<i>80.00</i>	80.00
REVERSE SENSOR	1 SET	\$	<i>400.00</i>	400.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	<i>1,200.00</i>	1,200.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	<i>120.00</i>	120.00
TO REMOVE & TRANSFER TAILGATE INNER LINING & GARNISH TO NEW TAIL GATE	\$	<i>120.00</i>	120.00
TO REMOVE & REFIT REAR WINDSCREEN TO NEW TAILGATE	\$	<i>150.00</i>	150.00
TO CONDUCT WHEEL ALIGNMENT CHECK	\$	<i>120.00</i>	120.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>80.00</i>	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>1,200.00</i>	1,200.00

Total:	\$	22,369.00
7% GST:	\$	1,565.83
Grand Total:	\$	23,934.83

23811.50

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY

t 62628888 f 64529823

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD

Your Ref: XD7648E
Our Ref: SLW3055J



To: AXA INSURANCE

CC

Fax

Date: 12/6/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MERCEDES GLC 250
Chassis No.: WDC2539462F308024
Engine No.: 27492031158245
Year of Make: 2017
Accident Date: 7 May 2018

ESTIMATE FOR VEHICLE NO. : SLW3055J

DESCRIPTION

TAIL GATE INNER LOWER TRIM

QTY	List Price	
1	\$	325.00
Total:	\$	325.00
LESS 10%	\$	(32.50)
Parts Total:	\$	292.50

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE REAR RH TAIL LAMP PANEL, REAR RH FENDER, REAR REINFORCEMENT

\$ 400.00

TO SPRAY PAINT ON THE REAR RH TAIL LAMP PANEL, REAR RH FENDER, REAR REINFORCEMENT, END PANEL

\$ 750.00

Total:	\$	1,442.50
7% GST:	\$	100.98
Grand Total:	\$	1,543.48

REVISED AND FINALISE

MBM WHEELPOWER PTE LTD

Your Ref: XD7648E
Our Ref: SLW3055J

To: AXA INSURANCE


CC

Fax

Date: 12/6/2018
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MERCEDES GLC 250
Chassis No.: WDC2539462F308024
Engine No.: 27492031158245
Year of Make: 2017
Accident Date: 7 May 2018

ESTIMATE FOR VEHICLE NO.: SLW3055J

DESCRIPTION	QTY	List Price
TAIL GATE 2434	1	\$ 2,700.00
TAIL GATE WEATHERSTRIP	1	\$ 395.00
TAIL GATE INNER TRIM	1	\$ 435.00
REAR WINDSCREEN MOULDING 190	1	\$ 380.00
TAIL GATE LAMP RH 420	1	\$ 850.00
TAIL LAMP RH 497	1	\$ 1,350.00
REAR BUMPER 832	1	\$ 1,650.00
REAR BUMPER CLIPS	10	\$ 90.00
REAR BUMPER LOWER COVER 405	1	\$ 540.00
TAIL PIPE COVER RH 310	1	\$ 465.00
REAR REINFORCEMENT 485	1	\$ 820.00
REAR BUMPER REFLECTOR RH	1	\$ 65.00
EXHUAUST PIPE TIP RH	1	\$ 135.00
LOADING COMPARTMENT RIGHT	1	\$ 410.00
LOADING COMPARTMENT FLAP	1	\$ 285.00
RIVET	10	\$ 90.00
END PANEL 1362	1	\$ 1,655.00
END PANEL TOP GARNISH 275	1	\$ 390.00
TAIL GATE "MERCEDES" LOGO	1	\$ 85.00
TAIL GATE "GLC 250" EMBLEM	1	\$ 110.00
TAIL GATE "4 MANTIC" EMBLEM	1	\$ 110.00
Total:	\$	13,010.00
LESS 10%	\$	(1,301.00)
Parts Total:	\$	11,709.00



Not Mantic
8 11/40.50
Subject to AXA approval
6 days

SPECIAL NETT

WINDSCREEN SEALANT

1 \$ 40.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$ 1,200.00

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

\$ 80.00

TO REMOVE & TRANSFER TAILGATE INNER LINING & GARNISH TO NEW TAIL GATE

\$ 80.00

TO REMOVE & REFIT REAR WINDSCREEN TO NEW TAILGATE

\$ 120.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ 20.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 750.00

Total: \$ 13,999.00

7% GST: \$ 979.93

Grand Total: \$ 14,978.93

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

T 62828688 F 64529823

Company Registration Number : 200204110W

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SLW3055J		
Vehicle Type:	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	With Sun Roof		
Vehicle Scheme:	Normal		
Vehicle Make:	MERCEDES BENZ		
Vehicle Model:	GLC250 4MATIC AUTO		
Chassis No.:	WDC2539462F308024		
Propellant:	Petrol		
Engine No.:	27492031158245		
Engine Capacity:	1991 cc		
Maximum Power Output:	155.0 kW (207 bhp)		
Maximum Laden Weight:	2400 kg		
Unladen Weight:	1735 kg		
Year Of Manufacture:	2017		
Original Registration Date:	06 Feb 2018		
Lifespan Expiry Date:	-		
COE Category:	E - Open - all except motorcycle		
Quota Premium:	\$47,390.00		
COE Expiry Date:	05 Feb 2028		
Road Tax Expiry Date:	05 Feb 2019		
PARF Eligibility Expiry Date:	05 Feb 2028		
Inspection Due Date:	05 Feb 2021		
Intended Transfer Date:	25 May 2018		
CO2 Emission:	152.00 (g/km)		
CEV/VES Rebate Utilised Amount:	-		
CO Emission:	0.234900 (g/km)		
HC Emission:	0.035200 (g/km)		
NOx Emission:	0.018900 (g/km)		
PM Emission:	0.610000 (mg/km)		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

SLW 3055J

DOA 07/05/2018

DOR 02/2018

IA calculation: 26/11/2018 (Olivia)

OI cleared:

NO

OI letter:

EST NETT VALUE:

		Revised	Cross	Check
1	2,700.00	2,700.00		
2	395.00	395.00		
3	435.00			435.00
4	165.00			165.00
5	175.00		175.00	
6	30.00		30.00	
7	185.00			185.00
8	2,080.00			2,080.00
9	380.00	380.00		
10	950.00			950.00
11	850.00	850.00		
12	850.00		850.00	
13	1,350.00	1,350.00		
14	1,350.00		1,350.00	
15	1,650.00	1,650.00		
16	90.00	90.00		
17	540.00	540.00		
18	520.00			520.00
19	465.00			465.00
20	465.00			465.00
21	75.00			75.00
22	820.00			820.00
23	65.00	65.00		
24	65.00			65.00
25	25.00		25.00	
26	135.00			135.00
27	135.00		135.00	
28	410.00			410.00
29	285.00			285.00
30	90.00			90.00
31	1,655.00			1,655.00
32	390.00			390.00
33	300.00		300.00	
34	85.00	85.00		
35	110.00	110.00		
36	110.00	110.00		
37	180.00		180.00	
38	350.00		350.00	
20,910.00		8,325.00	3,395.00	9,190.00
10%		7,492.50	3,055.50	8,271.00
		40.00	0.00	480.00
		1,050.00	120.00	1,200.00
		8,582.50	3,175.50	9,951.00

		Revised	Cross	Check
1	80.00	40.00		
2	80.00			80
3	400.00			400.00
	560.00	40.00	0.00	480.00
1	1,200.00			1,200.00
2	120.00	80.00		
3	120.00	80.00		
4	150.00	120.00		
5	120.00		120.00	
6	80.00	20.00		
7	1,200.00	750.00		
	2,990.00	1,050.00	120.00	1,200.00

r	?	x	
2,700.00	435.00	175.00	
395.00	165.00	30.00	
380.00	185.00	850.00	
850.00	2,080.00	1,350.00	
1,350.00	950.00	465.00	
1,650.00	520.00	75.00	
90.00	465.00	25.00	
540.00	820.00	135.00	
65.00	65.00	300.00	
85.00	135.00	180.00	
110.00	410.00	350.00	
110.00	285.00		
	90.00		
	1,655.00		
	390.00		
8,325.00	8,650.00	3,935.00	20,910.00
90.00	90.00	90.00	90.00
7,492.50	7,785.00	3,541.50	18,819.00
40.00	80.00	40.00	
	400.00		
40.00	480.00	40.00	560.00
80.00	1,200.00	40.00	
80.00		40.00	
120.00		30.00	
20.00		120.00	
750.00		60.00	
		450.00	
1,050.00	1,200.00	740.00	2,990.00
7,492.50	7,785.00	3,541.50	18,819.00
40.00	480.00	40.00	560.00
1,050.00	1,200.00	740.00	2,990.00
8,582.50	9,465.00	4,321.50	22,369.00
p	?	l	
7,532.50	9,465.00	1,050.00	18,047.50

Lauren.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 27/5/2019

Survey Details:

Date of loss	7-May-18
Date of appointment	10-May-18
Date of survey	11-May-18
Location of survey	MBM WHEELPOWER PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLW3055J
Make and Model	MERCEDES BENZ GLC250 4MATIC
Date of registration	6-Feb-18
Parf Rebate	
Market Value	\$ 202,000.00
Parf Rebate	\$ 74,577.00
Nett Loss	\$ 127,423.00

Repair details:

Initial Estimate	\$ 22,369.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 8,890.50
Check items (estimate)	\$ -
Labour	\$ 2,250.00
Total	\$ 11,140.50
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>6 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: Insured rear ended third party vehicle. Inform insured and he aware that his NCD is affected and AXA to settle at best.

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	11,920.34	
Loss of use	\$	-	
Loss of rental	\$	1,050.00	7DAYS X \$150
Loss of income	\$	-	
LTA search fees	\$	2.00	
Others		-	
Proposed Total	\$	12,972.34	



MANDATE IA (S8M00GOH / SLW 3055J)

Type

🔍 Question

Message

Liability: Insured rear ended third party vehicle. Inform insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$11,920.35 (w/GST) Loss of Rental : \$1,050.00 (7days x \$150) LTA Search: \$2.00 Total: \$12,972.34 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (27/05/2019)

Reply



Re:MANDATE IA (S8M00GOH / SLW 3055J)

Type

🔗 Question

Message

Hi, pls offer COR : \$10,900 (w/GST) Loss of Rental : \$1,050.00 (7days x \$150) LTA Search: \$2.00. TY

Reply

« Re:RE: Re:MANDATE IA (S8M00GOH / SLW 3055J)

Type

🔗 Question

Message

Hi, pls proceed as per mandate. TY.

[Reply](#)



mbm wheelpower
DARE TO BE

Your ref: XD7648E
Our ref : SLW3055J

5th July 2018

AXA Insurance (Singapore) Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

TEL: 6338 7288

Attn: Motor Claims Dept

WITHOUT PREJUDICE

Dear Sir / Mdm,

Accident involving SLW3055J and XD7648E along Slip Road of Lower Delta Road Into Jalan Bt Merah on 07/05/2018 at 12:00hrs

We refer to the above said accident.

Our investigation reveals that you are the insurers of the vehicle XD7648E at the material time of the accident and that the said accident was caused solely by the negligence of the driver insured by your company. We hereby propose a direct settlement for our client's claim.

We enclosed herewith copy of

- 1 Final repair invoice
- 2 Authorisation Letter
- 3 Discharge Voucher
- 4 Car rental invoice
- 5 GIA search

We are instructed to claim the following

1 Costs of Repair - Lump sum - (\$11,140.50 + 7% gst)	\$ 11,920.34
2 Loss of rental (\$150 X 7 Days)	\$ 1,050.00
3 Gia search fee	\$ 2.00
Grand Total:	<u>\$ 12,972.34</u>

Please kindly let us know whether you are prepared to settle our client's claim.

Thanks & Warmest Regards,



Yin Siew
HP: 8588 3198
yinsiew.kon@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd
160 Sin Ming Drive #06-02
Sin Ming Autocity Singapore 575722
Customer Service Hotline 6262 8888
www.mbmwheelpower.com.sg
Company Registration Number: 200204110W
GST Registration Number: M90368446L



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008637/Kwa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: ERNEST TAY		Date : 13-09-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 7648E	Veh. Inspected	SLW 3055J
Policy No.	VFX/P1582555	Coverage (\$)	0.00
Claim No.	S8M00GOH	Excess (\$)	0.00
Assign From	ERNEST TAY	Assign Date	10/05/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDC2539462F308024	Colour	METALLIC BLACK
Odometer	7989	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/60 R18	BRIDGESTONE	9 mm
L/H Front Tyre	235/60 R18	BRIDGESTONE	9 mm
R/H Rear Tyre	235/60 R18	BRIDGESTONE	9 mm
L/H Rear Tyre	235/60 R18	BRIDGESTONE	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/05/2018	Inspection Date	11/05/2018
Survey held at	160 SIN MING DRIVE		
Repairer	MBM WHEELPOWER PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 3055J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE (CONSISTENT)	BENT	2,700.00	2,434.00
1	TAIL GATE WEATHERSTRIP (CONSISTENT)	DISTORTED	395.00	395.00
1	TAIL GATE INNER TRIM (CONSISTENT)	CRACKED	435.00	435.00
1	TAIL GATE INNER HANDLE GARNISH (CONSISTENT)	SERVICEABLE	165.00	-
1	TAIL GATE SWITCH BUTTON (CONSISTENT)	SERVICEABLE	175.00	-
1	TAIL GATE SWITCH COVER (CONSISTENT)	SERVICEABLE	30.00	-
1	TAIL GATE BUZZER (CONSISTENT)	NOT NECESSARY	185.00	-
1	REAR WINDSCREEN (CONSISTENT)	NOT NECESSARY	2,080.00	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	380.00	190.00
1	FLOOR BOARD COMPARTMENT COVER (CONSISTENT)	NOT NECESSARY	950.00	-
1	TAIL GATE LAMP RH (CONSISTENT)	CRACKED	850.00	420.00
1	TAIL GATE LAMP LH (CONSISTENT)	SERVICEABLE	850.00	-
1	TAIL LAMP RH (CONSISTENT)	CRACKED	1,350.00	497.00
1	TAIL LAMP LH (CONSISTENT)	SERVICEABLE	1,350.00	-
1	REAR BUMPER (CONSISTENT)	BENT	1,650.00	832.00
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	90.00	90.00
1	REAR BUMPER LOWER COVER (CONSISTENT)	DENTED	540.00	405.00
1	REAR BUMPER LOWER TRIM (CONSISTENT)	NOT NECESSARY	520.00	-
1	TAIL PIPE COVER RH (CONSISTENT)	BENT	465.00	310.00
1	TAIL PIPE COVER LH (CONSISTENT)	TO REPAIR SEE LABOUR	465.00	-
1	REAR BUMPER TOWING COVER RH (CONSISTENT)	SERVICEABLE	75.00	-
1	REAR REINFORCEMENT (CONSISTENT)	BENT	820.00	485.00
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	CRACKED	65.00	65.00
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	NOT NECESSARY	65.00	-
1	DECOUPLING RING (CONSISTENT)	SERVICEABLE	25.00	-
1	EXHAUST PIPE TIP RH (CONSISTENT)	BENT	135.00	135.00
1	EXHAUST PIPE TIP LH (CONSISTENT)	TO REPAIR SEE LABOUR	135.00	-
1	LOADING COMPARTMENT RIGHT (CONSISTENT)	CRACKED	410.00	410.00
1	LOADING COMPARTMENT FLAP (CONSISTENT)	BENT	285.00	285.00

Report Ref No. CC4/ASM18008637/Kwa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	RIVET (CONSISTENT)	NECESSARY	90.00	90.00
1	END PANEL (CONSISTENT)	BENT	1,655.00	1,362.00
1	END PANEL TOP GARNISH (CONSISTENT)	CRACKED	390.00	275.00
2	REAR BUMPER SIDE BRACKET LH & RH @ \$150.00 (CONSISTENT)	TO REPAIR SEE LABOUR	300.00	-
1	TAIL GATE "MERCEDES" LOGO (CONSISTENT)	NECESSARY	85.00	85.00
1	TAIL GATE "GLC 250" EMBLEM (CONSISTENT)	NECESSARY	110.00	110.00
1	TAIL GATE "4 MANTIC" EMBLEM (CONSISTENT)	NECESSARY	110.00	110.00
1	REAR WINDSCREEN WIPER (CONSISTENT)	SERVICEABLE	180.00	-
1	REAR WIPER MOTOR (CONSISTENT)	SERVICEABLE	350.00	-
1	TAIL GATE INNER LOWER TRIM (CONSISTENT) (ADDITIONAL)	DENTED	325.00	325.00
	LESS 10% DISCOUNT		-2,123.50	-974.50
			19,111.50	8,770.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	BODY SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	400.00	-
			560.00	120.00
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF TAIL PIPE COVER LH, TAIL PIPE COVER LH AND REAR BUMPER SIDE BRACKET LH & RH.		1,200.00	1,200.00
	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR.		120.00	80.00
	TO REMOVE & TRANSFER TAILGATE INNER LINING & GARNISH TO NEW TAIL GATE.		120.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN TO NEW TAILGATE.		150.00	120.00
	TO CONDUCT WHEEL ALIGNMENT CHECK.	NOT NECESSARY	120.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,200.00	750.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE , REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE REAR RH TAIL LAMP PANEL, REAR RH FENDER, REAR REINFORCEMENT. (ADDITIONAL)	NOT NECESSARY	400.00	-
	TO SPRAY PAINT ON THE REAR RH TAIL LAMP PANEL, REAR RH FENDER, REAR REINFORCEMENT, END PANEL.	NOT NECESSARY	750.00	-
			4,140.00	2,250.00
GRAND TOTAL			23,811.50	11,140.50
RECOMMENDED COST OF REPAIRS				11,140.50

Report Ref No. CC4/ASM18008637/Kwa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.