



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008637/Kwa3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 13-09-2019



ATTN: RICHARD ANG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	XD 7648E	<b>Veh. Inspected</b>	SLW 3055J
<b>Policy No.</b>	VFX/P1582555	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M00GOH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	RICHARD ANG	<b>Assign Date</b>	10/05/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ GLC250 (A)	<b>c.c</b>	1991
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	WDC2539462F308024	<b>Colour</b>	METALLIC BLACK
<b>Odometer</b>	7989	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	235/60 R18	BRIDGESTONE	9 mm
<b>L/H Front Tyre</b>	235/60 R18	BRIDGESTONE	9 mm
<b>R/H Rear Tyre</b>	235/60 R18	BRIDGESTONE	9 mm
<b>L/H Rear Tyre</b>	235/60 R18	BRIDGESTONE	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	07/05/2018	<b>Inspection Date</b>	11/05/2018
<b>Survey held at</b>	160 SIN MING DRIVE		
<b>Repairer</b>	MBM WHEELPOWER PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>6 Working Days</b>
-------------------------------------	-----------------------